

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 10/12/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 13 days.

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1406/2018/PH
Date : 8-Dec-18

Vehicle IN workshop. Kindly arrange for survey.

AXA Insurance Singapore Pte Ltd

8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Hi Adrian

*You recommended 13 days
We took 15 days exclude 1 PH
and 1 Sunday - jb - 17 Apr 19*

Attn: Motor Claims Dept
Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr Lee Woo Tuck
Address : Blk 541 Bukit Panjang Ring Rd
: #22-863
Singapore 670541
Telephone : HP +6581389139
Type of Claim : Own Damage Claims
Policy No. : GA 233986
Vehicle No : **SLJ 4190 M**
Model Code : Audi A7 SB 2.0 TFSI
Model / Year : Jan-16
Engine No : CYP 005908
Chassis No : WAUZZZ4G6GN077913
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Dec-18
Place of Accident : BT Panjang Rd cross junction TWDS CCK Rd.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLJ 4190 M .

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To tow and recover vehicle from scene of accident. <i>(By owner)</i>	S/N \$	280.00	\$ 74.90
2	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	\$ 480.00
3	To dislodge and reinstall A-pillar, lhs front and rear door harness, multi-lock system and power window devices. Inspect for damages.	S/N \$	780.00	\$ 390.00
4	To remove and reinstall front seat assembly, back rest, ABCD pillar trims, sill trims, carpets, electronic components and fuse tray.	S/N \$	1,800.00	\$ 1,800.00
5	To remove centre console and dashboard assy for A-pillar and door hinge renewal. Inspect for damages.	S/N \$	3,200.00	\$ 3,200.00
6	To dismantle front bumper, lhs fender, lhs headlight, lhs front door, lhs rear door, lhs sill panel trim. Cut out and reweld lhs A-pillar lower and lhs sill panel. To repair lhs rear fender. Renew lhs front fender, lhs front door, lhs rear door, lhs wing mirror assy and lhs sill panel trim. Re-organize crashmanagement components. Reinstall all parts removed. <i>(Added 1 days as spoken, repairing if inner reinforcement)</i>	\$	8,400.00	\$ 4,900.00
SUB TOTAL LABOUR CHARGES			\$ 14,940.00	\$ 10,844.90

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLJ 4190 M .

<u>S/n</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
		<i>c/f</i>		\$ 10,844.90
7	To respray lhs front fender, lhs front door, lhs wing mirror cover, hinges, lhs rear door, lhs sill panel trim, lhs rear fender, lhs A-pillar lower, lhs sill panel and door handle. To carry out joint sealant works and stone chip treatment.		\$ 6,700.00	\$ 5,150.00
8	To renew lhs front and rear rims. To carry out wheel alignment. Inspect front suspension assy for further damages.	S/N	\$ 320.00	\$ 320.00
9	To carry out diagnostic check.	S/N	\$ 384.00	\$ 384.00
TOTAL LABOUR CHARGES			\$ 22,344.00	\$ 16,698.90

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 4190 M .

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER ADAPTER - LH	\$ 32.00	
2	FRONT WHEEL SPOILER - LH	\$ 335.00	
3	FRONT STONE CHIP GUARD - LH	\$ 220.00	\$ 219.50
4	ADHESIVE TAPE	\$ 49.00	
5	BRACKET FOR TRIM - FRONT LH	\$ 14.00	\$ 14.00
5	GUIDE PIECE - LH	\$ 37.00	\$ 37.00
6	FRONT FENDER - LH	\$ 1,496.00	\$ 1,496.00
7	ATTACHMENT PARTS FOR FENDER	\$ 88.00	
8	FRONT FENDER STONE GUARD FILM - LH	\$ 99.00	\$ 98.20
9	FRONT FENDER BARCKET - LH UPPER	\$ 16.00	
10	FRONT FENDER BRACE - LH	\$ 72.00	
11	CLOSING ELEMENT FOR FENDER - LH	\$ 46.00	\$ 47.90
12	SEALING ELEMENT - LH	\$ 35.00	
13	SEAL WING - LH	\$ 18.00	\$ 17.10
14	WHEEL HOUSING LINNER - LH	\$ 246.00	\$ 246.00
15	ATTACHMENT PARTS FOR WHEEL HOUSING LINER	\$ 62.00	\$ 62.00
16	SIDE MEMBER TRIM - LH	\$ 815.00	\$ 814.50
17	ATTACHMENT PARTS FOR SIDE MEMBER TRIM	\$ 111.00	\$ 111.00
18	ADHESIVE TAPE FOR SIDE MEMBER TRIM	\$ 14.00	\$ 13.70
19	STONE GUARD FILM - LH FRONT	\$ 102.00	\$ 102.00
20	SILL TRIM STRIP - LH FRONT	\$ 163.00	\$ 163.00
SUB-TOTAL SPARE PARTS CHARGES		\$ 4,070.00	\$ 3,441.90

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 4190 M .

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 3,441.90
21	SILL TRIM STRIP - SATIN BLACK - LH REAR	\$	136.00	\$ 136.00
22	FRONT DOOR - LH	\$	3,703.00	\$ 3,703.00
23	BONDING AGENT	\$	43.00	
24	CLEANING SOLUTION	\$	64.00	
25	BUMP STOP BUFFER	\$	13.00	
26	ATTACHMENT PARTS FOR DOOR	\$	161.00	
27	OUTER DOOR SEAL - LH	\$	150.00	\$ 149.50
28	DOOR HINGE - LH UPPER	\$	149.00	\$ 148.50
29	DOOR HINGE - LH LOWER	\$	153.00	\$ 152.50
30	DOOR CATCH	\$	112.00	
31	COVER FOR DOOR CATCH	\$	20.00	
32	DOOR SEAL INNER - LH UPPER	\$	495.00	
33	DOOR SEAL INNER - LOWER	\$	139.00	
34	BRACKET FOR DOOR SEAL - LH	\$	37.00	
35	DOOR SEAL CORNER TRIM COVER - LH FRONT	\$	68.00	
36	DOOR HANDLE EXTERIOR TRIM PLATE - LH CHROME	\$	516.00	
37	KEY HOLE CAP - LH FRONT	\$	97.00	
38	MOUNTING BAR - LH FRONT DOOR	\$	119.00	
39	POWER WINDOW LIFTER - LH	\$	323.00	
40	POWER WINDOW LIFTER MOTOR - LH	\$	273.00	
	SUB-TOTAL SPARE PARTS CHARGES		\$ 6,771.00	\$ 7,731.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 4190 M .

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
			\$ 7,731.40
		<i>c/f</i>	
41	DOOR CONTROL UNIT - LH FRONT	\$ 653.00	
42	MOLDING - ROFT CHROME - LH	\$ 611.00	
43	ROOF FRAME SEAL - LH	\$ 134.00	
44	WINDOW SLOT SEAL WITH TRIM STRIP - LH FRONT	\$ 294.00	\$ 293.50
45	WINDOW SLOT SEAL WITH TRIM STRIP - LH REAR	\$ 319.00	\$ 319.00
46	TRIM FOR B PILLARE - GLOSSY BLACK - LH	\$ 234.00	\$ 233.50
47	COVER FOR PILLAR B,SATIN BLACK - LH	\$ 15.00	\$ 14.70
48	WING MIRROR ASSEMBLY - LH	\$ 1,400.00	
49	WING MIRROR HOUSING - LH	\$ 238.00	
50	WING MIRROR GLASS - LH	\$ 1,094.00	
51	WING MIRROR COVER SIGNAL INDICATOR - LH	\$ 124.00	
52	FRONT DOOR GLASS - LH	\$ 1,059.00	\$ 1,059.00
53	REAR DOOR GLASS - LH	\$ 283.00	\$ 282.50
54	UNDERBODY TRIM - LH	\$ 273.00	
55	UNDERBODY TRIM - LH FRONT	\$ 128.00	
56	LED HEADLIGHT - LH	\$ 11,281.00	
57	REAR DOOR - LH	\$ 3,703.00	
58	OUTER DOOR SEAL - LH	\$ 150.00	
59	BONDING AGENT	\$ 43.00	
60	CLEANING SOLUTION	\$ 64.00	
	SUB-TOTAL SPARE PARTS CHARGES	\$ 22,100.00	\$ 9,933.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 4190 M .

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 9,933.60
61	ATTACHMENT PARTS FOR DOOR		\$ 75.00	
62	DOOR CATCH		\$ 112.00	
63	COVER FOR DOOR CATCH		\$ 20.00	
64	SECTIONAL PART -PILLAR A/B WITH FRAME		\$ 2,687.00	\$ 2,687.00
65	ARCYLIC SEALANT		\$ 180.00	\$ 180.00
66	CAVITY WAX		\$ 140.00	\$ 140.00
67	STONE CHIP TREATMENT		\$ 180.00	\$ 180.00
68	LHS RIM	2	\$ 450.00	\$ 450.00
69	SUNDRIES		\$ 800.00	\$ 68.60
	TOTAL SPARE PARTS CHARGES	:	\$ 48,455.00	\$ 13,639.20
	TOTAL LABOUR CHARGES	:	\$ 22,344.00	\$ 16,698.90
	GRAND TOTAL	:	\$ 70,799.00	\$ 30,338.10

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AXA Insurance Singapore Pte Ltd 8 Shenton Way #27-01 AXA Tower Singapore 068811 Attn: Motor Claims Dept Tel: 6880 4602 - Fax 6880 4838		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1406/2018/PH 11-Jan-19 CHANG 1 SLJ 4190 M Audi A7 SB 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	LED HEADLIGHT - LH	\$ 11,694.00	<i>not given</i>
GRAND TOTAL		\$ 11,694.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AXA Insurance Pte Ltd
No 8 Shenton Way
#27-01 AXA Tower
Singapore 068811
Attn: Motor Claims Dept
Yr Ref: SLJ 4190 M

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1406/2018/MAS

15 May 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLJ 4190 M, Audi A7 SB 2.0 TFSI

With reference to the above mentioned vehicle, no. **SLJ 4190 M**, claimant, **Mr. Lee Woo Tuck**, please find the related document as per attached.

1. A copy of the Original invoice no. 85013733 - \$31,712.77
2. A copy of letter of Discharge duly signed by client

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer generated document. No signature is required.

Norah Khai

Claims Dept

Encls

AXA Insurance – SLJ 4190 M

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 684 11183

Premium Automobiles

Telefax

to **AXA Insurance Singapore Pte Ltd**
8 Shenton Way
#27-01 AXA Tower
Singapore 068811
Attn: Motor Claims Dept
Your Ref: **SLJ4190M**

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1406/2018/TF

18 Jan 2018⁹

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi *A7SB 2.0 TFSI*
Vehicle Chassis No. : *WAUZZZ4G6GN077913*
Vehicle Regn No. : **SLJ4190M**
Vehicle Mileage : 51495KM
Vehicle Owner : Mr. Lee Woo Tuck
Certificate No : GA233986/1
Policy Excess : *\$ 749.00*
Accident Date : 5 December 2018
Place : Bt Panjang Rd cross Junction twds CCK Rd
Repair Cost : *\$ 31,712.77*
WIP No. : 35138
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : *Lee Woo Tuck*

Time : _____

Date : 18/1/18

Service Request Details

Claim	S8M015MK
Reference	CS/ASM18022034/Abbs2
Loss Date	December 5, 2018
Report Date	Dec 6, 2018 9:07:00 AM
Request Date	December 7, 2018
Due Date	December 7, 2019
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (ODI)
Type of Loss	Own Damage
Services	Accelerated workshop survey

Actions

Next Step: Complete Work Finish the work

More ▾

Vehicle Information	
Incident Vehicle Registration #	SLJ4190M
Make	AUDI
Model	A7 SPORTBACK 2.0 TFSI
Service Address	
55 Ubi Road 1 Road, , 408699	
Primary Contact/Insured	
LEE WOO TUCK BLK 541 BUKIT PANJANG RING RD, #22-863, 670541, Singapore	
Claim Handler	
TED Kitty 6568804602 kitty.teo@axa.com.sg	

Additional Instructions: EXCESS \$700

Document Type:

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
------	------	----------	--------	---------------

Service Request Details

Claim	S8M015MK
Reference	CS/ASM18022034/Albs2
Loss Date	December 5, 2018
Report Date	Dec 6, 2018 9:07:00 AM
Request Date	December 7, 2018
Due Date	December 7, 2019
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (OD)
Type of Loss	Own Damage
Services	Accelerated workshop survey

Actions

Next Step: Finish the work

Vehicle Information	
Incident Vehicle Registration #	SLJ4190M
Make	AUDI
Model	A7 SPORTBACK 2.0 TFSI
Service Address	
55 Ubi Road 1 Road...	408699
Primary Contact/Insured	
LEE WOO TUCK BLK 541 BUKIT PANJANG RING RD, #22-863, 670541, Singapore	
Claim Handler	
TEO Kitty 6568804602 kitty.teo@axa.com.sg	

Additional Instructions: EXCESS \$700

Messages Invoices History Documents Assessment Metrics Notes

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	ADJUSTED AMOUNT	STATUS	SHARE	CLONE
TEO Kitty	12/7/18 7:30 AM	0	29638.1	Open	<input type="button" value="Share"/>	<input type="button" value="Clone"/>

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

General Details

Involving: 1 2015 AUDI A7 SPORTBACK 2.0 TFSI (SLJ4190M)

Date of Loss: December 5, 2018

Time of Loss: 18:50

Loss Description: SLJ4190M (INSD) C/W FT7790E (TP)

Comment

Workshop Details

Total Rebate Amount: 87924

Nett Loss Amount: \$84,076.00

Assigned Workshop: LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion: 7

« Assessment Details

[General & Workshop Details](#)
[Vehicle & Driver Details](#)
[Taxes & Ratio](#)
[Parts & Labour](#)
[Miscellaneous](#)
[Summary](#)

Vehicle & Driver Details

Vehicle Registration#	SLJ4190M	Purchase Date	<input type="text" value="mm/dd/yyyy"/>
Registration State	<input type="text" value="SINGAPORE"/>	Registration Date *	<input type="text" value="01/27/2016"/>
Mileage	<input type="text" value="51495"/>	Age of Vehicle	<input type="text" value="2"/>

CATEGORY POLICY INFORMATION ASSESSMENT INFORMATION

Manufacturing Year	<input type="text" value="2015"/>
--------------------	-----------------------------------

Make	<input type="text" value="AUDI"/>
------	-----------------------------------

Model	<input type="text" value="A7 SPORTBACK 2.0 TFSI"/>
-------	--

Type	<input type="text" value=""/>
------	-------------------------------

Type of Paint	<input type="text" value=""/>
---------------	-------------------------------

Chassis No	<input type="text" value="WAUZZZ4G6GN077913"/>
------------	--

Engine No	<input type="text" value="CYP005908"/>
-----------	--

Engine Capacity	<input type="text" value="1984 cc"/>
-----------------	--------------------------------------

CATEGORY FNOL INFORMATION POST SURVEY INFORMATION

Driver Name	<input type="text" value="LEE WOO TUCK"/>
-------------	---

Date of Birth	<input type="text" value="July 13, 1958"/>
---------------	--

Age	<input type="text" value="60"/>
-----	---------------------------------

Occupation	<input type="text" value="Unknown"/>
------------	--------------------------------------

Education Qualification	<input type="text" value="Other"/>
-------------------------	------------------------------------

Driving Experience	<input type="text" value="40"/>
--------------------	---------------------------------

Driver License #	<input type="text" value=""/>
------------------	-------------------------------

Assessment Details

Detailed Assessment

Inspection Date * 

Condition of Vehicle at time of survey

Total Loss Yes No

Towing Charges

Voluntary Excess

Compulsory Excess

Young/Inexperienced/Unarmed Driver Excess

Other Excess

Steering (Serviceable) Yes No

Footbrake (Serviceable) Yes No

Handbrake (Serviceable) Yes No

Engine Modification Yes No

Pre-accident condition

Tyre Condition

Spare wheel

Rear Tyre Size

Rear left side

Rear right side

Age of Tyres

Front Tyre Size

Front left side

Front right side

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTR%	DISC QUNTY%	SALV AGES	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT.	0	74.9	0	0	Reviewing		
	0		TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	0	480	0	0	Reviewing		
	0		TO DISLodge AND REINSTALL A-PILLAR, LHS FRONT AND REAR DOOR HARNESS, MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	0	390	0	0	Reviewing		
	0		TO REMOVE AND REINSTALL FRONT SEAT ASSEMBLY, BACK REST, ABCD PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAY.	0	1800	0	0	Reviewing		

Claim Portal

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO CARRY OUT DIAGNOSTIC CHECK	0	364	0	0	Reviewing		

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR	Reviewing		15		
	0	FRONT BUMPER ADAPTER - LH	Reviewing		0	NOT NECESSARY	
	0	FRONT WHEEL SPOILER - LH	Reviewing		0	NOT NECESSARY	
	0	FRONT STONE CHIP GUARD - LH	Reviewing		219.5	NECESSARY	
	0	ADHESIVE TAPE	Reviewing		0	NOT NECESSARY	
	0	BRACKET FOR TRIM - FRONT LH	Reviewing		14	NECESSARY	
	0	GUIDE PIECE - LH	Reviewing		37	NECESSARY	
	0	FRONT FENDER - LH	Reviewing		1496	DENIED	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	SIDE MEMBER TRIM - LH	Reviewing		814.5	DISTORTED	
	0	ATTACHMENT PARTS FOR SIDE MEMBER TRIM	Reviewing		111	NECESSARY	
	0	ADHESIVE TAPE FOR SIDE MEMBER TRIM	Reviewing		13.7	NECESSARY	
	0	STONE GUARD FILM - LH FRONT	Reviewing		102	NECESSARY	
	0	SILL TRIM STRIP - LH FRONT	Reviewing		163	NECESSARY	
	0	SILL TRIM STRIP - SATIN BLACK - LH REAR	Reviewing		136	NECESSARY	
	0	FRONT DOOR - LH	Reviewing		3703	DISTORTED	
	0	BONDING AGENT	Reviewing		0	NOT NECESSARY	
	0	CLEANING SOLUTION	Reviewing		0	NOT NECESSARY	
	0	BUMP STOP BUFFER	Reviewing		0	NOT NECESSARY	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	KEY HOLE CAP	Reviewing	0	0	NOT NECESSARY	
	0	MOUNTING BAR - LH FRONT DOOR	Reviewing	0	0	NOT NECESSARY	
	0	POWER WINDOW LIFTER - LH	Reviewing	0	0	NOT NECESSARY	
	0	POWER WINDOW LIFTER MOTOR - LH	Reviewing	0	0	NOT NECESSARY	
	0	DOOR CONTROL UNIT - LH FRONT	Reviewing	0	0	NOT NECESSARY	
	0	MOLDING - ROFT CHROME - LH	Reviewing	0	0	NOT NECESSARY	
	0	ROOF FRAME SEAL - LH	Reviewing	0	0	NOT NECESSARY	
	0	WINDOW SLOT SEAL WITH TRIM STRIP - LH FRONT	Reviewing	293.5	293.5	CUT	
	0	WINDOW SLOT SEAL WITH TRIM STRIP - LH REAR	Reviewing	319	319	CUT	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	UNDERBODY TRIM - LH FRONT	Reviewing	0	0	NOT NECESSARY	
	0	LED HEADLIGHT - LH	Reviewing	0	0	NOT NECESSARY	
	0	REAR DOOR - LH	Reviewing	0	0	REPAIR	
	0	OUTER DOOR SEAL - LH	Reviewing	0	0	NOT NECESSARY	
	0	BONDING AGENT	Reviewing	0	0	NOT NECESSARY	
	0	CLEANING SOLUTION	Reviewing	0	0	NOT NECESSARY	
	0	ATTACHMENT PARTS FOR DOOR	Reviewing	0	0	NOT NECESSARY	
	0	DOOR CATCH	Reviewing	0	0	NOT NECESSARY	
	0	COVER FOR DOOR CATCH	Reviewing	0	0	NOT NECESSARY	
	0	SECTIONAL PART - PILLAR A / B WITH FRAME	Reviewing	2687	2687	BUCKLED	
	0	ARCYLIC SEALANT	Reviewing	180	180	NECESSARY	
	0	CAVITY WAX	Reviewing	140	140	NECESSARY	

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Estimated Claim Amount \$0.00 Adjusted Claim Amount \$29,638.10

CATEGORY	ESTIMATE	ADJUSTED
Labour	\$0.00	\$16,698.90
Miscellaneous	\$0.00	\$13,639.20
Excess		-\$700.00

Submit for Review