



EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	STONE CHIP TREATMENT	Reviewing		180	NECESSARY	
	0	LHS RIM	Reviewing		450	CUT	
	0	SUNDRIES	Reviewing		68.6	NECESSARY	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	TRIM FOR B PILLAR - GLOSSY BLACK - LH	Reviewing		233.5	CUT	
	0	COVER FOR PILLAR B, SATIN BLACK - LH	Reviewing		14.7	NECESSARY	
	0	WING MIRROR ASSEMBLY - LH	Reviewing		0	NOT NECESSARY	
	0	WING MIRROR HOUSING - LH	Reviewing		0	REPAIR	
	0	WING MIRROR GLASS - LH	Reviewing		0	NOT NECESSARY	
	0	WING MIRROR COVER SIGNAL INDICATOR - LH	Reviewing		0	NOT NECESSARY	
	0	FRONT DOOR GLASS - LH	Reviewing		1059	CUT	
	0	REAR DOOR GLASS - LH	Reviewing		282.5	CUT	
	0	UNDERBODY TRIM - LH	Reviewing		0	NOT NECESSARY	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	ATTACHMENT PARTS FOR DOOR	Reviewing	0	0	NOT NECESSARY	
	0	OUTER DOOR SEAL - LH	Reviewing	149.5	149.5	NECESSARY	
	0	DOOR HINGE - LH UPPER	Reviewing	148.5	148.5	BENT	
	0	DOOR HINGE - LH LOWER	Reviewing	152.5	152.5	BENT	
	0	DOOR CATCH	Reviewing	0	0	NOT NECESSARY	
	0	COVER FOR DOOR CATCH	Reviewing	0	0	NOT NECESSARY	
	0	DOOR SEAL INNER - LH UPPER	Reviewing	0	0	NOT NECESSARY	
	0	DOOR SEAL INNER - LOWER	Reviewing	0	0	NOT NECESSARY	
	0	BRACKET FOR DOOR SEAL - LH	Reviewing	0	0	NOT NECESSARY	
	0	DOOR SEAL CORNER TRIM COVER - LH FRONT	Reviewing	0	0	REPAIR	
	0	DOOR HANDLE EXTERIOR TRIM PLATE - LH CHROME	Reviewing	0	0	REPAIR	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	ATTACHMENT PARTS FOR FENDER	Reviewing	0	0	NOT NECESSARY	
	0	FRONT FENDER STONE GUARD FILM - LH	Reviewing	98.2	98.2	NECESSARY	
	0	FRONT FENDER BRACKET - LH UPPER	Reviewing	0	0	NOT NECESSARY	
	0	FRONT FENDER BRACE - LH	Reviewing	0	0	NOT NECESSARY	
	0	CLOSING ELEMENT FOR FENDER - LH	Reviewing	47.9	47.9	DAMAGED	
	0	SEALING ELEMENT - LH	Reviewing	0	0	NOT NECESSARY	
	0	SEAL WING - LH	Reviewing	17.1	17.1	DAMAGED	
	0	WHEEL HOUSING LINER - LH	Reviewing	246	246	DEFORMED	
	0	ATTACHMENT PARTS FOR WHEEL HOUSING LINER	Reviewing	62	62	NECESSARY	



EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO REMOVE CENTRE CONSOLE AND DASHBOARD ASSY FOR A-PILLAR AND DOOR HINGE RENEWAL. INSPECT FOR DAMAGES.	0	3200	0	0	Reviewing		
	0		TO DISMANTLE FRONT BUMPER, LHS FENDER, LHS HEADLIGHT, LHS FRONT DOOR, LHS REAR DOOR, LHS SILL PANEL TRIM, CUT OUT AND REWELD LHS A-PILLAR LOWER AND LHS SILL PANEL.)	0	4900	0	0	Reviewing		
	0		TO REPAIR LHS REAR FENDER, RENEW LHS FRONT FENDER, LHS FRONT DOOR, LHS REAR DOOR, LHS WING MIRROR ASSY AND LHS SILL PANEL TRIM, RE-ORGANIZE CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED.)	0	0	0	0	Reviewing		
	0		TO RESPRAY LHS FRONT FENDER, LHS FRONT DOOR, LHS WING MIRROR COVER, HINGES, LHS REAR DOOR, LHS SILL PANEL TRIM, LHS REAR FENDER, LHS A-PILLAR LOWER, LHS SILL PANEL AND DOOR HANDLE, TO CARRY OUT JOINT SEALANT WORKS AND STONE CHIP TREATMENT.	0	5150	0	0	Reviewing		
	0		TO RENEW LHS FRONT AND REAR RIMS, TO CARRY OUT WHEEL ALIGNMENT, INSPECT FRONT SUSPENSION ASSY FOR FURTHER DAMAGES.	0	320	0	0	Reviewing		



CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Sum Insured	0	0	License Type		
Market Value	0	172000	License Issue Date		mm/dd/yy
			License Expiration Date		mm/dd/yy
			Address	BLK 541 BUKIT PANJANG RING RD, #22-863, 670541, Singapore	
			Address type	Residential	
			Gender	Male	
			Marital status	Married	
			Identification #	S1289014A	





NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 RESURVEY.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	May 29, 2019
 PRELI ADVISED SLJ 4190M - 1.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	April 23, 2019
 PRELI ADVISED SLJ 4190M.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	December 11, 2018
 SLJ 4190M ESTIMATE_0001.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	December 11, 2018
 photograph.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	December 11, 2018
 SLJ4190M INSD GIA.PDF	Reports & Statement	GIA Report	RATAN BHOSALE Pragati	December 6, 2018
 OD EMAIL.pdf	Letters and Correspondence	Workshop	RATAN BHOSALE Pragati	December 6, 2018