

ASS. REC. BY:

REF: CS/C7118022038/Atd3

Special Instruction:

Surveyor
menmen

Adian

ASSIGNMENT (Office)

From (Person):

Elaine cheong

of

C71

Date/Time: 7/12/18 @ 1:33pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJ41520E

Insured:

SKK 7225L

at Workshop m/s

MCS Garage

Tel:

9270 0917

of

10 kaki Bukit Rd 2 # 03-25 First East Centre.

Policy No:

DMPCSN3027141800

Claim No:

SNM18D05611C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 02/12/2018

CA / REV / REP. / REV 24 HRS 'up

H.O.D. Endorsement:

Date/Time:

2:02pm @ 7/12/18

Person Contacted:

Kendrick

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SJ41520E -x

SKK 7225L -x

lump Sum \$8000 - Finalized (Red: 49565.56, 86%)

REF:

ASSIGNMENT

19/11/09.

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of:

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR. Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJU1520E

Yr Regn

2009 Nov

Type: ☒ M/Car ☐ M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW- 520i

C/C

1995

Colour

Black

A/C

Insured / Std / NI / NA

Sp. Reading

146645

T/Radio

Insured / Std / NI / NA

Eng/No:

C/No:

WBANT120300X30352

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R16

R:

225/55R16

BS / ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

07/12/18

Survey held at

MCS Garage

Des. of Damages: ☒ Fr / ☒ Rear / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

T.P. Ling.

mv: 32k.

PV: 24k

Nett: 8k

RECEIVED 08 MAY 2013

Date/Time, File Pass to?



Preli. Report

8/5 Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

14

Resurvey No. of Trip:

1

5371A Buspen

Survey Fee:

Transportation:

) S - RS - SI

) Photos

) Others

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

TP
3000/-

TOTAL

320

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Dec 2018		07 Dec 2018 13:33 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ANG SIEW LIAN, ID: S1103455A		
Main Claimant:	FAST & FURIOUS AUTOMOTIVE, Co. Reg. No.: 53295371A		
Vehicle Reg. No.:	SJU1520E	Date of Loss:	02/12/2018 08:00 - :59
Claim Type:	TP / SNM18D05611C02	Policy/Cover Note No.:	DMPCSN3027191800 (Comprehensive)
Vehicle Reg. No. (Insured):	SKK7225L	Policy No. (Claimant):	5097328601
		Excess:	S\$0.00
Repairer:	MCS GARAGE (HQ) 10 KAKI BUKIT ROAD 2, #03-25 FIRST EAST CENTRE, 417868 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/12/2018]		
Driver/Custodian (Insured):	ANG SIEW LIAN (63 / Female), NRIC: S1103455A		
Adj Asg. Remarks:	NO EST, ASSIGN ADRIAN LING AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths

Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
SEGA PARAM
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
JANICE HAN JIA LIN
TAN YINGXIAN, SELWYN
CHEONG YUNHUI, CLARISSA
EDISON TAM CHYI EU

Unique Entity Number :200721148H

✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6

#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)

FAX ✓ : (65) 65356802 (General)

: (65) 65355905 (Litigation)

E-mail : jactan@visionlawllc.com

BRANCH

TEL : 65 63580703

FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO **HEAD OFFICE** FOR THIS MATTER

Our Ref: AM.jt.Ins.M89.108902.18 (sj)
Your Ref: **SNM18D05611C02**

07 December 2018

CHINA TAIPING INSURANCE (S'PORE) PTE LTD

3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Attention: Motor Claims Department

BY FAX: 6224 7175

email: claimsdept@sg.cntaiping.com

email: lucas.lee@sg.cntaiping.com

Dear Sirs,

ACCIDENT INVOLVING SJY 1520 E & SKK 7225 J ON 02 DECEMBER 2018 ALONG JALAN SENANG & SENANG CRESCENT AT ABOUT 0800 HOURS

We refer to your letter dated 06 December 2018 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of Adrian Ling as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue:

MCS Garage

10 Kaki Bukit Road 2

#03-25 First East Centre

Singapore 417868

Contact Person:

Mr Kendrick (9270 0917) / 8285-7623 (Ah Hock)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALLI M
(HEAD OFFICE)

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

cc: SJU 1520 E – By Fax: 6538-4322

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.


EDMUND MOTOR

Visit us to enjoy: **0% Downpayment**
1.98% Loan | 1 Year Warranty by BCC
1 Free Servicing | High Trade-in




SGCARMART CARNIVAL
15-16th December 2018
@ Downtown East


FOR SALE BY OWNER
Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!
[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Year COE Renewal Toyota Corolla Altis 1.6A


\$2000 Downpayment! Monthly
\$538 Onwards! Lowest 2.88%
P.a. @ GV Cars Financing!
GV Credit Pte Ltd StarAd


CERTIFIED PRE-OWNED MERCEDES-BENZ

[View our cars](#)

Browse by Category
Save Search
Print
Sort by Date Posted
20 results/page

9 vehicles
Search 5 Series 520i
Advanced Search
Search
View All

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	5 Series 520i	Any	Any	2009	Any	Any	Any	Available
	☐ BMW 5 Series 520i	\$29,800	N.A	19-Feb-2009	1,995 cc	-	Luxury	Available
The One And Only White Beauty With 1 Ownership, Owner Bought It Brand New From PML, Well Maintained By Owner Till Today. Renew The COE Now At \$30K Plus And Only Depreciate At Only \$6K Plus Per Year To... ☆ Posted: 24-Nov-2018 Tags: 2009 BMW 520i, 2009 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW								
	☐ BMW 5 Series 520i XL (New 10-yr COE)	\$61,800	\$6,170 /yr	25-Feb-2009	1,995 cc	240,000 km	Luxury	Available
Major Parts Changed. 4 Sep Just Spent \$5k To Gearbox Overhaul, Valve Body, Gearbox Oil Cooler, Engine Oil Cooler And Starter. Got Receipts To Prove. \$63000 For 10 Years COE. ☆ Posted: 07-Dec-2018 Tags: 2009 BMW 520i, 2009 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW								
	☐ BMW 5 Series 520i XL (New 10-yr COE)	\$65,800	\$6,570 /yr	27-Mar-2009	1,995 cc	-	Luxury	Available
100% Loan Available. Low Down Payment Available, No Worries About Down Payment, Bank And In House Loan Available, Low Interest Rate, Low Down Payment Or No Down Payment Available, High Trade In, Fast A... ☆ Posted: 29-Nov-2018 Tags: 2009 BMW 520i, 2009 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW								
	☐ BMW 5 Series 520i XL	\$28,400	N.A	07-Apr-2009	1,995 cc	166,000 km	Luxury	Available
Matte Frozen Blue Spraywork Done, Rsw 19" Rims, Car In A Very Good And Healthy Condition, Owner Selling Due To Change Of Car, Ideal For Coe Renewal Or Good For A Short Term Driving, Consignment Unit,... Prem Roy Motoring ☆ Posted: 03-Dec-2018 Tags: 2009 BMW 520i, 2009 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW								
 GET YOUR COE RENEWAL LOAN Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.								
	☐ BMW 5 Series 520i XL (New 10-yr COE)	\$65,800	\$6,570 /yr	10-Jul-2009	1,995 cc	-	Luxury	Available
New Arrival! Cheapest In Town! (Low Depreciation Of \$6.5K Per Annum Only!) High Spec! XL Model! New Facelift! M-Sport Bodykit! Nice Gunmetal Grey! Very Mint Condition! Interior And Exterior Look Like ... ☆ Posted: 06-Dec-2018 Tags: 2009 BMW 520i, 2009 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW								
	☐ BMW 5 Series 520i XL	\$31,800	\$10,100 /yr	17-Nov-2009	1,995 cc	102,069 km	Luxury	Available
Ideal For Short Term Drive & Renewal COE. Road Tax Till May 2019! Low Depreciation! High Loan At Low Interest Rate! Fully Agent (PML) Unit. Warranty & Servicing Can Be Arrange. High Trade-In Are Wel... ☆ Posted: 19-Nov-2018 Tags: 2009 BMW 520i, 2009 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW								
	☐ BMW 5 Series 520i XL	\$31,800	\$9,920 /yr	23-Nov-2009	1,995 cc	133,000 km	Luxury	Available
Best Price For Short Term Use, Also Suitable For COE Renewal, Call Now For Test Drive. ☆ Posted: 04-Dec-2018 Tags: 2009 BMW 520i, 2009 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW								

[Shortlisted](#)
[History](#)
[Compare](#)



☐ **BMW 5 Series 520i**

\$35,600

\$12,930 /yr

21-Dec-2009

1,995 cc

Luxury

Available

Can You Believe? This Car Is Still Good As New, Very Low Usage. Outside Is Kilat, Inside Also Still New. Leather All Good Smells. No Engine Oil Leak At All. High LTA Rebates, Present LTA Rebates Is Ov...

DIRECT OWNER

★ Posted: 02-Dec-2018 Tags: 2009 BMW 520i, 2009 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW



☐ **BMW 5 Series 520i XL**

\$32,800

\$11,130 /yr

31-Dec-2009

1,995 cc

Luxury

Available

Major Wear And Tear Done, Include New AC Compressor, New Radiator And Water Pump, New Brake Booster And Vacuum Pump, New Ignition Coil, New Amaron Battery, New Lower Arms (all), New Rotor And Brake Pa...

★ Posted: 21-Nov-2018 Tags: 2009 BMW 520i, 2009 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make **Model** **Price** **Depreciation** **Reg Date** **Eng Cap** **Mileage** **Veh Type** **Status**

For old advertisements, view Expired ads


20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used 5 Series 520i, 5 Series 520i Singapore, used 5 Series 520i Singapore, used 5 Series 520i, used vehicles Singapore or even buy used 5 Series 520i Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow **sgCarMart.com**



[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	5371A
Vehicle Details	
Vehicle No.:	SJU1520E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Dec 2018
Vehicle Make:	B.M.W.
Vehicle Model:	520I AUTO ABS AIRBAG 2WD XENON HEADLAMP
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	C060I510N46B20BE
Chassis No.:	WBANT12030CX30352
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$44,567.00
Original Registration Date:	19 Nov 2009
First Registration Date:	19 Nov 2009
Transfer Count:	1
Actual ARF Paid:	\$44,567.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Nov 2019
PARF Rebate Amount:	\$22,283.00
Intended COE Rebate Details	
COE Expiry Date:	18 Nov 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$18,002.00
COE Rebate Amount:	\$1,705.00
Total Rebate Amount:	\$23,988.00

The information contained herein is correct as at 07 Dec 2018

OK

MCS Garage

10 Kaki Bukit Road 2 #03-25, First East Centre Singapore 471868

Tel: 9270 0917 6538 4322

TP Chiam
Denise

Vehicle No.: SJU 1520E

Model: B M W

<u>QTY</u>	<u>List Price:</u>	<u>Prices \$</u>
1	Front bonnet <i>Distorted</i>	2435.45 ✓
1	Front bonnet BMW logo <i>new</i>	59.95 ✓
2	Front bonnet lock- R/L @ 108.25 <i>Dend</i>	216.50 ✓
2	Front bonnet lock catch- R/L @ 41.55 <i>Dend</i>	83.10 ✓
1	Front bonnet lock cable <i>new</i>	110.20 +
1	Front bonnet safety lock <i>new</i>	89.65 x
1	Front bonnet insulator <i>crushed</i>	183.38 ✓
15	Front bonnet insulator clips @ 4.50 <i>new</i>	67.50 <i>30</i>
2	Front bonnet hinges- R/L @ 115.00 <i>new</i>	230.00 +
2	Front bonnet damper- R/L @ 141.60 <i>new</i>	283.20 +
1	Front bumper <i>Distorted</i>	1658.20 ✓
4	Front bumper PDC sensor @ 311.63 <i>2 pieces dend</i>	1246.52 <i>500</i>
1	Front bumper PDC sensor with harness <i>new</i>	216.50 x
1	Front bumper CTR grille <i>crushed</i>	121.45 ✓
2	Front bumper fog lamps- R/L @ 271.20 <i>new</i>	542.40 +
2	Front bumper fog lamp grille @ 61.95 <i>new</i>	123.90 +
1	Front bumper sponge <i>crushed</i>	110.82 ✓
1	Front bumper reinforcement <i>Best</i>	691.75 ✓
2	Front bumper reinforcement stay- R/L @ 135.00 <i>Best</i>	270.00 ✓
2	Front bumper side grip- R/L @ 45.00 <i>new</i>	90.00 ✓
2	Front bumper spray nozzle cover @ 18.20 <i>new</i>	36.40 x
1	Front bumper top seal <i>new</i>	68.60 ✓
2	Front fenders- R/L @ 1018.20 <i>new</i>	2036.40 +
2	Front fender inner shields- R/L @ 128.15 <i>new</i>	256.30 +
2	Front grille- R/L @ 180.85 <i>crushed</i>	361.70 ✓
2	Front headlamps- R/L @ 2342.55 <i>crushed</i>	4685.10 ✓
2	Front headlamp lower brackets @ 48.85 <i>crushed</i>	97.70 ✓
2	Front headlamp spray nozzle pen @ 182.60 <i>new</i>	365.20 +
1	Front headlamp spray nozzle hose <i>new</i>	142.60 x
2	Front headlamp panels- R/L @ 189.65 <i>new</i>	379.30 x
2	Front headlamp HID bolb @ 381.95 <i>new</i>	763.90 x

Vehicle No.: SJU 1520E

2	Front headlamp control unit @ 830.60	1661.20 +
2	Front headlamp side garnish @ 81.50	163.00 +
1	Front support panel <i>Disbled</i>	990.80 ✓
1	Front support top panel <i>3rd</i>	280.60 ✓
2	Horn @ 130.20 <i>New</i>	260.40 +
1	Air cleaner intake <i>new</i>	81.55 +
1	Air cleaner box <i>new</i>	441.60 +
1	Air con condenser <i>Dented</i>	949.65 ✓
1	Air con condenser air vent	187.25 +
1	Air con discharge pipe	441.50 +
1	Air con suction pipe	460.50 +
1	Air con liquid pipe	281.60 +
1	Air con compressor	1101.50 +
1	Radiator assy <i>Dented</i>	890.50 ✓
2	Radiator side brackets @ 48.55	97.10 +
2	Radiator top mount @ 28.85	57.70 +
2	Radiator bottom mount @ 28.85	57.70 +
1	Radiator top hose	68.60 +
1	Radiator bottom hose	142.60 +
1	Radiator auxiliary fan assy	1365.50 +
2	Engine mountings- R/L @ 241.20	482.40 +
1	Engine under cover	189.90 +
1	Oil cooler @ 680.90	680.90 +
1	Front door- RH <i>Dented</i>	1899.65 ✓
1	Front door outer handle	181.50 +
1	Front door glass outer moulding	241.20 +
1	Front door glass frame moulding	211.90 +
1	Front door glass run channel	255.63 +
1	Front door glass regulator assy	481.95 +
1	Front door inner lock	541.60 +
1	Front door inner trim board	891.60 +
1	Front door w/strip <i>new</i>	261.90 ✓
1	Rear door- RH <i>Dented</i>	1895.50 ✓
1	Rear door outer handle	181.50 +
1	Rear door 1/4 glass moulding	241.20 +

Vehicle No.: SJU 1520E

1	Rear door glass outer moulding		211.90	+
1	Rear door glass frame moulding		241.60	+
1	Rear door glass run channel		245.51	+
1	Rear door glass regulator assy	NH	481.95	+
1	Rear door glass guide	NH	160.90	+
1	Rear door inner lock		488.65	+
1	Rear door inner trim board		891.60	+
1	Rear door checker		115.20	+
2	Rear door hinges @ 89.95		179.90	+
1	Rear door w/strip	NH	281.60	✓
1	Rear door opening w/strip	NH	292.30	+
1	Rear fender- RH	Distorted	2150.90	✓
1	Rear fender inner panel	Rep	1655.00	+
1	Rear fender inner shield	2	189.63	+
1	Rear fender absorber- RH		441.50	+
1	Rear top arm		560.90	+
1	Rear lower arm	NH	840.90	+
1	Rear knuckle arm	NH	1365.00	+
1	Rear wheel hub bearing		541.60	+
1	Rear drive shaft- RH		1381.50	+
1	Side sill panel garnish- RH	Rehd	621.55	✓
1	Centre pillar- RH	Rep	1085.90	+
1	Rear windscreen moulding	NH	195.50	✓
			51263.84	
Less 5%			(2563.19)	
Subtotal			48700.65	

Special Nett Item:

1 Set	Front no plate with holder	Best	60.00	✓
1 bot	Air con oil	NH	65.00	30
1 bot	Radiator coolant	NH	60.00	40
1 Set	Rear windscreen sealant	NH	80.00	60
1	Rear sport wheel- RH	NH	650.00	+
1	Rear tyre- RH	Punched	450.00	200
Subtotal			1365.00	

Vehicle No.: SJU 1520E

Labour Charges:

Towing charges	150.00	120
To checking F/R electrical wiring	120.00	30
To remove, refix R/interior trims to assist repair	150.00	80
To remove, refix R/windscreen	180.00	120
To remove, refix R/undercarriage	300.00	X
To check wheel alignment	120.00	80
To remove, refix A/C condenser and refill A/C gas	180.00	120
To respray undercoating	150.00	80
To dignos erase fault memory after repair	450.00	150
To respray painting and etc	2200.00	1400
Panel beating, cut, weld, remove and replacing above parts	3500.00	1800
Subtotal	7500.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

57565.65

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 25347.75

L/S: 8K ✓

14 Days.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18022038/ATD3N2
Date: 10/05/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3027191800
Claimant Vehicle No :	SJU1520E	Insured Vehicle No :	SKK7225L
Date of Loss:	02/12/2018	Nature of Claim:	TP
		Claim No:	SNM18D05611C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU1520E	Engine No:	C060I510N46B20BE
Make & Model:	BMW 520I, 2.0 ABS AIRBAG 2WD XENON HEADLAMP (A)	Chassis No:	WBANT12030CX30352
Reg. Date:	19/11/2009 (Man. Year: 2009)	Odometer:	146645 km
Colour:	Black		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R16	Rear Tyre Size:	225/55R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	50,065.65	21,367.76	28,697.89	57.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,500.00	3,980.00	3,520.00	46.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	57,565.65	25,347.76	32,217.89	55.97
Approved Total (Overridden) (S\$)		8,000.00		
Nett Amount (S\$)	57,565.65	8,000.00	49,565.65	86.10

INSPECTION

Date of Assignment:	07/12/2018	
Date Inspected:	07/12/2018 Inspected At:	MCS GARAGE (HQ) 10 KAKI BUKIT ROAD 2, #03-25 FIRST EAST CENTRE Singapore 417868
Estimated Period of Repair:	14.0 days	

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2019)
Parts:	143	BMW 520i 2.0 ABS AIRBAG 2WD XENON HEADLAMP (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJU1520E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Distorted	2,435.45 FL	*2,435.45 FL
2	1		*FRONT BONNET BMW LOGO	Necessary	59.95 FL	*59.95 FL
3	2		*FRONT BONNET LOCK-R/L	Damaged	216.50 FL	*216.50 FL
4	2		*FRONT BONNET LOCK CATCH-R/L	Damaged	83.10 FL	*83.10 FL
5	1		*FRONT BONNET LOCK CABLE	Not Necessary	110.20 FL	*- FL
6	1		*FRONT BONNET SAFETY LOCK	Not Necessary	89.65 FL	*- FL
7	1		*FRONT BONNET INSULATOR	Crumpled	183.38 FL	*183.38 FL
8	15		*FRONT BONNET INSULATOR CLIPS	Necessary	67.50 FL	*30.00 FL
9	2		*FRONT BONNET HINGES-R/L	Not Necessary	230.00 FL	*- FL
10	2		*FRONT BONNET DAMPER-R/L	Not Necessary	283.20 FL	*- FL
11	1		*FRONT BUMPER	Distorted	1,658.20 FL	*1,658.20 FL
12	1		*FRONT BUMPER PDC SENSOR (4 Pcs)	Damaged (2 Pcs only)	1,246.52 FL	*500.00 FL
13	1		*FRONT BUMPER PDC SENSOR WITH HARNESS	Not Necessary	216.50 FL	*- FL
14	1		*FRONT BUMPER CTR GRILLE	Cracked	121.45 FL	*121.45 FL
15	2		*FRONT BUMPER FOG LAMPS-R/L	Not Necessary	542.40 FL	*- FL
16	2		*FRONT BUMPER FOG LAMP GRILLE	Not Necessary	123.90 FL	*- FL
17	1		*FRONT BUMPER SPONGE	Cracked	110.82 FL	*110.82 FL
18	1		*FRONT BUMPER REINFORCEMENT	Bent	691.75 FL	*691.75 FL
19	2		*FRONT BUMPER REINFORCEMENT STAY-R/L	Bent	270.00 FL	*270.00 FL
20	2		*FRONT BUMPER SIDE GRIP-R/L	Necessary	90.00 FL	*90.00 FL
21	2		*FRONT BUMPER SPRAY NOZZLE COVER	Not Necessary	36.40 FL	*- FL
22	1		*FRONT BUMPER TOP SEAL	Necessary	68.60 FL	*68.60 FL
23	2		*FRONT FENDERS-R/L	Repair	2,036.40 FL	*- FL
24	2		*FRONT FENDER INNER SHIELDS-R/L	Not Necessary	256.30 FL	*- FL
25	2		*FRONT GRILLE-R/L	Cracked	361.70 FL	*361.70 FL
26	2		*FRONT HEADLAMPS-R/L	Cracked	4,685.10 FL	*4,685.10 FL
27	2		*FRONT HEADLAMP LOWER BRACKETS-R/L	Cracked	97.70 FL	*97.70 FL
28	2		*FRONT HEADLAMP SPRAY NOZZLE PEN	Not Necessary	365.20 FL	*- FL
29	1		*FRONT HEADLAMP SPRAY NOZZLE HOSE	Not Necessary	142.60 FL	*- FL
30	2		*FRONT HEADLAMP PANELS-R/L	Not Necessary	379.30 FL	*- FL
31	2		*FRONT HEADLAMP HID BOLB	Not Necessary	763.90 FL	*- FL
32	2		*FRONT HEADLAMP CONTROL UNIT	Not Necessary	1,661.20 FL	*- FL
33	2		*FRONT HEADLAMP SIDE GARNISH	Not Necessary	163.00 FL	*- FL
34	1		*FRONT SUPPORT PANEL	Distorted	990.80 FL	*990.80 FL
35	1		*FRONT SUPPORT TOP PANEL	Bent	280.60 FL	*280.60 FL
36	2		*HORN	Not Necessary	260.40 FL	*- FL
37	1		*AIR CLEANER INTAKE	Not Necessary	81.55 FL	*- FL
38	1		*AIR CLEANER BOX	Not Necessary	441.60 FL	*- FL
39	1		*AIR CON CONDENSER	Dented	949.65 FL	*949.65 FL
40	1		*AIR CON CONDENSER AIR VENT	Not Necessary	187.25 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*AIR CON DISCHARGE PIPE	Not Necessary	441.50 FL	*- FL
42	1		*AIR CON SUCTION PIPE	Not Necessary	460.50 FL	*- FL
43	1		*AIR CON LIQUID PIPE	Not Necessary	281.60 FL	*- FL
44	1		*AIR CON COMPRESSOR	Not Necessary	1,101.50 FL	*- FL
45	1		*RADIATOR ASSY	Dented	890.50 FL	*890.50 FL
46	2		*RADIATOR SIDE BRACKETS	Not Necessary	97.10 FL	*- FL
47	2		*RADIATOR TOP MOUNT	Not Necessary	57.70 FL	*- FL
48	2		*RADIATOR BOTTOM MOUNT	Not Necessary	57.70 FL	*- FL
49	1		*RADIATOR TOP HOSE	Not Necessary	68.60 FL	*- FL
50	1		*RADIATOR BOTTOM HOSE	Not Necessary	142.60 FL	*- FL
51	1		*RADIATOR AUXILIARY FAN ASSY	Not Necessary	1,365.50 FL	*- FL
52	2		*ENGINE MOUNTINGS-R/L	Not Necessary	482.40 FL	*- FL
53	1		*ENGINE UNDER COVER	Not Necessary	189.90 FL	*- FL
54	1		*OIL COOLER	Not Necessary	680.90 FL	*- FL
55	1		*FRONT DOOR-RH	Dented	1,899.65 FL	*1,899.65 FL
56	1		*FRONT DOOR OUTER HANDLE	Not Necessary	181.50 FL	*- FL
57	1		*FRONT DOOR GLASS OUTER MOULDING	Not Necessary	241.20 FL	*- FL
58	1		*FRONT DOOR GLASS FRAME MOULDING	Not Necessary	211.90 FL	*- FL
59	1		*FRONT DOOR GLASS RUN CHANNEL	Not Necessary	255.63 FL	*- FL
60	1		*FRONT DOOR GLASS REGULATOR ASSY	Not Necessary	481.95 FL	*- FL
61	1		*FRONT DOOR INNER LOCK	Not Necessary	541.60 FL	*- FL
62	1		*FRONT DOOR INNER TRIM BOARD	Not Necessary	891.60 FL	*- FL
63	1		*FRONT DOOR W/STRIP	Necessary	261.90 FL	*261.90 FL
64	1		*REAR DOOR-RH	Dented	1,895.50 FL	*1,895.50 FL
65	1		*REAR DOOR OUTER HANDLE	Not Necessary	181.50 FL	*- FL
66	1		*REAR DOOR 1/4 GLASS MOULDING	Not Necessary	241.20 FL	*- FL
67	1		*REAR DOOR GLASS OUTER MOULDING	Not Necessary	211.90 FL	*- FL
68	1		*REAR DOOR GLASS FRAME MOULDING	Not Necessary	241.60 FL	*- FL
69	1		*REAR DOOR GLASS RUN CHANNEL	Not Necessary	245.51 FL	*- FL
70	1		*REAR DOOR GLASS REGULATOR ASSY	Not Necessary	481.95 FL	*- FL
71	1		*REAR DOOR GLASS GUIDE	Not Necessary	160.90 FL	*- FL
72	1		*REAR DOOR INNER LOCK	Not Necessary	488.65 FL	*- FL
73	1		*REAR DOOR INNER TRIM BOARD	Not Necessary	891.60 FL	*- FL
74	1		*REAR DOOR CHECKER	Not Necessary	115.20 FL	*- FL
75	2		*REAR DOOR HINGES	Not Necessary	179.90 FL	*- FL
76	1		*REAR DOOR W/STRIP	Necessary	281.60 FL	*281.60 FL
77	1		*REAR DOOR OPENING W/STRIP	Not Necessary	292.30 FL	*- FL
78	1		*REAR FENDER-RH	Distorted	2,150.90 FL	*2,150.90 FL
79	1		*REAR FENDER INNER PANEL	Repair	1,655.00 FL	*- FL
80	1		*REAR FENDER INNER SHIELD	Not Necessary	189.63 FL	*- FL
81	1		*REAR FENDER ABSORBER-RH	Not Necessary	441.50 FL	*- FL
82	1		*REAR TOP ARM	Not Necessary	560.90 FL	*- FL
83	1		*REAR LOWER ARM	Not Necessary	840.90 FL	*- FL
84	1		*REAR KNUCKLE ARM	Not Necessary	1,365.00 FL	*- FL
85	1		*REAR WHEEL HUB BEARING	Not Necessary	541.60 FL	*- FL
86	1		*REAR DRIVE SHAFT-RH	Not Necessary	1,381.50 FL	*- FL
87	1		*SIDE SILL PANEL GARNISH-RH	Deformed	621.55 FL	*621.55 FL
88	1		*CENTRE PILLAR-RH	Repair	1,085.90 FL	*- FL
89	1		*REAR WINDSCREEN MOULDING	Necessary	195.50 FL	*195.50 FL
90	1		*SET FRONT NO PLATE WITH HOLDER	Bent	60.00 FS	*60.00 FS
91	1		*BOT AIR CON OIL	Necessary	65.00 FS	*30.00 FS
92	1		*BOT RADIATOR COOLANT	Necessary	60.00 FS	*40.00 FS
93	1		*SET REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
94	1		*REAR SPORT WHEEL-RH	Not Necessary	650.00 FS	*- FS
95	1		*REAR TYRE-RH	Punctured	450.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 52,628.84 22,471.85

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 5.00/5.00% (S\$)					2,563.19	1,104.09
Total Parts (S\$)					50,065.65	21,367.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	150.00	120.00
2	TO CHECKING F/R ELECTRICAL WIRING	New	120.00	30.00
3	TO REMOVE,REFIX R/INTERIOR TRIMS TO ASSIST REPAIR	New	150.00	80.00
4	TO REMOVE,REFIX R/WINDSCREEN	New	180.00	120.00
5	TO REMOVE,REFIX R/UNDERCARRIAGE	New	300.00	0.00
6	TO CHECK WHEEL ALIGNMENT	New	120.00	80.00
7	TO REMOVE,REFIX A/C CONDENSER AND REFILL A/C GAS	New	180.00	120.00
8	TO RESPRAY UNDERCOATING	New	150.00	80.00
9	TO DIGNOS ERASE FAULT MEMORY AFTER REPAIR	New	450.00	150.00
10	TO RESPRAY PAINTING AND ETC	New	2,200.00	1,400.00
11	PANEL BEATING,CUT,WELD,REMOVE AND REPLACING ABOVE PARTS	New	3,500.00	1,800.00
Gross Labour Cost (S\$)			7,500.00	3,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >