



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKF1228S

Ng Yun Ruenn Lena

Blk 18D Holland Drive
#22-427
Singapore 275018

Work: 96690045PATRICK

Vehicle & Document Information

WIP No **29184**
Reg No/Reg Date **SKF1228S / 20/03/2012**
Date In/Mileage **/ 0**
Chassis No **WDD2040452A673448**
Engine No **27191031352234**
Make/Model **MB/C 180K (BlueEFFI**
Colour/Trim **027 779 Alabandine / 042 228 Leather Alp**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	06/12/2018/ 17:13	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE :2100293578 // 05-12-2018 DRIVE IN:06-12-2018 // TP CAR NO:SLT8385P (AXA INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
A BPILAB REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.				960 1440.00
A BPIRES RESPRAY REAR BUMPER				600 720.00
S BPNSUB SUPPLY & INSTALL 1 SET OF REVERSE SENSORS.NETT				? 680.00
M REAR BUMPER	1.00	1361.96	00.00	1361.96
M LH/R BUMPER GARNISH	1.00	132.56	00.00	132.56
M RH/R BUMPER GARNISH	1.00	132.56	00.00	132.56
M CT/R BUMPER GARNISH	1.00	186.40	00.00	186.40
M RH/R BASIC MOUNTING FOR BUMPER	1.00	67.58	00.00	67.58
M REAR CROSS MEMBER	1.00	670.31	00.00	670.31

Rasul

Hp 90010068

3 days

17/01/19 @ 1600

Renewing 64 paint

Alan Quek

Cycle & Carriage Industries Pte Ltd

Body Care & Repair Center

DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272

Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 5,771.37
7% GST on 5771.37 404.00

Authorized signatory and company stamp

Total Payable 6,175.37

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg