

INS. CASE OWNER:

Winnetto

CC 4, Asm 180

2054, Afa352

LKK: 86498
IDAC:

Surveyor:

2up

DOI:

ASSIGNMENT

7/12/8

Date / Time:

7/12/8

Registered in Merimen:

Pre-assign / CCU / FTE

SKK 5455A

S8m015KG



Insured Vehicle No.:

Name of Insured:

Subramaniam S/o Muryandi

Insured Tel No.:

HP:

D.O.A: 6/12/8

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SKX 2310K



INSRS:

WSP:

Tel:

Liability:

RMKS:

Premium



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

4/12
UPA

SKX 2310K - x; SKK 5455A - x

Video footage / Smart claim to drive

11/12/18

Spoke to OI (Mr Subramaniam), confirmed accident details, moving in to road about without stop/ slow down, intrusion TP claim and HUP issue. OI agree to settle and aware HUP will be affected. Send letter to OI.

16/8/19

Rec cor to TP (Pending LOD).

23/8/19

LOD m CTO seek mandate.

24/8/19

Pending mandate approval.

4/9

TP claiming LOD. Re-seek mandate. mandate approved \$18,375, offer TP GTS \$18,360 (Pending acceptance). TP reject offer. Re-offer max \$18,375 call-in. Pending acceptance.

9/9

TP reject offer. seek AAA instruction to offer TP @ GTS \$18,490.00. (Approved).

PRELIMINARY ADVICE

Date/Time:

Sent By:

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 11/12/18

After call ltr to OI: 15/12/18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: Adrain

Repair Cost:

PIP

SS

15,601.00

(10 days)

Reduction:

\$12,746

% 45

FINAL SETTLEMENT

Date/Time:

10/10/19

3.50pm

Confirm with:

Kelvin

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

H1

Repair Cost:

(W/GS)

SS

16,693.07

Loss of Rental (LOR):

SS

2475.00

(15 days)

x \$165.00

Loss of Use (LOU):

SS

(5 days)

x

Loss of Income (LOI):

SS

(5 days)

x

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

Disbursement:

SS

Legal Cost

SS

Total:

SS

19,170.07

FINAL PAYMENT

Date/Time:

19/12/19

Confirm with:

Premium Automobiles Pte Ltd

Payor:

SS

19,170.07

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

SS

Payee (if N/A):

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs: 10 ~~hrs~~ days Res.: Yes or No

Lum Sum: 1-b-1 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

TPAXA.

MV: 118K

PV: 73.3K

Nett: 44.7K

* 10 repair days + 2 Sundays + 1 PRS = 13 days. P/P \$15,601.00. (Red = \$12,746.00 / 45%)

Date/Time, File Pass to?

☐

Preli. Report

☐

Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photos

Other

TOTAL

Report Format:

Lump Sum / I.B.I. (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Veh No SKX2310K Yr Regn 2015 Oct

Type: ☒ M. Car / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Lexus ES250

C.G. 2494.

Colour: Black A/C Insured / Std / NI / NA

Sp. Reading 63298 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTHBJ166002087402

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ STD A/Rim or

Tyre Size: F: 215/55 R17.

R: 215/55 R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.I. 07/12/18

Survey held at

Premium

Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKX 2310 K.

S/N	Parts Description	Damaged Parts & Prices			
		S/Nett			
1	FRONT DOOR - LH	\$	1,342.00	\$	1,342.00
2	FRONT DOOR SEAL - LH	\$	242.00	\$	242.00
3	FRONT DOOR LOWER SEAL - LH	\$	132.00	\$	176.00
4	FRONT WINDOW LOWER CHROME MOUNDING - LH	\$	176.00		
5	FRONT WINDOW UPPER CHROME MOUNDING - LH	\$	209.00		
6	FRONT DOOR B-PILLER TRIM - LH OUTER	\$	330.00		
7	FRONT DOOR HANDLE - LH	\$	418.00	\$	380.00
8	FRONT DOOR HANDLE END CAP - LH	\$	55.00	\$	55.00
9	FRONT DOOR HANDLE BRACKET - LH	\$	396.00	\$	396.00
10	FRONT DOOR LOCK - LH	\$	363.00	\$	924.00
11	FRONT WINDOW LIFTER - LH	\$	264.00		
12	FRONT DOOR CHECK ROD - LH	\$	209.00		
13	REAR DOOR - LH	\$	1,386.00	\$	1,386.00
14	REAR DOOR SEAL - LH	\$	242.00	\$	242.00
15	REAR DOOR LOWER SEAL - LH	\$	77.00	\$	77.00
16	REAR DOOR FRONT SEAL - LH	\$	88.00	\$	88.00
17	REAR WINDOW LOWER CHROME MOUNDING - LH	\$	154.00		
18	REAR WINDOW UPPER CHROME MOUNDING - LH	\$	264.00		
19	REAR DOOR HANDLE - LH	\$	418.00		
SUB TOTAL SPARE PARTS CHARGES		\$	6,765.00	\$	5,308.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKX 2310 K.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	
	c/f	\$	5,308.00
21	REAR DOOR HANDLE END CAP - LH	\$ 121.00	
22	REAR DOOR HANDLE BRACKET - LH		
23	REAR DOOR LOCK - LH	\$ 924.00	
24	REAR WINDOW LIFTER- LH	\$ 264.00	
25	REAR DOOR HINGE - LH UPPER	\$ 66.00	
26	REAR DOOR HINGE - LH LOWER	\$ 66.00	
27	REAR DOOR CHECK ROD -LH	\$ 209.00	
28	SIDE SKIRT - LH	\$ 770.00	\$ 770.00
29	SIDE SKIRT CLIP	12 \$ 60.00	\$ 120.00
30	B-PILLAR PANEL / SILL PANEL - LH		
31	FRONT DOOR INNER SEAL - LH	\$ 341.00	
32	REAR DOOR INNER SEAL - LH	\$ 341.00	
33	FRONT ENTRANCE SCUFF PLATE - LH	\$ 187.00	
34	REAR ENTRANCE SCUFF PLATE - LH	\$ 143.00	
35	RIM "17	\$ 2,750.00	\$ 2,750.00
36	Sundries	\$ 300.00	
37	A/Sealer	S/N \$ 180.00	\$ 90.00
38	C/Wax	S/N \$ 140.00	\$ 70.00
39	Added parts -s ee attached	\$ 308.00	\$ 183.00
40	Stone Chip	S/N \$ 180.00	\$ 90.00
TOTAL SPARE PARTS CHARGES		\$ 14,115.00	\$ 9,381.00
TOTAL LABOUR CHARGES		\$ 14,232.00	\$ 6,220.00
GRAND TOTAL		\$ 28,347.00	\$ 15,601.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKX 2310 K.

S/n	Nature of Jobs	Estimated Charges			
1	To remove and reinstall lhs front and rear door's multi-lock systems and power window devices. Inspect for damages and renew if necessary.	S/N	\$	560.00	\$ 280.00
2	To remove and reinstall lhs front seat assy, ABCD pillar trims, sill trims, floor carpets, electronic components and fuse trays. Disengage lhs seat belt and head airbag.	S/N	\$	1,800.00	\$ 900.00
3	To dismantle lhs front and rear doors, and lhs side member trim. Cut out and weld lhs B-pillar. Renew lhs front and rear doors, align to position. Repair lhs rear fender. Reinstall all parts removed.		\$	5,400.00	\$ 2,400.00
4	To respray rhs front and rear door, lhs side member trim, lhs sill panel, door entrances, B-pillar, lhs rear fender and rear bumper. To carry out joint sealer works and carry out stone chip treatment.		\$	6,000.00	\$ 2,400.00
5	To renew lhs front rim. Carry out wheel alignment.	S/N	\$	280.00	\$ 140.00
6	To carry out diagnostic check.	S/N	\$	192.00	\$ 100.00
TOTAL LABOUR CHARGES		:	\$	14,232.00	\$ 6,220.00

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AXA Insurance Singapore Pte Ltd 8 Shenton Way #27-01 AXA Tower Singapore 068811 Attn: Motor Claims Dept Tel: 6880 4602 - Fax 6880 4838		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/1401/2018/JE 20-Dec-18 CHANG 1 SKX 2310 K LEXUS ES 250	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	FRONT DOOR INNER SPOOGE - LH	\$ 88.00		
2	FRONT DOOR HANDLE UNDER SEAL - LH	\$ 88.00	\$	88.00
3	SRS AIRBAG STICKER	\$ 44.00	\$	40.00
4	REAR FENDER FOIL - LH	\$ 55.00	\$	55.00
5	CHASSIS NUMBER STICKER	\$ 33.00		
GRAND TOTAL		:	\$ 308.00	\$ 183.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1401/2018/JE
Date : 7-Dec-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle no : SKK 54555 A

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Hi Adrian

10 days -exclude 1 Sunday

jb 21 Jan 19

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr Quek Boon Chuon
Address : Blk 13 Ghim Moh Road
Singapore 270013
Telephone : HP +65 9176 2220
Type of Claim : Third Party Claims
Policy No. : 1700063827
Vehicle No : **SKX 2310 K**
Model Code : Toyota Lexus ES250 A
Model / Year : 30 Oct 2015
Engine No : 2ARF101864
Chassis No : JTHBJ1GG002087402
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Dec-18
Place of Accident : Along International Park

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1401/2018/JE
Date	:	7-Dec-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle no : SKK 54555 A

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name	:	Mr Quek Boon Chuon
Address	:	Blk 13 Ghim Moh Road Singapore 270013
Telephone	:	HP +65 9176 2220
Type of Claim	:	Third Party Claims
Policy No.	:	1700063827
Vehicle No	:	SKX 2310 K
Model Code	:	Toyota Lexus ES250 A
Model / Year	:	30 Oct 2015
Engine No	:	2ARF101864
Chassis No	:	JTHBJ1GG002087402
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	6-Dec-18
Place of Accident	:	Along International Park

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKX 2310 K.

S/n	Nature of Jobs	Estimated Charges
1	To remove and reinstall lhs front and rear door's multi-lock systems and power window devices. Inspect for damages and renew if necessary.	S/N \$ 560.00 280.
2	To remove and reinstall lhs front seat assy, ABCD pillar trims, sill trims, floor carpets, electronic components and fuse trays. Disengage lhs seat belt and head airbag.	S/N \$ 1,800.00 x 900.
3	To dismantle lhs front and rear doors, and lhs side member trim. Cut out and weld lhs B-pillar. Renew lhs front and rear doors, align to position. Repair lhs rear fender. Reinstall all parts removed.	\$ 5,400.00 2400.
4	To respray rhs front and rear door, lhs side member trim, lhs sill panel, door entrances, B-pillar, lhs rear fender and rear bumper. To carry out joint sealer works and carry out stone chip treatment.	\$ 6,000.00 2400.
5	To renew lhs front rim. Carry out wheel alignment.	S/N \$ 280.00 120.
6	To carry out diagnostic check.	S/N \$ 192.00 100.
TOTAL LABOUR CHARGES		: \$ <u>14,232.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKX 2310 K.

S/N	Parts Description		Damaged Parts & Prices S/Nett
1	FRONT DOOR - LH <i>Distorted</i>	\$	1,342.00 ✓ ✓
2	FRONT DOOR SEAL - LH <i>at</i>	\$	242.00 ✓
3	FRONT DOOR LOWER SEAL - LH <i>at</i>	\$	132.00 ✓ 176
4	FRONT WINDOW LOWER CHROME MOUNDING - LH <i>Part</i>	\$	176.00 +
5	FRONT WINDOW UPPER CHROME MOUNDING - LH <i>Part</i>	\$	209.00 +
6	FRONT DOOR B-PILLER TRIM - LH OUTER <i>new</i>	\$	330.00 +
7	FRONT DOOR HANDLE - LH <i>Part</i>	\$	418.00 ✓ 380
8	FRONT DOOR HANDLE END CAP - LH <i>Part</i>	\$	55.00 ✓
9	FRONT DOOR HANDLE BRACKET - LH <i>Damaged</i>	\$	396.00 ✓
10	FRONT DOOR LOCK - LH <i>Part</i>	\$	363.00 ✓ 924
11	FRONT WINDOW LIFTER - LH <i>new</i>	\$	264.00 +
12	FRONT DOOR CHECK ROD - LH <i>new</i>	\$	209.00 +
13	REAR DOOR - LH <i>Distorted</i>	\$	1,386.00 ✓
14	REAR DOOR SEAL - LH <i>Part</i>	\$	242.00 ✓
15	REAR DOOR LOWER SEAL - LH	\$	77.00 ✓
16	REAR DOOR FRONT SEAL - LH <i>new</i>	\$	88.00 ✓
17	REAR WINDOW LOWER CHROME MOUNDING - LH <i>Part</i>	\$	154.00 +
18	REAR WINDOW UPPER CHROME MOUNDING - LH <i>Part</i>	\$	264.00 +
19	REAR DOOR HANDLE - LH <i>new</i>	\$	418.00 +
SUB TOTAL SPARE PARTS CHARGES		:	\$ 6,765.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKX 2310 K.

S/N	Parts Description		Damaged Parts & Prices S/Nett
21	REAR DOOR HANDLE END CAP - LH <i>green</i>	\$	121.00 <i>x</i>
22	REAR DOOR HANDLE BRACKET - LH <i>green</i>		<i>x</i>
23	REAR DOOR LOCK - LH <i>new</i>	\$	924.00 <i>x</i>
24	REAR WINDOW LIFTER - LH <i>new</i>	\$	264.00 <i>x</i>
25	REAR DOOR HINGE - LH UPPER <i>Not New</i>	\$	66.00 <i>x</i>
26	REAR DOOR HINGE - LH LOWER <i>Not New</i>	\$	66.00 <i>x</i>
27	REAR DOOR CHECK ROD - LH <i>Not New</i>	\$	209.00 <i>x</i>
28	SIDE SKIRT - LH <i>Defect</i>	\$	770.00 <i>—</i>
29	SIDE SKIRT CLIP <i>new</i>	12 \$	60.00 <i>30 120</i>
30	B-PILLAR PANEL / SILL PANEL - LH <i>Replaced</i>		<i>x</i>
31	FRONT DOOR INNER SEAL - LH <i>green</i>	\$	341.00 <i>x</i>
32	REAR DOOR INNER SEAL - LH <i>green</i>	\$	341.00 <i>x</i>
33	FRONT ENTRANCE SCUFF PLATE - LH <i>green</i>	\$	187.00 <i>x</i>
34	REAR ENTRANCE SCUFF PLATE - LH <i>green</i>	\$	143.00 <i>x</i>
35	RIM "17 <i>cut</i>	\$	<u>2,750.00</u> <i>✓</i>
36	Sundries <i>Not New</i>	\$	300.00 <i>x</i>
37	A/Sealer <i>green</i>	S/N \$	180.00 <i>+ 90 ✓</i>
38	C/Wax <i>green</i>	S/N \$	140.00 <i>+ 70 ✓</i>
39	Stone Chip <i>green</i>	S/N \$	180.00 <i>+ 90 ✓</i>
TOTAL SPARE PARTS CHARGES		:	\$ 13,807.00
TOTAL LABOUR CHARGES		:	\$ 14,232.00
GRAND TOTAL		:	\$ 28,039.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

28704

29008

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AXA Insurance Singapore Pte Ltd 8 Shenton Way #27-01 AXA Tower Singapore 068811 Attn: Motor Claims Dept Tel: 6880 4602 - Fax 6880 4838		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/1401/2018/JE 20-Dec-18 CHANG 1 SKX 2310 K LEXUS ES 250
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	FRONT DOOR INNER SPOOGE - LH <i>per</i>		
2	FRONT DOOR HANDLE UNDER SEAL - LH <i>per</i>	\$ 88.00	<i>K</i>
3	SRS AIRBAG STICKER <i>per</i>	\$ 88.00	\$ 88.00
4	REAR FENDER FOIL - LH <i>per</i>	\$ 44.00	\$ 40.00
5	CHASSIS NUMBER STICKER <i>per</i>	\$ 55.00	\$ 55.00
		\$ 33.00	<i>X</i>
GRAND TOTAL		\$ 308.00	\$ 183.00

For Premium Automobiles Pte Ltd

Adrian Ling
H.S.


Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian L.
Surveyed Date : 07/12/01
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 10 days.



Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1401/2018/JE
Date	:	7-Dec-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle no : SKK 54555 A

AXA Insurance Singapore Pte Ltd

8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Attn: Motor Claims Dept
Tel: 6880 4602 - Fax 6880 4838

Owner's Name	:	Mr Quek Boon Chuon
Address	:	Blk 13 Ghim Moh Road Singapore 270013
Telephone	:	HP +65 9176 2220
Type of Claim	:	Third Party Claims
Policy No.	:	1700063827
Vehicle No	:	SKX 2310 K
Model Code	:	Toyota Lexus ES250 A
Model / Year	:	30 Oct 2015
Engine No	:	2ARF101864
Chassis No	:	JTHBJ1GG002087402
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	6-Dec-18
Place of Accident	:	Along International Park

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKX 2310 K.

S/n	Nature of Jobs	Estimated Charges
1	To remove and reinstall lhs front and rear door's multi-lock systems and power window devices. Inspect for damages and renew if necessary.	S/N \$ 560.00 280.
2	To remove and reinstall lhs front seat assy, ABCD pillar trims, sill trims, floor carpets, electronic components and fuse trays. Disengage lhs seat belt and head airbag.	S/N \$ 1,800.00 x 900.
3	To dismantle lhs front and rear doors, and lhs side member trim. Cut out and weld lhs B-pillar. Renew lhs front and rear doors, align to position. Repair lhs rear fender. Reinstall all parts removed.	\$ 5,400.00 2900.
4	To respray rhs front and rear door, lhs side member trim, lhs sill panel, door entrances, B-pillar, lhs rear fender and rear bumper. To carry out joint sealer works and carry out stone chip treatment.	\$ 6,000.00 2400. 1500.
5	To renew lhs front rim. Carry out wheel alignment.	S/N \$ 280.00 140
6	To carry out diagnostic check.	S/N \$ 192.00 100
TOTAL LABOUR CHARGES		: \$ 14,232.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKX 2310 K.

S/N	Parts Description	Damaged Parts & Prices S/Nett	
1	FRONT DOOR - LH <i>Distorted</i>	\$	1,342.00 ✓
2	FRONT DOOR SEAL - LH <i>at</i>	\$	242.00 ✓
3	FRONT DOOR LOWER SEAL - LH <i>at</i>	\$	132.00 ✓
4	FRONT WINDOW LOWER CHROME MOUNDING - LH <i>for</i>	\$	176.00 +
5	FRONT WINDOW UPPER CHROME MOUNDING - LH <i>for</i>	\$	209.00 +
6	FRONT DOOR B-PILLER TRIM - LH OUTER <i>new</i>	\$	330.00 +
7	FRONT DOOR HANDLE - LH <i>Dist</i>	\$	418.00 ✓
8	FRONT DOOR HANDLE END CAP - LH <i>Dist</i>	\$	55.00 ✓
9	FRONT DOOR HANDLE BRACKET - LH <i>?</i>	\$	396.00 ?
10	FRONT DOOR LOCK - LH <i>?</i>	\$	363.00 ?
11	FRONT WINDOW LIFTER - LH <i>new</i>	\$	264.00 +
12	FRONT DOOR CHECK ROD - LH <i>new</i>	\$	209.00 +
13	REAR DOOR - LH <i>Distorted</i>	\$	1,386.00 ✓
14	REAR DOOR SEAL - LH <i>for</i>	\$	242.00 ✓
15	REAR DOOR LOWER SEAL - LH	\$	77.00 ✓
16	REAR DOOR FRONT SEAL - LH <i>new</i>	\$	88.00 ✓
17	REAR WINDOW LOWER CHROME MOUNDING - LH <i>for</i>	\$	154.00 +
18	REAR WINDOW UPPER CHROME MOUNDING - LH <i>for</i>	\$	264.00 +
19	REAR DOOR HANDLE - LH <i>new</i>	\$	418.00 +
SUB TOTAL SPARE PARTS CHARGES		\$	6,765.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKX 2310 K.

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		<u>S/Nett</u>	
21	REAR DOOR HANDLE END CAP - LH <i>green</i>	\$	121.00 <i>+</i>
22	REAR DOOR HANDLE BRACKET - LH <i>green</i>		<i>+</i>
23	REAR DOOR LOCK - LH <i>new</i>	\$	924.00 <i>+</i>
24	REAR WINDOW LIFTER- LH <i>new</i>	\$	264.00 <i>+</i>
25	REAR DOOR HINGE - LH UPPER <i>?</i>	\$	66.00 <i>?</i>
26	REAR DOOR HINGE - LH LOWER <i>?</i>	\$	66.00 <i>?</i>
27	REAR DOOR CHECK ROD - LH <i>?</i>	\$	209.00 <i>?</i>
28	SIDE SKIRT - LH <i>Rehnd</i>	\$	770.00 <i>✓</i>
29	SIDE SKIRT CLIP <i>new</i>	12 \$	60.00 <i>30</i>
30	B-PILLAR PANEL / SILL PANEL - LH <i>Rehnd</i>		<i>+</i>
31	FRONT DOOR INNER SEAL - LH <i>green</i>	\$	341.00 <i>+</i>
32	REAR DOOR INNER SEAL - LH <i>green</i>	\$	341.00 <i>+</i>
33	FRONT ENTRANCE SCUFF PLATE - LH <i>green</i>	\$	187.00 <i>+</i>
34	REAR ENTRANCE SCUFF PLATE - LH <i>green</i>	\$	143.00 <i>+</i>
35	RIM "17 <i>cut</i>	\$	2,750.00
36	Sundries <i>?</i>	\$	300.00 <i>?</i>
37	A/Sealer <i>green</i>	S/N \$	180.00 <i>90</i>
38	C/Wax <i>green</i>	S/N \$	140.00 <i>70</i>
39	Stone Chip <i>green</i>	S/N \$	180.00 <i>90</i>
TOTAL SPARE PARTS CHARGES		:	\$ 13,807.00
TOTAL LABOUR CHARGES		:	\$ 14,232.00
GRAND TOTAL		:	\$ 28,039.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian L
Surveyed Date : 07/12/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 10 days.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AXA Insurance Singapore Pte Ltd 8 Shenton Way #27-01 AXA Tower Singapore 068811 Attn: Motor Claims Dept Tel: 6880 4602 - Fax 6880 4838		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/1401/2018/JE 20-Dec-18 CHANG 1 SKX 2310 K LEXUS ES 250
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	FRONT DOOR INNER SPOOGE - LH	\$ 88.00	
2	FRONT DOOR HANDLE UNDER SEAL - LH	\$ 88.00	\$ 88.00
3	SRS AIRBAG STICKER	\$ 44.00	\$ 40.00
4	REAR FENDER FOIL - LH	\$ 55.00	\$ 55.00
5	CHASSIS NUMBER STICKER	\$ 33.00	
GRAND TOTAL		\$ 308.00	\$ 183.00

For Premium Automobiles Pte Ltd

Authorised Signature



Service Request Details

Claim

S8M015RG

Reference

None

Loss Date

December 6, 2018

Request Date

December 7, 2018

Due Date

December 14, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

07-12-2018 @ 10:11am

Tony Verin

Adrian.

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKX2310K

Make

TPVD TOYOTA