

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5880H**AAD1812-040***Not Authorised*
1/1/2018

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5880H

VF1ABL15AUC281457

RENAULT

LATITUDE

5.12.2018

III**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>n</i> 1,108.46	<i>X</i>
2	1 BUMPER LOWER REAR	\$	<i>sn</i> 768.84	
3	1 BUMPER BRACKET CTR REAR	\$	<i>sn</i> 113.47	
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>sn</i> 135.97	
5	1 BUMPER RETAINER RH REAR	\$	<i>sn</i> 44.99	
6	1 BUMPER REFLECTOR RH	\$	<i>sn</i> 43.61	
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>sn</i> 135.97	
8	1 BUMPER RETAINER LH REAR	\$	<i>sn</i> 44.99	
9	1 BUMPER REFLECTOR LH	\$	<i>sn</i> 43.61	
10	1 BUMPER BEAM REAR	\$	<i>n</i> 777.52	
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>n</i> 225.95	
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>n</i> 225.95	
13	1 OUTER PANEL REAR (End Panel)	\$	<i>n</i> 1,471.77	
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>sn</i> 404.56	
15	1 TAILLAMP LH	\$	<i>sn</i> 552.55	
16	1 TAILLAMP PANEL LH	\$	<i>n</i> 986.70	
17	1 BOOT REAR	\$	<i>n</i> 2,872.68	

\$ **9,957.60**10% \$ **995.76**\$ **8,961.84****Special Nett**

1	1SET PARKING AID	\$	<i>sn</i> 700.00 <i>X</i>
2	1SET REAR BUMPER CLIP	\$	<i>na</i> 66.00 <i>X</i>
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00 <i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1812-040**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5880H

4 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn 10.00	}	X
5 1SET BUMPER RETAINER RH CLIP RR	\$	nn 20.00		
6 1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn 10.00		
7 1SET BUMPER RETAINER CLIP LH RR	\$	nn 20.00		
8 1SET BUMPER LOWER REAR RIVET	\$	nn 22.00		
9 1SET BUMPER LOWER REAR CLIP	\$	nn 66.00		
10 1 EXHAUST MOUNTING REAR	\$	nn 17.82		
11 2 REAR WINDSCREEN SELANT	\$	nn 80.00		
12 1 WINDSCREEN MOULDING	\$	nn 100.00	}	
13 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn 100.00		

TOTAL \$ 1,244.82**TOTAL PARTS \$ 10,206.66****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	nn 3,000.00	X
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1812-040**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5880H

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ *nn* 170.00 X

To check steering geometry and computer wheel
alignment

\$ *nn* 220.00 X**TOTAL \$ 7,410.00****Over All Total \$ 26,578.50****(LUMP SUM)****Repair Days****10 DAYS***1 day*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: