

**VIFI PTE LTD**

REPAIRS WITH ETHICS

Your Ref: SH8185E
Our Ref: SKX4810X

To: INDIA INT'L INS PTE LTD

CC

Email

Fax

Date: 06-12-18
From: Ezuwan
Fax: 6659 0111
Contact: 8811 1110
Make / Model: HONDA VEZEL 1.5X A
Chassis No.: RU11106470
Engine No.: L15B4026473
Year of Make: 2015
Accident Date: 03-12-18

ESTIMATE FOR VEHICLE NO. : SKX4810X

DESCRIPTION	QTY	List Price
REAR BUMPER <i>DE-</i>	1	\$ 980.00
REAR BUMPER CLIP <i>du -</i>	10	\$ 60.00
REAR TAIL GATE <i>9m -</i>	1	\$ 1,850.00
REAR HONDA EMBLEM <i>4m X</i>	1	\$ 60.00
REAR VEZEL EMBLEM <i>du -</i>	1	\$ 80.00
REAR END PANEL <i>repair</i>	1	\$ 680.00
REAR LH TAILGATE LAMP <i>X</i>	1	\$ 350.00
REAR RH TAILGATE LAMP <i>?</i>	1	\$ 350.00
Total: \$		4,410.00
LESS 10%		(441.00)
Parts Total: \$		3,969.00
<i>Resur after repair paint</i>		
SPECIAL NETT		
ANTI RUST COATING	1	\$ 60 150.00
BODY SEALANT	1	\$ 60 120.00
REVERSE SENSOR		\$ m 210.00
LABOUR		
TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS		\$ 400 500 600.00
TO CHECK & RECONNECT ALL NECESSARY WIRING		\$ 60 150.00
TO REMOVE & REPLACE REAR WINDSCREEN TO NEW TAIL GATE		\$ 120 150.00
TO DISMANTLE & TRANSFER TAIL GATE FITTINGS & MECHANISM TO NEW TAIL GATE / FACILITATE REPAIR		\$ 60 100.00
TO SPRAY PAINTING ON THE AFFECTED AREA		\$ 400 400 1,800.00
Total: \$		7,249.00
7% GST: \$		507.43
Grand Total: \$		7,756.43

Please survey the vehicle at :-

1 Bukit Batok Crescent
#06-12, WCEGA PLAZA
SINGAPORE 658064
(Kindly contact Ezuwan @ 8811 1110)

VIFI PTE LTD
1 BUKIT BATOK CRESCENT
#06-12, WCEGA PLAZA
t 67670011

Company Registration Number : 201315095D