

20/03/2002

ASS. REC. BY:

REF:

CS/FCI/8022074/KSD3ⁿ² Special Instruction:

Surveyor:

CWS

From (Person):

Kenneth

Karen Tan

ASSIGNMENT (Office)

of FCI

Date/Time:

4:47pm @ 07/12/18

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLS 5433J

Insured:

SHA 3056 U

at Workshop m/s

Ah Lim Motor

Tel:

64831244

of

No. 10 Amk Ind. Park 2A #01-09

Policy No:

Claim No:

D18008552MPSH

Sum Insured:

Excess:

D.O.A.

30/11/2018

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement:

Date/Time:

5:40pm @ 7/12/18

Person Contacted:

Wei Jeei

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLS 5433J - X

SHA 3056 U - CS/FCI/7014005/Ah Lim

D.O.A: 15/07/17

10/12/18 VNI Yef.

14/12/18 revised PA to Karen Tan via email.

1/4 B1192-37 Cabernet

REF: FCI

ASSIGNMENT

From: Date: 13/12/18
 Estimated Cost:
 OD: TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLS 5433J
 at Workshop n/s: Ah Lim Motor
 of No-10 AMK Ind. Park 2A #01-09
 Insured:
 Policy No:
 Claims No:
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh: 3:30pm

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: \$ 80k
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 02 days Res.: Yes or No
 Lum Sum: 1.21 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'DS'

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SLS 5433J Yr Regn: 09 17
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or Wagon: 1998
 Make: Mercedes A/5
 Colour: M. DBLue A/C: Insured / Std / NI / NA
 Sp. Reading: 22926 T/Radio: Insured / Std / NI / NA
 Eng/No:
 Ch/No: TM 6C W10711401 26145
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size F: 205/55R16
 R:
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front R/Bal. 2 mm
 L/Bal. 8 mm
 D.O.A. 7/11/18
 Rear R/Bal. 5 mm
 L/Bal. 5 mm
 D.O.I. 13/12/18
 Survey held at
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

14/12 File pcr to Coroner

(\$ 1,787.44 Red. 60%)

follow insured d.o.a. 30/11/2018.

RECEIVED 01 APR 2019

Date/Time, File Pass to?

01/04/19
Typist
☐
☒

Prel. Report

Final Report

Date/Time, File Return to?

3)

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) S + RS. SI

) Photos

) Others

TOTAL

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)☐ Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$) 1,192.32 P/P

110

50

50

10

220



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008552MFSH

Date: 14 December 2018

Our Ref: CS/FCI18022074/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLS 5433J .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 13/12/2018 at the premises of M/s Ah Lim Motor Company and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,979.76</u> .
Revised Estimate Amount	: S\$ <u>1,192.32</u> .
"Check" Items Amount	: S\$ <u>118 40</u> .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 2 Days

Yours faithfully,
Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	03-12-2018	Our Ref No.	D18008552MFSH
Accident Date	30-11-2018	Claim Type.	Third Party
Insured Vehicle	SHA3056U	Third Party Vehicle.	SLS5433J
Survey Location	NO. 10 ANG MO KIO IND PARK 2A #01-09 AMK AUTOPOINT		
Contact Person.	ZILA		
Contact No.	64831244/ 0	Fax No.	64836170
Survey Type	DIRECT SETTLEMENT:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	AH LIM MOTOR COMPANY	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	KARENT		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 14 December 2018 3:00 PM
To: 'Karen Tan'; 'CWS Motor Claims'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: SURVEY ASSESSMENT - D18008552MFSH/1
Attachments: SLS 5433J - Preli Advise -.pdf

Dear Karen,

Enclosed preliminary revised of vehicle SLS 5433J.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 7 December 2018 5:43 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008552MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 7 December 2018 4:47 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008552MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 0280F

Vehicle Details

Vehicle No.: SLS5433J
Vehicle to be Exported: No
Intended Deregistration Date: 03 Dec 2018
Vehicle Make: MAZDA
Vehicle Model: MAZDA5 WAGON 2.0 AT EU6
Primary Colour: Blue
Manufacturing Year: 2017
Engine No.: PE10520386
Chassis No.: JM6CW1071H0126145
Maximum Power Output: 111.0 kW (148 bhp)
Open Market Value: \$17,537.00
Original Registration Date: 27 Sep 2017
First Registration Date: 27 Sep 2017
Transfer Count: 1
Actual ARF Paid: \$17,537.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 26 Sep 2027
PARF Rebate Amount: \$13,152.00




Intended COE Rebate Details

COE Expiry Date: 26 Sep 2027
COE Category: E - Open - all except motorcycle
COE Period(Years): 10
QP Paid: \$48,005.00
COE Rebate Amount: \$42,311.00
Total Rebate Amount: \$55,463.00

The information contained herein is correct as at 03 Dec 2018

OK

Sketch Plan Pg. 4

REPUBLIC OF SINGAPORE		
IDENTITY CARD NO. S6960095F		
	Name JOHN ROY COX	
	Race CAUCASIAN	
	Date of birth 10-09-1969	Sex M
	Country/Place of birth UNITED KINGDOM	

90279127.

97060280F

96697566

N/C

Morning

Yes - Camera - 6m

5px.

In car

John Cox

Clare Savery

Matthew Cox (Child) (P)

Louise Cox (Child) (P)

Gemma Cox (Child) (P)

9501589	
	
NRIC No. S6960095F	
	Nationality BRITISH
	Date of issue 28-09-2018
Address 22 SPRINGLEAP VIEW SINGAPORE 787927	

Sketch Plan Pg. 6



redefining / insurance

Date: 03/12/18

To: Owner of Vehicle Number: SL54335

The following has been advised to you via your workshop, Ah Lim Motor Company through their staff, Zila Eileen / Mui Hong.

Please tick the applicable box if you had been advice on the content as seen below:

- ☒ You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
 - ☐ You had been advised by the workshop on the liability and merits of the case accordingly.
 - ☐ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
 - ☐ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
 - ☐ There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
 - ☐ The estimated waiting time for the spare parts to arrive is _____. The estimated arrival time does not include the repair period.
 - ☐ You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.
 - ☐ For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.
- For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using **any combination** of genuine original parts and/or original equipment manufacturer (OEM) parts.
- ☐ You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
 - ☐ For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.

☒ Others 1 claim, Third Party

Signed and acknowledge by:

[Signature]

Name and signature of policyholder/authorised driver

[Signature]

Name and signature of workshop personnel including company stamp





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : CLARE SAVEREUX
22 SPRINGLEAF VIEW

SINGAPORE 797927

TEL: 90279127

ATTN:

Estimate No: MC0913657

Date: 06 Dec 2018

Policy No: P209175

Veh Reg No: SLS5433J

Make/Model: MAZDA 5 WAGON 2.0
AT EU6

Your Ref No: SLS5433J

Claim Type: Third Party → MS 1st cap

Accident Date: 07/11/2018

TP Veh Reg No: SHA3056U

Not Authored
Resuming B&P claim

2 day

Estimate Repair Cost to Vehicle No :SLS5433J

Description	Quantity	List Price SS	Amount SS
SPARE PARTS			
1 TAILGATE EMBLEM	1 PC	42.00 X	
2 TAILGATE MAZDA LOGO LH	1 PC	43.10 X	
3 TAILGATE TECHNOLOGY LOGO RH	1 PC	76.10 X	
4 REAR BUMPER	1 PC	915.40	
5 REAR BUMPER SIDE RETAINERS	2 PC	90.60 X	
6 REAR BUMPER REINFORCEMENT	1 PC	148.00 X	
7 TAILGATE LOGO (S) LH	1 PC	34.50 X	
8 TAILGATE INNER LOCK - CHECK PRICE	1 PC	0.00 X	
		1,349.70	
	Less 20%	269.94	1,079.76
Special Nett			
9 REVERSE CAMERA - CHECK PRICE	1 PC	0.00 X	
10 REVERSE SENSOR	1 SET	200.00 X	
		200.00	200.00
LABOUR			
11 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00 101	
12 TO REMOVE & REINSTALL/REPLACE REAR REVERSE CAMERA	1 PC	120.00 2501	
13 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	
14 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00 X	
15 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR BUMPER REINFORCEMENT.TO KNOCK & REPAIR END PANEL,TAILGATE INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	700.00 2001	
16 TO SPRAY TAILGATE,END PANEL,REAR BUMPER,REAR BUMPER REINFORCEMENT.	1 PC	700.00 2001	
		1,700.00	1,700.00





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : CLARE SAVEREUX
22 SPRINGLEAF VIEW

SINGAPORE 797927

TEL: 90279127

ATTN:

Estimate No: MC0913657
Date: 06 Dec 2018
Policy No: P209175
Veh Reg No: SLS5433J
Make/Model: MAZDA 5 WAGON 2.0
AT EU6

Your Ref No: SLS5433J
Claim Type: Third Party
Accident Date: 07/11/2018
TP Veh Reg No: SHA3056U

Estimate Repair Cost to Vehicle No :SLS5433J

Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 2,979.76
		Add GST @ 7%	208.58
		Total Amount Payable	S\$ 3,188.34

TOTAL: SINGAPORE DOLLAR THREE THOUSAND ONE HUNDRED EIGHTY EIGHT AND CENTS THIRTY FOUR ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18022074/Ksd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 23-04-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3056U	Veh. Inspected	SLS 5433J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008552MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	07/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 5 (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6CW1071H0126145	Colour	METALLIC DARK BLUE	
Odometer	22924	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	TOYO	8 mm	
L/H Front Tyre	205/55 R16	TOYO	8 mm	
R/H Rear Tyre	205/55 R16	TOYO	5 mm	
L/H Rear Tyre	205/55 R16	TOYO	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/11/2018	Inspection Date	13/12/2018	
Survey held at	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 5433J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE EMBLEM	NOT NECESSARY	42.00	-
1	TAILGATE MAZDA LOGO LH	NOT NECESSARY	43.10	-
1	TAILGATE TECHNOLOGY LOGO RH	NOT NECESSARY	76.10	-
1	REAR BUMPER	BUCKLED	915.40	915.40
2	REAR BUMPER SIDE RETAINERS	SERVICEABLE	90.60	-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	148.00	-
1	TAILGATE LOGO (5) LH	NOT NECESSARY	34.50	-
1	TAILGATE INNER LOCK (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-269.94	-183.08
			1,079.76	732.32
SPECIAL NETT ITEMS				
1	REVERSE CAMERA (NPA)(SN)	SERVICEABLE	-	-
1	SET REVERSE SENSOR (SN)	SERVICEABLE	200.00	-
			200.00	-
LABOUR				
	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS,TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	10.00
	TO REMOVE & REINSTALL/REPLACE REAR REVERSE CAMERA. }		120.00	50.00
	TO REMOVE & REINSTALL/REPLACE REAR BUMPER SENSORS. }		80.00	-
	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	NOT NECESSARY	60.00	-
	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR BUMPER REINFORCEMENT.TO KNOCK & REPAIR END PANEL.TAILGATE INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT AND TAILGATE INNER LOCK.		700.00	200.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY TAILGATE,END PANEL,REAR BUMPER,REAR BUMPER REINFORCEMENT.		700.00	200.00
			1,700.00	460.00
GRAND TOTAL			2,979.76	1,192.32
RECOMMENDED COST OF REPAIRS				1,192.32

Report Ref No. CS/FCI18022074/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.