

INSURANCE

INS. CASE OWNER:

ACWIN

CC 3/AIG1802

WATER, RIVER

LKK

IDAC

Surveyor:

RECALL

DOI:

ASSIGNMENT
15/12/18

Date/Time:

7/12/18

Registered in Merit:

7/12/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLU 9292L

Name of Insured:

DEH ENG THAM

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

9/12/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: TAN LAM ENG

Driver Tel No.:

(V/L YES / NO)

Claim No.:

13657863454

Policy No.:

1300032455

Make / Model:

1700EN

Place of Accident:

TAMPINES MTE 10

OI GIA REPORT: YES / NO

YES

TP GIA REPORT: YES / NO

YES

Insured Liability:

%

Final ? Yes / No

SLS 4011A



INSRS:

WSP:

Tel:

Liability:

RMKS:

performance



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

SLS 4011A - X

SLU 9292L - X

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

201-1142-18

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

17/12/18
7/12/18
10/07/19

- PINAUGED

- ORIGINAL TP LOD IN

- TPO REPORT FOR WAIVER APPROVAL

- REPORT DONE

- BOOK WAIVER TO AIG

- AIG APPROVED WAIVER

- CONFIRMED AMOUNT. NO POCS IN ORDER.

215 W/OI MDM TAN

CONFIRMED - AGREED

9 AWARE NCH ISSUE.

13-12-18

VIDEO FROM OI - CI COMING
OUT FROM CLIP ROAD.

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/P

SS 13,408.10

(8 days)

Reduction:

38

%

Email

Call

FINAL SETTLEMENT

Date/Time:

20/06/19

Confirm with:

CHONG

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

15

Repair Cost:

CW1690

SS 14,346.67

If NO or B 28, Ass. Lia:

OI CHANGED CASE

Loss of Rental (LOR):

SS

-

(

days)

Loss of Use (LOU):

SS

1,200.00

(5 x 10 days)

2998.00

Loss of Income (LOI):

SS

-

(5

x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

CLA/TA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/Independent)

Legal Cost:

SS

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4320.00

Total:

SS

16,548.67

Global Sum SS:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

14,346.67

Name 1:

PERFORMANCE MOTORS LIMITED

Payee 2: (Strike if N.A.)

SS

1,200.00

Name 2:

NG CHONG SHING JOHNSON

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

DATE/TIME

From

REF: *Alh*

50114

ASSIGNMENT

From: _____ Date: *13.12.18*

Estimated Cost: _____

OD *C* / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: *SLS 4011A*

at Workshop n/s: *Performance*

of: *303 Alexandra Rd*

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: *Intihiran*

(Policy Condition)

Remark: *The veh had commenced its repair at the time of inspection.*

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No


Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT



Veh No: *SMH 276A (SLS 4011A)* Regn: *2017 / SGP*

Type: *C* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *B.M.W 540I* C.C. *2998*

Colour: *BLACK* A/C Insured / Std / NI / NA

Sp. Reading: *04 011* T/Radio: Insured / Std / NI / NA

Eng/No: _____

CiNo: *WBA JB320XOWA 75105*

Gen. Cond: Good / *C* / Poor / Burnt

Steering: *S* / In order / Jammed / Leaked / Burnt or

Brake: *S* / In order / Jammed / Leaked / Burnt or

Modi: *C* / Nil / S/Rim / STD A/Rim or

Tyre Size: F: *275/30 R20*

R: _____

BS / DUN / EXNOVA / *C* / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front *6* mm Rear *6* mm

R/Bal. *6* mm L/Bal. *6* mm

D.O.A. *05/12/18* D.O.I. *13/12/18*

Survey held at *PERFORMANCE*

Des. of Damages: Frt / Rear / O/S / *C* / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<i>2-4-19</i>	<i>\$13,408.10</i>
	<i>Crash: \$2,266.80/30%</i>

Date/Time, File Pass to? ☐ : Prol. Report

1) ☐ : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Site Insp (\$ ☐)

Interview (\$ ☐)

Tech. Invs (\$ ☐)

Weekend (\$ ☐)

Photos: _____

Other: _____

TOTAL: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18022078/jb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 07-12-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLU 9292L	Veh. Inspected	SLS 4011A
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	07/12/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	05/12/2018	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Performance Motors Limited

Member of the Sime Darby Group
Reg. No. 197401358W GST Reg. No. M2-0020081-X

115, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190120 (Sales & Admin)
63190111 (AfterSales)
64747777

280, Kembangan Road
East Coast Centre
Singapore 438188
Tel: 63190688 (AfterSales)
Fax: 63448777

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190128 (AfterSales)
63190133/330 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

07 DEC 2018

ESTIMATE

Estimate No. :	b1 49376	Page No. : 1 of 5
Date Issued :	07/12/2018	
Prepared by :	Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR -

Ng Thong Shing, Johnson
Blk 261 Tampines St 21
#07-308

Singapore 520261

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS40111	WA75105	22/09/2017	540iA	0

DESCRIPTION

To replace front left fender, front left door, side sill left
and attachments including knock out on dent area

4250 / 5,180.00

Painting front left fender, front left door, rear left door
side sill left, A pillar, rear left fender and rear
bumper.

4535 / 6,077.00

To replace tyre and wheel rim including balancing. (1x).

11 X 94.00

To check steering geometry and conduct wheel alignment
according to BMW specification (1x)

11 X 531.00

To check electrical wiring systems

150 / 172.00

To install strip on side sill left.

150 / 172.00

To carry out body cavity preservation.
(Per panel).

11 X 236.00

Sundries.

? 150.00

Total Labour 1: 12,542.00

DESCRIPTION

ALLOY RIM ORBITGREY 8JX20 V SPK 759 XAA
FRT LH DOOR ALUMINIUM repair
FRT LH SIDE PANEL ALUMINIUM repair
M PERFORMANCE SIDE SKIRT STRIPES new
M PERFORMANCE CARBON MIRROR CAP LH cut
LH TURN INDICATOR EXTERIOR MIRROR new
SET EXTERIOR MIRROR CAMERA HOLDER new
SET OF SCREWS new
LH HEATED OUTSIDE MIRROR MEMORY BUS new
FRT LH DOOR WINDOW FRAME COVER (GLA new
FRT LH DOOR OUTER SHAFT COVER (GLAN new

QTY	PRIC	VALUE
1	2,167.45	2,167.45
1	1,863.20	1,863.20
1	929.15	929.15
1	319.10	319.10
1	871.05	871.05
1	75.15	75.15
1	60.10	60.10
1	52.30	52.30
1	979.50	979.50
1	145.80	145.80
1	153.05	153.05

78-10

978-90

Performance Motors Limited

Member of the Sime Darby Group
Reg. No. 197401559M GST Reg. No. M2-0020081-X



315, Alexandra Road
Sime Darby Performance Centre
Singapore 119944
Tel: 63190120 (Sales & Admin)
63190121 (AfterSales)
63190122 (AfterSales)

120, Selegie Road
East Coast Centre
Singapore 416180
Tel: 63190888 (AfterSales)
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 119944
Tel: 63190534 (AfterSales)
63190533/330 (Motors)
64796601 (AfterSales)
64796624 (Motors)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 49376
Date Estimated : 07/12/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
WA75105	22/09/2017	540ia	0

DESCRIPTION	QTY	PRIC	VALUE
H SILL TRIM PRIMED (M) <i>See /</i>	1	508.05	508.05
Total Parts :			8,123.90

Claims OD / *See* / Disputed losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time *13/12/18 @ 1230* Excess S\$ _____

Surveyor's Name *Rahul* Sign _____

Surveyor's Tel *92014068* Authorised Yes / No _____

Authorised Date _____ Time _____

REPAIR BY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend *8 days*

Labour 1	:	12,542.00
Parts	:	8,123.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,446.61
Grand Total	:	22,112.51

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

Subsidiary of the General Motors Group
Co. Reg. No. 2010010000 GST Reg. No. M2-0000001-X



SUPPLEMENTARY

Estimate No. : b1 49376
Date Estimated : 07/12/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Ng Chong Shing, Johnson
Blk 261 Tampines St 21
#02-306

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 520261

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SL54011A	WA75105	22/09/2017	5401A	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RENT LH DOOR SIDE WINDOW GREEN (ESG) *	363.20	1.00		363.20 <i>See</i>
* 3m s/f: CRYSTALLINE FRONT SIDE DOOR	336.45			<i>See</i>
Total Labour :				
Total Parts :				363.20
Total Labour & Parts :				363.20

(A) TO REPLACE FRONT DOOR SIDE WINDOW GLASS AND ATTACHMENTS 7287 *See*

Performance Motors Limited

A member of the Performance Group
GST Reg No. M2-000001-01



FINAL REPORT

Estimate No. : b1 49376
Date Estimated : 07/12/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Ng Chong Shing, Johnson
81k 261 Tampines St 21
#07-306

Singapore 520261

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE		
SLB4011A	WA75105	22/09/2017	5401A	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT			
To replace LH wingmirror assembly, LH side skirting include making good the front LH fender, front LH door, rear LH door, LH 'A' pillar, rear LH fender and knocking out dents caused by the accident	4250.00		4,250.00			
To spray paint front LH fender, front LH door, rear LH door, LH side skirting, LH 'A' pillar and rear LH fender	4535.00		4,535.00			
To check electrical wiring systems and lightings at the LH section for proper function	150.00		150.00			
To install M performance strips on LH side skirting	150.00		150.00			
To replace front door side window glass and attachments.	287.00		287.00			
Sundries	150.00		150.00			

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
3m s/f Crystalline Front Side Door	336.45	1.00		336.45
M PERFORMANCE SIDE SKIRT STRIPES	319.10	1.00		319.10
M PERFORMANCE CARBON MIRROR CAP LH	871.05	1.00		871.05
LH TURN INDICATOR EXTERIOR MIRROR	78.10	1.00		78.10
SET EXTERIOR MIRROR CAMERA HOLDER	60.10	1.00		60.10
SET OF SCREWS	52.30	1.00		52.30
LH HEATED OUTSIDE MIRROR MEMORY BUS	998.90	1.00		998.90
FRT LH DOOR SIDE WINDOW GREEN (ESG) *	363.20	1.00		363.20
FRT LH DOOR WINDOW FRAME COVER (GLA	145.80	1.00		145.80
FRT LH DOOR OUTER SHAFT COVER (GLAN	153.05	1.00		153.05
LH SILL TRIM PRIMED (M)	508.05	1.00		508.05

SUPPLEMENTARY ITEMS

Total Labour:	9,522.00
Total Parts:	3,886.10
Total Labour & Parts:	13,408.10
Deduction for Excess:	0.00
Total Repair Costs less Excess:	13,408.10
GST @7%:	938.57
Grand Total:	14,346.67

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Tampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190889 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64786601 (AfterSales)
64786624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

07 DEC 2018

E S T I M A T E

Estimate No. : b1 49376
Date Estimated : 07/12/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Ng Chong Shing, Johnson
Blk 261 Tampines St 21
#07-306

Singapore 520261

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS4011A	WA75105	22/09/2017	540ia	0

DESCRIPTION

To replace front left fender, front left door, side sill left
and attachments including knock out on dent area.

4250 ~~5,100.00~~

Painting front left fender, front left door, rear left door,
side sill left, A pillar, rear left fender and rear
bumper.

4535 ~~6,077.00~~

To replace tyre and wheel rim including balancing. (1x).

X 94.00

To check steering geometry and conduct wheel alignment
according to BMW specification (1x)

X 531.00

To check electrical wiring systems

150 ~~177.00~~

To install strip on side sill left.

150 ~~177.00~~

To carry out body cavity preservation.
(Per panel).

X 236.00

Sundries.

? 150.00

Total Labour 1: 12,542.00

DESCRIPTION

ALLOY RIM ORBITGREY 9JX20 V SPK 759 X
FRT LH DOOR ALUMINIUM repair
FRT LH SIDE PANEL ALUMINIUM repair
M PERFORMANCE SIDE SKIRT STRIPES new
M PERFORMANCE CARBON MIRROR CAP LH cut
LH TURN INDICATOR EXTERIOR MIRROR 600
SET EXTERIOR MIRROR CAMERA HOLDER new
SET OF SCREWS new
LH HEATED OUTSIDE MIRROR MEMORY BUS new
FRT LH DOOR WINDOW FRAME COVER (GLA) new
FRT LH DOOR OUTER SHAFT COVER (GLAN) new

QTY	PRIC	VALUE
1	2,167.45	2,167.45
1	1,863.20	1,863.20
1	929.15	929.15
1	319.10	319.10
1	871.05	871.05
1	75.15	75.15
1	60.10	60.10
1	52.30	52.30
1	979.50	979.50
1	145.80	145.80
1	153.05	153.05

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

289, Kampong Arang Road
East Coast Centre
Singapore 438180

Tel: 63190888 (AfterSales)
Fax: 63449773

323, Alexandra Road
Sime Darby Business Centre
Singapore 159944

Tel: 63190538 (AfterSales)
63190533/530 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 49376**
Date Estimated : **07/12/2018**
Prepared By : **Inthiran A/L Thurasamy**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS4011A	WA75105	22/09/2017	540iA	0

DESCRIPTION

LH SILL TRIM PRIMED (M) *sm /*

QTY	PRIC	VALUE
1	508.05	508.05

Total Parts : **8,123.90**

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date & Time 13/12/18 @ 1230 Excess S\$

Surveyor's Name Rahul Sign

Surveyor's Tel 96010068 Authorised Yes / No

Authorised Date Time

RESUME BY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail

No. of Working Days Recommend 8 days

Labour 1	:	12,542.00
Parts	:	8,123.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,446.61
Grand Total	:	22,112.51

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY ****

**** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****

10 Sin Ming Drive Singapore 575701

www.lta.gov.sg

11 Dec 2018

Our ref 1112180203N057024718

NG CHONG SHING, JOHNSON
APT BLK 261 TAMPINES STREET 21
#07-306
SINGAPORE 520261



Dear Sir/Madam

NOTIFICATION ON SUCCESSFUL REPLACEMENT OF VEHICLE REGISTRATION NO. SLS4011A WITH VEHICLE REGISTRATION NO. SMH276A

You may be pleased to know that your application of 11 Dec 2018 for replacement of registration number is approved.

2. The details of the vehicle after the transaction are as follows:

Vehicle Registration No. : SMH276A (Previously SLS4011A)
Vehicle Make : B.M.W.
Vehicle Model : 540i SR LED NAV HUD RCP MSPORT
Chassis No. : WBAJB320X0WA75105
Engine No./ Motor No. : 12435022B58B30A / -

3. Please change the number plates on your existing vehicle (ie. Chassis No. : WBAJB320X0WA75105, Engine No./ Motor No. : 12435022B58B30A / -) to display the new/ replacement registration number, SMH276A by 14 Dec 2018. It is an offence to keep or use a vehicle without displaying the correct vehicle registration number assigned. The penalty for first offence is a fine not more than \$1,000 or imprisonment of not more than 3 months. For second or subsequent offence, the fine is not more than \$2,000 or imprisonment of not more than 6 months.

4. Please contact our customer service officers on tel: 1800-CALL LTA (1800-2255 582) if you have any questions. You can either quote the Business Transaction Reference No. 20181211115855131961 or the vehicle registration number when making your enquiry.

Yours sincerely

Ng Lay Choo (Ms)
Deputy Director, VRL Service Operations
Vehicle Services Group
Land Transport Authority

[This letter is computer-generated, no signature is required.]

From 01 Jun 2019, your hardcopy letters will be replaced with SMSes and e-letters in your OneMotoring inbox. Hardcopy letters will only be sent for letters mandated by law, such as summonses. If you wish to continue receiving hardcopy letters, please notify LTA by 31 May 2019 by logging in to www.onemotoring.com.sg using your SingPass/CorpPass.

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S):

Class 3

Motor cars with unladen weight \leq 3000kg with \leq 7 passengers, exclusive of driver; and other motor vehicles with unladen weight \leq 2500kg

EFFECTIVE DATE

24 May 2016

NP 473A
Licence No: S8125011A



REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number: S 8 1 2 5 0 1 1 A

NG CHONG SHING, JOHNSON

Date of Birth: 05 Aug 1981
Issue Date: 24 May 2016



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S8125011A**



Name

NG CHONG SHING, JOHNSON

黄 毓 腾

Race

CHINESE

Date of birth

06-08-1981

Sex


M

S8125011A

Country of birth

SINGAPORE

4409918



NRIC No. **S8125011A**

Date of issue

12-05-2009

Address

**APT BLK 261 TAMPINES STREET 21
#07-306
SINGAPORE 520261**

THE SCHEDULE

Private Car Insurance Policy

This Policy sets out the terms of a contract between NTUC Income Insurance Co-operative Limited (INCOME) and you (the Policyholder named in the schedule to this Policy).

The statements, information and declaration provided by you at the time of proposal shall form the basis of this contract. We (INCOME) will provide the insurance set out in this Policy in respect of events occurring during the Period of Insurance shown in the Schedule and any further period for which we may accept a renewal premium.

The provision of this insurance is subject to:

1. any Endorsement specified as operative in the Schedule
2. the Conditions and General Exclusions of this Policy, and
3. the payment of the premium specified in the Schedule.

This Policy, the Schedule and the Certificate of Insurance are to be read together as one document.

GST Reg No. M4-0003030-8

Policy Number	: S105526293		
The Policyholder	: NG CHONG SHING, JOHNSON		
	: BLK 261 #07-306		
	: TAMPINES STREET 21		
	: TAMPINES EAST ZONE 4		
	: SINGAPORE 520261		
Period of Insurance	: 15 Nov 2018 To 14 Nov 2019		
Sum Insured	: Market Value of Insured Vehicle at Time of Loss		
Premium (inclusive GST)	: S\$2,565.66		
Interest Insured			
Cover Type	: drive PREMIUM		
Primary Driver	: NG CHONG SHING, JOHNSON		
Named Driver (1)	: N/A		
Named Driver (2)	: N/A		
Make/Model	: BMW/540i M SPORT	Capacity	: 3000cc
Registration Number	: 5L54011A	Registration Year	: 2017
Chassis Number	: WBAJB320X0WA75105	Off-peak Car	: No
Repair at Owner's Preferred Workshop	: Yes	Insure with COE	: Yes
Excess (Section 1)	: S\$1,500	NCD Entitlement	: 40%
Excess (Section 2)	: N/A	NCD Protection	: No
Windscreen Excess	: S\$100	Loyalty Discount	: 5%
Additional Excess	: N/A		
Unnamed Driver Excess	: Please refer to Terms and Conditions		
Hire Purchase Company	: SPEEDO CAPITAL PTE. LTD.		
Optional Cover			
Transport Allowance	: No		
Excess Waiver	: N/A		

Memo A : N/A

Endorsement Operative : M7

Agency : SPEEDO CAPITAL PTE. LTD. (00000615301)

Date of Issue : 15 Nov 2018 11:10 hrs

DUTY OF DISCLOSURE

We would remind you that you must disclose to us, fully and faithfully, the facts you know or ought to know, otherwise you may not receive any benefit from your Policy.

Signed in Singapore by order of the Board of Directors



Chief Executive

10 Sin Ming Drive Singapore 575701
www.lta.gov.sg

11 Dec 2018

Our ref 1112180203N057024718

NG CHONG SHING, JOHNSON
APT BLK 261 TAMPINES STREET 21
#07-306
SINGAPORE 520261



Dear Sir/Madam

NOTIFICATION ON SUCCESSFUL REPLACEMENT OF VEHICLE REGISTRATION NO. SLS4011A WITH VEHICLE REGISTRATION NO. SMH276A

You may be pleased to know that your application of 11 Dec 2018 for replacement of registration number is approved.

2. The details of the vehicle after the transaction are as follows:

Vehicle Registration No. : SMH276A (Previously SLS4011A)
Vehicle Make : B.M.W.
Vehicle Model : 540I SR LED NAV HUD RCP MSPORT
Chassis No. : WBAJB320X0WA75105
Engine No./ Motor No. : 12435022B58B30A / -

3. Please change the number plates on your existing vehicle (ie. Chassis No. : WBAJB320X0WA75105, Engine No./ Motor No. : 12435022B58B30A / -) to display the new/ replacement registration number, SMH276A by 14 Dec 2018. It is an offence to keep or use a vehicle without displaying the correct vehicle registration number assigned. The penalty for first offence is a fine not more than \$1,000 or imprisonment of not more than 3 months. For second or subsequent offence, the fine is not more than \$2,000 or imprisonment of not more than 6 months.

4. Please contact our customer service officers on tel: 1800-CALL LTA (1800-2255 582) if you have any questions. You can either quote the Business Transaction Reference No. 20181211115855131961 or the vehicle registration number when making your enquiry.

Yours sincerely

Ng Lay Choo (Ms)
Deputy Director, VRL Service Operations
Vehicle Services Group
Land Transport Authority

[This letter is computer-generated, no signature is required.]

Print Received Message

This mail is associated with :

***SLS4011A (1765575677SG)
[SLU9292L]**

TP

NG CHONG SHING JOHNSON
Dec 5 2018 8:00PM
[PEH ENG THIAM (BAI YONGTIAN)]
Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 05/08/2019 13:52 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$15548.67) - SLS4011A - Claim Handler: Kesaval, Jaclyn-M

Approved:15548.67.

Joy Irene (LKKAUTO)

From: Joy Irene (LKKAUTO)
Sent: Tuesday, 11 December 2018 2:19 PM
To: 'pehengthiam@gmail.com'
Cc: Admin A
Subject: ACCIDENT INVOLVING SLU 9292L AND SLS 4011A ON 15/12/2018

OUR REF: LKK: CC3/AIG18022078/jb3

PEH ENG THIAM (BAI YONGTIAN)

Policy Holder

Dear Sir/Madam,

ACCIDENT INVOLVING SLU 9292L AND SLS 4011A ON 15/12/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us.

We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SL54011A	Model:	
Date of Accident:	5.12.2018		

Global Sum Settlement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	\$	22112.51	
Final Repair Cost	\$	14346.67	
Loss of Use	\$	12000	10 days at \$ 120 per day
Rental (if any)	\$		days
LTA / GIA Search Fee	\$	200	
Others:	\$		
	\$		
Final Settlement Sum	\$	15548.67	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A)	For Non GIA Registered Workshop: Agreed Liability _____ (%)		
B)	For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____		
	BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks			

Payment Instruction: Payee's Breakdown		
1)	Performance Motors Ltd	\$ 14346.67
2)	Performance Motors Ltd	\$ 200
3)	Ng Chung Shing Johnson	\$ 12000

Signed by appointed surveyor _____

Date _____

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
Survey Report; Medical Report/ Bill (if any))


AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, Mr. Cheng Sheng Johnson (the third party claimant) of 261 Tampines Street 21 #01-306 (520261) (address), owner of SLS4011A (vehicle no.) hereby authorize Performance Motors Ltd ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SLS4011A that was damaged pursuant to the accident which occurred on 5.12.2018 (date) along Tampines Avenue 10 (location) involving vehicle no/s SU9292L ("the accident").


I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 13 (day) of Dec (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)



PERFORMANCE MOTORS LIMITED
303 Alexandra Road
Dorby Performance Centre
Singapore 159541
TEL: 63150100 (Sales)
63150111 (AfterSales)
Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$14346.67 (Repair Cost), S\$1200 (Loss of ~~rental~~ use), S\$ 2 (Disbursement), for vehicle no. SL54011A that was damaged pursuant to the accident which occurred on 5-12-18 (date) along Tampines Avenue 10 (location) involving vehicle no/s SLU92921. This is pursuant to the inspection conducted on 13-12-18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Ng Chong Shing Johnson ("the third party claimant") of vehicle no. SL54011A make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SL54011A (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 20 (day) of 08 (month) 2019 (year)



Signed by appointed surveyor



PERFORMANCE MOTORS LIMITED
303 Alexandra Road
Darby Performance Centre
Singapore 159941
TEL: 63180100 (Sales)
63180111 (After-sales)

Signed by "the workshop" (with chop)

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X

109, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

260, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449771

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



SERVICE TAX INVOICE

Repair Order No. : B1 1323043	Page No. : 1 of 2
Date IN : 13/12/2018	Invoice Number : 2083612 / WSB
Cust. Svc. Advisor: Inthiran A/L Thurasamy	Invoice Date : 03/04/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Mr Ng Chong Shing, Johnson
Blk 261 Tampines St 21
#07-306

Singapore 520261

- INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO. /	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS4011A	WA75105	22/09/2017	540IA	4011

- - - - LABOUR 1 - - - -

To replace left side skirting and left wing mirror assembly etc including to make good the front left fender, front left door, rear left door,	NETT
left 'A' pillar, rear left fender and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.	4,250.00
To respray front left fender, front left door, rear left door, left side skirting, left 'A' pillar and rear left fender etc.	4,535.00
To check electrical wiring systems and lighting at the left section for proper function.	150.00
To install M Performance strips on left side skirting.	150.00
To replace front left door window glass and attachments.	287.00
Sundries.	150.00
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.	0.00
DATE OF ACCIDENT : 5.12.2018. 3RD PARTY CAR : SLU9292L.	
YOUR REF NO : NIL.	
VEHICLE WAS SURVEYED BY MR RASUL FROM LKK AUTO CONSULTANTS PTE LTD ON 13.12.2018 AT 12.30 PM.	
AUTHORISED REPAIR BY MS JOY IRENE FROM LKK ON 11.12.2018 VIA E-MAIL.	
PROPOSE LOSS OF USE = \$120X10. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	0.00
GIA SEARCH FEE = \$2.00.	0.00

Total Labour 1: **9,522.00**

- - - - PARTS - - - -

	Qty	Retail Price	NETT
M PERFORMANCE SIDE SKIRT STRIPES	1	319.10	319.10
LH TURN INDICATOR EXTERIOR MIRROR	1	78.10	78.10
SET EXTERIOR MIRROR CAMERA HOLDER	1	60.10	60.10
LH HEATED OUTSIDE MIRROR MEMORY BUS	1	998.90	998.90
FRT LH DOOR OUTER SHAFT COVER (GLAN	1	153.05	153.05
LH SILL TRIM PRIMED (M)	1	508.05	508.05
SET OF SCREWS	1	52.30	52.30

101, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Tampung Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796634 (Motorrad)**SERVICE TAX INVOICE**

Repair Order No. : B1 1323043	Page No. : 2 of 2
Date IN : 13/12/2018	Invoice Number : 2083612 / WSB
Cust. Svc. Advisor: Inthiran A/L Thurasamy	Invoice Date : 03/04/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

M PERFORMANCE CARBON MIRROR CAP LH	1	871.05	871.05
FRT LH DOOR WINDOW FRAME COVER (GLA	1	145.80	145.80
FRT LH DOOR SIDE WINDOW GREEN (ESG)	1	363.20	363.20
3m s/f: Crystalline Front Side Door	1	336.45	336.45
Total Parts :			3,886.10

Labour Charges :	9,372.00	Total Labour & Parts Charges :	S\$ 13,408.10
Parts Charges :	3,886.10	Less Insurance Excess :	S\$ 0.00
Lubricant/Misc :	150.00	Invoice Total Amount Exclude GST :	S\$ 13,408.10
		GST @ 7% :	S\$ 938.57
		Invoice Total Amount Include GST :	S\$ 14,346.67

Computer generated invoice. No signature is required.	Amount Payable Include GST :	S\$ 14,346.67
---	------------------------------	----------------------

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-189598

Date of Request: 07/12/2018

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 07/12/2018
Enquiry By Melanie Setiawati
TP Vehicle No. SLU9292L
Accident Date 05/12/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLU9292L	AIG Asia Pacific Insurance Pte. Ltd.	02/11/2018-01/11/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735**TAX INVOICE**

Our Ref No: GR-18-189598

Date of Request: 07/12/2018

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 07/12/2018
Enquiry By Melanie Setiawati
TP Vehicle No. SLU9292L
Accident Date 05/12/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING


















Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Dec 2018 Edit Reg		13 Dec 2018 00:00 Edit Adj Rpt	\$513,408.10 Edit Estimates	\$513,408.10 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: PEH ENG THIAM (BAI YONGTIAN) , ID: S7308901H									
Main Claimant: NG CHONG SHING JOHNSON , ID: S8125011A									
Vehicle Reg. No.:	SLS4011A	Date of Loss:	05/12/2018 20:00 - :59 [14 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1765575677SG	Policy/Cover Note No.:	(Comprehensive) Coverage: 02/11/2018 - 01/11/2019						
Vehicle Reg. No. (Insured):	SLU9292L	Policy No. (Claimant):	5105526293						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJQian.Ler@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 18/12/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (05/08/2019): Alert - Adj Mandate Approved (\$515548.67) - SLS4011A - Claim Handler: Kesaval, J...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS4011A (1765575677SG)
[SLU9292L]
TP
NG CHONG SHING JOHNSON
Dec 5 2018 8:00PM
[PEH ENG THIAM (BAI YONGTIAN)]
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	13/12/18 14:32	FROM OI REAR CAM													Load MP4					
2	13/12/18 14:36	FROM OI - FRONT CAMERA													Load MP4					
Letters/Correspondences															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	(Draft)	Third Party Express Settlement - Payment Breakdown													Edit					
Photos/Images															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	10/07/19 10:59	Odometer Reading													Load JPG	<input checked="" type="checkbox"/>				
2	10/07/19 10:59	Chassis Number													Load JPG	<input checked="" type="checkbox"/>				
3	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
4	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
5	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
6	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
7	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
8	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
9	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
10	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
11	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
12	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
13	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
14	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
15	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
16	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
17	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
18	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
19	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
20	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
21	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
22	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
23	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
24	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
25	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
26	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
27	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
28	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
29	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				
30	10/07/19 10:59	General View													Load JPG	<input checked="" type="checkbox"/>				

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
31	10/07/19 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
32	10/07/19 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
33	10/07/19 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
34	10/07/19 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
35	10/07/19 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
36	10/07/19 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
37	10/07/19 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
38	10/07/19 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
39	10/07/19 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
40	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	10/07/19 11:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Video				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/12/18 18:13	TP EST & GIA REPORT		Load PDF	
2	17/12/18 18:39	TP ESTIMATE- MARKED		Load PDF	
3	22/07/19 14:06	LETTER TO OI		Load PDF	
4	22/07/19 14:06	GIA SEARCH		Load PDF	
5	27/08/19 10:06	WORKSHOP INVOICE		Load PDF	
6	27/08/19 10:06	AUTHORISATION TO ACT FORM		Load PDF	
7	27/08/19 10:06	Release Voucher		Load PDF	
8	27/08/19 10:06	LOD		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	10/12/18 10:37	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLU9292L (Insd veh)	Model:	BMW 540i 3.0 SR LED NAV
	SLS4011A (TP veh)		HUD RCP MSPORT (A)
Date of Accident:	05/12/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$		23,192.14
Final Repair Cost	:	\$		14,346.67
Loss of Use	:	\$		1,200.00
				10.00 days at \$120.00 per day
Rental (if any)	:	\$		0.00
				days
LTA / GIA Search Fee	:	\$		2.00
Others:	:	\$		0.00
	:	\$		
Final Settlement Sum	:	\$		15,548.67

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/~~No~~—BOLA Scenario No: _____

15

BOLA Liability: _____100_____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 14,348.67
2)	Ng Chong Shing Johnson	:	\$ 1,200.00
3)		:	\$

JOANNE LEE KHANG MIN

27 Aug
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18022078/R1HB3Q2

Date: 27/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLS4011A

Insured Vehicle No : SLU9292L

Date of Loss: 05/12/2018

Nature of Claim: TP

Claim No: 1765575677SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS4011A

Make & Model: BMW 540i, 3.0 SR LED NAV HUD RCP MSport (A)

Engine No: 12435022B58B30A

Reg. Date: 22/09/2017 (Man. Year: 2017)

Chassis No: WBAJB320X0WA75105

Colour: Black

Odometer: 4011 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/30 R20

Rear Tyre Size: 275/30 R20

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,995.90	4,036.10	4,959.80	55.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,679.00	9,372.00	3,307.00	26.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,674.90	13,408.10	8,266.80	38.14
+ GST 7.00/7.00% (S\$)	1,517.24	938.57	578.67	38.14
Nett Amount (S\$)	23,192.14	14,346.67	8,845.47	38.14
+ Loss of Use (10.0 x S\$120.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		15,548.67		

INSPECTION

Date of Assignment: 13/12/2018

Date Inspected: 13/12/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*ALLOY RIM ORBITGREY 9J20 V SPK 759	Not Necessary	2,167.45 FS	*- FS
3	1		*FRT LH DOOR ALUMINIUM	Repair	1,863.20 FS	*- FS
4	1		*FRT LH SIDE PANEL ALUMINIUM	Repair	929.15 FS	*- FS
5	1		*M PERFORMANCE SIDE SKIRT STRIPES	Necessary	319.10 FS	*319.10 FS
6	1		*M PERFORMANCE CARBON MIRROR CAP LH	Cut	871.05 FS	*871.05 FS
7	1		*LH TURN INDICATOR EXTERIOR MIRROR	Broken	78.10 FS	*78.10 FS
8	1		*SET EXTERIOR MIRROR CAMERA HOLDER	Necessary	60.10 FS	*60.10 FS
9	1		*SET OF SCREWS	Necessary	52.30 FS	*52.30 FS
10	1		*LH HEATED OUTSIDE MIRROR MEMORY BUS	Scratched	998.90 FS	*998.90 FS
11	1		*FRT LH DOOR WINDOW FRAME COVER (GLA)	Scratched	145.80 FS	*145.80 FS
12	1		*FRT LH DOOR OUTER SHAFT COVER (GLAN)	Scratched	153.05 FS	*153.05 FS
13	1		*LH SILL TRIM PRIMED (M)	Scratched	508.05 FS	*508.05 FS
14	1		*FRT LH DOOR SIDE WINDOW GREEN (ESG)	Scratched	363.20 FS	*363.20 FS
15	1		*3M S/F:CRYSTALINE FRONT SIDE DOOR	Scratched	336.45 FS	*336.45 FS
Total Parts (S\$)					8,995.90	4,036.10

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT DOOR SIDE WINDOW GLASS AND ATTACHMENTS	New	287.00	287.00
2	TO REPLACE FRONT LEFT FENDER ,FRONT LEFT DOOR ,SIDE SILL LEFT AND ATTACHMENTS INCLUDING KNOCK OUT ON DENT AREA	New	5,100.00	4,250.00
3	PAINTING FRONT LEFT FENDER ,FRONT LEFT DOOR ,REAR LEFT DOOR ,SIDE SILL LEFT ,A PILLAR ,REAR LEFT FENDER AND REAR BUMPER	New	6,077.00	4,535.00
4	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING	New	94.00	0.00
5	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION	New	531.00	0.00
6	TO CHECK ELECTRICAL WIRING SYSTEMS	New	177.00	150.00
7	TO INSTALL STRIP ON SIDE SILL LEFT	New	177.00	150.00
8	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	236.00	0.00
Gross Labour Cost (S\$)			12,679.00	9,372.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >