

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

07 DEC 2018

E S T I M A T E

Estimate No. : b1 49376
Date Estimated : 07/12/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Ng Chong Shing, Johnson
Blk 261 Tampines St 21
#07-306

Singapore 520261

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS4011A	WA75105	22/09/2017	540iA	0

DESCRIPTIONVALUE

To replace front left fender, front left door, side sill left
and attachments including knock out on dent area.

4250 5,100.00

Painting front left fender, front left door, rear left door,
side sill left, A pillar, rear left fender and rear
bumper.

4535 6,077.00

To replace tyre and wheel rim including balancing. (1x).

X 94.00

To check steering geometry and conduct wheel alignment
according to BMW specification (1x)

X 531.00

To check electrical wiring systems

150 177.00

To install strip on side sill left.

150 177.00

To carry out body cavity preservation.
(Per panel).

X 236.00

Sundries.

? 150.00

Total Labour 1: **12,542.00**DESCRIPTIONQTYPRICVALUE

ALLOY RIM ORBITGREY 9JX20 V SPK 759	1	2,167.45	2,167.45
FRT LH DOOR ALUMINIUM repair	1	1,863.20	1,863.20
FRT LH SIDE PANEL ALUMINIUM repair	1	929.15	929.15
M PERFORMANCE SIDE SKIRT STRIPES new	1	319.10	319.10
M PERFORMANCE CARBON MIRROR CAP LH cut	1	871.05	871.05
LH TURN INDICATOR EXTERIOR MIRROR base	1	75.15	75.15
SET EXTERIOR MIRROR CAMERA HOLDER new	1	60.10	60.10
SET OF SCREWS new	1	52.30	52.30
LH HEATED OUTSIDE MIRROR MEMORY BUS sed	1	979.50	979.50
FRT LH DOOR WINDOW FRAME COVER (GLA sed	1	145.80	145.80
FRT LH DOOR OUTER SHAFT COVER (GLAN sed	1	153.05	153.05



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49376
Date Estimated : 07/12/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS4011A	WA75105	22/09/2017	540iA	0

DESCRIPTION	QTY	PRIC	VALUE
LH SILL TRIM PRIMED (M) <i>sm /</i>	1	508.05	508.05
Total Parts :			8,123.90

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time <u>13/12/18 @ 1230</u>	Excess S\$ _____
Surveyor's Name <u>Rahul</u>	Sign _____
Surveyor's Tel <u>92012068</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESUMEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>8 days</u>	

Labour 1	:	12,542.00
Parts	:	8,123.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,446.61
Grand Total	:	22,112.51

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **