

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z**AAD1812-046***Not Authorized**1 Long @ ?**Book Value ??*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9910Z

VF1ABL15AUC277432

~~TOYOTA~~~~PRIUS~~

6.12.2018

III**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>BT/CM</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>CM</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>CM</i> 113.47	✓
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	<i>SL</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61	X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>CM</i> 135.97	✓
8	1 BUMEP R RETAINER LH REAR	\$	<i>CM</i> 44.99	✓
9	1 BUMPER REFLECTOR LH	\$	<i>BR</i> 43.61	✓
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	✓
13	1 BOOT REAR	\$	<i>R</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>SL</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$	<i>WT</i> 323.05	<i>SOL</i>
16	1 BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 493.35	✓
17	1 BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35	X
18	1 BOOT BADGE 'RENAULT'	\$	<i>SL</i> 225.36	✓
19	1 BOOT BADGE	\$	<i>SL</i> 225.36	✓
20	1 BOOT STRUT LH	\$	<i>SL</i> 276.08	} X
21	1 BOOT STRUT RH	\$	<i>SL</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>SL</i> 586.45	
25	1 BOOT SWITCH	\$	<i>SL</i> 168.13	
26	1 BOOT LOCK	\$	<i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>SL</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>SL</i> 221.81	

Trans-cab Auto Services Pte Ltd**AAD1812-046**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

30	1 FENDER PANEL REAR LH	\$	Bu 3,299.13	✓
31	1 WHEELARCH REAR LH	\$	SL 543.47	X
32	1 FENDER PANEL INNER TRIM REAR LH	\$	Reform 671.45	✓
33	1 FUEL FLAG	\$	SL 343.57	X
34	1 WHEEL HOUSING PANEL REAR LH	\$	R 4,682.09	X
35	1 CHASSIS PANEL REAR LH L70Y	\$	Bu 3,766.43	✓
36	1 TAILLAMP LH	\$	mgum 552.55	✓
37	1 TAILLAMP PANEL LH	\$	Bu 986.70	✓
38	1 OUTER PANEL REAR (End Panel)	\$	Bu 1,471.77	✓
39	1 OUTER PANEL REAR (End Panel)TRIM	\$	CM 404.56	✓
40	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	Bu/Bu 2,189.88	✓
41	1 SPARE WHEEL PANEL TRIM	\$	SL 612.21	X
42	1 EXHAUST REAR	\$	R 7,489.05	X
43	1 EXHAUST CAP REAR	\$	R 230.49	X

TOTAL	\$	38,607.73
10%	\$	3,860.77
	\$	34,746.95

Specical Nett

1	1SET PARKING AID	\$	Shay 700.00	Goosa
2	1SET REAR BUMPER CLIP	\$	na 66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	na 33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na 10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	na 20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na 10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na 20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na 22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na 66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	SL 17.82	X
11	1SET BOOT FINISHER CLIP	\$	na 24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	na 30.00	✓
13	1 BOOT STICKER "6555-3333"	\$	na 30.00	✓
14	1 BOOT INNER TRIM CLIP	\$	na 45.00	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na 35.00	X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na 35.00	X
17	1 FENDER INNER TRIM CLIP LH	\$	na 28.00	✓

Trans-cab Auto Services Pte Ltd**AAD1812-046**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

18	1 FENDER INNER TRIM CLIP RH	\$	na 28.00 X
19	1 TAILLAMP CLIP RH	\$	na 5.00 X
20	1 TAILLAMP CLIP LH	\$	na 5.00 ✓
21	2 REAR WINDSCREEN SELANT	\$	na 80.00 40SN
22	1 WINDSCREEN MOULDING	\$	na 100.00 ✓
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na 100.00 30SN
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	na 385.00 X
25	1 SPARE TYRE	\$	na 330.00 X

TOTAL \$ 2,225.02**TOTAL PARTS \$ 36,971.97****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 1100l
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00 2000l
To Rust-Proofing Of The Affected Areas.	\$	170.00 120l
To reinstall rear bumper parking sensor.	\$	170.00 60l
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 60l
To repair and realign rear exhaust pipe.	\$	170.00
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 } 60l
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00 } 100l

Trans-cab Auto Services Pte Ltd**AAD1812-046**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	801
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	na 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	1201
To check steering geometry and computer wheel alignment	\$	na 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	na 380.00	X

TOTAL \$ 14,340.00**Over All Total \$ 51,311.97****(LUMP SUM)****Repair Days****20 DAYS****16 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd**AAD1812-046**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9910Z

VF1ABL15AUC277432

RENAULT

LATITUDE

6.12.2018

III**PART****LIST**

1	1	BUMPER COVER FRT
2	1	BUMPER SPOILER FRT
3	1	BUMPER ABSORBER FRT
4	1	BUMPER RETAINER FRT LH
5	1	BUMPER SUPPORT FRT
6	1	BUMPER RETAINER FRT RH
7	1	BUMPER SUPPORT FRT
8	1	BUMPER UNDERTRAY FRT
9	1	BUMPER GRILLE LOWER FRT
10	1	BUMPER FOG LAMP GRILLE LH
11	1	BUMPER FOG LAMP GRILLE RH
12	1	BUMPER BEAM FRT
13	1	TOW COVER FRT
14	1	RADIATOR GRILLE
15	1	RADIATOR GRILLE BADGE 'RENAULT'
16	1	RADIATOR GRILLE FRAME
17	1	FRAME FULL SUPPORT PANEL
18	1	FRAME FULL SUPPORT BRACKET
19	1	FRONT BRACE PANEL
20	1	HORN
21	1	HORN BRACKET
22	1	HEADLAMP LH
22	1	HEADLAMP HARNESS
22	1	HEADLAMP RH
22	1	HEADLAMP HARNESS
22	1	HEADLAMP PANEL FRT LH
25	1	HEADLAMP PANEL FRT RH
26	1	BONNET

\$	<i>Bu</i>	1,259.42	✓
\$	<i>SL</i>	181.75	} X
\$	<i>SL</i>	394.68	
\$	<i>SL</i>	151.41	
\$	<i>SL</i>	123.88	
\$	<i>SL</i>	150.77	
\$	<i>SL</i>	123.88	
\$	<i>SL</i>	472.83	
\$	<i>SL</i>	266.80	
\$	<i>SL</i>	207.21	
\$	<i>SL</i>	207.21	
\$	<i>R</i>	914.08	
\$	<i>SL</i>	28.61	
\$	<i>CMA</i>	1,707.78	✓
\$	<i>R</i>	225.36	✓
\$	<i>CMA</i>	1,353.75	✓
\$	<i>CMA</i>	615.90	✓
\$	<i>R</i>	89.79	X
\$	<i>R</i>	177.22	X
\$	<i>SL</i>	314.17	X
\$	<i>R</i>	40.45	X
\$	<i>CMA</i>	1,184.43	✓
\$	<i>SL</i>	928.29	X
\$	<i>mgcm</i>	1,184.43	✓
\$	<i>R</i>	928.29	X
\$	<i>R</i>	152.15	X
\$	<i>R</i>	152.15	X
\$	<i>R</i>	1,941.63	✓

Trans-cab Auto Services Pte Ltd**AAD1812-046**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

27	1	BONNET INSULATOR	\$	SH 405.73	X
28	1	BONNET STRUT LH	\$	SH 88.61	X
29	1	BONNET STRUT RH	\$	SH 88.61	X
30	1	BONNET HINGE LH	\$	R 348.31	X
31	1	BONNET HINGE RH	\$	R 348.31	X
32	1	BONNET LOCK	\$	DIR 305.48	
33	1	BONNET CABLE	\$	SH 119.19	X
34	1	BONNET CABLE COVER	\$	SH 161.03	
35	1	BONNET SEAL OUTER	\$	SH 92.36	
36	1	BONNET SEAL INNER	\$	SH 157.28	
37	1	FENDER PANEL FRT LH	\$	R 783.83	
38	1	WHEELARCH FRT LH	\$	SH 278.84	
39	1	FENDER BRACKET LOWER LH	\$	SH 15.79	
40	1	FENDER INSULATOR LH	\$	SH 130.84	
41	1	FENDER PANEL FRT RH	\$	R 783.83	
42	1	WHEELARCH FRT RH	\$	SH 278.84	
43	1	FENDER BRACKET LOWER RH	\$	SH 15.79	
44	1	FENDER INSULATOR RH	\$	SH 130.84	
45	1	WIPER RESERVOIR	\$	SH 348.25	
46	1	WIPER RESERVOIR NECK	\$	SH 136.11	
47	1	WIPER RESERVOIR MOTOR	\$	SH 270.06	
48	1	AIR CLEANER LOWER	\$	SH 271.26	X
49	1	AIR CLEANER HOSE	\$	SH 76.14	
50	1	AIR CLEANER BOX	\$	SH 464.20	
51	1	TURBO DUCT	\$	SH 1,027.80	
52	1	A/C HEATER VALVE	\$	SH 484.50	
53	1	SUBFRAME OUTER FRT	\$	SH 2,652.45	
54	1	SUBFRAME BRACKET OUTER LH	\$	R 92.36	
55	1	SUBFRAME BRACKET OUTER RH	\$	R 92.36	
56	1	ENGINE UNDERTRAY	\$	SH 564.98	
57	1	A/C CONDENSER	\$	2,020.37	?
58	1	A/C CONDENSER GARNISH LH UPPER	\$	SH 39.67	X
59	1	A/C CONDENSER GARNISH RH UPPER	\$	SH 39.67	
60	1	A/C CONDENSER GARNISH LH	\$	SH 58.81	
61	1	A/C CONDENSER GARNISH RH	\$	SH 59.60	
62	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	SH 208.39	
63	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	SH 658.72	X
74	1	A/C PIPE COMPRESSOR	\$	SH 334.29	

Trans-cab Auto Services Pte Ltd**AAD1812-046**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

75	1	A/C PIPE	\$	S 658.72	}	X
76	1	A/C COMPRESSOR	\$	S 2,684.61		
77	1	AIR COOLER	\$	S 792.60		
78	1	AIR INTERCOOLER HOSE (LONG)	\$	S 1,014.13		
79	1	AIR INTERCOOLER HOSE (Short)	\$	S 375.14		
80	1	TRANSMISSION COOLER	\$	S 1,219.30	}	
81	1	TRANSMISSION COOLER PAD	\$	S 17.96		
82	1	RADIATOR	\$	1,202.20	}	X
83	2	RADIATOR STUD UPPER	\$	S 14.41		
84	2	RADIATOR BUSH UPPER	\$	S 50.12		
85	2	RADIATOR MTG LOWER	\$	S 55.85		
86	1	RADIATOR FAN COWLING	\$	S 820.54		
87	1	RADIATOR FAN MOTOR LH	\$	S 967.36		
88	1	RADIATOR FAN MOTOR RH	\$	S 1,479.46		
89	1	RADIATOR TANK	\$	S 324.62		
90	1	RADIATOR HOSE UPPER	\$	S 240.56		
91	1	RADIATOR HOSE LOWER	\$	S 491.18		
92	1	RADIATOR TANK HOSE	\$	S 61.18		
93	1	AUTO COMPUTER	\$	S 5,032.17		
94	1	INJECTION COMPUTER	\$	S 4,706.30		
95	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	S 5,154.52		
96	1	STEERING PUMP ELECTRIC	\$	S 2,306.90		
97	1	STEERING PINION RACK	\$	S 4,413.11		

TOTAL	\$	63,994.74
10%	\$	6,399.47
	\$	57,595.27

Special Nett

1	1SET RADIATOR GRILLE FRAME CLIP	\$	S 52.00	✓
2	1SET BUMPER CLIP FRT	\$	S 66.00	✓

Trans-cab Auto Services Pte Ltd**AAD1812-046**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

3	1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	}	X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50		
5	1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00		
6	1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50		
7	1	TOW COVER FRT	\$	Sh	14.50		
8	1SET	RADAIOR GRILLE SCREW	\$	na	16.00		
9	1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00		
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00		
11	2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00		
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00		
21	1	Windscreen moulding	\$	na	100.00	}	
22	1SET	Front licence plate with holder	\$	Pd	80.00 25na		

TOTAL	\$	562.50
TOTAL PARTS	\$	58,157.77

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts,
adjust and realign the same

\$ 6,000.00 500

Towing Fees.

\$ 120.00 50

To apply paint protection system (PPS) maintain
and enhancement

\$ na 380.00 X

Putty and spray painting of the affected portion.

\$ 6,000.00 440

To rust-proofing of the affected areas.

\$ 170.00 30

To remove and refit interior fittings, trimmings,
garnish, fittings and other, to enable repair.

\$ na 380.00 X

To check steering geometry and computer wheel
alignment

\$ na 220.00 X

Trans-cab Auto Services Pte Ltd

AAD1812-046

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00 X
To lift-up engine with gear box and refit.	\$	nn 440.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	nn 440.00 X
To remove and refit air bag system and reset.	\$	nn 480.00 X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	nn 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	380.00 1001
To replace, refix and top up coolant for radiator	\$	170.00 501
To vacuum, replace, refix and recharge Air Intercooler	\$	nn 170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00 X

TOTAL \$ 17,000.00**Over All Total \$ 75,157.77****Repair Days (LUMP SUM)****20-Days**

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: