

INSURANCE CASE OWNER

CC 4, III 180 22133, 69a39

LKK:
IDAC:

Surveyor:

X678

DOI:

ASSIGNMENT

01/2/18

Date / Time:

10/2/18

Registered in Merimen:

10/2/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SHC 8751 C

Claim No. : _____

Name of Insured : C7PL

Policy No. : _____

Insured Tel No. : _____ HP: _____

Make / Model : _____

Excess Sec II : SS _____ D.O.A. : 31/2/2018

Place of Accident : AIRPORT @ LVO

Is driver the owner? (YES / NO) Nature of Accident : _____

If NO, Driver Name / Age : _____

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : _____ (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SLU 5832 E

INSRS:
WSP: World Auto
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date / Time

STAGE DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time: 10/2/18 / 1:30pm. Confirm with: Sophia

Confirm by: Guo Asang

Repair Cost: P/P

SS 5646.60 (5 days) Reduction: \$266.40 % 59

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 28/2/18 / 12:45pm. Confirm with: Sophia

Email ☒ Call ☐

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost: (W/EST)

SS 6041.86

OI VEOV ended TP.

Loss of Rental (LOR):

SS - (days)

Loss of Use (LOU):

SS 350.00 (\$50 x 7 days)

Loss of Income (LOI):

SS - (\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ (Tick only one)

GIA/LTA Search

SS -

Medical:

SS -

Disbursement:

SS 60.00 (e.g. ☒ Independent)

Legal Cost

SS -

Total: SS 6391.86 Global Sum SS: 6390.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Payee 1:

SS 6390.00

Name 1:

World Auto Pte Ltd

Payee 2: (Strike if N.A.)

SS -

Name 2:

Payee 3: (Strike if N.A.)

SS -

Name 3:

1) Claim status: ☒ Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$500/-

COPY SENT

Yarl.

REF: III

C4597K

ASSIGNMENT

From: Date: 10/12/18

Estimated Cost:

OD TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

STU 5832E

at Workshop n/s:

World Auto

at:

No. 1 Kranji loop

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bol. or Market Value:

IDAC Accident Rptd:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res:

Yes or No

Lum Sum:

1-7-1 %

3 Val:

Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: 4U5832E Yr From: 07 Dec 2017

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

C/S - 1798

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp Reading:

69574

T/Radio: Insured / Std / NI / NA

Eng/No:

C/Nr:

JTDKB3FU 4035 64 554

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

U

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A:

D.O.L:

10-12-18

Survey held at:

w/s

5pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time:

Action / Instruction

P/P \$5646.60

(Red = \$8106.40 / 59%)

* 5 repair days + 2 PRS = 7 days.

Date/Time: File Pass 4/7



: Prel. Report

11



: Final Report

Date/Time: File Return 10/7

2/

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1. 3 + RS 54

1. Photo

1. Office

(10/11)

Report Format:

Lump Sum / I.B.I. (\$

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL ST #04-05 IOB BUILDING

049711

Attention : Motor Claim Department

Contact : 6223 8122

Estimate : ES000425

Date : 08/12/2018

Vehicle Num. : SLU 5832E(LCR)

Make/Model : TOYOTA PRIUS HYBRID

Chassis/Eng# :

Accident Date : 07/12/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR BOOT LID X Repair ✓		1,350.00 922.5
2.	1	REAR WINDSCREEN GLASS MOULDING X ✓		250.00 100(SN)
3.	1	REAR WINDSCREEN LOWER MOULDING X ✓		180.00 30(SN)
4.	1	REAR BOOTLID OUTER GARNISH X ✓		570.00
5.	1	REAR BOOT WEATHER STRIP X ✓		280.00 X
6.	2	REAR TAIL LAMP X ✓	900.00	1,800.00 X
7.	1	REAR BUMPER X ✓		900.00 458.6
8.	2	REAR BUMPER TAILLAMP X ✓	750.00	1,500.00 357.9
9.	1	REAR BOOT PRIUS EMBLEM X ✓		89.00 52.9
10.	1	REAR BOOT HYBRID EMBLEM (PRIUS) X ✓		89.00 60.8
11.	1	REAR BUMPER REINFORCEMENT X ✓		350.00 318.8
12.	1	REAR END PANEL X ✓		750.00 602.1
13.	1	REAR END PANEL TOP GARNISH X ✓		170.00 X
14.	1	REAR BOOT SPARE TYRE LOCKING BOLT X ✓		78.00 X
15.	2	REAR BOOT SPARE TYRE FOAM (FOR TOOLS) X ✓	380.00	760.00 X
16.	1	REAR LOWER BUMPER X ✓		570.00
17.	2	REAR BUMPER EXTENSION FILLER X ✓	230.00	460.00 335.2
18.	1	REAR ANTENNA SENSOR X ✓		188.00 X
19.	1	REAR BOOT INNER TRIM BOARD X ✓		350.00 X
List Total S\$:				10,684.00 4448.8
25.00% Discount S\$:				2,671.00
				8,013.00 3336.6
SPECIAL NETT ITEMS :				
1.	2PC	REAR WINDSCREEN SEALANT X ✓	180.00	360.00 40
2.	1	REAR BOOTLID OUTER GARNISH CLIPS X ✓		40.00 10
3.	1	REAR BUMPER CLIP X ✓		40.00 10

CONTINUE / ...

World Auto Consultants hence notify
 Repairer of the following:
 survey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

WORLD AUTO PTE LTD

#7 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL ST #04-05 IOB BUILDING

049711

Attention : Motor Claim Department

Contact : 6223 8122

Estimate : ES000425

Date : 08/12/2018

Vehicle Num. : SLU 5832E(LCR)

Make/Model : TOYOTA PRIUS HYBRID

Chassis/Eng# :

Accident Date : 07/12/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

4.	1	REVERSE SENSOR ✓		280.00
5.	1	REAR END PANEL TOP GARNISH CLIPS		40.00
6.	1	REAR BOOT INNER TRIM BOARD CLIP		40.00
7.	2	REAR TAILLAMP CLIPS	40.00	80.00
8.	1	TOWING CHARGE		60.00

Special Nett Total S\$:

940.00

LABOUR :

TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES

REMOVE & REFIT REAR WINDSCREEN GLASS
(2PC WINDSCREEN GLASS)

TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO
REPLACED PARTS.

TO DISMANTLE REAR DAMAGE PARTS, CUT AND WELD REAR
SUPPORT PANEL, KNOCK, STRAIGHTEN AND RESHAPE O/S REAR
CHASSIS FRAME AND REPLACE RECOMMENDED PARTS.

TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS

DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE
REPAIRS AND REACTIVATE BACK SAME
(HV HYBRID SYSTEM SAFETY PROCEDURES)

PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING
FAULT CODES AND REINITIALISING HV HYBRID SYSTEM FOR POST
REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES)

180.00

360.00

180.00

1,600.00

1,400.00

450.00

450.00

CONTINUE / ...

No photos showing battery dismantled.

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000425

Date : 08/12/2018
 Vehicle Num. : SLU 5832E(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 07/12/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS
 AND REVERSE SENSORS AND START/STOP UNIT CAPACITORS

180.00

40

Labour Total S\$:

1860

4,800.00

2360

5 Days.

Total : 5646.6

part by part.

before paint photos.

Guo Qiao - 8288082

10/12/18

E. & O.E.

Total S\$:

13,753.00

for WORLD AUTO PTE LTD

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000425

Date : 08/12/2018
 Vehicle Num. : SLU 5832E(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 07/12/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR BOOT LID X Repair / BT		1,380.00 / 922.5
2.	1	REAR WINDSCREEN GLASS MOULDING X / SATO = 3 MCC		250.00 / 100 (SN)
3.	1	REAR WINDSCREEN LOWER MOULDING X / BR = 30 (SN)		180.00 / 30 (SN)
4.	1	REAR BOOTLID OUTER GARNISH X / BR		570.00 /
5.	1	REAR BOOT WEATHER STRIP X / NN		280.00 X
6.	2	REAR TAIL LAMP X / NN	900.00	1,800.00 X
7.	1	REAR BUMPER X / PH-CRA, LHX NN		900.00 / 458.6
8.	2	REAR BUMPER TAILLAMP X / PH-CRA, LHX NN	750.00	1,500.00 X
9.	1	REAR BOOT PRIUS EMBLEM X / 3 MCC		89.00 / 557.9
10.	1	REAR BOOT HYBRID EMBLEM (PRIUS) X / 3 MCC		89.00 / 52.8
11.	1	REAR BUMPER REINFORCEMENT X / BT		350.00 / 318.8
12.	1	REAR END PANEL X / BT		750.00 / 602.1
13.	1	REAR END PANEL TOP GARNISH X / NN		170.00 X
14.	1	REAR BOOT SPARE TYRE LOCKING BOLT X / NN		78.00 X
15.	2	REAR BOOT SPARE TYRE FOAM (FOR TOOLS) X / NN	380.00	760.00 X
16.	1	REAR LOWER BUMPER X /		570.00 /
17.	2	REAR BUMPER EXTENSION FILLER X / BR	167.6	230.00 / 335.2
18.	1	REAR ANTENNA SENSOR X / NN		460.00 X
19.	1	REAR BOOT INNER TRIM BOARD X / NN		188.00 X
List Total S\$:				10,684.00
25.00% Discount S\$:				2,671.00
				8,013.00

SPECIAL NETT ITEMS :				
1.	2PC	REAR WINDSCREEN SEALANT X / MCC	180.00	360.00 X 40
2.	1	REAR BOOTLID OUTER GARNISH CLIPS X / MCC		40.00 / 10
3.	1	REAR BUMPER CLIP X /		40.00 / 10

CONTINUE / ...

Auto Consultants hence notify
 Repairer of the following:
 survey before/after spray painting

- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000425

Date : 08/12/2018
 Vehicle Num. : SLU 5832E(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 07/12/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
4.	1	REVERSE SENSOR ✓ DM		280.00 200
5.	1	REAR END PANEL TOP GARNISH CLIPS X		40.00 X
6.	1	REAR BOOT INNER TRIM BOARD CLIP X		40.00 X
7.	2	REAR TAILLAMP CLIPS X	40.00	80.00 X
8.	1	TOWING CHARGE ?		60.00 X
Special Nett Total S\$:			280	940.00
LABOUR :				
TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES				180.00 200 60
REMOVE & REFIT REAR WINDSCREEN GLASS (2PC WINDSCREEN GLASS)				200 360.00 200 60
TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.				60 180.00 60
TO DISMANTLE REAR DAMAGE PARTS, CUT AND WELD REAR SUPPORT PANEL, KNOCK, STRAIGHTEN AND RESHAPE O/S REAR CHASSIS FRAME AND REPLACE RECOMMENDED PARTS.				700 1,600.00 400 600
TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS				800 1,400.00 60
DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES) ?				250 450.00 * 250
PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISING HV HYBRID SYSTEM FOR POST REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES) ?				250 450.00 * 250

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000425

Date : 08/12/2018
 Vehicle Num. : SLU 5832E(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 07/12/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS
 AND REVERSE SENSORS AND START/STOP UNIT CAPACITORS

180.00

40

Labour Total S\$:

4,800.00

~~4,980.00~~

5 KDays.

temp

part by part.

before paint photos.

En. Qiao - 8288082

10/12/18

~~5,680.00~~

20% 1,115.00

E. & O.E.

Total S\$:

13,753.00

=====

for WORLD AUTO PTE LTD

While notify
 following:
 - repair after spray painting
 - damaged part(s) during resurvey
 - are subject to confirmation
 - survey is on a "Without Prejudice" basis
 - legal modification(s) is allowed
 - supplementary item(s) must be resurveyed and
 - subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4597K
Vehicle Details	
Vehicle No.:	SLU5832E
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2ZRS064988
Chassis No.:	JTDKB3FU403564554
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	07 Dec 2017
First Registration Date:	07 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Dec 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	06 Dec 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,109.00
COE Rebate Amount:	\$43,228.00
Total Rebate Amount:	\$46,978.00

The information contained herein is correct as at 11 Dec 2018

OK

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL ST #04-05 IOB BUILDING

049711

Attention : Motor Claim Department

Contact : 6223 8122

Estimate : ES000425

Date : 08/12/2018

Vehicle Num. : SLU 5832E(LCR)

Make/Model : TOYOTA PRIUS HYBRID

Chassis/Eng# :

Accident Date : 07/12/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOT LID X Repair		1,350.00
2.	1	REAR WINDSCREEN GLASS MOULDING X {NN		250.00
3.	1	REAR WINDSCREEN LOWER MOULDING X {NN		180.00
4.	1	REAR BOOTLID OUTER GARNISH ?		570.00
5.	1	REAR BOOT WEATHER STRIP ?		280.00
6.	2	REAR TAIL LAMP ?	900.00	1,800.00
7.	1	REAR BUMPER ?		900.00
8.	2	REAR BUMPER TAILLAMP ?	750.00	1,500.00
9.	1	REAR BOOT PRIUS EMBLEM - {MCC		89.00
10.	1	REAR BOOT HYBRID EMBLEM (PRIUS) - {MCC		89.00
11.	1	REAR BUMPER REINFORCEMENT ?		350.00
12.	1	REAR END PANEL X Repair		750.00
13.	1	REAR END PANEL TOP GARNISH ?		170.00
14.	1	REAR BOOT SPARE TYRE LOCKING BOLT X {NN		78.00
15.	2	REAR BOOT SPARE TYRE FOAM (FOR TOOLS) X {NN	380.00	760.00
16.	1	REAR LOWER BUMPER - {MCC		570.00
17.	2	REAR BUMPER EXTENSION FILLER ?	230.00	460.00
18.	1	REAR ANTENNA SENSOR		188.00
19.	1	REAR BOOT INNER TRIM BOARD X NN		350.00
List TotalS\$:				10,684.00
25.00% Discount S\$:				2,671.00
				8,013.00
SPECIAL NETT ITEMS :				
1.	2PC	REAR WINDSCREEN SEALANT X NN	180.00	360.00
2.	1	REAR BOOTLID OUTER GARNISH CLIPS - {MCC		40.00
3.	1	REAR BUMPER CLIP		40.00

CONTINUE / ...

LKR Auto Consultants hence notify
Repairer of the following:

- Resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL ST #04-05 IOB BUILDING

049711

Attention : Motor Claim Department

Contact : 6223 8122

Estimate : ES000425

Date : 08/12/2018

Vehicle Num. : SLU 5832E(LCR)

Make/Model : TOYOTA PRIUS HYBRID

Chassis/Eng# :

Accident Date : 07/12/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
4.	1	REVERSE SENSOR		280.00
5.	1	REAR END PANEL TOP GARNISH CLIPS		40.00
6.	1	REAR BOOT INNER TRIM BOARD CLIP		40.00
7.	2	REAR TAILLAMP CLIPS	40.00	80.00
8.	1	TOWING CHARGE		60.00
Special Nett Total S\$:				940.00
LABOUR :				
TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES				180.00 X
REMOVE & REFIT REAR WINDSCREEN GLASS (2PC WINDSCREEN GLASS)				360.00 X
TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.				180.00 X
TO DISMANTLE REAR DAMAGE PARTS, CUT AND WELD REAR SUPPORT PANEL, KNOCK, STRAIGHTEN AND RESHAPE O/S REAR CHASSIS FRAME AND REPLACE RECOMMENDED PARTS.				1,600.00 400
TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS				1,400.00 600
DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)				450.00 X
PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINTIALISING HV HYBRID SYSTEM FOR POST REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES)				450.00 X

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000425

Date : 08/12/2018
 Vehicle Num. : SLU 5832E(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 07/12/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS AND REVERSE SENSORS AND START/STOP UNIT CAPACITORS		180.00
		Labour Total S\$:		4,800.00

4 Days.

~~temp~~

part by part.

before paint photos.

En. Qiaf - 82880582

10/12/18

E. & O.E.

Total S\$: 13,753.00

for WORLD AUTO PTE LTD

Notice to the policyholder

When the repairer is not the policyholder, the repairer must notify the policyholder of the following:

- When spray painting is required
- When part(s) are replaced during resurvey
- When the repair is subject to confirmation
- When the repair is on a "Without Prejudice" basis
- When legal modification(s) is allowed
- When supplementary item(s) must be resurveyed and
- When the repair is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____



Reg No: 52977287 J

CASH SALE/WORK ORDER

迅速拖車服務 SPEEDWAY RECOVERY SERVICE

Singapore Post Centre Post Office P.O. Box 201 Singapore 914007

Tel: 6841 0080

No: E 17847

Date: 7/12/15

Name/Company

World Auto

Vehicle No.

SLU5832E

Model

Plus

From

T-2 Airport

To

Kranji

Remarks

93373026

Time:

20:35 - 21:10 - 21:50

Amount

\$ 600

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misadventure to your vehicle whilst being towed.

Tow Truck

24 HRS TOWING SERVICE
6841 0080

www.speedwayrecovery.com
Email: speedwaytowing@gmail.com

Received By

[Signature]

- ☐ Jump Start
- ☐ Tyre Replacement
- ☒ Accident/Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☐ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo Payment
- ☐ Trips

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 10 December 2018 10:20 AM
To: ainee31@worldauto.com.sg; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: worldautopl@yahoo.com.sg; Zuhaidah Samsuri
Subject: RE: Request for Third Party Motor Claim Survey (SLU5832E) DOA: 07-12-2018

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLU5832E and let us have your report urgently.

This claim will be handled by Ms Aida.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

10:51 am @ 10/12/18
Per @ Ainee
vehicle In

From: ainee31@worldauto.com.sg [mailto:aine31@worldauto.com.sg]
Sent: 10 December, 2018 9:54 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: worldautopl@yahoo.com.sg
Subject: RE: Request for Third Party Motor Claim Survey (SLU5832E) DOA: 07-12-2018

DEAR ALL,

- LKK Auto Consultants Pte Ltd

Ainee
Thanks and Rgds,
World Auto Pte Ltd
Kranji: 63621776
Fax: 63631250

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, December 10, 2018 9:24 AM
To: aine31@worldauto.com.sg
Cc: worldautopl@yahoo.com.sg
Subject: RE: Request for Third Party Motor Claim Survey (SLU5832E) DOA: 07-12-2018

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: aine31@worldauto.com.sg [<mailto:aine31@worldauto.com.sg>]
Sent: 08 December, 2018 11:48 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: worldautopl@yahoo.com.sg
Subject: Request for Third Party Motor Claim Survey (SLU5832E) DOA: 07-12-2018

Good afternoon,
We would like to request for a Third Party Motor Claim Survey, details as follow;

Our Vehicle: SLU5832E
Your Insured: SHC8751C
DOA: 07-12-2018

Our vehicle is currently in the workshop, address as follow;

World Auto Pte Ltd
No.1, Kranji Loop
Singapore 739535

Please response immediately upon receiving this request, send us your list of Loss Adjustor for our choice within 48 hours.

Kindly note that should you fail to response to us within the above stipulated timeline, we may, at our discretion, appoint our own Loss Adjustor to perform this PRI.

Ainee
Thanks and Rgds,
World Auto Pte Ltd
Kranji: 63621776
Fax: 63631250

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

Print Received Message

This mail is associated with :

***SLU5832E (MCT18120202)**
[SHC8751C]
TP
LCRF PTE LTD
Dec 7 2018 8:00PM
[-]
World Auto Pte Ltd - Kranji

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 22/08/2019 11:37 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6461.86) - SLU5832E - Claim Handler: Zuhaidah Bte Samsuri

Approved:6461.86.

cc4/111 18072133/69a3

cecilia



WORLD AUTO PTE LTD

47 JALAN PEMIMPIN #01-02/03

HALCYON 2

SINGAPORE 577200

Tel: 64513933 Fax: 64557576

Date: 6/8/2019

Your ref: SHC 8751C

Our ref: TP/2364/18

India International Insurance Pte Ltd

BY EMAIL

64 Cecil Street

#04/#05 IOB Building

Singapore 049711

Dear Sirs

ACCIDENT INVOLVING SLU 5832E & SHC 8751C ON 7.12.18 ALONG T2 AIRPORT

Reference is made to the aforesaid matter (on behalf of our clients M/S LCRF PTE LTD)

Enclosed herewith are the following documents for your information and necessary actions only:-

- A. Final Repair Bill;
- B. Letter of Authorisation

We are claiming the following:-

1. Final bill	:	\$5,646.60
2. Gst 7%	:	\$ 395.26
3. Pre-repair inspection (\$60 x 2 day)	:	\$ 120.00
4. Loss of use (\$60 x 5 days)	:	\$ 300.00
		<u>\$6,461.86</u>

Kindly revert with your clients' mandate for settlement.

Yours faithfully,

World Auto Pte Ltd

World Auto Pte Ltd

Encls:

LETTER OF AUTHORISATION

In the matter of the following accident:-

DATE OF ACCIDENT : 07/12/2018

CLIENT'S VEHICLE NO : SLU5832E

PLACE OF ACCIDENT : T2 AIRPORT

THIRD PARTY VEHICLE NO : SHC8751C

I/We, LCRF PTE LTD

ADDRESS: 29 PAYA LEBAR ROAD, PAYA LEBAR OFFICE CENTRE

UEN/NRIC/FIN NO : 201624597K

Tel. (O) _____ (H) _____ (MOBILE) _____

I/We hereby authorize and appoint World Auto Pte Ltd to act for me/us in respect of the above matter up to the final conclusion of the said matter.

I/We hereby authorize and appoint World Auto Pte Ltd to act for me/us for the purpose of negotiating and enter into settlement with the tortfeasor, their insurers or solicitors appointed by the tortfeasor/insurers without the need to commence action.

I/We hereby authorize World Auto Pte Ltd to receive on my/our behalf all settlement sums and disbursements including loss of use/rental to pay to yourselves all costs you may at any time receive in connection with the above mention matter.

DATED THIS 8TH DAY OF DEC YEAR 2018



Name: LCRF PTE LTD
UEN No: 201624597K

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT18120202
Claimant Ref: SLU 5832E

We/I, WORLD AUTO PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 6,390.00 (global sum) ~~(repair cost) S\$ 6,390.00~~ ~~(repair cost) S\$ 6,390.00~~ vehicle no. SLU 5832E that was damaged pursuant to the accident which occurred on 07/12/2018 (date) at AIRPORT BOULEVARD TWDS T2 TAXI Q (location) involving vehicle no. SHC 8751C (insured vehicle). This is pursuant to the inspection conducted on 10/12/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner LCRF PTE LTD ("the third party claimant") of vehicle no. SLU 5832E to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLU 5832E (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 6,390.00 to WORLD AUTO PTE LTD

Dated this 30 day of August 2019

CLAIMANT:
Signature: [Signature]
Signed by "the workshop" (with chop)
Name: Sophia Tan
NRIC: 614345881D
Address: 5 Kim Chuan Lane
3 537010
Nationality: Singaporean
Occupation: Claims Manager

WITNESS:
Signature: [Signature]
Signed by appointed Surveyor
Name: LKK AUTO CONSULTANTS PTE LTD
NRIC: 199607198R
Address: 51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK
#02-25 SINGAPORE 408933
Nationality: _____
Occupation: _____

WORLD AUTO PTE LTD

47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG

S'PORE 577200

Tel No. : 64513933 Fax No. : 64557576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL ST, #04/#05/#06-02 IOB BUILDING

S'PORE 049711

Attention : Motor Claim Department

Contact : 63476100 63476139-LALITA Fax No. : 62244174

Tax Invoice : F189473

Date : 06/08/2019

Vehicle Num. : SLU 5832E

Make/Model : TOYOTA PRIUS, 1.8 HYBRID

Chassis/Eng# :

Accident Date : 07/12/2018

Claim No. : TP/2364/2018

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOT LID		922.50
2.	1	REAR BOOTLID OUTER GARNISH		570.00
3.	1	REAR BUMPER		458.60
4.	1	REAR BUMPER TAILLAMP RH		557.90
5.	1	REAR BOOT PRIUS EMBLEM		52.90
6.	1	REAR BOOT HYBRID EMBLEM		60.80
7.	1	REAR BUMPER REINFORCEMENT		318.80
8.	1	REAR END PANEL		602.10
9.	1	REAR LOWER BUMPER		570.00
10.	2	REAR BUMPER EXTENSION FILLER	167.60	335.20
List Total S\$:				4,448.80
25.00% Discount S\$:				1,112.20
				3,336.60
SPECIAL NETT ITEMS :				
1.	1	REAR WINDSCREEN GLASS MOULDING		100.00
2.	1	REAR WINDSCREEN GLASS LOWER MOULDING		30.00
3.	1	REAR WINDSCREEN SEALANT		40.00
4.	1SET	REAR BOOTLID OUTER GARNISH CLIPS		10.00
5.	1SET	REAR BUMPER CLIPS		10.00
6.	1	REVERSE SENSOR		200.00
7.	1	TOWING CHARGE		60.00
Special Nett Total S\$:				450.00
LABOUR :				
TRANSFER REAR BOOTLID MECHANISM & ACCESSORIES				60.00
REMOVE & REFIT REAR WINDSCREEN GLASS (x2pcs)				200.00
APPLY RUSTPROOFING/TUFFCOATING TREATMENT TO REPLACED PARTS				60.00
DISMANTLE & REPLACE REAR DAMAGED PARTS, CUT/WELD REAR SUPPORT PANEL, KNOCK, STRAIGHTEN & RESHAPE O/S REAR				700.00

CONTINUE / ...

47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG

S'PORE 577200

Tel No. : 64513933 Fax No. : 64557576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL ST, #04/#05/#06-02 IOB BUILDING

S'PORE 049711

Attention : Motor Claim Department

Contact : 63476100 63476139-LALITA Fax No. : 62244174

Tax Invoice : F189473

Date : 06/08/2019

Vehicle Num. : SLU 5832E

Make/Model : TOYOTA PRIUS, 1.8 HYBRID

Chassis/Eng# :

Accident Date : 07/12/2018

Claim No. : TP/2364/2018

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount SS
		FRAME CHASSIS		
		PUTTY & SPRAY PAINT ON REAR AFFECTED AREAS		800.00
		CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS & REVERSE SENSORS & START/STOP CAPACITORS		40.00
		Labour Total SS :		1,860.00

Total SS :	5,646.60
GST 7% SS :	395.26
Amount Due SS :	6,041.86
=====	



WORLD AUTO PTE LTD



Reg No: 52977287 J

CASH SALE/WORK ORDER

迅速拖車服務 SPEEDWAY RECOVERY SERVICE

Singapore Post Centre Post Office P.O. Box 201 Singapore 914007

Tel: 6841 0080

No: E 17847

Date: 7/12/15

Name/Company World Auto

Vehicle No. SLU5832E Model Plus

From T-2 Airport

To Kranji

Remarks 93373026

Time: 20:35 - 21:10 - 21:50

- ☐ Jump Start
- ☐ Tyre Replacement
- ☒ Accident Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☐ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo Payment
- ☐ Trips

Amount \$ 800

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misadventure to your vehicle whilst being towed.

Tow Truck

24 HRS TOWING SERVICE
6841 0080
www.speedwayrecovery.com
Email: speedwaytowing@gmail.com

Received By

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Mar 2019 Edit Reg		10 Dec 2018 00:00 Edit Adj Rpt	\$5,646.60 Edit Estimates	\$5,646.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	LCRF PTE LTD , Co. Reg. No.: 201624597K								
Vehicle Reg. No.:	SLU5832E	Date of Loss:	07/12/2018 20:00 - :59 [12 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18120202	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHC8751C	Policy No. (Claimant):	999994927						
		Excess:							
Repairer:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 63621776								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 19/12/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
- III_SG (22/08/2019): Alert - Adj Mandate Approved (\$6461.86) - SLU5832E - Claim Handler: Zuhaidah Bt... - III_SG (20/06/2019): Alert - Adj Mandate Approved (\$0.00) - SLU5832E - Claim Handler: Zuhaidah Bte S...									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLU5832E (MCT18120202)
[SHC8751C]
TP
LCRF PTE LTD
Dec 7 2018 8:00PM
[COMFORT TRANSPORTATION PTE LTD]
World Auto Pte Ltd - Kranji

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Photos/Images								3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	19/07/19 13:24	General View							Load JPG	☒	
2	19/07/19 13:24	General View							Load JPG	☒	
3	19/07/19 13:24	General View							Load JPG	☒	
4	19/07/19 13:24	General View							Load JPG	☒	
5	19/07/19 13:24	General View							Load JPG	☒	
6	19/07/19 13:24	General View							Load JPG	☒	
7	19/07/19 13:24	General View							Load JPG	☒	
8	19/07/19 13:24	General View							Load JPG	☒	
9	19/07/19 13:24	General View							Load JPG	☒	
10	19/07/19 13:24	General View							Load JPG	☒	
11	19/07/19 13:24	General View							Load JPG	☒	
12	19/07/19 13:24	General View							Load JPG	☒	
13	19/07/19 13:24	General View							Load JPG	☒	
14	19/07/19 13:24	General View							Load JPG	☒	
15	19/07/19 13:24	General View							Load JPG	☒	
16	19/07/19 13:24	General View							Load JPG	☒	
17	19/07/19 13:24	General View							Load JPG	☒	
18	19/07/19 13:24	General View							Load JPG	☒	
19	19/07/19 13:24	General View							Load JPG	☒	
20	19/07/19 13:24	General View							Load JPG	☒	
21	19/07/19 13:24	General View							Load JPG	☒	
22	19/07/19 13:24	General View							Load JPG	☒	
23	19/07/19 13:24	General View							Load JPG	☒	
24	19/07/19 13:24	General View							Load JPG	☒	
25	19/07/19 13:24	General View							Load JPG	☒	
26	19/07/19 13:24	General View							Load JPG	☒	
27	19/07/19 13:24	General View							Load JPG	☒	
28	19/07/19 13:24	General View							Load JPG	☒	
29	19/07/19 13:24	General View							Load JPG	☒	
30	19/07/19 13:24	General View							Load JPG	☒	
31	19/07/19 13:25	Odometer Reading							Load JPG	☒	
32	19/07/19 13:25	Chassis Number							Load JPG	☒	
33	19/07/19 13:25	Dismantled Parts							Load JPG	☒	
34	19/07/19 13:25	Dismantled Parts							Load JPG	☒	
35	19/07/19 13:25	Dismantled Parts							Load JPG	☒	
36	19/07/19 13:25	Dismantled Parts							Load JPG	☒	
37	19/07/19 13:25	Dismantled Parts							Load JPG	☒	

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	19/07/19 13:25	Dismantled Parts		☒
39	19/07/19 13:25	Dismantled Parts		☒
40	19/07/19 13:25	Dismantled Parts		☒
41	19/07/19 13:25	Dismantled Parts		☒
42	19/07/19 13:25	Dismantled Parts		☒
43	19/07/19 13:25	Dismantled Parts		☒
44	19/07/19 13:25	Dismantled Parts		☒
45	19/07/19 13:25	Dismantled Parts		☒
46	19/07/19 13:25	Dismantled Parts		☒
47	19/07/19 13:25	Dismantled Parts		☒
48	19/07/19 13:25	Dismantled Parts		☒
49	19/07/19 13:25	Dismantled Parts		☒
50	19/07/19 13:25	Dismantled Parts		☒
51	19/07/19 13:25	Dismantled Parts		☒
52	19/07/19 13:25	Dismantled Parts		☒
53	19/07/19 13:25	Dismantled Parts		☒
54	19/07/19 13:25	Dismantled Parts		☒
55	19/07/19 13:25	Dismantled Parts		☒
56	19/07/19 13:25	Dismantled Parts		☒
57	19/07/19 13:25	Dismantled Parts		☒
58	19/07/19 13:25	Dismantled Parts		☒
59	19/07/19 13:25	Dismantled Parts		☒
60	19/07/19 13:25	Dismantled Parts		☒
61	19/07/19 13:25	Dismantled Parts		☒
62	06/08/19 12:19	Reinspection Photo		☒
63	06/08/19 12:19	Reinspection Photo		☒
64	06/08/19 12:19	Reinspection Photo		☒
65	06/08/19 12:19	Reinspection Photo		☒
Documentation			1 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/12/18 14:46	ACKNOWLEDGEMENT EMAIL TO III DD 10.12.2018		
2	14/12/18 10:43	TP ESTIMATE + TOWING		
3	14/12/18 10:43	TP GIA REPORT		
4	21/08/19 16:30	TOWING FEE		
5	21/08/19 16:30	LOD		
6	11/09/19 08:07	WORKSHOP INVOICE		
7	11/09/19 08:07	AUTHORISATION TO ACT FORM		
8	11/09/19 08:07	DISCHARGE VOUCHER		
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	11/12/18 10:31	Singapore Accident Statement		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18022133/GGA3Q2

Date: 11/09/2019

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SLU5832E	Insured Vehicle No :	SHC8751C
Date of Loss:	07/12/2018	Nature of Claim:	TP
		Claim No:	MCT18120202

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU5832E	Engine No:	2ZRS064988
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Chassis No:	JTDKB3FU403564554
Reg. Date:	07/12/2017 (Man. Year: 2017)	Odometer:	69574 km
Colour:	Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,893.00	3,726.60	5,166.40	58.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,860.00	1,920.00	2,940.00	60.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,753.00	5,646.60	8,106.40	58.94
+ GST 7.00/7.00% (S\$)	962.71	395.26	567.45	58.94
Nett Amount (S\$)	14,715.71	6,041.86	8,673.85	58.94
+ Loss of Use (7.0 x S\$50.00/day) (S\$)		350.00		
	Nett Liability (S\$)	6,391.86		
	Global Sum Settlement (S\$)	6,390.00		

INSPECTION

Date of Assignment:	10/12/2018		
Date Inspected:	10/12/2018	Inspected At:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop Singapore 739535
Estimated Period of Repair:	5.0 days		

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Aug 2019)	
Parts: 144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLU5832E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	1,350.00 FL	*922.50 FL
2	1		*REAR BOOTLID OUTER GARNISH	Broken	570.00 FL	*570.00 FL
3	1		*REAR BOOT WEATHER STRIP	Not Necessary	280.00 FL	*- FL
4	2		*REAR TAIL LAMP	Not Necessary	1,800.00 FL	*- FL
5	1		*REAR BUMPER	Deformed	900.00 FL	*458.60 FL
6	1		*REAR BUMPER TAILLAMP	O/S Cracked	1,500.00 FL	*557.90 FL
7	1		*REAR BOOT PRIUS EMBLEM	Necessary	89.00 FL	*52.90 FL
8	1		*REAR BOOT HYBRID EMBLEM (PRIUS)	Necessary	89.00 FL	*60.80 FL
9	1		*REAR BUMPER REINFORCEMENT	Bent	350.00 FL	*318.80 FL
10	1		*REAR END PANEL	Buckled	750.00 FL	*602.10 FL
11	1		*REAR END PANEL TOP GARNISH	Not Necessary	170.00 FL	*- FL
12	1		*REAR BOOT SPARE TYRE LOCKING BOLT	Not Necessary	78.00 FL	*- FL
13	2		*REAR BOOT SPARE TYRE FOAM (FOR TOOLS)	Not Necessary	760.00 FL	*- FL
14	1		*REAR LOWER BUMPER	Deformed	570.00 FL	*570.00 FL
15	2		*REAR BUMPER EXTENSION FILLER	Broken	460.00 FL	*335.20 FL
16	1		*REAR ANTENNA SENSOR	Not Necessary	188.00 FL	*- FL
17	1		*REAR BOOT INNER TRIM BOARD	Not Necessary	350.00 FL	*- FL
18	2		*REAR WINDSCREEN SEALANT	Necessary	360.00 FS	*40.00 FS
19	1		*REAR BOOTLID OUTER GARNISH CLIPS	Necessary	40.00 FS	*10.00 FS
20	1		*REAR BUMPER CLIP	Necessary	40.00 FS	*10.00 FS
21	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
22	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
23	1		*REAR BOOT INNER TRIM BOARD CLIP	Not Necessary	40.00 FS	*- FS
24	2		*REAR TAILLAMP CLIPS	Not Necessary	80.00 FS	*- FS
25	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	187.50 FS	*100.00 FS
26	1		*REAR WINDSCREEN LOWER MOULDING	Necessary	135.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,456.50	4,838.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,563.50	1,112.20
Total Parts (\$\$)	8,893.00	3,726.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGE	New	60.00	60.00
2	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	New	180.00	60.00
3	REMOVE & REFIT REAR WINDSCREEN GLASS	New	360.00	200.00
4	TO APPLY RUSTPROOFING / TUFF COATING TREATMENT TO REPLACED PARTS.	New	180.00	60.00
5	TO DISMANTLE REAR DAMAGE PARTS, CUT AND WELD REAR SUPPORT PANEL, KNOCK, STRAIGHTEN AND RESHAPE O/S REAR CHASSIS FRAME AND REPLACE RECOMMENDED PARTS.	New	1,600.00	700.00
6	TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS	New	1,400.00	800.00
7	DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)	New	450.00	0.00
8	PERFORM WHOLE VEHICLE DIAGNOSTIC INCLUDING CLEARING FAULT CODES AND REINTIALISING HV HYBRID SYSTEM FOR POST REPAIRS (HV HYBRID SYSTEM SAFETY PROCEDURES)	New	450.00	0.00
9	TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS AND REVERSE SENSORS AND START / STOP UNIT CAPACITORS	New	180.00	40.00
Gross Labour Cost (S\$)			4,860.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >