

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000425

Date : 08/12/2018
 Vehicle Num. : SLU 5832E(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 07/12/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOT LID X Repair		1,350.00
2.	1	REAR WINDSCREEN GLASS MOULDING X {NN		250.00
3.	1	REAR WINDSCREEN LOWER MOULDING X {NN		180.00
4.	1	REAR BOOTLID OUTER GARNISH ?		570.00
5.	1	REAR BOOT WEATHER STRIP ?		280.00
6.	2	REAR TAIL LAMP ? ee	900.00	1,800.00
7.	1	REAR BUMPER ?		900.00
8.	2	REAR BUMPER TAILLAMP ?	750.00	1,500.00
9.	1	REAR BOOT PRIUS EMBLEM /		89.00
10.	1	REAR BOOT HYBRID EMBLEM (PRIUS) /		89.00
11.	1	REAR BUMPER REINFORCEMENT ?		350.00
12.	1	REAR END PANEL X Repair		750.00
13.	1	REAR END PANEL TOP GARNISH ?		170.00
14.	1	REAR BOOT SPARE TYRE LOCKING BOLT X {NN		78.00
15.	2	REAR BOOT SPARE TYRE FOAM (FOR TOOLS) X {NN	380.00	760.00
16.	1	REAR LOWER BUMPER / ee		570.00
17.	2	REAR BUMPER EXTENSION FILLER ?	230.00	460.00
18.	1	REAR ANTENNA SENSOR ?		188.00
19.	1	REAR BOOT INNER TRIM BOARD X NN		350.00
List TotalS\$:				10,684.00
25.00% Discount S\$:				2,671.00
				8,013.00
SPECIAL NETT ITEMS :				
1.	2PC	REAR WINDSCREEN SEALANT X NN	180.00	360.00
2.	1	REAR BOOTLID OUTER GARNISH CLIPS /		40.00
3.	1	REAR BUMPER CLIP /		40.00

CONTINUE / ...

LKR Auto Consultants hence notify
 Repairer of the following:

- Resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000425

Date : 08/12/2018
 Vehicle Num. : SLU 5832E(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 07/12/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
4.	1	REVERSE SENSOR		280.00
5.	1	REAR END PANEL TOP GARNISH CLIPS		40.00
6.	1	REAR BOOT INNER TRIM BOARD CLIP		40.00
7.	2	REAR TAILLAMP CLIPS	40.00	80.00
8.	1	TOWING CHARGE		60.00
Special Nett Total S\$:				940.00
LABOUR :				
		TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES		180.00
		REMOVE & REFIT REAR WINDSCREEN GLASS (2PC WINDSCREEN GLASS)		360.00
		TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.		180.00
		TO DISMANTLE REAR DAMAGE PARTS, CUT AND WELD REAR SUPPORT PANEL, KNOCK, STRAIGHTEN AND RESHAPE O/S REAR CHASSIS FRAME AND REPLACE RECOMMENDED PARTS.		1,600.00
		TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS		1,400.00
		DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)		450.00
		PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINTIALISING HV HYBRID SYSTEM FOR POST REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES)		450.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000425

Date : 08/12/2018
 Vehicle Num. : SLU 5832E(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 07/12/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS AND REVERSE SENSORS AND START/STOP UNIT CAPACITORS		180.00
		Labour Total S\$:		4,800.00

4 Days.

~~temp~~

part by part.

before paint photos.

Eno Qiaf - 8288082

10/12/18

E. & O.E.**Total S\$: 13,753.00**

=====

for WORLD AUTO PTE LTD

...ence notify
 e following:
 ...after spray painting
 ...damaged part(s) during resurvey
 ...es are subject to confirmation
 ...d party survey is on a "Without Prejudice" basis
 ...illegal modification(s) is allowed
 * Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Reg No: 52977287 J

CASH SALE/WORK ORDER

迅速拖車服務 SPEEDWAY RECOVERY SERVICE

Singapore Post Centre Post Office P.O. Box 201 Singapore 914007

Tel: 6841 0080

No: E 17847

Date: 7/12/15

Name/Company World Auto

Vehicle No. SLU5832E Model Plus

From T-2 AIRPORT

To Kranji

Remarks 93373026

Time: 20:35 - 21:10 - 21:50

- ☐ Jump Start
- ☐ Tyre Replacement
- ☒ Accident/Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☐ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo Payment

☐ Trips

Amount \$ 600

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

[Signature]
Tow Truck

24 HRS TOWING SERVICE
6841 0080

www.speedwayrecovery.com
Email: speedwaytowing@gmail.com

[Signature]
Received By