

ASS. REC. BY:

REF: CS/EGT18022/37/R1sd3/02

Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): Yee Pei Li

of

EGT

Date/Time: 10/12/18 @ 11:36am

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFY 9225G

Insured:

GBH 2851G

at Workshop m/s

TC Autoclinic

Tel:

96450023

of

25 Leng Kee Road

Policy No:

Claim No:

GBH 2851G / RH / PI

Sum Insured:

Excess:

Make of Veh:

D.O.A.

4/12/18

(Client's Record)

CA / REV / REP. / REV 24 HRS (OS)

H.O.D. Endorsement:

Date/Time: 11:43am @ 10/12/18

Person Contacted:

Shawn

Vehicle IN / ~~OUT~~

Date/Time	Action/Instruction (✓) Estimate	advise consistency of damage
	SFY9225G-NBA/INC18021835/Y	DOA: 4/12/18
	GBH 2851G-NBA/INC18021835/Y	DOA: 4/12/18
13/12/18	@ 16:51 p.m. revised PA to Pei Li via email	

Person

REF: EGI

1365F

ASSIGNMENT

From: Date: 11/12/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SF9 9225G
at Workshop m/s: TC Autoclinic
of: 28 Leng Kee Road

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

2pm - 4pm
Shawn

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (DS)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SF9 9225G Yt Regn: 2015 / AUG

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN S/LPHY 1.6 CVT C.C. 1598

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: 97681 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MNTBBAB17Z0024367

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Jammed / Leaked / Burnt or

Brake: ☒ Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60R16
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or KAPSEN

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 04/12/18 D.O.I. 11/12/18

Survey held at TC AUTOCLINIC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
17/01/19 Confirmed p/r \$ 2,796.16 @ 5 days with Rasu.
(\$ 2,881.76 Red 51%)

RECEIVED 17 JAN 2019

Date/Time, File Pass to?

17/01/19



Preli. Report

1) TYPH



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation

\$ + PS \$

Photos

Others

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech Invs (\$

☐ Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) 2,796.16

250

TOTAL



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: GBH2851G/RH/pl

Date: 13 December 2018

Our Ref: CS/EGH18022137/R1sd3

The Motor Claims Department
ERGO INSURANCE PTE LTD

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. SFY 9225G

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/12/2018 at the premises of M/s TC Autoclinic Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 5,677.92</u>
Revised Estimate Amount	: <u>S\$ 4,716.68</u>
"Check" Items Amount	: <u>S\$ -</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:

The vehicle sustained damages at the n/s rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 6 Days

Yours faithfully,
Mohammed Rasul
Automotive Assessor

Shirley Hiew (LKK Auto)

From: Shawn Chua <shawnychua@tanchong.com>
Sent: Thursday, 17 January 2019 11:40 AM
To: Rasul (LKKAuto)
Cc: SUR
Subject: RE: SFY9225G Finalized Claim

Ergo Ref: **GBH2851G/RH/PL**

Our Ref: **SFY9225G**

Confirmed amount of \$2796.16 before GST, 5 days of repair.

Shawn Chua
Service Executive
TC AutoClinic Pte Ltd
25 Leng Kee Road
Singapore 159097
DID: +65 67038515
HP: +65 96450023
Fax: +65 64795019



From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Thursday, January 17, 2019 11:29 AM
To: Shawn Chua <shawnychua@tanchong.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SFY9225G Finalized Claim

Hi Shawn,

Finalise amount of \$ 2,796.16 / 5 days of repair, as spoken
Kindly confirm


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK
Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Shawn Chua [<mailto:shawnychua@tanchong.com>]
Sent: Thursday, 17 January, 2019 11:18 AM
To: Rasul (LKKAUTO)
Cc: SUR
Subject: RE: SFY9225G Finalized Claim

Ergo Ref: **GBH2851G/RH/PL**
Our Ref: **SFY9225G**

Good morning.

Attached is the revised finalized claim for SFY9225G.

Shawn Chua
Service Executive
TC AutoClinic Pte Ltd
25 Leng Kee Road
Singapore 159097
DID: +65 67038515
HP: +65 96450023
Fax: +65 64795019



From: Shawn Chua
Sent: Friday, January 11, 2019 4:10 PM
To: Rasul (rasul@lkkauto.com) <rasul@lkkauto.com>
Cc: 'SUR' <sur@lkkauto.com>
Subject: SFY9225G Finalized Claim

Ergo Ref: **GBH2851G/RH/PL**
Our Ref: **SFY9225G**

Good afternoon.

Attached is **SFY9225G** finalized claim. We didn't replace the rear left fender & quarter glass so I made some adjustment to the labour.

Kindly reply so that I can close the case soon.

Thank you very much for your time & assistance.

Shawn Chua
Service Executive
TC AutoClinic Pte Ltd
25 Leng Kee Road
Singapore 159097
DID: +65 67038515

HP: +65 96450023
Fax: +65 64795019



Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 13 December 2018 4:51 PM
To: 'Yee Pei Li'; 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: assignments; SUR
Subject: RE: GBH2851G / TP : SFY9225G/LKK / DOA : 04/12/2018
Attachments: SFY 9225G - Preli Advise.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SFY 9225G.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 10 December, 2018 11:49 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; 'Yee Pei Li' <peili.yee@ergo.com.sg>
Subject: RE: GBH2851G / TP : SFY9225G/LKK / DOA : 04/12/2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Monday, 10 December 2018 11:36 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>
Subject: OI : GBH2851G / TP : SFY9225G/LKK / DOA : 04/12/2018

Dear Catherine/Nivitha,

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 10 December 2018 11:36 AM
To: 'admin-d@lkkauto.com'
Cc: 'ASSIGNMENTS@LKKAUTO.COM'
Subject: OI : GBH2851G / TP : SFY9225G/LKK / DOA : 04/12/2018
Attachments: GBH2851G - SAS.pdf; SFY9225G - SAS.pdf; SFY9225G - ESTIMATE.pdf; SFY9225G - PRS FORM.pdf

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **TC AUTOCLINIC PTE LTD**,

ADDRESS : 25 LENG KEE ROAD
SINGAPORE 159097

PERSON TO CONTACT : SHAWN CHUA @ 6703 8515 / 9645 0023

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on DIRECT SETTLEMENT basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimates, insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
Tel : +65 6829 9199
Fax : +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

ERGO

Date: 10.12.2018
Our Reference: GBH 2851G/RH/pl
Your Reference: SFY 9225G

To: TC AUTOCLINIC PTE LTD

Sent via Fax
or
Email

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SFY 9225G
Insured's Vehicle: GBH 2851G
Date Of Accident: 04.12.2018


We acknowledge receipt of your request for PRS on: 08.12.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPk	JP Knights Pte Ltd	VAC	Vicom Ltd

☐	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐	Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐	We acknowledge your interest for direct settlement, we will assess & revert soon.
☐	Our Insured's driver has not reported the accident to us to date.
☒	Others: <u>We write to confirm our agreement to have a direct settlement of this claim with quantum to be agreed. OFFICER-IN-CHARGE - ROHAINI</u>

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				<u>FAX : 6829 9247</u>

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 232/1C/TCAC/CCR/2018
DATE : 07-DEC-2018

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 68299199
FAX : 68299247/9248
ATTN : CLAIM MANAGER

OWNER'S NAME : LIM KOK YONG
ADDRESS : BLK 526 CHOA CHU KANG ST 51
#06-279
S(680526)
TELEPHONE NO : 96775510

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 5098485016
VEHICLE NO : SFY9225G
MODEL CODE : BDTARCZB17EWA----A
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT)
ENGINE NO : HR16971983B
CHASSIS NO : MNTBBAB17Z0024367
MILEAGE : 97448 KM
DATE IN : 07/12/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 04/12/2018

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SFY9225G

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	/
2	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	/
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	200.00	100 X nn
4	WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	93.00	/
5	ZZ/001	REPLACE REAR LEFT FENDER, REAR BUMPER ETC REPAIR PANELS	1560.00	975 1170
6	ZZ/002	REPLACE LEFT QUARTER GLASS TO FACILITATE REPAIR	150.00	/ X nn
7	ZZ/003	INSTALL SOLAR FILM ON LEFT QUARTER GLASS	32.00	/ X nn
8	ZZ/004	REMOVE & INSTALL HEADLINER, SEATS & CARPETING TO FACILITATE REPAIR	120.00	/ X nn
9	ZZ/005	REPLACE REAR LEFT RIM	30.00	/
10	ZZ/006	RESPRAY REAR LEFT FENDER, REAR BUMPER ETC	750.00	500
11	ZZ/007	QC, RETUNE & CONSULT CHECK		
12	ZZ/008	COMPLIMENTARY WASH & VACUUM		
TOTAL LABOUR CHARGES			3110.00	

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFY9225G

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	ALLOY RIM(G11/B17)16X6.5 <i>SCA</i>	40300-SSW166		280.00 ✓
2	LEFT QUARTER GLASS <i>SCA</i>	83301-3SB1A		526.40 <i>X 17 X</i>
3	REAR BUMPER <i>SCA</i>	85022-3ST4H	649.30 ✓	
4	LEFT BUMPER BRACKET <i>SCA</i>	85227-3ST1A	35.90 ✓	
5	FENDER CLOSING PLATE <i>X</i>	78819-3SBOA	32.80 <i>X 17 X</i>	
6	REAR LEFT FENDER <i>SCA</i>	GB101-3SBMA	1483.90 <i>X BUC X</i>	
SUB TOTAL			2201.90	0.00 806.40
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			440.38	0.00 0.00
GRAND TOTAL			1761.52	0.00 806.40
OVERALL TOTAL			2567.92	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SFY9225G

TOTAL LABOUR CHARGES	3110.00
TOTAL SPARE PARTS CHARGES	2567.92
GRAND TOTAL	5677.92 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME

SURVEYED DATE

AUTHORIZED DATE

EXCESS CLAUSE

LIABILITY

REMARKS

: RASUL - HP 90010068

: 12/12/18 @ 1535

:

: 0.00

: 0.00

:

6 days (5 days)
Reay 64 paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 232/1C/TCAC/CCR/2018
DATE : 07-DEC-2018

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 68299199
FAX : 68299247/9248
ATTN : CLAIM MANAGER

OWNER'S NAME : LIM KOK YONG
ADDRESS : BLK 526 CHOA CHU KANG ST 51
#06-279
S(680526)
TELEPHONE NO : 96775510

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 5098485016
VEHICLE NO : SFY9225G
MODEL CODE : BDTARCZB17EWA----A
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT)
ENGINE NO : HR169719838
CHASSIS NO : MNTBBAB17Z0024367
MILEAGE : 97448 KM
DATE IN : 07/12/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 04/12/2018

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SFY9225G

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	120.00
2 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	55.00
3 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	200.00	.00
4 WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	93.00	93.00
5 ZZ/001	REPLACE REAR BUMPER, LEFT BUMPER BRACKET REPAIR REAR LEFT FENDER	1560.00	1170.00
6 ZZ/002	REPLACE LEFT QUARTER GLASS TO FACILITATE REPAIR	150.00	.00
7 ZZ/003	INSTALL SOLAR FILM ON LEFT QUARTER GLASS	32.00	.00
8 ZZ/004	REMOVE & INSTALL HEADLINER, SEATS & CARPETING TO FACILITATE REPAIR	120.00	.00
9 ZZ/005	REPLACE REAR LEFT RIM	30.00	30.00
10 ZZ/006	RESPRAY REAR LEFT FENDER, REAR BUMPER ETC	750.00	500.00
11 ZZ/007	QC, RETUNE & CONSULT CHECK		
12 ZZ/008	COMPLIMENTARY WASH & VACUUM		
TOTAL LABOUR CHARGES		3110.00	1968.00

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFY9225G

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	ALLOY RIM(G11/B17)16X6.5	40300-SSW166			280.00	OK
2	LEFT QUARTER GLASS	83301-3SB1A			526.40	X
3	REAR BUMPER	85022-3ST4H	649.30			OK
4	LEFT BUMPER BRACKET	85227-3ST1A	35.90			OK
5	FENDER CLOSING PLATE	78819-3S80A	32.80			X
6	REAR LEFT FENDER	68101-3S8MA	1483.90			X
SUB TOTAL			685.20	0.00	280.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			137.04	0.00	0.00	
GRAND TOTAL			548.16	0.00	280.00	
OVERALL TOTAL			828.16			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SFY9225G

NETT ITEM	685.20
LESS 20.00%)	-137.04
NETT AMOUNT	548.16

LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00

SPECIAL NETT ITEM	280.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	280.00

TOTAL LABOUR CHARGES	1968.00
TOTAL SPARE PARTS CHARGES	828.16

TOTAL CHARGES	2796.16 ✓
ADD 7 % GST	195.73

GRAND TOTAL	2991.89
-------------	---------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18022137/R1sd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 18-01-2019		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 2851G	Veh. Inspected	SFY 9225G	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBH2851G/RH/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	10/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SYLPHY 1.6 CVT	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	MNTBBAB17Z0024367	Colour	GREY	
Odometer	97681	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16	KAPSEN	6 mm	
L/H Front Tyre	195/60 R16	KAPSEN	6 mm	
R/H Rear Tyre	195/60 R16	KAPSEN	6 mm	
L/H Rear Tyre	195/60 R16	KAPSEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/12/2018	Inspection Date	11/12/2018	
Survey held at	TC AUTOCLINIC PTE LTD 25 LENG KEE RD SINGAPORE 159097			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFY 9225G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (N)	SCRATCHED	649.30	649.30
1	LEFT BUMPER BRACKET (N)	NECESSARY	35.90	35.90
1	FENDER CLOSING PLATE (N)	NOT NECESSARY	32.80	-
1	REAR LEFT FENDER (N)	SERVICEABLE	1,483.90	-
	LESS 20% DISCOUNT		-440.38	-137.04
			1,761.52	548.16
SPECIAL NETT ITEMS				
1	ALLOY RIM (G11/B17) 18X6.5 (SN)	SCRATCHED	280.00	280.00
1	LEFT QUARTER GLASS (SN)	NOT NECESSARY	526.40	-
			806.40	280.00
LABOUR				
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.		120.00	120.00
	REPLACE REVERSE SENSOR,NECESSARY ADJUSTMENT & FUNCTION TEST.		55.00	55.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.	NOT NECESSARY	200.00	-
	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION-PASSENGER.		93.00	93.00
	REPLACE REAR LEFT FENDER,REAR BUMPER ETC REPAIR PANELS.		1,560.00	1,170.00
	REPLACE LEFT QUARTER GLASS TO FACILITATE REPAIR.	NOT NECESSARY	150.00	-
	INSTALL SOLAR FILM ON LEFT QUARTER GLASS.	NOT NECESSARY	32.00	-
	REMOVE & INSTALL HEADLINER,SEATS & CARPETING TO FACILITATE REPAIR.	NOT NECESSARY	120.00	-
	REPLACE REAR LEFT RIM.		30.00	30.00
	RESPRAY REAR LEFT FENDER,REAR BUMPER ETC.		750.00	500.00
			3,110.00	1,968.00
GRAND TOTAL			5,677.92	2,796.16
RECOMMENDED COST OF REPAIRS				2,796.16

Report Ref No. CS/EGI18022137/R1sd3n2



Report Ref No. CS/EGI18022137/R1sd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.