

2/03/2002

ASS. REC. BY:

REF: CS3/AIG18022155/Crd3

Special Instruction:

Surveyor: Ameling
Mumen

ASSIGNMENT (Office)

From (Person): Chin Lee Ying

of AIG

Date/Time: 10/12/18 @ 2.07pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBH 2534Y

Insured: GBH 9209R

at Workshop m/s Ann Joo Motor

Tel: 64550747

of Blk 176 Sin Ming Drive # 01-17

Policy No: 1800121834

Claim No: 8885175188SG.

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 30/11/18

11/12/18 @ after 3pm

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS (wp)

Date/Time: 3:16pm @ 10/12/18

Person Contacted: Yiwen

Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	<u>GBH 2534Y - X</u>
	<u>GBH 9209R - X</u>

PRS

REF: AIG

B 1600A

ARRIVAL

XPR

ASSIGNMENT

From: Date: 11/12/18

Estimated Cost:

OD WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBH 2534Y

at Workshop m/s: Ann Joo Motor

of: Blk 176 Sin Ming Drive # 01-17

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: After 3pm

Veh No: GBH 2534Y Yr Regn: 31 Mar 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Nissan NL 350 c.c. 2488

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 6428 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JN1MC2E 268 000 8661

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Tyre Size: F: 195R15
R: 11

BS / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal. 8	mm	R/Bal. 8	mm
L/Bal. 8	mm	L/Bal. 8	mm

D.O.A. D.O.I. 11-12-18

Survey held at: w/s 4pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Frt a/s

The U/C / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value:

IDAC Accident Rport: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (w/s)

Date: Person Contacted: Vehicle: IN / OUT

Date / Time	Action / Instruction
	\$1000 \$2000
	MV - 64,000
	PV - 36,236
	NV - 27,764

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2)

Report Format: DAR

Lump Sum / I.B.I: (\$)

Days Of Repair: 3

Resurvey No. of Trip: -

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech Invs (\$)
 Weekend (\$)

Survey Fee: 180

Transportation: S + RS, \$

Photos

Others: 20

TOTAL: 200

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBH9209R AND GBH2534Y ON 30/11/2018

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: Monday, 10 December, 2018 2:07:29 PM
Attachments:  tmp4582.tif  tmp3C39.tif

Hi LKK,

Kindly contact Yiwen to arrange for survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

K. K. CHENG & CO

Advocates and Solicitors
 101 Upper Cross Street #05-21
 People's Park Centre
 Singapore 058357
 Tel: 6227 1272 Fax: 6227 5563

Our Ref: AJ/GBH 2534Y
 Your Ref: GBH 9209R
 (Please quote our reference number when replying)

5 December 2018

AIG ASIA PACIFIC INSURANCE PTE LTD
 Singapore

By fax only: 6835-7416

Attention: Motor Claims Department

Dear Sirs

NOTICE OF ACCIDENT

Claimant: SELERA MANUFACTURING AND FOOD SUPPLIES
Pre-action Protocol for Non-injury Motor Accident Cases involving motor
accident occurring on or before 1st April 2016 ["Protocol"]

We refer to your letter dated 5 December 2018.

Firstly, we object to the appointment of any of the motor surveyors proposed by in your List as a single joint expert. We have already stated this at para 4 of our Notice of Accident dated 4 December 2018.

Secondly, we have also given you our proposed list of proposed motor surveyors at para 4 of our Notice of Accident dated 4 December 2018.

Thirdly, if you object to our proposed list of proposed motor surveyors, this matter shall proceed on the basis of para 2.9 of the Protocol. Accordingly, our client shall appoint a surveyor of his choice to conduct the pre-repair survey. And our client shall have his motor vehicle repaired after the pre-repair survey had been done by your appointed surveyor.

Fourthly, for the sake of clarity, we do not agree to your appointed surveyor conducting the Pre-Repair Survey as the single joint expert.

If you wish to conduct a post-repair inspection, please instruct your appointed surveyor to inform our client's repairer of the same during the pre-repair survey.

Finally, the location and contact person of the workshop are as follows:-

Name of Workshop	:	Ann Joo Motor Pte Ltd
Address	:	Blk 176 Sin Ming Drive #01-17 Sin Ming Autocare Singapore 575721
Telephone No	:	64550747
Contact person	:	Yiwen

Your faithfully

CHENG KIM KUAN
 cc Workshop (Ref: GBH 2534Y)



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	1600A
Vehicle Details	
Vehicle No.:	GBH2534Y
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Dec 2018
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5MT 5DR
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	YD25422633A
Chassis No.:	JN1MC2E26Z0008661
Maximum Power Output:	-
Open Market Value:	\$25,062.00
Original Registration Date:	31 Mar 2018
First Registration Date:	31 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$1,254.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Mar 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$39,000.00
COE Rebate Amount:	\$36,263.00
Total Rebate Amount:	\$36,263.00

The information contained herein is correct as at 12 Dec 2018

OK

03)Dented (04)Bent (05)Broken (06)Scratched (07)Deformed
 (08)Unconfirmed (09)Not Working

MOTOR CAR (Frt)

SC (0)H (1)C
 (1)E (2)F (3)G (4)H (5)I (6)J (7)K (8)L (9)M (10)N (11)O (12)P (13)Q (14)R (15)S (16)T (17)U (18)V (19)W (20)X (21)Y (22)Z
 Aug 2005
 (1)A (2)B (3)C (4)D (5)E (6)F (7)G (8)H (9)I (10)J (11)K (12)L (13)M (14)N (15)O (16)P (17)Q (18)R (19)S (20)T (21)U (22)V (23)W (24)X (25)Y (26)Z

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper			
1005	992341	Frt Bumper Clips	DD	✓	
1006	991325	Frt Bumper Bracket	NEC	✓	
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement	DS	✓	
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp	CUT	✓	
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp	BR	✓	
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990119	Battery			
1068	990224	Battery Cover			

[Handwritten Signature]
 17/12/18

Vehicle No.

G0H 2534Y

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Steer			

- A New Chapter - Skoda Singapore
- 10 days self drive in Hokkaido
- COE bidding - 1st round of December 2018

nissan nv350 Price Range Depreciation 2017 Vehicle Type

Advanced Search

Home » Used Cars » Valley Trading » Nissan NV350 2.5A

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Leasing

 YOUR PREFERRED CAR LEASING OPTION IN SINGAPORE

 6769 7117 8720 5000 8720 8000

Nissan NV350 2.5A

Overview Financial Accessories Similar Research Photos Map

PREMIUM AD

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$69,900	?
Depreciation	\$7,820 /yr View models with similar depreciation	?
Reg Date	23-Nov-2017 (8yrs 11mths 5days COE left)	?
Manufactured	2017	?
Mileage	18 km	?
Transmission	Auto	?
Engine Cap	2,488 cc	?
Curb Weight	1,800 kg	?
Fuel type	Diesel	?
Features	Latest 2018 Euro 6 Nissan NV350 Panel Van 2.5 AT, Immediate Delivery.	?
Accessories	5 Years Or 140,000Km Warranty By Tan Chong Motor Sales. Free 3 x Servicing.	?
Description	Latest 2018 Euro 6 Nissan NV350 Panel Van 2.5 AT, 5 Years Or 140,000Km Warranty By Tan Chong Motor Sales. Free 3 x Servicing.	?
COE	\$46,890	?
OMV	\$25,238	?
ARF	\$1,262	?
Dereg Value	\$41,906 as of today (change)	?
No. of Owners	1	?
Type of Veh	Van	?
Category	Premium Ad Car, Low Mileage Car	?
Availability	Available	?



Location Map

Seller Information

Company	Valley Trading » dealer's pricelist » 47 vehs sold 50 vehs available
Address	210 Turf Club Road Lot C6 Search cars nearby this location
Location	Car Mall @ The Grandstand
Office No	63445088
Contact Person(s)	Thomas 96302490 Richard Teo 90251988 Patrick Teo 96681822

Useful Services

 **Afraid of lemons? Request to have this car evaluated professionally.**
 Vehicle Evaluation

 **Find out the market value for your car. Get a free Car Valuation.**
 Free Valuation

Posted on: 07-Nov-2018 | Last Updated on: 29-Nov-2018
 Tags: Nissan NV350, nissan nv350, 2017 Nissan NV350, 2017 nissan nv350, Nissan, NV350, nv350, Used Nissan

Upfront Payment

» more Financial info

Transfer Fee	N.A.	?
Down Payment	\$6,990 (change)	Maximum 90% Loan ?

Compare

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Dec 2018 Edit Reg		10 Dec 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	YAP AIRCON SERVICING & REPAIR , Co. Reg. No.: 53106170A								
Main Claimant:	SELERA MANUFACTURING AND FOOD SUPPLIES								
Vehicle Reg. No.:	GBH2534Y	Date of Loss:	30/11/2018 00:00 - :59 [8 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8885175188SG	Policy/Cover Note No.:	1800121834 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBH9209R	Policy No. (Claimant):							
		Excess:							
Repairer:	Ann Joo Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #02-17, Singapore 575721, 575721 Sin Ming - Tel: 64510747								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 19/12/2018]								
Claimant's Solicitor:	K. K. Cheng & Co								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
<ul style="list-style-type: none"> AIG_SG (11/12/2018): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS <input type="checkbox"/>									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBH2534Y (8885175188SG)
[GBH9209R]

TP

SELERA MANUFACTURING AND FOOD SUPPLIES

Nov 30 2018 12:00AM

[YAP AIRCON SERVICING & REPAIR]

Ann Joo Motor Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <input type="button" value="View in Browser"/>	
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	17/12/18 12:33	General View						Load JPG	<input checked="" type="checkbox"/>		
2	17/12/18 12:33	General View						Load JPG	<input checked="" type="checkbox"/>		
3	17/12/18 12:33	General View						Load JPG	<input checked="" type="checkbox"/>		
4	17/12/18 12:33	General View						Load JPG	<input checked="" type="checkbox"/>		
5	17/12/18 12:33	General View						Load JPG	<input checked="" type="checkbox"/>		
6	17/12/18 12:33	General View						Load JPG	<input checked="" type="checkbox"/>		
7	17/12/18 12:33	General View						Load JPG	<input checked="" type="checkbox"/>		
8	17/12/18 12:33	General View						Load JPG	<input checked="" type="checkbox"/>		
9	17/12/18 12:33	General View						Load JPG	<input checked="" type="checkbox"/>		
10	17/12/18 12:33	General View						Load JPG	<input checked="" type="checkbox"/>		
11	17/12/18 12:33	General View						Load JPG	<input checked="" type="checkbox"/>		
Documentation										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	11/12/18 10:46	OI GIA REPORT						Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST			<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.					
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)					
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>					

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18022155/GCD3E2
Date: 31/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800121834
Claimant Vehicle No : GBH2534Y	Insured Vehicle No :	GBH9209R
Date of Loss: 30/11/2018	Nature of Claim:	TP
		Claim No: 8885175188SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH2534Y	Engine No:	YD25422633A
Make & Model:	NISSAN NV350, 2.5 D Panel Van (M)	Chassis No:	JN1MC2E26Z0008661
Reg. Date:	31/03/2018 (Man. Year: 2017)	Odometer:	6428 km
Colour:	Silver		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	10/12/2018	
Date Inspected:	11/12/2018 Inspected At:	Ann Joo Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #02-17, Singapore 575721 Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Dented	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
4	1		*FRT BUMPER REINFORCEMENT	* Check	0.00 F	*- F
5	1		*FRT BUMPER SPONGE	* Check	0.00 F	*- F
6	1		*FRT RH BUMPER FOG LAMP COVER	Cut	0.00 F	*- F
7	1		*FRT RH BUMPER FOG LAMP	* Check	0.00 F	*- F
8	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >