



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Mr Chia Shih Sheung 14 Jalan Tarum Singapore 576733 Contact No Mobile: 81810167	Cust No/Name	/Mr Chia Shih Sheung
	Reg No/Reg Date	SLW1887M / 31/01/201
	Date In/Mileage	/ 0
	Chassis No	KNAFX411MJ5761160
	Engine No	G4FGHH691081
	Make/Model	KIA/CERATO K3 1.6 A EX CAP
	Colour/Trim	MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	07/12/2018/ 14:59	TLC	442 / CocoLu	40085			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER, REPAIR REAR FENDER RH, REAR END PANEL								1100 1650.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR								60.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER, REAR FENDER RH AND REAR END PANEL								1200 1260.00
M SUNDRY Sundry								20.00
M	COVER-RR BUMPER	DE-			1.00	688.00	00.00	688.00
M	COVER-RR BUMPER, CTR	DE-			1.00	347.00	00.00	347.00
M	BEAM-RR BUMPER	?			1.00	318.00	00.00	318.00
M	STAY-RR BUMPER RH	?			1.00	120.00	00.00	120.00
M	BRACKET-RR BUMPER SIDE MTG, RH	RE-			1.00	29.00	00.00	29.00

Estimate

Resul

Hp 90010068

5 days

18/12/18 @ 1135

Resul by paint

Estimate

Resul
Hp 90010068
5 days
18/12/18 @ 1135
Resul by paint

Confirm & accepted by

	Nett	4,492.00
7% GST on	4492.00	314.44
Total Payable		4,806.44

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.