



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

SJU 537 P
KIA CERATO K3
4/5 85650 / 1

Not Allured
Lm
4/5 85650
6 dy.
10/12/18
Theraputic Halling

ATTN:					
NO.	DESCRIPTION - PARTS	QTY			
	BOOTLID <i>P63</i>	<i>Body ID/sec</i>	\$	894.00	==
	BOOTLID LOCK	<i>twi</i>	\$	112.00	==
	BOOTLID WEATHERSTRIP	<i>twi</i>	\$	100.00	—
	BOOTLID INNER TRIM	<i>11</i>	\$	82.00	X
	BOOTLID LOGO	<i>neu</i>	\$	32.00	—
	BOOTLID EMBLEM - CERATO	<i>neu</i>	\$	31.00	—
	BOOTLID EMBLEM - K3	<i>neu</i>	\$	42.00	—
	BOOTLID LAMP L+R	<i>11</i>	\$	1,420.00	X
	BOOTLID SWITCH OPENER	<i>11</i>	\$	230.00	X
	REAR BUMPER <i>668</i>	<i>100/100</i>	\$	698.00	—
	REAR BUMPER SIDE RETAINER L+R	<i>neu</i>	\$	180.00	—
	REAR BUMPER BRACKET L+R	<i>34</i>	\$	66.00	—
	REAR BUMPER REFLECTOR L+R	<i>11</i>	\$	468.00	—
	REAR BUMPER REVERSE SENSOR <i>0118 x 2 = 356</i>	<i>shield</i>	\$	708.00	295
	REAR BUMPER REVERSE SENSOR HOLDER <i>15 x 2 = 30</i>	<i>neu</i>	\$	150.00	290
	REAR BUMPER REVERSE SENSOR WIREHARNES	<i>11</i>	\$	173.00	X
	REAR BUMPER REINFORCEMENT <i>323.00</i>	<i>cm</i>	\$	360.00	?
	REAR BUMPER REINFORCEMENT BRACKET L+R	<i>34</i>	\$	150.00	?
	REAR BUMPER BUZZER SENSOR	<i>11</i>	\$	280.00	X
	REAR BUMPER LOCK SENSOR	<i>11</i>	\$	198.00	X
	REAR END PANEL	<i>100</i>	\$	315.00	?
	REAR END PANEL TOP GARNISH	<i>twi</i>	\$	58.00	?
	REAR SPARE WHEEL PANEL	<i>11</i>	\$	602.00	X
	REAR SPARE WHEEL PANEL TOP BOARD	<i>ungraded</i>	\$	159.00	—
	EXHAUST PIPE	<i>11</i>	\$	729.00	X
	EXHAUST PIPE HEAT SHEID	<i>11</i>	\$	60.00	X
	EXHAUST PIPE GASKET	<i>11</i>	\$	28.00	X
	EXHAUST PIPE MOUNTING	<i>11</i>	\$	40.00	X
	<i>P-3485</i>				
	<i>102</i>	SUBTOTAL	\$	8,365.00	
	<i>3036.50</i>	LESS 10%	\$	836.50	
		PARTS TOTAL	\$	7,528.50	
	SPECIAL NETT	QTY		PRICE	
	REAR NUMBER PLATE	<i>11</i>	\$	80.00	X
	REVERSE CAM <i>1 set</i>	<i>5 whb</i>	\$	400.00	300
	REAR END PANEL SEALANT	<i>neu</i>	\$	100.00	50
	SPARE WHEEL PANEL SEALANT	<i>neu</i>	\$	100.00	50
	SPARE WHEEL INSULATOR <i>120</i>	<i>120</i>	\$	400.00	120
	REAR BUMPER CLIPS	<i>neu</i>	\$	100.00	50
	REAR FENDER INNER TRIM CLIPS	<i>11</i>	\$	100.00	X

BOOTLID INNER TRIM CLIPS	11	\$	80.00	X
REAR END PANEL TOP GARNISH CLIPS	11	\$	80.00	X
REAR BUMPER SPOILER COMPLETE SET	CM	\$	2,800.00	900
REAR BUMPER SPOILER SEAL	111	\$	150.00	50
Exhaust Pipe chrome mounting tips	34	\$	600.00	80
SPECIAL NETT TOTAL		\$	4,390.00	
LABOUR		QTY	PRICE	
TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN	1000	\$	1,600.00	
TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1000	\$	1,400.00	
TO RUST PROOF ACCIDENT AFFECTED AREA	✓	\$	80.00	
TO RNR EXHAUST PIPE TO ASSIST WORK LAOD	60	\$	150.00	
TO RNR REAR BOOT MECHANISM	60	\$	200.00	
TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS	80	\$	400.00	
TO RNR REVERSE SENSOR & CHECK FUNCTION.	50	\$	80.00	
TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION	20	\$	80.00	
TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.	11X	\$	150.00	
TO DO WATER LEAK TEST .	11X	\$	100.00	
LABOUR TOTAL		\$	4,240.00	
GRAND TOTAL COST		\$	16,158.50	

PAGE 2 OF 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P - 3136.50
S.N - 1600.00
1600 - 2350.00

7086.50
202

5669.20