



ASM Automotive Services Pte Ltd

No 2, Kwong Min Road, Singapore 628705
Tel: 6265 0980 / 6265 8806 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C



FROM : Jaclyn Lai
TEL. NO. : 6265-0980 / 9236-8218
EMAIL : jaclynlai@asmauto.com.sg

TO : China Taiping Insurance (Sg) P/L
ATTN : Motor Claim Department
TEL. NO. : 6389-6111 (main)
EMAIL : claimsdept@sg.cntaiping.com

CC : Sibre Brakes (S.E.A) Pte Ltd
ATTN : Mr. Terry

DATE : 22.01.2019

VEHICLE NO. : GBH 5608 Z
MODEL NO. : NISSAN NV200 DX 1.6 AUTO
CHASSIS NO. : VM20124490
ENGINE NO. : HR16123263D
LTA REG DATE : 2-Jul-18

CLAIM TYPE : Own Damaged
D.O.A : 29.11.2018
CLAIM REF NO. : asm/AC18122/JL

Quotation for Accident Repair - SUPPLEMENTARY 2

<u>S/N</u>	<u>SPARE PARTS</u>	<u>QUANTITY</u>	<u>UNIT PRICE</u>	<u>AMOUNT</u>
1	Seat belt assy, LHS	1	\$ 1,041.30	\$ 1,041.30
2	Seat belt assy, RHS	1	\$ 1,041.30	\$ 1,041.30
3	Airbag control unit	1	\$ 1,121.25	\$ 1,121.25
4	Bumper sensor	1	\$ 570.00	\$ 570.00
SUB-TOTAL :				\$ 3,773.85
LESS 30% :				\$ 1,132.16
BALANCE :				\$ 2,641.70

LABOUR CHARGES

1 Perform computer diagnose to check airbag warning light lit up, found above parts faulty. \$ 500.00
Replace above damaged parts.

TOTAL LABOUR : \$ 500.00

GRAND TOTAL : \$ 3,141.70