

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3251G

DATE 7/12/2018 10:51

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 553.00
	Rear Bumper Clip 10 pcs			\$ 22.00
	Rear Bumper Reflector Lamp (RH) *			\$ 30.60
	<i>Rear Bumper under cover</i>			
	SUB TOTAL			\$ 605.60
	LESS 20% <i>25%</i>			\$ 121.12
	DISCOUNTED TOTAL			\$ 484.48
	Rear Bumper Rubber Mat			\$ 50.00
	Rear Bumper Advertisement Logo			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00
				\$ 300.00
	Labour Charge			<i>200</i>
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
	Wiring Charge			\$ 30.00
	Remove/Refix Reverse Sensor			\$ 80.00
	TOTAL LABOUR			\$ 810.00
	ESTIMATE TOTAL			\$ 1,594.48

Nett

Nett

Nett

Nett

200

X

X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kah/Ala

7/12/18 1620L.

2 Drs

PIP

Before Paint photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.