

ASS. REC. BY:

REF:

CS/CTI18022176/R1rd30

Special Instruction:

Surveyor:
Munmen

Ravi

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

CTI

Date/Time:

10/12/18 @ 4:38pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCU 36684

Insured:

8KTS742Z

at Workshop m/s

Mova

Tel:

62723892 / 97762311

of

Blk 1008, Bkt Merah Lane 3 #01-04

Ah Wei

Policy No:

DMPCSN/636/21802

Claim No:

SNMIED05702C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

06/12/2018

CA / REV / REP. / REV 24 HRS

lup

11/12/18

H.O.D. Endorsement:

Date/Time:

4:53pm @ 10/12/18

Person Contacted:

Nithen

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓)

Estimate

SCU 36684 - NBA/CTI18022016/Y

DOA: 6/12/18

SKT 5742Z - NBA/CTI18022016/Y

DOA: 6/12/18

11/1/19

LS \$3200 confirmed by email (Ref 3059, 499)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Dec 2018		10 Dec 2018 16:38 Edit Adj Rpt				Pending for Survey Report Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	LOO SUET YING, ID: S6922485G		
Main Claimant:	LOCK THIAM HOCK, ID: S0331372G		
Vehicle Reg. No.:	SCU3668H	Date of Loss:	06/12/2018 16:00 - :59
Claim Type:	TP / SNM18D05702C02	Policy/Cover Note No.:	DMPCSN1636121802 (Comprehensive)
Vehicle Reg. No. (Insured):	SKT5742Z	Policy No. (Claimant):	5025431793-10
		Excess:	S\$0.00
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3, 159722 Bukit Merah - Tel: 62723892/64763333		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 19/12/2018]		
Driver/Custodian (Insured):	LOO SUET YING (49 / Female), NRIC: S6922485G		
Adj Asg. Remarks:	EST \$6697.13, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1372G
Vehicle Details	
Vehicle No.:	SCU3668H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	3ZZ4623395
Chassis No.:	MR053ZEC107138435
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,355.00
Original Registration Date:	05 Jan 2007
First Registration Date:	05 Jan 2007
Transfer Count:	0
Actual ARF Paid:	\$16,891.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	04 Jan 2027
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$50,645.00
COE Rebate Amount:	\$40,897.00
Total Rebate Amount:	\$40,897.00

The information contained herein is correct as at 07 Dec 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	06/12/2018 17:33
Date Of Accident	06/12/2018 16:25
Exact Location Of Accident	TELOK BLANGAH ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SCU3668H
Insured/Policyholder	
Name Of Registered Owner	LOCK THIAM HOCK
NRIC No	S0331372G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96462756
Alternative Phone No	OFFICE-96462756
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5025431793-10
Cover Note Number	
Driver	
Name of Driver	LOCK THIAM HOCK
NRIC No	S0331372G
Date Of Birth	12/11/1943
Occupation	INDOOR
Date Of Driving Pass	10/02/1965
Driving Experience	53 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96462756
Fax Number	
Contact Number	OFFICE-96462756
EMail Address	NOEMAIL

Address	BLK 347 CLEMENTI AVE 5 #12-76
Postcode	120347
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKT5742Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: SCU 3668 H	ACCIDENT DATE & TIME: 6/12/18 4:25 pm
CONTACT NUMBER: 96462756	E-MAIL ADDRESS:
LOCATION: Telok Blangah Road	
<p>my vehicle was stopped at the traffic light junction, it is Red light, suddenly I felt an impact from behind, vehicle SKT 5742 Z hit the rear of my vehicle.</p>	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION	
Please state:	
<input type="checkbox"/> Claim Own Policy <input checked="" type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input type="checkbox"/> Reporting Only	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

07/12/2018

CHINA TAIPING INSURANCE (S) PTE LTD

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909.

Attention :- XA017

Page # :- 1

Veh # :- SCU3668H

Veh Model :- TOYOTA COROLLA ALTIS 1.6

Estimate# :- CK418399

Claim # :-

ACC. Date :- 06/12/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1.	REAR BOOT <i>TH</i>	1	PC	795.00	795.00
2.	REAR BOOT HINGE - REPAIR <i>R</i>	2	PCS		
3.	REAR BOOT LOCK <i>TH</i>	1	PC	115.00	115.00
4.	REAR BOOT CATCH <i>X SU</i>	1	PC	45.00	45.00
5.	REAR BOOT WEATHERSTRIP <i>TH</i>	1	PC	70.00	70.00
6.	REAR FENDER LAMP L & R <i>? COK</i>	2	PCS	340.00	680.00
7.	REAR TAIL LAMP LOWER PANEL L & R (FILLER) <i>Repair</i>	2	PCS	160.00	320.00
8.	REAR TAIL LAMP LOWER BRACKET L & R <i>? (RA) O/S</i>	2	PCS	60.00	120.00
9.	REAR BUMPER RETAINER L & R <i>TH</i>	2	PCS	38.00	76.00
10.	REAR BUMPER <i>OG</i>	1	PC	425.00	425.00
11.	REAR FENDER L & R - REPAIR <i>R</i>	2	PCS		
12.	REAR BOOT LOGO (1.6) EVVT-I <i>TH</i>	2	PCS	39.00	78.00
13.	REAR BOOT LOGO (COROLLA ALTIS) <i>TH</i>	2	PCS	39.00	78.00
14.	REAR END PANEL <i>Repair</i>	1	PC	795.00	795.00
15.	REAR END PANEL TOP GARNISH <i>? X SUC</i>	1	PC	90.00	90.00
16.	REAR EXHAUST PIPE <i>X SUC</i>	1	PC	469.00	469.00
17.	REAR BUMPER CLIPS <i>TH</i>	10	PCS	4.80	48.00
18.	REAR END PANEL TOP GARNISH CLIPS <i>TH</i>	10	PCS	4.80	48.00

LIST TOTAL S\$

4,252.00

25% DISCOUNT S\$

-1,063.00

3,189.00

SPECIAL NET ITEMS :

1.	REAR PARKING SENSORS <i>TH</i>	1	PC	<i>200</i> 250.00	250.00
----	--------------------------------	---	----	-------------------	--------

SPECIAL NET TOTAL S\$

250.00

LABOUR :

TO REPAIR REAR FENDER L & R, REAR TAIL INNER
PANEL L & R. TO REMOVE & REPLACE ALL ACCIDENT
DAMAGED PARTS

TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS

TO INSPECT REAR TAIL LAMP WATER LEAKAGE TEST

TO REMOVE & REPLACE REAR PARKING SENSORS &
CHECK WIRING

TO APPLY SEAL ON WELDING JOINT & NEW PARTS

TO RUST PROOF ACCIDENT DAMAGED PARTS

TO REMOVE REAR BOOT MECHANISM, REAR BOOT LOCK
AND OTHER ATTACHMENT PARTS

TO REMOVE REAR BOOT SIDE TRIM L & R, SPARE
TYRE & OTHER ATTACHMENT PARTS

750 *600*
~~850.00~~
900 *700* ~~1,200.00~~
~~40.00~~
~~80.00~~
~~80.00~~
~~60.00~~
~~80.00~~
~~120.00~~

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

07/12/2018

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- **XA017**

Page # :- 1 133450
Veh # :- SCU3668H
Veh Model :- TOYOTA COROLLA ALTIS 1.6
Estimate# :- CK418399
Claim # :-
ACC. Date :- 06/12/18
Terms :- C.O.D Days
Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	TO CHECK CHASSIS ALIGNMENT		100	250.00
	TO REMOVE REAR EXHAUST SILENCER AND CHECK EXHAUST SILENCER SYSTEM		60.00	
	LABOUR TOTAL S\$			2,820.00

E. & O.E

NON-TAX AMOUNT S
AMOUNT S\$ 6,259.00
GST @ 7 % 438.13
AMOUNT DUE S\$ 6,697.13

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rane
13/12/18
4p 90010068
6 days
4/5
11/12/18 @ 1515
Resurvey after repair

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

07/12/2018

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1

Veh # :- SCU3668H

Veh Model :- TOYOTA COROLLA ALTIS 1.6

Estimate# :- CK418399

Claim # :-

ACC. Date :- 06/12/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BOOT <i>PH ✓</i>	1 PC	795.00	795.00
2.	REAR BOOT HINGE - REPAIR	2 PCS		
3.	REAR BOOT LOCK <i>PH ✓</i>	1 PC	115.00	115.00
4.	REAR BOOT CATCH <i>X</i>	1 PC	45.00	45.00
5.	REAR BOOT WEATHERSTRIP <i>PH ✓</i>	1 PC	70.00	70.00
6.	REAR FENDER LAMP L & R <i>PH ✓</i>	2 PCS	340.00	680.00
7.	REAR TAIL LAMP LOWER PANEL L & R (FILLER) <i>PH ✓</i>	2 PCS	160.00	320.00
8.	REAR TAIL LAMP LOWER BRACKET L & R <i>PH ✓</i> (Rt only)	1 PCS	60.00	60.00
9.	REAR BUMPER RETAINER L & R <i>PH ✓</i>	2 PCS	38.00	76.00
10.	REAR BUMPER <i>PH ✓</i>	1 PC	425.00	425.00
11.	REAR FENDER L & R - REPAIR	2 PCS		
12.	REAR BOOT LOGO (1.6) EVVT-I <i>PH ✓</i>	2 PCS	39.00	78.00
13.	REAR BOOT LOGO (COROLLA ALTIS) <i>PH ✓</i>	2 PCS	39.00	78.00
14.	REAR END PANEL <i>PH ✓</i>	1 PC	795.00	795.00
15.	REAR END PANEL TOP GARNISH <i>PH ✓</i>	1 PC	90.00	90.00
16.	REAR EXHAUST PIPE <i>X</i>	1 PC	469.00	469.00
17.	REAR BUMPER CLIPS <i>PH ✓</i>	10 PCS	4.80	48.00
18.	REAR END PANEL TOP GARNISH CLIPS <i>PH ✓</i>	10 PCS	4.80	48.00
LIST TOTAL S\$				4,252.00
25% DISCOUNT S\$				-1,063.00
<i>Parts \$ 1854.75</i>				
<i>Sn \$ 200</i>				3,189.00
SPECIAL NET ITEMS :				
1.	REAR PARKING SENSORS <i>PH ✓</i>	1 PC <i>2018</i>	250.00	250.00
SPECIAL NET TOTAL S\$				250.00
LABOUR :				
TO REPAIR REAR FENDER L & R, REAR TAIL INNER PANEL L & R. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS <i>PH ✓</i>				750 600
TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS				850.00
TO INSPECT REAR TAIL LAMP WATER LEAKAGE TEST				900 700 1,200.00
TO REMOVE & REPLACE REAR PARKING SENSORS & CHECK WIRING				40 80.00
TO APPLY SEAL ON WELDING JOINT & NEW PARTS				X 80.00
TO RUST PROOF ACCIDENT DAMAGED PARTS				60.00
TO REMOVE REAR BOOT MECHANISM, REAR BOOT LOCK AND OTHER ATTACHMENT PARTS				40 80.00
TO REMOVE REAR BOOT SIDE TRIM L & R, SPARE TYRE & OTHER ATTACHMENT PARTS				60 120.00

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel: (65) 6272 3892
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

07/12/2018

CHINA TAIPING INSURANCE (S) PTE LTD
 3 Anson Road
 #16-00 Springleaf Tower
 Singapore 079909.

Attention :- XA017

Page # :- 1 133450
 Veh # :- SCU3668H
 Veh Model :- TOYOTA COROLLA ALTIS 1.6
 Estimate# :- CK418399
 Claim # :-
 ACC. Date :- 06/12/18
 Terms :- C.O.D Days
 Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	TO CHECK CHASSIS ALIGNMENT			100 250.00
	TO REMOVE REAR EXHAUST SILENCER AND CHECK EXHAUST SILENCER SYSTEM			X 60.00
	LABOUR TOTAL S\$			2,820.00

E. & O.E

NON-TAX AMOUNT S
 AMOUNT S\$ 6,259.00
 GST @ 7 % 438.13
 AMOUNT DUE S\$ 6,697.13

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Revised
4p 20010068
6 days
4/8
11/12/18 @ 1515
Resurvey after repair

Veron Chen (LKKAuto)

From: Tan Yoong Wei <tanyw@mov.com.sg>
Sent: Friday, 11 January 2019 12:59 PM
To: Veron Chen (LKKAuto)
Subject: RE: FINALISE SCU3668H

Ok please close at \$3200 with 6 working days

Best Regards,
Tan Yoong Wei
Estimator
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Friday, 11 January 2019 11:38 AM
To: Tan Yoong Wei; Rasul (LKKAuto); SUR
Cc: Hsiao Tong (LKKAuto)
Subject: RE: FINALISE SCU3668H

Dear Yoong Wei,

WITHOUT PREJUDICE

Confirmed Lump Sum \$3200/- with 6 working days

Kindly send Final invoice and all supporting documents to CHINA TAIPING

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Yoong Wei <tanyw@mov.com.sg>
Sent: Thursday, 10 January 2019 1:42 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: FINALISE SCU3668H

Hi rasul,
Please advice whether we can finalise cost of repair
Lumpsum \$3200 with 6 working days ?
Thank you.

Best Regards,
Tan Yoong Wei
Estimator
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 11 January 2019 11:38 AM
To: Tan Yoong Wei; Rasul (LKKAUTO); SUR
Cc: Hsiao Tong (LKKAUTO)
Subject: RE: FINALISE SCU3668H

Dear Yoong Wei,

WITHOUT PREJUDICE

Confirmed Lump Sum \$3200/- with 6 working days

Kindly send Final invoice and all supporting documents to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Yoong Wei <tanyw@movauto.com.sg>
Sent: Thursday, 10 January 2019 1:42 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: FINALISE SCU3668H

Hi rasul,
Please advice whether we can finalise cost of repair
Lumpsum \$3200 with 6 working days ?
Thank you.

Best Regards,

Tan Yoong Wei

Estimator

Mova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Dec 2018		10 Dec 2018 16:38 Edit Adj Rpt	S\$3,200.00 Edit Estimates	S\$3,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LOO SUET YING , ID: S6922485G								
Main Claimant:	LOCK THIAM HOCK , ID: S0331372G								
Vehicle Reg. No.:	SCU3668H	Date of Loss:	06/12/2018 16:00 - :59 [143 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D05702C02	Policy/Cover Note No.:	DMPCSN1636121802 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKT5742Z	Policy No. (Claimant):	5025431793-10						
		Excess:	S\$0.00						
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3, 159722 Bukit Merah - Tel: 62723892/64763333								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 19/12/2018]								
Driver/Custodian (Insured):	LOO SUET YING (49 / Male), NRIC: S6922485G								
Adj Asg. Remarks:	EST \$6697.13, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


Claim Documents

*SCU3668H (SNM18D05702C02)
[SKT5742Z]
TP
LOCK THIAM HOCK
Dec 6 2018 4:00PM
[LOO SUET YING]
Mova Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	06/12/18 18:15	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	06/12/18 18:11	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	06/12/18 18:11	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	06/12/18 18:11	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	06/12/18 18:11	Driving License [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	06/12/18 18:11	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/01/19 15:04	General View	Load PDF	
2	10/01/19 15:05	Reinspection Photo	Load PDF	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/12/18 16:37	REPAIR EST	Load PDF	
2	10/12/18 16:37	TP GIA	Load PDF	
3	10/12/18 16:38	OI GIA	Load PDF	
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	06/12/18 18:14	Sketch Plan [Linked Accident Report Documents]	Load TIF	

Linked Accident Report Documents

			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	06/12/18 18:15	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	06/12/18 18:11	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	06/12/18 18:11	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	06/12/18 18:11	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	06/12/18 18:11	Driving License	Load JPG	<input checked="" type="checkbox"/>
5	06/12/18 18:11	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	06/12/18 18:14	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18022176/R1VD3E2

Date: 14/01/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN1636121802

Claimant Vehicle
No : SCU3668HInsured Vehicle
No : SKT5742Z

Date of Loss: 06/12/2018

Nature of Claim: TP

Claim
No: SNM18D05702C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SCU3668H

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 3ZZ4623395

Reg. Date: 05/01/2007 (Man. Year: 2006)

Chassis No: MR053ZEC107138435

Colour: Grey

Odometer: 168365 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size: 195/60 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,439.00	2,054.75	1,384.25	40.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,820.00	1,990.00	830.00	29.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,259.00	4,044.75	2,214.25	35.38
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	6,259.00	3,200.00	3,059.00	48.87
+ GST 7.00/7.00% (S\$)	438.13	224.00	214.13	48.87
Nett Amount (S\$)	6,697.13	3,424.00	3,273.13	48.87

INSPECTION

Date of Assignment: 10/12/2018

Date Inspected: 11/12/2018 Inspected At:

Mova Automotive Pte Ltd (Bukit Merah)
Blk 1008, #01-04/06/08/94, Bukit Merah
Lane 3
Singapore 159722

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Jan 2019)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCU3668H)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	795.00 FL	*795.00 FL
2	2		*REAR BOOT HINGE (NPA)	Repair	0.00 FL	*- FL
3	1		*REAR BOOT LOCK	Bent	115.00 FL	*115.00 FL
4	1		*REAR BOOT CATCH	Serviceable	45.00 FL	*- FL
5	1		*REAR BOOT WEATHERSTRIP	Necessary	70.00 FL	*70.00 FL
6	2		*REAR FENDER LAMP L & R	Cracked	680.00 FL	*680.00 FL
7	2		*REAR TAIL LAMP LOWER PANEL L & R (FILLER)	Repair	320.00 FL	*- FL
8	1		*REAR TAILLAMP LOWER BRACKET L & R	O/S Cracked	120.00 FL	*60.00 FL
9	2		*REAR BUMPER RETAINER L & R	Necessary	76.00 FL	*76.00 FL
10	1		*REAR BUMPER	Deformed	425.00 FL	*425.00 FL
11	2		*REAR FENDER L& R (NPA)	Repair	0.00 FL	*- FL
12	2		*REAR BOOT LOGO (1.6) EVVT-I	Necessary	78.00 FL	*78.00 FL
13	2		*REAR BOOT LOGO (COROLLA ALTIS)	Necessary	78.00 FL	*78.00 FL
14	1		*REAR END PANEL	Repair	795.00 FL	*- FL
15	1		*REAR END PANEL TOP GARNISH	Serviceable	90.00 FL	*- FL
16	1		*REAR EXHAUST PIPE	Serviceable	469.00 FL	*- FL
17	10		*REAR BUMPER CLIPS	Necessary	48.00 FL	*48.00 FL
18	10		*REAR END PANEL TOP GARNISH CLIPS	Necessary	48.00 FL	*48.00 FL
19	1		*REAR PARKING SENSORS	Not Working	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,502.00	2,673.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,063.00	618.25
Total Parts (\$\$)	3,439.00	2,054.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR REAR FENDER L & R, REAR TAIL INNER PANEL L & R. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS	New	850.00	750.00
2	TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS	New	1,200.00	900.00
3	TO INSPECT REAR TAIL LAMP WATER LEAKAGE TEST	New	40.00	40.00
4	TO REMOVE & REPLACE REAR PARKING SENSORS & CHECK WIRING	New	80.00	40.00
5	TO APPLY SEAL ON WELDING JOINT & NEW PARTS	New	80.00	0.00
6	TO RUST PROOF ACCIDENT DAMAGED PARTS	New	60.00	60.00
7	TO REMOVE REAR BOOT MECHANISM, REAR BOOT LOCK AND OTHER ATTACHMENT PARTS	New	80.00	40.00
8	TO REMOVE REAR BOOT SIDE TRIM L & R, SPARE TYRE & OTHER ATTACHMENT PARTS	New	120.00	60.00
9	TO CHECK CHASSIS ALIGNMENT	New	250.00	100.00
10	TO REMOVE REAR EXHAUST SILENCER AND CHECK EXHAUST SILENCER SYSTEM	New	60.00	0.00
Gross Labour Cost (\$\$)			2,820.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >