

15/5/2010

INS. CASE OWNER:

CC 4 / AXA1802

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO. Driver Name / Age:

Driver Tel No.:

HP:

D.O.A:

Nature of Accident:

(YES / NO)

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act: (NO NEED)

Release Voucher: DS FORM

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by: MRB

FINALIZATION

Date/Time:

Confirm with:

Confirm by: MRB

Repair Cost:

SS 10,282.89

(5 days) Reduction: 41 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 15-06-19

Confirm with: EVELYN

If NO or B 28, Ass. Lia:

Final Liability:

SS 190

(Agreed / Assessed) BOLA S/N No.:

01 REPR ENDED TP.

Repair Cost:

SS 11,002.69

Loss of Rental (LOR):

SS -

(590 x 5 days)

Loss of Use (LOU):

SS 450.00

(5 x 5 days)

Loss of Income (LOI):

SS -

(5 x 5 days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

SS -

Medical:

SS -

(e.g. Tow/ Independent)

Disbursement:

SS -

Legal Cost

SS -

Total:

SS 11,452.69

Global Sum SS:

Email ☒ Call ☐

FINAL PAYMENT

Date/Time: 15-06-19

Confirm with: EVELYN

Payee 1:

SS 11,452.69

Name 1:

WEARNES AUTOMOTIVE PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18022179/eb3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 10-12-2018



Code : ASM

Policy Particulars :- THIRD PARTY CLAIM

1.	Insured Veh.	SMF 2264G	Veh. Inspected	SKK 6155J
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	10/12/2018

Vehicle Particulars & Condition

2.	Make & Model	c.c	0
	Engine No.	HIDDEN	Year of Reg.
	Chassis No.		Colour
	Odometer	-	Steering
	Brakes		Modification
	General		

Conditions of Tyres

3.		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

Description of Damages

4.

General Information

5.

Accident Date	05/12/2018	Inspection Date
Survey held at	WEARNES AUTOMOTIVE PTE LTD 45 LENG KEE ROAD SINGAPORE 159103.	

Remarks

5a.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

SERVICE ESTIMATE

63413 - C00001 SL: SERVICE SALES - PC
Wearnes Automotive Pte Ltd (159-f&L)
28 Leng Kee Road

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 07/12/2018

WIP No. : 42354

Veh.In/Out: 07/12/2018

*Tel.No. : Work: 63765063

Reg.No. : SKK6155J

Reg.date : 17/03/2017

Mileage : 0

Chassis No: YV1PS10B0H1013615

Singapore 159105

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Wearnes Automotive P

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BOOT LID, REAR EMBLEM, REAR BUMPER, REAR BRACKET, REAR LOWER SPOILER, REAR SENSOR, REAR PANEL, ETC	0	4000.00	0		4,000.00 S	2400 ✓
800	TO PUTTY SPRAY PAINT ON REAR BOOT LID, REAR BUMPER, REAR END PANEL, ETC	0	2800.00	0		2,800.00 S	2100 ✓
802	TO TRANSFER REAR BOOT LID PART	0	250.00	0		250.00 S	✓
802	TO REMOVE & INSTALL REAR BOOT COMPARTMENT PARTS	0	1600.00	0		1,600.00 S	800 ✓
R06	TO INSTALL REAR NUMBER PLATE INCLUDE HOLDER	0	60.00	0		60.00 S	74 ✓
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0		450.00 S	✓
	BOOT REAR S90 17- H ✓	1.0 EA	2240.80			2,240.80 S	2,016.72

Done
HP 90010068
5 days
17/01/19 @ 1500 hrs
Reay bk paint

SERVICE ESTIMATE

63413 - C00001 SL: SERVICE SALES - PC
Wearnes Automotive Pte Ltd (159-f&L)
28 Leng Kee Road

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date : 07/12/2018

WIP No. : 42354

Singapore 159105

Veh.In/Out: 07/12/2018

*Tel.No. : Work: 68765063

Reg.No. : SKK6155J

Closed by : Derek Oh Siong Wee

Reg.date : 17/03/2017

Svc Consultant :

Mileage : 0

Remarks : Wearnes Automotive P

Chassis No: YV1PS10BDH1013615

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

EMBLEM 'VOLVO' REAR	1.0 EA	85.20			85.20	\$ 76.68
EMBLEM 'S90' S90 17-	1.0 EA	78.10			78.10	\$ 70.39
EMBLEM 'T5' XC60 S80	1.0 EA	88.00			88.00	\$ 79.20
BUMPER INSTALLING HT	1.0 EA	83.40			83.40	\$ 75.06
ADHESIVE TUBE CHEMIC	4.0 EA	75.80			303.20	\$ 272.88
BUMPER COVER REAR S9	1.0 EA	1412.30			1,412.30	\$ 1,271.07
TOW COVER REAR S90 1	1.0 EA	62.40			73.90	\$ 66.51
BUMPER BRACKET REAR	1.0 EA	79.20			79.20	\$
BUMPER SPACER LHR SV	1.0 EA	79.20			79.20	\$
BUMPER SPACER RHR SV	1.0 EA	79.20			79.20	\$
BUMPER RETAINER LHR	1.0 EA	28.60			28.60	\$
BUMPER RETAINER RHR	1.0 EA	28.60			28.60	\$
PARK HOLDER LHR CTR	1.0 EA	29.90			29.90	\$ 26.91
PARK HOLDER RHR CTR	1.0 EA	29.90			29.90	\$ 26.91
PARK HOLDER LHR CORN	1.0 EA	47.30			47.30	\$ 42.57
PARK HOLDER RHR CORN	1.0 EA	47.30			47.30	\$ 42.57
PARK HOLDER LHR SIDE	1.0 EA	26.90			26.90	\$ 24.21

SERVICE ESTIMATE

63413 - C00001 SL: SERVICE SALES - PC
 Wearnes Automotive Pte Ltd (159-f&L)
 28 Leng Kee Road

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 3

Inv.date: 07/12/2018

WIP No. : 42354

Veh.In/Out: 07/12/2018

*Tel.No. : Work: 68765063

Reg.No. : SKK6155J

Reg.date: 17/03/2017

Mileage : 0

Chassis No: YV1PS10BDH1013615

Singapore 159105

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Wearnes Automotive P

Op.No	Description	Hech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	PARK HOLDER RHR SIDE <i>✓</i>	1.0 EA	26.90			26.90	\$ 24.21
	CLIP <i>✓</i>	10.0 EA	6.30			63.00	\$ 56.70
	PROTECTING PLATE REA <i>3 NN</i>	1.0 EA	253.30			253.30	\$
	BUMPER CLIP S90 17- <i>✓</i>	10.0 EA	5.60			56.00	\$ 50.40
	BUMPER BRACKET LHR S <i>?</i>	1.0 EA	46.70			46.70	\$
	BUMPER BRACKET RHR S <i>?</i>	1.0 EA	46.70			46.70	\$
	BUMPER BRACKET LHR E <i>?</i>	1.0 EA	4.50			4.50	\$
	BUMPER BRACKET RHR E <i>?</i>	1.0 EA	4.50			4.50	\$
	CAMERA BRACKET REAR <i>?</i> <i>x4/4</i>	1.0 EA	67.80			67.80	\$
	PROTECTION <i>?</i>	1.0 EA	13.30			13.30	\$
	CAMERA REAR S90 17- <i>?</i>	1.0 EA	762.20			762.20	\$
	BUMPER RAIL REAR S90 <i>?</i>	1.0 EA	1304.80			1,304.80	\$
	BOOT HANDLE <i>?</i>	1.0 EA	337.30			337.30	\$
	BOOT LOCK <i>?</i>	1.0 EA	390.50			390.50	\$
	BOOT LOCK COVER <i>?</i>	1.0 EA	6.80			6.80	\$

Gross Total: 17,373.80

Labour Total 9,160.00
 Parts Total 8,213.80
 Package Total 0.00

Net..... 17,373.80
 GST @ 7.0% 1,216.17
 Total..... 18,589.95
 Paid..... 0.00
 Please Pay.. 18,589.95

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

12385.30

SERVICE ESTIMATE

0 - A00005
 AXA INSURANCE PTE LTD
 8 SHENTON WAY,
 #27-01 AXA TOWER,
 SINGAPORE 068811

SL: AXA INSURANCE PTE LTD

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1
 Inv.date : 28/01/2019
 WIP No. : 42354
 Veh.In/Out: 17/01/2019 25/01/2019
 *Tel.No. : 6338 7288
 Reg.No. : SKK6155J
 Reg.date : 17/03/2017
 Mileage : 0
 Chassis No: YV1PS10BDH1013615

Closed by : Richmond Ho
 Svc Consultant :
 Remarks : Wearnes Automotive P

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount G
802	TO REPLACE REAR BOOT LID, REAR EMBLEM,REAR BUMPER, REAR BRACKTE,REAR LOWER SPOILER,REAR SENSOR,REAR PANEL,ETC	0	2400.00	0		2,400.00 S
800	TO PUTTY SPRAY PAINT ON REAR BOOT LID,REAR BUMPER,REAR END PANEL,ETC	0	2100.00	0		2,100.00 S
802	TO TRANSFER REAR BOOT LID PART	0	250.00	0		250.00 S
802	TO REMOVE & INSTALL REAR BOOT COMPARTMENT PARTS	0	800.00	0		800.00 S
R06	TO INSTALL REAR NUMBER PLATE INCLUDE HOLDER	0	60.00	0		60.00 S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0		450.00 S
	BOOT REAR S90 17- ①	1.0 EA	2240.80	10		2,016.72 S

SERVICE ESTIMATE

0 - A00005
 AXA INSURANCE PTE LTD
 8 SHENTON WAY,
 #27-01 AXA TOWER,
 SINGAPORE 068811

SL: AXA INSURANCE PTE LTD

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2
 Inv.date. : 28/01/2019
 WIP No. : 42354
 Veh.In/Out: 17/01/2019 25/01/2019
 *Tel.No. : 6338 7288
 Reg.No. : SKK6155J
 Reg.date. : 17/03/2017
 Mileage : 0
 Chassis No: YV1PS10BDH1013615

Closed by : Richmond Ho
 Svc Consultant :
 Remarks : Wearnes Automotive P

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	EMBLEM 'VOLVO' REAR (2) (3)	1.0 EA	85.20	10		76.68	S
	EMBLEM 'S90' S90 17- (4)	1.0 EA	78.10	10		70.29	S
	EMBLEM 'T5' XC60 S80 (5)	1.0 EA	88.00	10		79.20	S
	BUMPER INSTALLING HT (6)	1.0 EA	83.40	10		75.06	S
	ADHESIVE TUBE CHEMIC	4.0 EA	75.80	10		272.88	S
	BUMPER COVER REAR S90 (7)	1.0 EA	1412.30	10		1,271.07	S
	TOW COVER REAR S90 1 (8)	1.0 EA	73.90	10		66.51	S
	CLIP (9)	10.0 EA	6.30	10		56.70	S
	BUMPER CLIP S90 17- (10)	10.0 EA	5.60	10		50.40	S
	PARK HOLDER LHR CTR (11)	1.0 EA	29.90	10		26.91	S
	PARK HOLDER RHR CTR (12)	1.0 EA	29.90	10		26.91	S
	PARK HOLDER LHR CORN (13)	1.0 EA	47.30	10		42.57	S
	PARK HOLDER RHR CORN (14)	1.0 EA	47.30	10		42.57	S
	PARK HOLDER LHR SIDE (15)	1.0 EA	26.90	10		24.21	S
	PARK HOLDER RHR SIDE (16)	1.0 EA	26.90	10		24.21	S

Gross Total. 10,282.89

Labour Total 6,060.00
 Parts Total 4,222.89
 Package Total 0.00

Net..... 10,282.89
 GST @ 7.0% 719.80
 Total..... 11,002.69
 Paid..... 0.00
 Please Pay.. 11,002.69

GST: S=StdRated; O=OutOfScope; Z=ZeroRated



Service Request Details

Claim

S8M015M9

Reference

None 

Loss Date

December 5, 2018

Request Date

December 10, 2018

Due Date

December 17, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

10.12.2018 @ 1003am
Peak wh not in.

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKK6155J

Make

TPVD VOLVO

Model

S90 BLACK

Service Address

...

Primary Contact/Insured

LEE HION YAN

22 ENG KONG GARDEN, 549238, Singapore

91556089

Claim Handler

HO Winnie

6568804833

winnie.ho@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)

Catherine Chong (LKK Auto)

From: Derek Oh Siong Wee <derek.oh@wearnes.com>
Sent: Friday, 7 December, 2018 7:13 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: Tan Yang Hoe; Ryan Lee Leong Hwee; Hazel Cheng; Mandy Woon; Richmond Ho
Subject: DIRECT SETTLEMENT FOR SKK6155J AND SMF2264G
Attachments: 1944_001.pdf

Importance: High

Categories: Shailendra

Hi

Please refer to the above attachment and check if possible for direct settlement

Best Regards,

Derek Oh
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
D (65) 6430 4895 M (65) 9818 7217
www.wearnes.com derek.oh@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Wednesday, 19 December 2018 1:57 PM
To: Poh Kin (LKKAUTO); Derek Oh Siong Wee
Cc: Tan Yang Hoe; Ryan Lee Leong Hwee; Hazel Cheng; Mandy Woon; Richmond Ho
Subject: RE: DIRECT SETTLEMENT FOR SKK6155J AND SMF2264G

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Merry Christmas
& HAPPY NEW YEAR

From: Poh Kin (LKKAUTO)
Sent: Wednesday, 19 December 2018 11:43 AM
To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Derek Oh Siong Wee <derek.oh@wearnes.com>
Cc: Tan Yang Hoe <yanghoe.tan@wearnes.com>; Ryan Lee Leong Hwee <ryan.lee@wearnes.com>; Hazel Cheng

<hazel.cheng@wearnes.com>; Mandy Woon <mandy.woon@wearnes.com>; Richmond Ho
<richmond.ho@wearnes.com>
Subject: RE: DIRECT SETTLEMENT FOR SKK6155J AND SMF2264G
Importance: High

Ref: CC4/ASM18022179/eb3

Dear Asher,

Kindly assist to reply **urgently**.

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Derek Oh Siong Wee [<mailto:derek.oh@wearnes.com>]

Sent: Wednesday, 19 December 2018 10:48 AM

To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Poh Kin (LKKAuto) <pohkin@lkkauto.com>

Cc: Tan Yang Hoe <yanghoe.tan@wearnes.com>; Ryan Lee Leong Hwee <ryan.lee@wearnes.com>; Hazel Cheng <hazel.cheng@wearnes.com>; Mandy Woon <mandy.woon@wearnes.com>; Richmond Ho <richmond.ho@wearnes.com>

Subject: RE: DIRECT SETTLEMENT FOR SKK6155J AND SMF2264G

Importance: High

Hi

Any update

Best Regards,

Derek Oh

Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd

249 Alexandra Road Singapore 159935

D (65) 6430 4895 M (65) 9818 7217

www.wearnes.com derek.oh@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Derek Oh Siong Wee
Sent: Friday, 14 December, 2018 5:48 PM
To: 'Asher Sng (LKKAuto)' <AsherSng@lkkauto.com>
Cc: Tan Yang Hoe <yanghoe.tan@wearnes.com>; Ryan Lee Leong Hwee <ryan.lee@wearnes.com>; Hazel Cheng <hazel.cheng@wearnes.com>; Mandy Woon <mandy.woon@wearnes.com>; Richmond Ho <richmond.ho@wearnes.com>
Subject: FW: DIRECT SETTLEMENT FOR SKK6155J AND SMF2264G
Importance: High

Hi Asher

Any update on liability clearance, thank you

Best Regards,

Derek Oh
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
D (65) 6430 4895 M (65) 9818 7217
www.wearnes.com derek.oh@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Derek Oh Siong Wee
Sent: Friday, 7 December, 2018 7:13 PM
To: 'motor.survey@axa.com.sg' <motor.survey@axa.com.sg>
Cc: Tan Yang Hoe <yanghoe.tan@wearnes.com>; Ryan Lee Leong Hwee <ryan.lee@wearnes.com>; Hazel Cheng <hazel.cheng@wearnes.com>; Mandy Woon <mandy.woon@wearnes.com>; Richmond Ho <richmond.ho@wearnes.com>
Subject: DIRECT SETTLEMENT FOR SKK6155J AND SMF2264G
Importance: High

Hi

Please refer to the above attachment and check if possible for direct settlement

Best Regards,

Derek Oh
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
D (65) 6430 4895 M (65) 9818 7217
www.wearnes.com derek.oh@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*



MANDATE IA (S8M015M9 / SKK 6155J)

Type

🔗 Question

Message

Liability: Insured rear ended third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$11,002.69 (w/GST) Loss of Use: \$500.00 (5days x \$100)
Total: \$11,502.69 Immediate Advice with Mandate and relevant document uploaded for your easy reference.
Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (02/05/2019)

Reply

◀ Re:MANDATE IA (S8M015M9 / SKK 6155J)

Type

🔔 Question

Message

Please offer \$80 for LOU and you may proceed with COR. thanks.

Reply

6/4/2019

Claim Portal

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Menu



Re:MANDATE IA (S8M015M9 / SKK 6155J)

Type

🔗 Question

Message

last consideration \$90/day

Reply

(PAYMENT BREAKDOWN)

Vehicle No	:	82K 6155J (Insd veh)	Model	:	VOLW S90.
	:	8MF 22646 (TP veh)			
Date of Accident	:	05/12/2018			

Global Sum Settlement	:	☐ YES	☒ NO
Liability	:	100 %	(Agreed/Assessed)

Repair Estimate	:	\$ 18589.95	
Final Repair Cost	:	\$ 11002.69	
Loss of Use	:	\$ 600	5 days at \$ 120 per day
Rental (if any)	:	\$	days at \$ (incls of GST) per day
Others	:	\$	
	:	\$	
	:	\$	
	:	\$	
Final Settlement Sum	:	\$ 11602.69	

Remarks: _____

Payment Instruction: Payee's Breakdown

1)	WARRANTS AUTOMOTIVA PUEBLO	:	\$ 11602.69
2)		:	\$
3)		:	\$
4)		:	\$



Our Reference: SKK6155J/7015309
Your Reference: SMF2264G

By Email / Mail

20 February 2019

AXA INSURANCE PTE LTD C/O LKK AUTO CONSULTANTS
Attn: Third Party Claim Department -

ACCIDENT INVOLVING SKK6155J & SMF2264G ON 05 Dec 2018.

Dear Officer,

We wish to inform you that the repairs to our client vehicle have been completed.

We hereby submit the claims as follows:

Details	Remarks	Amount (SGD)
Cost of Repairs		11,002.69
Loss Of Use	120.00 x 5 days	600.00
Others		
TOTAL		11,602.69

Kindly let us have your offer to Christine.yow@wearnes.com

Your soonest reply is much appreciated. Thank you.



Yours faithfully
Christine Yow
D (65) 6430 4899
Wearnes Automotive Pte Ltd
Bodyshop and Paint Division
249 Alexandra Road
Singapore 159935

This is a computer generated printout, no signature is required.

Wearnes Automotive Pte. Ltd.
45 Leng Kee Road, Singapore 159103 T 65 6430 4700 www.wearnesauto.com

Co reg no. 199501400R

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMF 2264G (Insd veh)	Model:	VOLVO S90 T5
	SKK 6155J (TP veh)		
Date of Accident:	05/12/2018		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:	\$		18,602.27
Final Repair Cost	:	\$		11,002.69
Loss of Use	:	\$		450.00
Rental (if any)	:	\$		5 days at \$0.00 per day
LTA / GIA Search Fee	:	\$		days

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	11,452.69

Is Third Party Workshop GIA Registered?	[X]	YES	[]	NO	(Kindly indicate below)
A) For Non GIA Registered Workshop: Agreed Liability _____ (%)					
B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____					
BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)					
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks _____					

Payment Instruction: Payee's Breakdown		
1)	WEARNES AUTOMOTIVE PTE. LTD.	: \$ 11,452.69

NUR SHAQILAH BTE ABDOL
WAHAB

27/06/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18022179/R1eb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811
ATTN: JAS TAN

Date : 27-06-2019



Code : ASM

Policy Particulars :- THIRD PARTY CLAIM

1.	Insured Veh.	SMF 2264G	Veh. Inspected	SKK 6155J
	Policy No.	VPA/P2199920	Coverage (\$)	0.00
	Claim No.	S8M015M9	Excess (\$)	0.00
	Assign From	JAS TAN	Assign Date	10/12/2018

Vehicle Particulars & Condition

2.	Make & Model	VOLVO S90 T5	c.c	1969
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	YV1PS10BDH1013615	Colour	BROWN
	Odometer	67909	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		

Conditions of Tyres

3.		Size	Make	Balance
	R/H Front Tyre	245/45ZR18	PIRELLI	6 mm
	L/H Front Tyre	245/45ZR18	PIRELLI	6 mm
	R/H Rear Tyre	245/45ZR18	PIRELLI	6 mm
	L/H Rear Tyre	245/45ZR18	PIRELLI	6 mm

Description of Damages

4.	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
----	--

General Information

5.	Accident Date	05/12/2018	Inspection Date	17/01/2019
	Survey held at	249 ALEXANDRA RD		
	Repairer	WEARNES AUTOMOTIVE PTE LTD		

Remarks

5a.	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
-----	---

Estimate Days of Repair

5b.	ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-----	-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKK 6155J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOT REAR (SN) (CONSISTENT)	BENT	2,240.80	2,016.72
1	EMBLEM 'VOLVO' REAR (SN) (CONSISTENT)	NECESSARY	85.20	76.68
1	EMBLEM 'S90' S90 17- (SN) (CONSISTENT)	NECESSARY	78.10	70.29
1	EMBLEM 'T5' XC60 S80 (SN) (CONSISTENT)	NECESSARY	88.00	79.20
1	BUMPER INSTALLING MT (SN) (CONSISTENT)	NECESSARY	83.40	75.06
4	ADHESIVE TUBE CHEMIC (SN) (CONSISTENT)	NECESSARY	303.20	272.88
1	BUMPER COVER REAR S9 (SN) (CONSISTENT)	DEFORMED	1,412.30	1,271.07
1	TOW COVER REAR S90 1 (SN) (CONSISTENT)	MISSING	73.90	66.51
1	BUMPER BRACKET REAR (SN) (CONSISTENT)	NOT NECESSARY	79.20	-
1	BUMPER SPACER LHR SV (SN) (CONSISTENT)	NOT NECESSARY	79.20	-
1	BUMPER SPACER RHR SV (SN) (CONSISTENT)	NOT NECESSARY	79.20	-
1	BUMPER RETAINER LHR (SN) (CONSISTENT)	NOT NECESSARY	28.60	-
1	BUMPER RETAINER RHR (SN) (CONSISTENT)	NOT NECESSARY	28.60	-
1	PARK HOLDER LHR CTR (SN) (CONSISTENT)	NECESSARY	29.90	26.91
1	PARK HOLDER RHR CTR (SN) (CONSISTENT)	NECESSARY	29.90	26.91
1	PARK HOLDER LHR CORN (SN) (CONSISTENT)	NECESSARY	47.30	42.57
1	PARK HOLDER RHR CORN (SN) (CONSISTENT)	NECESSARY	47.30	42.57
1	PARK HOLDER LHR SIDE (SN) (CONSISTENT)	NECESSARY	26.90	24.21
1	PARK HOLDER RHR SIDE (SN) (CONSISTENT)	NECESSARY	26.90	24.21
10	CLIP (SN) (CONSISTENT)	NECESSARY	63.00	56.70
1	PROTECTING PLATE REA (SN) (CONSISTENT)	NOT NECESSARY	253.30	-
10	BUMPER CLIP S90 17- (SN) (CONSISTENT)	NECESSARY	56.00	50.40
1	BUMPER BRACKET LHR S (SN) (CONSISTENT)	NOT NECESSARY	46.70	-
1	BUMPER BRACKET RHR S (SN) (CONSISTENT)	NOT NECESSARY	46.70	-
1	BUMPER BRACKET LHR E (SN) (CONSISTENT)	NOT NECESSARY	4.50	-
1	BUMPER BRACKET RHR E (SN) (CONSISTENT)	NOT NECESSARY	4.50	-
1	CAMERA BRACKET REAR (SN) (CONSISTENT)	NOT NECESSARY	67.80	-
1	PROTECTION (SN) (CONSISTENT)	NOT NECESSARY	13.30	-
1	CAMERA REAR S90 17- (SN) (CONSISTENT)	NOT NECESSARY	762.20	-
1	BUMPER RAIL REAR S90 (SN) (CONSISTENT)	NOT NECESSARY	1,304.80	-
1	BOOT HANDLE (SN) (CONSISTENT)	NOT NECESSARY	337.30	-

Report Ref No. CC4/ASM18022179/R1eb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LOCK (SN) (CONSISTENT)	NOT NECESSARY	390.50	-
1	BOOT LOCK COVER (SN) (CONSISTENT)	NOT NECESSARY	6.80	-
1	REAR NUMBER PLATE INCLUDE HOLDER (SN) (CONSISTENT)	BENT	60.00	60.00
			8,285.30	4,282.89
	LABOUR			
	TO REPLACE REAR BOOT LID, REAR EMBLEM, REAR BUMPER, REAR BRACKET, REAR LOWER SPOILER, REAR SENSOR, REAR PANEL ETC.		4,000.00	2,400.00
	TO PUTTY SPRAY PAINT ON REAR BOOT LID, REAR BUMPER, REAR END PANEL, ETC.		2,800.00	2,100.00
	TO TRANSFER REAR BOOT LID PART.		250.00	250.00
	TO REMOVE & INSTALL REAR BOOT COMPARTMENT PARTS.		1,600.00	800.00
	TO CHECK WIRING INCLUDE RESETING OF ALL ELECTRICAL MODULES.		450.00	450.00
			9,100.00	6,000.00
	GRAND TOTAL		17,385.30	10,282.89
RECOMMENDED COST OF REPAIRS				10,282.89

Report Ref No. CC4/ASM18022179/R1eb3s2

MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.