

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/LH1/087/2018
DATE : 07-DEC-2018

DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
88 SOUTH BRIDGE ROAD

S(058716)
TEL : 6532 2888
FAX :

OWNER'S NAME : WONG ZHUANG WEN (HUANG ZHUANGWEN)
ADDRESS : APT BLK 240 BUKIT PANJANG RING ROAD
#08-127
S(670240)
TELEPHONE NO : 9060 7630

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : MT/00502746
VEHICLE NO : SMC88110
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YE11816
CHASSIS NO : JF1SJ5KC5JG110809
MILEAGE : 1 KM
DATE IN : 07/12/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : JEFF TEH TENG CHUEN
ACCIDENT DATE : 07/12/2018

Print Date : 29/07/2019
Print Time : 11:55:54

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMC8811D

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ANTI	TO CONDUCT ANTI-RUST PROTECTION FOR REAR UNDERCARRIAGE WITH ANTI-RUST COATING	350.00	290.00
2	UNDERPANEL	TO CONDUCT PANEL PROTECTION FOR REAR UNDERCARRIAGE	350.00	250.00
3	ZZ/001	TO SUPPLY AND REPLACE REAR BUMPER, REAR TAILGATE, BUMPER BEAM AND EXHAUST MUFFLER	3360.00	1680.00
4	ZZ/002	TO RESPRAY REAR BUMPER, TAILGATE, BUMPER BEAM AND END PANEL	2640.00	880.00
5	ZZ/003	REMOVE & REFIX EXHAUST FOR FACILITATE REPAIR AND CHECKING	540.00	280.00
6	ZZ/004	TRANSFER TAILGATE MECHANISM	350.00	300.00
7	ZZ/005	REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	350.00	250.00
8	ZZ/006	REMOVE & INSTALL REAR WINDSCREEN	350.00	350.00
9	ZZ/007	TO SUPPLY & INSTALL REVERSE SENSOR - 2 EYES	450.00	300.00
10	ZZ/008	TO SUPPLY & INSTALL REAR WINDSCREEN TINT FILM	180.00	150.00
11	ZZ/009	SUNDRIES	100.00	20.00
12	ZZ/011	TO RESPRAY REAR END PANEL AND SPARE TYRE WELL (SUPP)	440.00	440.00 ✓
13	ZZ/10	TO REPAIR REAR END PANEL (SUPP)	560.00	560.00 ✓
TOTAL LABOUR CHARGES			10020.00	5750.00

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMC8811D

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES				REMARKS
			NETT	LIST	S/NETT	S/LIST	
1	MUFFLER ASSY RH NA	44300SG010	601.20				X
2	R EXH CUTTER RH/LH GE3/SH	44370FG002	72.00				X
3	FLOOR PAN R R CP	52129SG0019P	432.00				X
4	SKIRT COMPL R	52401SG0109P	288.00				X
5	BUMPER FACE REAR FORESTER IL	57704SG012	540.00				OK
6	BEAM COMPL R EU	57711SG0219P	288.00				OK
7	COVER HOOK R	57731SG010NN	12.60				OK
8	COVER BMPR R (EXHAUST)(SUPP)	57731SG060	14.40				OK
9	PANEL CPL R/G NA	60809SG0109P	1072.80				OK
10	GLASS R/G	63019SG000	799.20				OK
11	RUBBER DAM GLS *2	63232SG000	14.40				OK
12	RUBBER R/G 63232SC010 LONGER	63232SG010	12.60				OK
13	LETTER MARK FORESTOR R	93079SG000	39.60				OK
14	LETTER MK R SUB	93079SG030	64.80				OK
15	CARGO STEP PANEL S/S	E7710SG000			450.00	bt ✓	OK
SUB TOTAL			2858.40	0.00	450.00	0.00	
LESS DISCOUNT (NETT-20 %)			571.68	0.00	0.00	0.00	
GRAND TOTAL			2286.72	0.00	450.00	0.00	
OVERALL TOTAL			2736.72				

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SMC88110

NETT ITEM	2858.40
LESS 20 %	-571.68
NETT AMOUNT	2286.72
LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00
SPECIAL NETT AMOUNT	450.00
S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00
TOTAL LABOUR CHARGES	5750.00
TOTAL SPARE PARTS CHARGES	2736.72
TOTAL CHARGES	8486.72
ADD 7 % GST	594.07
GRAND TOTAL	9080.79