

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/LHI/087/2018
DATE : 07-DEC-2018

DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
88 SOUTH BRIDGE ROAD

S(058716)
TEL : 6532 2888
FAX :

OWNER'S NAME : WONG ZHUANG WEN (HUANG ZHUANGWEN)
ADDRESS : APT BLK 240 BUKIT PANJANG RING ROAD
#08-127
S(670240)
TELEPHONE NO : 9060 7630

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : MT/00502746
VEHICLE NO : SMC8811D
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YE11816
CHASSIS NO : JF1SJ5KC5JG110809
MILEAGE : 1 KM
DATE IN : 07/12/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : JEFF TEH TENG CHUEN
ACCIDENT DATE : 07/12/2018

Print Date : 07/12/2018
Print Time : 19:25:50

MOTORIMAGE ENTERPRISES PTE. LTD.,
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMC8811D

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ANTI	TO CONDUCT ANTI-RUST PROTECTION FOR REAR UNDERCARRIAGE WITH ANTI-RUST COATING	350.00	
2	UNDERPANEL	TO CONDUCT PANEL PROTECTION FOR REAR UNDERCARRIAGE	350.00	
3	ZZ/001	TO SUPPLY AND REPLACE REAR BUMPER, REAR TAILGATE, BUMPER BEAM AND EXHAUST MUFFLER	3360.00	
4	ZZ/002	TO RESPRAY REAR BUMPER, TAILGATE, BUMPER BEAM AND END PANEL	2640.00	
5	ZZ/003	REMOVE & REFIX EXHAUST FOR FACILITATE REPAIR AND CHECKING	540.00	
6	ZZ/004	TRANSFER TAILGATE MECHANISM	350.00	
7	ZZ/005	REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	350.00	
8	ZZ/006	REMOVE & INSTALL REAR WINDSCREEN	350.00	
9	ZZ/007	TO SUPPLY & INSTALL REVERSE SENSOR - 2 EYES	450.00	
10	ZZ/008	TO SUPPLY & INSTALL REAR WINDSCREEN TINT FILM	180.00	
11	ZZ/009	SUNDRIES	100.00	
TOTAL LABOUR CHARGES			9020.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
 25 LENG KEE ROAD
 SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMC8811D

S/NO PARTS DESCRIPTION		PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	MUFFLER ASSY RH NA	44300SG010	601.20			
2	R EXH CUTTER RH/LH GE3/SH	44370FG002	72.00			
3	FLOOR PAN R R CP	52129SG0019P	432.00			
4	SKIRT COMPL R	52401SG0109P	288.00			
5	BUMPER FACE REAR FORESTER IL	57704SG012	540.00			
6	BEAM COMPL R EU	57711SG0219P	288.00			
7	COVER HOOK R	57731SG010NN	12.60			
8	COVER BMPR R (EXHAUST)(SUPP)	57731SG060	14.40			
9	PANEL CPL R/G NA	60809SG0109P	1072.80			
10	GLASS R/G	63019SG000	799.20			
11	RUBBER DAM GLS *2	63232SG000	14.40			
12	RUBBER R/G 63232SC010 LONGER	63232SG010	12.60			
13	LETTER MARK FORESTOR R	93079SG000	39.60			
14	LETTER MK R SUB	93079SG030	64.80			
SUB TOTAL			4251.60	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			850.32	0.00	0.00	0.00
GRAND TOTAL			3401.28	0.00	0.00	0.00
OVERALL TOTAL			3401.28			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMC8811D

TOTAL LABOUR CHARGES	9020.00
TOTAL SPARE PARTS CHARGES	3401.28

GRAND TOTAL	12421.28 *

* All charges do2 not include GST,

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.