

15/2/11

INS. CASE OWNER:

CC

/AXA1802

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A:

Nature of Accident:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
12/12/18	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	EMAIL 26.12.18
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
12.12.18 @ 5:16	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by:
FINALIZATION	Date/Time:	Confirm with:	Confirm by: MEB
Repair Cost:	PIP SS 5,999.13	(5 days) Reduction: 56 %	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: 15-04-19	Confirm with: PROUME	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No.:	27	If NO or B 28, Ass. Lia.:
Repair Cost:	W/LG SS 6,419.07	01 REAR ENDED TP.	
Loss of Rental (LOR):	SS - (days)		
Loss of Use (LOU):	SS 7,000.00 (\$100 x 7 days)		
Loss of Income (LOI):	SS - (\$ x days)		
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/> [Tick only one]			
GIA/LTA Search	SS 2.00		
Medical:	SS -		
Disbursement:	SS - (e.g. Tow/ Independent)		
Legal Cost	SS -		
Total:	SS 7,121.07	Global Sum SS:	
FINAL PAYMENT	Date/Time: 15-04-19	Confirm with: PROUME	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS 7,121.07	Name 1: PERFORMANCE MOTORS LIMITED	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18022182/eb3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 10-12-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJY 9048D	Veh. Inspected	SBX 95B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	10/12/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	06/12/2018	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X101, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

07 DEC 2018

ESTIMATE

Estimate No. : b1 49380 Page No. : 1 of 5
 Date Estimated : 07/12/2018
 Prepared By : Kevin Leong Wai Kit

- ESTIMATE REPAIR FOR -

Sin Wai Tuck
10 Prome Road
#11-06

Singapore 328318

- ACCOUNT - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBX95B	L898393	03/08/2012	X3 xDrive35i	0

DESCRIPTION

To replace rear bumper, reinforcement, tailgate & all attachments cause by accident.

1700 3,400.00 1,330

Painting on rear bumper & rear tailgate

1,705.00 1,534.50

To conduct water leak tests.

nn X 78.00

To supply and install rear windscreen solar film.

nn X 531.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00 135

To carry out body cavity preservation.
(Per panel) Tailgate

nn X 118.00

Sundries.

ncl 80 ? 150.00 80

Total Labour 1: 6,156.00

DESCRIPTION

BOOTLID repair
Set of mount ? Xnn

QTY PRIC VALUE

RR BUMPER CARRIER ECE

1 1,852.40 1,852.40

MOUNT BUMPER REAR LH

1 35.10 35.10

MOUNT BUMPER REAR RH

1 756.50 756.50 133.80

RR BUMPER LH MIDDLE MOUNT

1 192.15 192.15

RR BUMPER RH MIDDLE MOUNT

1 192.15 192.15

TRIM PANEL BUMPER RR BOTTOM (M)

1 142.55 142.55

COVERING LOWERM-PAKET / AHV

1 142.55 142.55

SET OF TRIM COVERS TOW FITTING (M)

1 258.00 258.00 250.26

RR BUMPER TRIM BUMPER PRIMED PDC (M)

1 119.05 119.05

EMBLEM GROMMET

1 93.45 93.45

MODEL LETTERING X3

1 1,625.30 1,625.30 1516.54

EMBLEM (M)

2 0.80 1.60 1.55

BMW EMBLEM

1 64.10 64.10 62.18

1 81.90 81.90

1 71.25 71.25

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49380
Date Estimated : 07/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBX95B	L898393	03/08/2012	X3 xDrive35i	0

DESCRIPTION	QTY	PRIC	VALUE
RR W/SCREEN <i>Xan</i>	1	1,063.05	1,063.05
DECOUPLING RING PDC TORQUE CONVERTE <i>?Xan</i>	4	5.05	20.20
BUMPER PDC SENSOR (SCHWARZ) <i>?Xan</i>	2	236.85	473.70
(DG) CLEANER R1 (100ML) <i>Xan</i>	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>Xan</i>	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206) <i>Xan</i>	1	27.85	27.85
Total Parts :			7,502.10

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time <i>11/12/18 1410</i>	Excess S\$ _____
Surveyor's Name <i>Rashid</i>	Sign _____
Surveyor's Tel <i>9000068</i>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No	
Surveyor's E-mail _____	
No. of Working Days Requirement <i>5 days</i>	

Labour 1	:	6,156.00
Parts	:	7,502.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	956.07
Grand Total	:	14,614.17

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

13753.40

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 49380
Date Estimated : 07/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -

Sin Wai Tuck
10 Prome Road
#11-06

Singapore 328318

- ACCOUNT - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SBX95B	L898393	03/08/2012	X3 xDrive35i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# TRUNK LID BADGE *	71.25	1.00	3.00	69.11
# EXPANDING RIVET *	1.35	20.00	3.00	26.19

Total Labour :	
Total Parts :	95.30
Total Labour & Parts :	95.30

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 49380
Date Estimated : 07/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -

Sin Wai Tuck
10 Prome Road
#11-06

Singapore 320318

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SBX95B	L898393	03/08/2012	X3 xDrive35i	0
DESCRIPTION	ORIGINAL PRICE		DISC. %	NETT
To replace rear bumper and attachments include making good the boot lid and knocking out dents caused by the accident	1700.00		10.00	1,530.00
To spray paint rear bumper and boot lid	1705.00		10.00	1,534.50
To check electrical wiring systems and lightings at the rear section for proper function	150.00		10.00	135.00
Sundries	80.00		0.00	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RR BUMPER CARRIER ECE	756.49	1.00	3.00	733.80
TRIM PANEL BUMPER RR BOTTOM (M)	258.00	1.00	3.00	250.26
RR BUMPER TRIM BUMPER PRIMED PDC (1,625.30	1.00	3.00	1,576.54
EMBLEM GROMMET	0.80	2.00	3.00	1.55
MODEL LETTERING X3	64.10	1.00	3.00	62.18
# TRUNK LID BADGE *	71.25	1.00	3.00	69.11
# EXPANDING RIVET *	1.35	20.00	3.00	26.19

SUPPLEMENTARY ITEMS

Total Labour :	3,279.50
Total Parts :	2,719.63
Total Labour & Parts :	5,999.13
Deduction for Excess :	0.00
Total Repair Costs less Excess:	5,999.13
GST @7%:	419.94
Grand Total :	6,419.07

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

07 DEC 2018

E S T I M A T E

Estimate No. : b1 49380
Date Estimated : 07/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Sin Wai Tuck
10 Prome Road
#11-06

Singapore 328318

- ACCOUNT - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBX95B	L898393	03/08/2012	X3 xDrive35i	0

DESCRIPTION

To replace rear bumper, reinforcement, tailgate & all attachments cause by accident.

1700 ~~3,400.00~~

Painting on rear bumper & rear tailgate

1,705.00

To conduct water leak tests.

X ~~75.00~~

To supply and install rear windscreen solar film.

X 531.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 ~~177.00~~

To carry out body cavity preservation.
(Per panel) Tailgate

X 118.00

Sundries.

? 150.00

Total Labour 1: 6,156.00

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID <i>repair</i>	1	1,852.40	1,852.40
Set of mount	1	35.10	35.10
RR BUMPER CARRIER ECE	1	756.50	756.50
MOUNT BUMPER REAR LH	1	192.15	192.15
MOUNT BUMPER REAR RH	1	192.15	192.15
RR BUMPER LH MIDDLE MOUNT	1	142.55	142.55
RR BUMPER RH MIDDLE MOUNT	1	142.55	142.55
TRIM PANEL BUMPER RR BOTTOM (M) <i>cut</i>	1	258.00	258.00
COVERING LOWERM-PAKET / AHV	1	119.05	119.05
SET OF TRIM COVERS TOW FITTING (M)	1	93.45	93.45
RR BUMPER TRIM BUMPER PRIMED PDC (<i>re</i>)	1	1,625.30	1,625.30
EMBLEM GROMMET	2	0.80	1.60
MODEL LETTERING X3	1	64.10	64.10
EMBLEM (M)	1	81.90	81.90
BMW EMBLEM	1	71.25	71.25

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49380
Date Estimated : 07/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBX95B	L898393	03/08/2012	X3 xDrive35i	0

DESCRIPTION	QTY	PRIC	VALUE
RR W/SCREEN X	1	1,063.05	1,063.05
DECOUPLING RING PDC TORQUE CONVERTE ?	4	5.05	20.20
BUMPER PDC SENSOR (SCHWARZ) ?	2	236.85	473.70
(DG) CLEANER R1 (100ML) X	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) X	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206) X	1	27.85	27.85
Total Parts :			7,502.10

Claims: OD / 2nd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 11/12/18 1410 Excess S\$ _____

Surveyor's Name Rohar Sign _____

Surveyor's Tel 9000068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No P.M.L. Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 5 days

Labour 1	:	6,156.00
Parts	:	7,502.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	956.07
Grand Total	:	14,614.17

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **




Service Request Details

Claim

S8M015SB

Reference

None 

Loss Date

December 6, 2018

Request Date

December 7, 2018

Due Date

December 14, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

10.12.2018 @ 9.56am
Caroline veh not in

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SBX95B

Make

TPVD BMW

Model

X3 SUV 2979C

Service Address

...

Primary Contact/Insured

SAFIE MOHAMMAD FADLY BIN

106 TANAH MERAH BESAR ROAD, #03-50, 498842, Singapore

65420084

FADLYSAFIE@GMAIL.COM

Claim Handler

HO Winnie

6568804833

winnie.ho@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)

[New Message](#)

Catherine Chong (LKK Auto)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Friday, 7 December, 2018 3:45 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: REQUEST FOR DIRECT SETTLEMENT - SBX95B & SJY9048D ON 06/12/2018
Attachments: SKM_558e18120715410.pdf; 004.JPG; 011.jpg; 012.jpg; 728861f1-3f04-4947-8ed8-6fb1006de8d5.jpg

Categories: Pragati

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Wednesday, 12 December 2018 5:18 PM
To: PBSP
Cc: Admin A; winnie.ho@axa.com.sg
Subject: RE: REQUEST FOR DIRECT SETTLEMENT - SBX95B & SJY9048D ON 06/12/2018 - S8M015SB

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAUTO)
Sent: Wednesday, 12 December 2018 4:54 PM
To: winnie.ho@axa.com.sg
Cc: Admin A <admin-a@lkkauto.com>; PBSP <pml-pbsp@simedarby.com.sg>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Subject: FW: REQUEST FOR DIRECT SETTLEMENT - SBX95B & SJY9048D ON 06/12/2018 - S8M015SB

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Please note that: -

LKK ref	Officer in charge
CC4/ASM18022182/eb3	Asher

To check availability of the case handler, you may contact the undersigned

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: HO Winnie <winnie.ho@axa.com.sg>

Sent: Wednesday, 12 December 2018 9:33 AM

To: Admin A <admin-a@lkkauto.com>

Cc: PBSP <pml-pbsp@simedarby.com.sg>

Subject: REQUEST FOR DIRECT SETTLEMENT - SBX95B & SJY9048D ON 06/12/2018 - S8M0155B

Dear all,

Please follow up with PML on the matter.

Thanks & Regards

Winnie Ho, Senior Admin Assistant, Motor Claims Department

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg

Email: winnie.ho@axa.com.sg

Customer Care No. 1800 8804741 / Fax: (65) 6880 4838



redefining / insurance



Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]

Sent: 11 December, 2018 5:23 PM

To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Subject: Re: REQUEST FOR DIRECT SETTLEMENT - SBX95B & SJY9048D ON 06/12/2018

Dear Sirs,

Kindly reply on liability.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: PBSP
Sent: Friday, 7 December 2018 3:44:45 PM
To: motor.survey@axa.com.sg
Subject: REQUEST FOR DIRECT SETTLEMENT - SBX95B & SJY9048D ON 06/12/2018

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this

message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.



MANDATE IA (S8M015SB)

Type

🔔 Question

Message

Liability: Insured rear ended third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$6,419.07 (w/GST) Loss of Use : \$800.00 (7days x \$120) LTA Search: \$2.00 Total: \$7,261.07 Immediate Advice with Mandate and relevant document uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng
(26/03/2019)

Reply



MANDATE IA (S8M015SB)

Type

🔗 Question

Message

Hi Asher, propose loss of use @ \$80 per day, up to \$100 max.

Reply

RE: LOD REMINDER - SBX95B & SJY9048D ON 06/12/2018

Kevin Leong Wai Kit <kevin.leong.waikit@simedarby.com.sg>

Mon 4/8/2019 4:34 PM

To: PBSP <pml-pbsp@simedarby.com.sg>;

Cc: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>;

Dear All,

Customer accept with \$ 100 x 7 day = \$ 700.00

Thank you

Regards,

Kevin Leong

Customer Service Advisor | Body and Paint

Performance Motors Limited

303 Alexandra Road

Sime Darby Performance Centre

Singapore 159941

Hp (+65) 9116 5600 | Fax (+65) 6479 4601

Kevin.leong.waikit@simedarby.com.sg



From: PBSP

Sent: Monday, April 08, 2019 2:56 PM

To: Kevin Leong Wai Kit

Cc: Asher Sng (LKKAuto)

Subject: Re: LOD REMINDER - SBX95B & SJY9048D ON 06/12/2018

Dear Kevin

You have requested for \$120/day for 7 days.

Please confirm customer's acceptance of \$100/day for 7 days to close the matter.

Thank you.

Regards,

Caroline

From: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Sent: Saturday, 6 April 2019 4:15 PM

To: PBSP

Subject: Re: LOD REMINDER - SBX95B & SJY9048D ON 06/12/2018

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Hi Sir,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair(w/GST)	\$ 6,419.00
2. Loss of Use (7 days x \$100)	\$ 700.00
3. LTA/GIA search fee	\$ 2.00
TOTAL	<u>\$ 7,121.07</u>

Kindly let us have your acceptance.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJY 9048D (Insd veh)	Model:	B.M.W. X3 XDRIVE35I
	SBX 95B (TP veh)		
Date of Accident:	06/12/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	14,716.14
Final Repair Cost	:	\$	6,419.07
Loss of Use	:	\$	700.00
Rental (if any)	:	\$	
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	7,121.07

Is Third Party Workshop GIA Registered?		<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____(%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____100_____(%)		Assessed Liability (*): _____(%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	PERFORMANCE MOTORS LTD	:	\$ 7,121.07

NUR SHAQILAH BTE ABDOL
WAHAB

23/04/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18022182/R1eb3s2		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811 ATTN: WINNIE HO		Date : 23-04-2019		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJY 9048D	Veh. Inspected	SBX 95B	
Policy No.	VPA/P2093518	Coverage (\$)	0.00	
Claim No.	S8M015SB	Excess (\$)	0.00	
Assign From	WINNIE HO	Assign Date	10/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. X3 XDRIVE35i	c.c	2979	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WBAWX72070L898393	Colour	BLACK	
Odometer	85036	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/40R19	PIRELLI	6 mm	
L/H Front Tyre	275/40R19	PIRELLI	6 mm	
R/H Rear Tyre	275/40R19	PIRELLI	6 mm	
L/H Rear Tyre	275/40R19	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/12/2018	Inspection Date	11/12/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBX 95B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	1,852.40	-
1	SET OF MOUNT (SN) (CONSISTENT)	NOT NECESSARY	35.10	-
1	RR BUMPER CARRIER ECE (SN) (CONSISTENT)	BENT	756.50	733.80
1	MOUNT BUMPER REAR LH (SN) (CONSISTENT)	NOT NECESSARY	192.15	-
1	MOUNT BUMPER REAR RH (SN) (CONSISTENT)	NOT NECESSARY	192.15	-
1	RR BUMPER LH MIDDLE MOUNT (SN) (CONSISTENT)	NOT NECESSARY	142.55	-
1	RR BUMPER RH MIDDLE MOUNT (SN) (CONSISTENT)	NOT NECESSARY	142.55	-
1	TRIM PANEL BUMPER RR BOTTOM (SN) (CONSISTENT)	CUT	258.00	250.26
1	COVERING LOWERM-PAKET / AHV (SN) (CONSISTENT)	NOT NECESSARY	119.05	-
1	SET OF TRIM COVERS TOW FITTING (SN) (CONSISTENT)	NOT NECESSARY	93.45	-
1	RR BUMPER TRIM BUMPER PRIMED PDC (SN) (CONSISTENT)	DEFORMED	1,625.30	1,576.54
2	EMBLEM GROMMET (SN) (CONSISTENT)	NECESSARY	1.60	1.55
3	MODEL LETTERING (SN) (CONSISTENT)	NECESSARY	64.10	62.18
1	EMBLEM (SN) (CONSISTENT)	NOT NECESSARY	81.90	-
1	BMW EMBLEM (SN) (CONSISTENT)	NOT NECESSARY	71.25	-
1	RR W/SCREEN (SN) (CONSISTENT)	NOT NECESSARY	1,063.05	-
4	DECOUPLING RING PDC TORQUE CONVERTE (SN) (CONSISTENT)	NOT NECESSARY	20.20	-
2	BUMPER PDC SENSOR (SCHWARZ) (SN) (CONSISTENT)	NOT NECESSARY	473.70	-
1	(DG) CLEANER R1 (100ML) (SN) (CONSISTENT)	NOT NECESSARY	26.15	-
2	(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) (SN) (CONSISTENT)	NOT NECESSARY	263.10	-
1	(DG/SL) GLASS PRIMER 30ML (VP206) (SN) (CONSISTENT)	NOT NECESSARY	27.85	-
1	REAR WINDSCREEN SOLAR FILM (SN) (CONSISTENT)	NOT NECESSARY	531.00	-
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	150.00	80.00
1	TRUNK LID BADGE (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	69.11	69.11
20	EXPANDING RIVET (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	26.19	26.19
			8,278.40	2,799.63

Report Ref No. CC4/ASM18022182/R1eb3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REPLACE REAR BUMPER, REINFORCEMENT, TAILGATE & ALL ATTACHMENTS CAUSE BY ACCIDENT. INCLUSIVE OF THE REPAIR OF BOOTLID.		3,400.00	1,530.00
	PAINTING ON REAR BUMPER & REAR TAILGATE.		1,705.00	1,534.50
	TO CONDUCT WATER LEAK TESTS.	NOT NECESSARY	75.00	-
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	135.00
	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL) TAILGATE.	NOT NECESSARY	118.00	-
			5,475.00	3,199.50
	GRAND TOTAL		13,753.40	5,999.13
RECOMMENDED COST OF REPAIRS				5,999.13

Report Ref No. CC4/ASM18022182/R1eb3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.