

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

7-Dec-18

ESTIMATE REPAIR BILL FOR MAZDA 3 REGN NO: SJS 7333 A

1 pc	Rear bumper	/
1 pc	Rear bumper reinforcement	X
1 pc	Rear bumper n/s & o/s reflector	/
1 pc	Rear bumper n/s & o/s side bracket	?
1 pc	End panel	/
1 pc	End panel top garnish	/
1 pc	Bootlid	/
1 pc	Bootlid emblem "Mazda 3"	/
1 pc	Bootlid logo	/
1 pc	Bootlid insulator	/
2 pcs	Bootlid hinges	/
1 pc	Rear windscreen	/
1 pc	Rear windscreen moulding	/
1 pc	Rear speaker panel	/
1 pc	Rear speaker panel board	/
1 pc	Rear n/s & o/s fender	/
1 pc	Rear n/s & o/s fender inner shield	?
1 pc	Rear o/s fender inner panel	n/s x repair o/s
1 pc	Rear n/s & o/s tail lamp	/
1 pc	Rear n/s & o/s reflector	/
1 pc	Rear flooboard panel	X repair
1 pc	Rear flooboard trim	X

Less 20%

\$ -

S/NETT

1 set	Rear bumper clips	/	\$	48.00
1 set	Reverse sensor	/	\$	280.00 200
2 pcs	Rear n/s & o/s fender inner shield clips @\$28.00	/	\$	56.00
1 pc	Sealant	/	\$	50.00

7-Dec-18

ESTIMATE REPAIR BILL FOR MAZDA 3 REGN NO: SJS 7333 A

Sundry	\$ 50.00 20
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 30
To dismantle and refit the rear windscreen	\$ 120.00 100
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 50
To labour charge for dismantle and renew the accident damaged parts. To cut/weld and heat on the rear n/s & o/s fender, rear o/s fender inner panel, end panel, floorboard panel, Rear speaker panel. Including knock-out, straighten, repair, reshape and adjust of the rear n/s & o/s chassis member	\$ 2,500.00 1800
To putty and spray painting on rear bumper, end panel, floorboard, bootlid, rear speaker panel, rear n/s & o/s fender, rear o/s fender inner panel	\$ 1,800.00 1440
To apply rustproofing on the repaired and replaced panels.	\$ 280.00 50

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahn 10/10/18
10/12/18 1030 Lx
7-8 Rep.
U/s
After Repair & Lx
check M.V. first

LKK Auto Consultant's hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance company

Acknowledged by Repairer
Signature:
Date:

to scrap
unconfirmed to Repri
Nett value \$2300