

ASS. REC. BY:

REF:

CSA/MSA18019222 / G&amp;A-1

Special Instructions:

Surveyor:

Guo Cheng

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSIG

Date/Time: 11/22/2018

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 4096S

Insured:

GY 3877C

at Workshop m/s:

Motor Inlet

Tel:

6281 0087

of

13/Leiki Bkt Rd 4 # 01-20

Policy No:

MSD/VCFT/18-000498

Claim No:

MSC/V/18071111

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 19/10/2018

CA / REV / REP. / REV 24 HRS

up

Date/Time:

12:10pm 23/10/18

Person Contacted:

Richard

H.O.D. Endorsement:

Vehicle ☒ IN/OUT

Date/Time

Action/Instruction (X) Estimate

Dentist finished

GBF 4096S - X


GY 3877C - CC4/11617003333/Tle 6392

Dont 10/2/17

Dismantle: 25/10/2018.

04/11/19

Submit LS 6580, 6 days (Red 63680, 39%/-)



RECEIVED 04 JAN 2019

3/1/2019


PPS  
KML. REF: MSG C6451w

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop n/s Motor Intel  
 of \_\_\_\_\_  
 Insured \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report, Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time

Action / Instruction

\$3000 - \$4000

Veh No: 6BF 4096S Yr Regn: 20 Oct 2016  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace cc 2982  
 Colour: Yellow A/C Insured / Std / NI / NA  
 Sp. Reading: 85559 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KDH 2010 204032

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195MS

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A.

D.O.I.

Survey held at

w/s 23-10-18 4:10 pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time: File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation

\$ + RS \$

Phone

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

PRS

Lump Sum / LB.I: (\$

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Oct 2018		23 Oct 2018 11:19 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

Insured:	PROPELL INTEGRATED PTE LTD, Co. Reg. No.: 0		[Created by insurer]
Main Claimant:	ROYAL AUTOWORKZ PTE LTD, Co. Reg. No.: 201716451W		
Vehicle Reg. No.:	GBF4096S	Date of Loss:	19/10/2018 00:00 - :59 [23 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-001411	Policy/Cover Note No.:	MSD/VCFT/18-000498 Coverage: 21/03/2018 - 20/03/2019
Vehicle Reg. No. (Insured):	GY3877C	Policy No. (Claimant):	
		Excess:	
Repalrer:	Motor Intel Automo Pte Ltd - Kaki Bukit (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 13/12/2018]		
Adj Asg. Remarks:	Liability unclear. Non Reporting. Contact Person: Mr Richard / 6281 0087. TP disagree with SJE list. Proceed to appoint LKK Auto Consultants as the SJE.		

### ASSOCIATED MAIL RECEIVED

- MSIG\_SG (11/12/2018): Report Send Back Alerts - GBF4096S (TP)

[View All](#)
[Compose Case Mail](#)

### ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
No results.						<a href="#">Assigned By</a>	<a href="#">Completed On</a>	<a href="#">Created On</a>	<a href="#">Done?</a>

**Catherine Chong (LKK Auto)**

---

**From:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Sent:** Tuesday, 11 December, 2018 10:54 AM  
**To:** Christina Wong; assignments  
**Subject:** RE: Our Ref:MSc/V/180991411 TP?GBF4096S

Dear Christina,

Thank you for the email.

**Dear Assignment Team,**

**FYNA**

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Christina Wong <Christina\_Wong@sg.msig-asia.com>  
**Sent:** Tuesday, 11 December 2018 10:51 AM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Subject:** Our Ref:MSc/V/180991411 TP?GBF4096S

Hi Veron

Please do paper survey I have sendback the report in Merimen.

Thanks





Best Regards

**Christina Wong**

Senior Executive, Claims Services (Motor)

Direct line +65 6643 1311 | Direct fax +65 6225 7402 | [christina\\_wong@sg.msig-asia.com](mailto:christina_wong@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us on    

A member of  INSURANCE GROUP

CHIA S ARUL LLC  
ADVOCATES & SOLICITORS  
UEN 201330709H

ARULCHELVAN S



Our Ref : AS.182316.In

Your Ref : TBA MSC V 18 001411

30 November 2018

Propell Integrated Pte Ltd  
15 Bukit Batok Street 22  
#06-00 Propell Building  
Singapore 659586

BY CERTIFICATE OF POSTING

MSIG Insurance (S) Pte Ltd  
No.4 Shenton Way  
#23-01 SGX Centre 2  
Singapore 068807

BY PDX

Dear Sir

ACCIDENT INVOLVING GBF 496S & GY 3877C ALONG WOODLANDS AVENUE 12  
BEFORE AVENUE 5 JUNCTION (FROM SLE) ON 19 OCTOBER 2018

We are instructed by the abovenamed to claim damages against you in connection with a road traffic accident on 19 October 2018 at about 2:45 p.m. along Woodlands Avenue 12 before Avenue 5 Junction (from SLE) involving our client's motor vehicle registration number GBF 4096S and vehicle registration number GY 3877C driven by you at all material time.

We are instructed that the accident was caused by your negligent driving and/or management of your vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:

a)	Costs of Repair (Inclusive 7% GST)	S\$ 10,143.60
b)	Rental (12 days x \$150) (Inclusive 7% GST)	S\$ 1,926.00
c)	Survey Report Fees	S\$ 670.00
d)	LTA	S\$ 7.49
e)	Costs	S\$ 1,700.00
	Total	S\$ 14,447.09

A copy of each of the following supporting documents is enclosed.

- a) A copy of our client's GIA report;
- b) A copy of the survey report, invoice and photographs of our client's motor vehicle;
- c) A copy of the repair bill.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.


Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer.


Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully,

MR ARULCHELVAN S

Enclosure(s)





# Motor Intel Auto Pte Ltd

Reg No: 201732961N  
GST No: 201732961N

13 Kaki Bukit Road 4,  
#01-20 Bartley Biz Centre  
Singapore - 417807  
Mobile no: 91501587 Phone no: 62810087  
Email: sales@mia.com.sg

Customer :

ROYAL AUTOWORKZ PTE LTD (GBF 4096 S)

BLK 126 YISHUN ST 11,  
#09-419,  
Singapore - 760126  
Phone no: 86861286

Proforma Invoice No:  
PI 166

Dated:  
November 14, 2018

S.No	Item	Description	Quantity	Unit	Rate(SGD)	Amount (SGD)
1	COST OF REPAIR	COST FO REPAIR (LUMP SUM)	1	JOB	9,480.00	9,480.00
Sub Total (SGD)						9,480.00
GST 7% (7%):						663.60
Total (SGD)						10,143.60

Amount in words :  
Ten Thousand One Hundred Forty Three and Sixty cents Singapore Dollar (SGD) Only

## Declaration:

We declare that this Proforma Invoice shows the actual price of the goods described and that all particulars are true and correct.

For Motor Intel Auto Pte Ltd

Authorized Signatory





# 長江企業(私人)有限公司

## Chiang Kang Enterprises Co. (Pte.) Ltd.



1995 - 2003

### TAX INVOICE

No. 4 Petain Road, Petain Court Singapore 208086 Tel: 6298 1936, 6294 0246 Fax: 6298 3864

RENTAL OF CARS, VANS, PICK-UPS & LORRIES  
GST Reg. No. 19-8304039-K

出租：汽車、廣告車、必甲與輕重型羅厘

HIRER'S PARTICULARS  
I/We \_\_\_\_\_ of \_\_\_\_\_  
If Different From Section 1

hereinafter called "the Hirer" hereby confirm having agreed to hire this day from CHIANG KANG ENTERPRISES CO. (PTE.) LTD. hereinafter called "the Owner" the undermentioned Vehicle at the rental fees as shown below and I further agree that I shall be held responsible for:-

- a) **THIRD PARTY ONLY MOTOR VEHICLE COVERAGE**  
the Excess which is the maximum amount of \$1500/- to cover for any third party damage or injury claims and also bear the full cost of any damage caused to the hired Vehicle resulting from any single accident including loss from inability to let the same Vehicle out on hire or loss resulting from theft and destruction of the Vehicle.
- b) **COMPREHENSIVE MOTOR VEHICLE COVERAGE**  
the Excess which is the maximum amount of \$2000/- for any damage caused to the hired Vehicle from any single accident or any loss resulting from third party damage claim, injury claim, theft or destruction of the Vehicle.
- c) Only persons above 24 years of age with more than 2 years driving experience, authorised licensed and signing this agreement may drive the vehicle. whether or not such damage or loss is by person/persons known or unknown to me or by negligence or any breach by me or the terms and Conditions of Hire, hereinafter mentioned and printed at the back hereof:

Vehicle Regn No. 車輛註冊號碼		GRF 3763 G		Rental Agreement 合同號碼 No. A 91442	
Section 1 Hirer's And/Or Driver's Particulars 租車者/駕駛員個人記錄				租出日期及時間	
Name: ERNEST SONG JIA LONG				Date & Time OUT 19 Oct 2018 1730 hrs.	
Address: BLK 126 YISHUN STREET 11				交車日期及時間	
# 09-419 S 760126				Date & Time IN 31 Oct 2018 1600 hrs	
				Chargeable	Rates Amount
居民證/護照號碼		駕駛執照號碼		天	@ \$
I/C No./Passport No: -		Driving Licence No: S 97179304		星期	@ \$
居民證/護照種類		Pass 日期		月	@ \$
Type of I/C/Passport: -		Pass Date: 23 Apr 2018		Month	@ \$
出生日期		發出地		ADD 7% GST	
Date of Birth: 28/05/1997		Place of Issue: SPORE		B126/-	
三號保險底金 \$1500/=		一號保險底金 \$2000/=		送車/費	
a) Third Party Only Policy Excess \$1500/=		b) Comprehensive Policy Excess \$2000/=		Delivery Fees	
車輛必須歸還車主於				總計	
Vehicle Must Be Returned To Owner's Office By:				Total Charge	
備註與付款記錄 附單				按金	
Remarks & Payment Records				Security Deposit	
				總金額	
				Total Payable	
				來銀	
				Amount Paid	
				收車費用	
				Collection Fees/Misc.	
				超過/小時	
				Extra Hours @ \$	
				租費不包括汽油	
				Rates Do Not Include Fuel	
				添油	
				Refuelling	
				加額費用	
				Total Additional Charges	
				總計	
				Grand Total	

### IMPORTANT! For Singapore Use only!

出車油箱	E 1/8 1/4 3/8 1/2 5/8 3/4 7/8 F	出車油箱	E 1/8 1/4 3/8 1/2 5/8 3/4 7/8 F
Fuel Tank OUT		Fuel Tank IN	
車牌號碼	1)	起	From:
Vehicle No:		至	To:
車牌號碼	2)	起	From:
Vehicle No:		至	To:
工具	輪胎	裝飾品	
Tools	Spare Tyre	Accessories	
車輛發出人	車輛接收人		
Vehicle Issued By:	Vehicle Collected By:		

NOTE: 註  
租車者或司機必須付所有停車及違反交通法例負起一切的責任。  
HIRER AND/OR DRIVER IS LIABLE FOR ALL PARKING AND TRAFFIC VIOLATIONS.

租車者不准載沙或石灰  
HIRER MUST NOT CARRY SAND AND CEMENT ON THE VEHICLE

我/我們同意以上及後頁租車公司所列的條規與條件。  
I/We have read and hereby agree to the terms and conditions on both sides of this rental agreement.

日期 31/10/2018  
Date:

租車者簽名  
Signature of Hirer:



*Signature*

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 19/10/2018 17:04  
Date Of Accident 19/10/2018 14:45  
Exact Location Of Accident WOODLANDS AVE 12 BEFORE AVE 5 JUNCT(FROM SLE)  
Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number GBF4096S  
Insured/Policyholder  
Name Of Registered Owner ROYAL AUTOWORKZ PTE LTD  
Co Reg No 201716451W  
Email Address NOEMAIL  
Mobile Phone No (LOCAL) +65-86861286  
Alternative Phone No OFFICE-86861286  
Vehicle Particulars  
Manufacturer TOYOTA  
Model HIACE 3.0 SUPER GL DARK PRIME AT  
Exact Purpose for which vehicle was being used at time of accident COMMERCIAL USE  
Are you claiming under your own insurance policy for repair to your vehicle? NO  
If No, Please state action to be taken REPORTING ONLY  
Vehicle Category COMMERCIAL VEHICLE  
Insurance Company  
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO  
Policy Number 5097168810  
Cover Note Number  
Driver  
Name of Driver ERNEST SONG JIALONG  
NRIC No S9717930A  
Date Of Birth 28/05/1997  
Occupation OUTDOOR  
Date Of Driving Pass 23/04/2018  
Driving Experience 0 YEAR AND 5 MONTH  
Gender MALE  
Mobile Number (LOCAL) +65-86867930  
Fax Number  
Contact Number  
EMail Address NOEMAIL

Injuries Sustain

Injured person in which vehicle?

GBF4096S

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

Address

BLK 126 YISHUN STREET 11 #09-419

Postcode

760126

Address BLK 126 YISHUN STREET 11 #09-419  
Postcode 760126  
Was driver an employee of the Insured's Company YES  
If No, Relationship of the Driver with the Insured  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
-  
Insurance Company of Driver's Own Vehicle -  
-  
-

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident 2  
Was any body injured in the Accident? YES  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GY3877C  
Vehicle Make/Model/Colour NISSAN CABSTAR  
Details Of Properties  
Vehicle Category COMMERCIAL VEHICLE  
Name of Driver SUBRAMANIAN VENKATESHVARAN  
NRIC/Passport Number G5047989M  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name ERNEST SONG JIALONG  
Approximate Age

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


19 OCT 2018

*Signature*

**IDAC KAKI BUKIT (VAC)**

Reporting Party's Signature  
Name: Singapore 415933  
Tel: 67416697  
Fax: 67492305  
Email: vackb@singnet.com.sg

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Woodland Ave 12 from SLE on the right most lane of a 3-lane road. Somewhere before Junction of Woodland Ave 12 and Ave 5, I stopped at the traffic light due to traffic light turning red. Moments after I stopped, I suddenly felt a strong impact from the rear portion of my vehicle. After the accident, I managed to see that vehicle B front portion collided into the rear portion of my vehicle. Hence I was involved in an accident of 2 vehicles. My body hit against the dashboard and I experienced body pain from the accident and will be seeking medical attention. Veh A: GBF 4196S.  
Veh B: GY 3877C.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

IDAC KAKI BUKIT (VAC)  
23 KAKI BUKIT AVE 4  
Singapore 415933

Reporting Centre Tel: 67416697  
Name: Fax: 67492305  
NRIC/FIN: Email: vackb@singnet.com.sg



# Thank you

Chia See Kim Angela Sharon has successfully logged out.

Your last login date and time was 28 Nov 2018, 16:58:08.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please CLEAR YOUR CACHE after each session.

## Session Transaction History

S/No	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction
1	Vehicle	GY3877C	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49

## Enquire Vehicle &amp; Owner Information ( Vehicle No. GY3877C As At 19 Oct 2018 / 14:45:00 )

## Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: AS.182316.LN

## Current Owner Details

Owner ID Type: Company

Owner ID: 199903182D

Owner Name: PROPELL INTEGRATED PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 15

Registered Street Name: BUKIT BATOK STREET 22

Registered Unit No.: # 06 - 00

Registered Building Name: PROPELL BUILDING

Registered Postal Code: 659586

## Current Vehicle Details

Vehicle No.: GY3877C

Make Description/Model: NISSAN / CABSTAR G

Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

## INVOICE

M/s. Royal Autoworkz Pte Ltd  
C/o. 13 Kaki Bukit Road 4  
#01-20 Bartley Biz Centre  
Singapore 417807


Invoice No. : HA/1811-09

Date : 03/11/2018

Descriptions	Amount (SGD)
Services rendered for appraiser / inspection report :-	
Survey Fee	
Photographs	
Transport Fees	
Re-inspection Fees	
Total :	SGD : \$ 670.00
SGD Dollar : Six Hundred Seventy Dollars Only.	
Our Reference : PAS/TP/0471018	
Vehicle No. : GBF4096S	
Make & Model : Toyota Hiace (Van)	
Your Claim No. : Third Party Claim	

### Notes:

All cheque payment should be Crossed and made payable to "PROMINENT APPRAISER SERVICES PTE LTD".  
Please indicate our "INVOICE NO." on the reverse side of the cheque.  
Should you have any enquiries, please do not hesitate to contact us.



For PROMINENT APPRAISER SERVICES PTE LTD



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)  
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

## VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0471018

Date of Report : 03/11/2018

To: M/s. Royal Autoworkz Pte Ltd  
C/o. 13 Kaki Bukit Road 4  
#01-20 Bartley Biz Centre  
Singapore 417807

Date of Assignment : 22/10/2018  
Report requested by : M/s. Royal Autoworkz Pte Lt  
Date of Accident : 19/10/2018  
Date of Inspection : 22/10/2018  
Claim No. : Third Party Claim  
Policy No. : -

### PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : GBF4096S  
Make & Model : Toyota Hiace (Van)  
Date of Registration : 20/10/2016  
Colour : Yellow

Engine Capacity (cc) : 2982cc  
Mileage (km) : 85559km  
Chassis / Frame No. : KDH2010204032  
Engine No. : 1KD2643889

### TYRE CONDITION

Front LH : 10 mm  
Make : Michelin

Front RH : 10 mm  
Make : Michelin

Rear LH : 10 mm  
Make : Michelin

Rear RH : 10 mm  
Make : Michelin

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

### PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good  
Paintwork : Good  
Handbrake : Serviceable  
Footbrake : Serviceable  
Steering : Serviceable  
Apparent Engine Modification : Nil

### PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Motor Intel Automo Pte. Ltd.  
13, Kaki Bukit Road 4, #01-20, Bartley Biz Centre, Singapore 417807

### ASSESSMENT

Repairer's Estimate : \$ 14,476.55  
Revised Amount : \$ 11,848.45  
Less Excess : \$ -  
Recommended Reserve : \$ 9,480.00 (Lump Sum)

Estimated Normal Period of Repairs : 8 Working Days

Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)  
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : GBF4096S

Report No. : PAS/TP/0471018

## GENERAL REMARKS

WITHOUT PREJUDICE

### THE ASSIGNMENT

The survey was conducted at M/s. Motor Intel Automo Pte. Ltd., 13, Kaki Bukit Road 4, #01-20, Bartley Biz Centre, Singapore 417807.

(Subsequent inspections have been conducted)

### POINT OF IMPACT

At the rear portion.

### DAMAGES

The tailgate, rear bumper, rear end panel, rear floor panel, rear chassis members, rear body panels, taillamps, etc.

*Other parts were also found damaged. (See schedule for details)*

### ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$11,848.45.

### CONCLUSION


The repairer has agreed to undertake the repairs at a lump sum of SGD \$9,480.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,  
Prominent Appraiser Services Pte Ltd

  
Andrew How  
Automobile Appraiser  
MSAAA  
Licensed Appraiser



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)  
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : GBF4096S

Report No. : PAS/TP/0471018

## APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (\$S)	Our Assessment (\$S)
1	1 pc	Tailgate	Dented	\$ 2,176.40	\$ 2,176.40 / 1950.10
2	1 pc	Rr windscreen adhesive dam kit	Necessary	\$ 91.20	\$ 91.20 /
3	1 pc	Tailgate wiper motor	Refit	\$ 599.20	\$ - /
4	2 pcs	Tailgate hinge R/L	Bent/Repair \$ 75.60	\$ 151.20	\$ - /
5	2 pcs	Tailgate stay support R/L	Bent/Jammed \$ 290.40	\$ 580.80	\$ 580.80 / NN
6	1 pc	Tailgate no.plate garnish	Dented/Cracked	\$ 157.80	\$ 157.80 /
7	1 pc	Tailgate reverse camera	Dented/Damaged	\$ 612.30	\$ 612.30 / XNF
8	1 pc	Tailgate emblem (Logo)	Dented/Necessary	\$ 80.10	\$ 80.10 /
9	1 pc	Tailgate sticker (HIACE)	Necessary	\$ 38.60	\$ 38.60 /
10	1 pc	Tailgate sticker (Super GL)	Necessary	\$ 36.20	\$ 36.20 /
11	1 pc	Tailgate weatherstrip	Torn/Necessary	\$ 391.20	\$ 391.20 /
12	1 pc	Tailgate inner trim board	Dented/Deformed	\$ 171.70	\$ 171.70 / CRA
13	16 pcs	Tailgate inner trim board clip	Necessary \$ 5.00	\$ 80.00	\$ 80.00 / 30
14	2 pcs	Tailgate stopper R/L	Refit \$ 41.30	\$ 82.60	\$ - /
15	1 pc	Tailgate auto lock closer	Dented/Jammed	\$ 843.80	\$ 843.80 /
16	1 pc	Tailgate lock control	Dented/Damaged	\$ 479.90	\$ 479.90 /
17	1 pc	Tailgate lock	Dented/Jammed	\$ 264.70	\$ 264.70 /
18	1 pc	Tailgate lock striker	Bent	\$ 103.20	\$ 103.20 /
19	2 pcs	Taillamp R/L	LH Broken/Cracked \$ 386.70	\$ 773.40	\$ 773.40 /
20	2 pcs	Taillamp lower cover R/L	LH Dented/Cracked \$ 128.40	\$ 256.80	\$ 256.80 /
21	1 pc	Rr bumper	Dented	\$ 432.80	\$ 432.80 /
22	1 pc	Rr bumper reinforcement	Dented	\$ 266.10	\$ 266.10 /
23	6 pcs	Rr bumper clip	Necessary \$ 3.20	\$ 19.20	\$ 19.20 /
24	2 pcs	Rr bumper retainer R/L	Cracked/Necessary \$ 32.70	\$ 65.40	\$ 65.40 /
25	4 pcs	Rr bumper bracket R/L	Dented/Bent \$ 25.80	\$ 103.20	\$ 103.20 /
26	2 pcs	Rr taillamp panel R/L (split)	LH Dented/Distorted \$ 274.30	\$ 548.60	\$ 274.30 /
27	1 pc	Rr end panel assy	Dented	\$ 804.50	\$ 804.50 /
28	1 pc	Rr end panel top garnish	Dented/Deformed	\$ 116.70	\$ 116.70 /
29	2 pcs	Rr air vent R/L	Refit \$ 62.60	\$ 125.20	\$ - /
30	1 pc	Rr lock antenna	Dented/Broken	\$ 162.40	\$ 162.40 /
31	1 pc	Rr body panel LH	Dented/Repair	\$ 1,498.30	\$ - /
32	2 pcs	Rr body panel inner trim R/L	Cracked/Deformed \$ 846.20	\$ 1,692.40	\$ 1,692.40 /
33	1 pc	Rr spare tyre carrier	Dented/Bent	\$ 281.40	\$ 281.40 /
34	1 pc	Rr spare tyre carrier lock assy	Dented/Bent	\$ 108.10	\$ 108.10 /
35	1 pc	Rr body panel RH	Dented/Repair	(Refer labour no. 2, 5, 6 & 7)	
36	1 pc	Rr floor panel	Dented/Repair	(Refer labour no. 2, 5, 6 & 7)	
37	2 pcs	Rr chassis member R/L	Dented/Repair	(Refer labour no. 2, 5, 6 & 7)	
				\$ 14,195.40	\$ 11,464.60
Less Discount : 25%				\$ 3,548.85	\$ 2,866.15
List Parts Sub-Total :				\$ 10,646.55	\$ 8,598.45
1	1 pc	Rr windscreen sealant	Necessary S/N	\$ 40.00	\$ 40.00 /
2	1 pc	Tailgate sticker (70km/h)	Necessary S/N	\$ 20.00	\$ 20.00 /
3	1 pc	Rr end panel sealant	Necessary S/N	\$ 40.00	\$ 40.00 /
Special Nett Sub-Total :				\$ 100.00	\$ 100.00
Parts Total :				\$ 10,746.55	\$ 8,698.45



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : GBF4096S

Report No. : PAS/TP/0471018

S/No.	Labour Descriptions	Repairer's Estimate (\$\$)	Our Assessment (\$\$)
1	To check rear electrical wiring system.	\$ 60.00	\$ 50.00 / 30
2	To remove and reinstall rear trim boards, garnishes, etc. for necessary repairs.	\$ 150.00	\$ 120.00 / 60
3	To transfer tailgate component parts to new tailgate.	\$ 100.00	\$ 80.00 / 50
4	To transfer rear windscreen to new tailgate.	\$ 120.00	\$ 120.00 / 100
5	To conduct chassis alignments.	\$ 320.00	\$ 300.00 / NBI
6	To straighten, repair, realign on affected area and replace damaged parts.	\$ 1,500.00	\$ 1,320.00 800/
7	To spray painting, blending on affected and adjacent area.	\$ 1,400.00	\$ 1,100.00 900/
8	To spray anti-rust coating on new and affected panels.	\$ 80.00	\$ 60.00 /
Labour Total :		\$ 3,730.00	\$ 3,150.00
Total (Parts & Labour) :		\$ 14,476.55	\$ 11,848.45

6 days

## For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 9,480.00

Under normal circumstances, the repairs should be completed within a reasonable period of 8 Working Days. (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

40 Photographs were taken at the time of inspection.

**N.B:** By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

Note: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Oct 2018		23 Oct 2018 11:19 <a href="#">Edit Adj Rpt</a>	<b>S\$5,800.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,800.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	PROPELL INTEGRATED PTE LTD, Co. Reg. No.: 0		
Main Claimant:	ROYAL AUTOWORKZ PTE LTD, Co. Reg. No.: 201716451W		
Vehicle Reg. No.:	GBF4096S	Date of Loss:	19/10/2018 00:00 - :59 [23 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-001411	Policy/Cover Note No.:	MSD/VCFT/18-000498 Coverage: 21/03/2018 - 20/03/2019
Vehicle Reg. No. (Insured):	GY3877C	Policy No. (Claimant):	
		Excess:	
Repairer:	Motor Intel Automo Pte Ltd (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 13/12/2018]		
Adj Asg. Remarks:	Liability unclear. Non Reporting. Contact Person: Mr Richard / 6281 0087. TP disagree with SJE list. Proceed to appoint LKK Auto Consultants as the SJE.		

### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- MSIG\_SG (11/12/2018): Report Send Back Alerts - GBF4096S (TP)

### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*GBF4096S (MSC/V/18-001411)  
[GY3877C]

TP

ROYAL AUTOWORKZ PTE LTD  
Oct 19 2018 12:00AM  
[PROPELL INTEGRATED PTE LTD]  
Motor Intel Automo Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/10/18 14:21	General View	1 Load JPG	✓
2	27/10/18 14:21	General View	1 Load JPG	✓
3	27/10/18 14:21	General View	1 Load JPG	✓
4	27/10/18 14:21	General View	1 Load JPG	✓
5	27/10/18 14:21	General View	1 Load JPG	✓
6	27/10/18 14:21	General View	1 Load JPG	✓
7	27/10/18 14:21	General View	1 Load JPG	✓
8	27/10/18 14:21	General View	1 Load JPG	✓
9	27/10/18 14:21	General View	1 Load JPG	✓
10	27/10/18 14:21	General View	1 Load JPG	✓
11	27/10/18 14:21	General View	1 Load JPG	✓
12	27/10/18 14:21	General View	1 Load JPG	✓
13	27/10/18 14:21	General View	1 Load JPG	✓
14	27/10/18 14:21	General View	1 Load JPG	✓
15	27/10/18 14:24	Photographs of Damaged Parts	1 Load JPG	✓
16	27/10/18 14:24	Photographs of Damaged Parts	1 Load JPG	✓
17	27/10/18 14:24	Photographs of Damaged Parts	1 Load JPG	✓
18	27/10/18 14:24	Photographs of Damaged Parts	1 Load JPG	✓
19	27/10/18 14:24	Photographs of Damaged Parts	1 Load JPG	✓
20	27/10/18 14:24	Photographs of Damaged Parts	1 Load JPG	✓
21	27/10/18 14:24	Photographs of Damaged Parts	1 Load JPG	✓
22	27/10/18 14:24	Photographs of Damaged Parts	1 Load JPG	✓
23	27/10/18 14:24	Photographs of Damaged Parts	1 Load JPG	✓
24	27/10/18 14:24	Photographs of Damaged Parts	1 Load JPG	✓
25	27/10/18 14:24	Photographs of Damaged Parts	1 Load JPG	✓
26	27/10/18 14:24	Photographs of Damaged Parts	1 Load JPG	✓
27	27/10/18 14:24	Photographs of Damaged Parts	1 Load JPG	✓
28	27/10/18 14:24	Photographs of Damaged Parts	1 Load JPG	✓
29	27/10/18 14:24	Photographs of Damaged Parts	1 Load JPG	✓
30	27/10/18 14:24	Photographs of Damaged Parts	1 Load JPG	✓
31	27/10/18 14:24	Photographs of Damaged Parts	1 Load JPG	✓
32	27/10/18 14:24	Photographs of Damaged Parts	1 Load JPG	✓
33	27/10/18 14:24	Photographs of Damaged Parts	1 Load JPG	✓
34	27/10/18 14:24	Photographs of Damaged Parts	1 Load JPG	✓
35	27/10/18 14:24	Photographs of Damaged Parts	1 Load JPG	✓

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	✓
37	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	✓
38	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	✓
39	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	✓
40	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	✓
41	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	✓
42	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	✓
43	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	✓
44	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	✓
45	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	✓
46	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	✓
47	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	✓
48	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	✓
49	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/10/18 15:22	Notice of PRI	Load PDF	
2	22/10/18 15:23	Email - PRI	Load PDF	
3	14/11/18 12:27	OI GY3877C accident report	Load PDF	
4	10/12/18 19:57	LOD, Final repair, Rental, GBF4096S report & Lta search	Load PDF	
5	10/12/18 19:57	Survey Report	Load PDF	
6	10/12/18 19:57	Survey Photos	Load PDF	
7	10/12/18 19:59	Survey Photos	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/01/19 15:40	PRS INVOICE	Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/MSG18019222/GQBS2-1  
**Date:** 04/01/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VCFT/18-000498  
**Claimant Vehicle No :** GBF4096S **Insured Vehicle No :** GY3877C  
 Date of Loss: 19/10/2018 Nature of Claim: TP Claim No: MSC/V/18-001411

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF4096S**  
 Make & Model: TOYOTA HIACE, 3.0 (A) Engine No: 1KD2643889  
 Reg. Date: 20/10/2016 (Man. Year: 2016) Chassis No: KDH2010204032  
 Colour: Yellow Odometer: 85559 km  
 Engine Capacity: 2982 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15  
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,746.55	5,290.60	5,455.95	50.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,730.00	2,000.00	1,730.00	46.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,476.55</b>	<b>7,290.60</b>	<b>7,185.95</b>	<b>49.64</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,800.00</b>		
<b>(S\$)</b>	14,476.55	5,800.00	8,676.55	59.94
<b>+ GST 7.00/7.00% (S\$)</b>	1,013.36	406.00	607.36	59.94
<b>Nett Amount (S\$)</b>	<b>15,489.91</b>	<b>6,206.00</b>	<b>9,283.91</b>	<b>59.94</b>

INSPECTION

Date of Assignment: 23/10/2018  
 Date Inspected: 23/10/2018 Inspected At: Motor Intel Automo Pte Ltd - Kaki Bukit (HQ)  
 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre  
 Singapore 417807  
 Estimated Period of Repair: 6.0 days

**Adjuster:** XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

*any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 04 Jan 2019)	
<b>Parts:</b>	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBF4096S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,176.40 FL	*1,950.10 FL
2	1		*RR WINDSCREEN ADHESIVE DAM KIT	Necessary	91.20 FL	*91.20 FL
3	1		*TAILGATE WIPER MOTOR	Not Necessary	599.20 FL	*- FL
4	2		*TAILGATE HINGE R/L	Repair	151.20 FL	*- FL
5	2		*TAILGATE STAY SUPPORT R/L	Not Necessary	580.80 FL	*- FL
6	1		*TAILGATE NO. PLATE GARNISH	Dented / Cracked	157.80 FL	*157.80 FL
7	1		*TAILGATE REVERSE CAMERA	Not fitted	612.30 FL	*- FL
8	1		*TAILGATE EMBLEM (LOGO)	Dented / Necessary	80.10 FL	*80.10 FL
9	1		*TAILGATE STICKER (HIACE)	Necessary	38.60 FL	*38.60 FL
10	1		*TAILGATE STICKER (SUPER GL)	Necessary	36.20 FL	*36.20 FL
11	1		*TAILGATE WEATHERSTRIP	Torn / Necessary	391.20 FL	*391.20 FL
12	1		*TAILGATE INNER TRIM BOARD	Cracked	171.70 FL	*171.70 FL
13	1		*TAILGATE INNER TRIM BOARD CLIP 16pcs	Necessary	80.00 FL	*30.00 FL
14	2		*TAILGATE STOPPER R/L	Not Necessary	82.60 FL	*- FL
15	1		*TAILGATE AUTO LOCK CLOSER	Not Necessary	843.80 FL	*- FL
16	1		*TAILGATE LOCK CONTROL	Not Necessary	479.90 FL	*- FL
17	1		*TAILGATE LOCK	Dented / Jammed	264.70 FL	*125.70 FL
18	1		*TAILGATE LOCK STRIKER	Repair	103.20 FL	*- FL
19	1		*TAILLAMP R/L	N/s Broken / O/s Not Necessary	773.40 FL	*386.70 FL
20	1		*TAILLAMP LOWER COVER R/L	N/s Dented / Cracked	256.80 FL	*128.40 FL
21	1		*RR BUMPER	Dented	432.80 FL	*432.80 FL
22	1		*RR BUMPER REINFORCEMENT	Dented	266.10 FL	*266.10 FL
23	6		*RR BUMPER CLIP	Necessary	19.20 FL	*19.20 FL
24	2		*RR BUMPER RETAINER R/L	Cracked / Necessary	65.40 FL	*65.40 FL
25	4		*RR BUMPER BRACKET R/L	Dented / Bent	103.20 FL	*103.20 FL
26	2		*RR TAILLAMP PANEL R/L	Repair	548.60 FL	*- FL
27	1		*RR END PANEL ASSY	Dented	804.50 FL	*804.50 FL
28	1		*RR END PANEL TOP GARNISH	Dented / Deformed	116.70 FL	*116.70 FL
29	2		*RR AIR VENT R/L	Not Necessary	125.20 FL	*- FL
30	1		*RR LOCK ANTENNA	Dented / Broken	162.40 FL	*162.40 FL
31	1		*RR BODY PANEL LH	Repair	1,498.30 FL	*- FL
32	2		*RR BODY PANEL INNER TRIM R/L	Cracked / Deformed	1,692.40 FL	*1,382.80 FL
33	1		*RR SPARE TYRE CARRIER	Repair	281.40 FL	*- FL
34	1		*RR SPARE TYRE CARRIER LOCK ASSY	Repair	108.10 FL	*- FL
35	1		*RR BODY PANEL RH (NPA)	Repair	0.00 FL	*- FL
36	1		*RR FLOOR PANEL (NPA)	Repair	0.00 FL	*- FL
37	2		*RR CHASSIS MEMBER R/L (NPA)	Repair	0.00 FL	*- FL
38	1		*RR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
39	1		*TAILGATE STICKER (70KM/H)	Necessary	20.00 FS	*15.00 FS
40	1		*RR END PANEL SEALANT	Necessary	40.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Sub Total (S\$)	14,295.40
					- List Item Discount on L Items 25.00/25.00% (S\$)	3,548.85
					Total Parts (S\$)	10,746.55

7,025.80

1,735.20

5,290.60

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK ELECTRICAL WIRING SYSTEM.	New	60.00	30.00
2	TO REMOVE AND REINSTALL REAR TRIM BOARDS, GARNISHES, ETC. FOR NECESSARY REPAIRS.	New	150.00	60.00
3	TO TRANSFER TAILGATE COMPONENTS PARTS TO NEW TAILGATE.	New	100.00	50.00
4	TO TRANSFER REAR WINDSCREEN TO NEW TAILGATE.	New	120.00	100.00
5	TO CONDUCT CHASSIS ALIGNMENTS.	New	320.00	0.00
6	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS.	New	1,500.00	800.00
7	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA.	New	1,400.00	900.00
8	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.	New	80.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>3,730.00</b>	<b>2,000.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >