

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Milah Yeo

Date: 18 Dec 2018

Preliminary Advice

Vehicle No	: SJT1805P	Accident Date	: 29/11/2018
Make	: TOYOTA COROLLA ALTIS	Policy No.	: A27764943QMX
Assignment Date	: 11/12/2018	Excess	: S\$500.00
Date of Inspection	: 11/12/2018	Est. Duration of Repair	: 4 days
Inspection At	: WTS Automotive Services Pte Ltd (HQ) 17 Kaki Bukit Road 4 #01-58/59/60/61/62, Bartley Biz Centre Singapore 417809		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,400.00
Revised Amount	:S\$	2,721.83
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,721.83

Lump Sum Repair	:S\$	2,150.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	16,000.00
COE / PARF Rebate	:S\$	10,357.00
Salvage Value	:S\$	
Margin for Repair	:S\$	5,643.00

Remarks

(X) The vehicle is economical for repair. Repairer repair on lump sum basis.

() The above survey was conducted on a 'without prejudice' basis.