

ASS. REC. BY:

REF:

CS/FCI18022256/Gtd3m

Special Instruction:

Surveyor: Guo (Brone)
KWS

ASSIGNMENT (Office)

From (Person): Eileen Lee

of

FCI

Date/Time: 11:19am @ 11/12/18

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJH 8017R

Insured:

SHB 3328E

at Workshop m/s:

Car Times Autolub

Tel:

6471 5111

of

160 Sir Ming Drive #02-04

Policy No:

Claim No:

D18008739MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09/12/18

CA / REV / REP. / REV 24 HRS

(Ds)

H.O.D. Endorsement:

Date/Time: 12:39pm @

Person Contacted:

Angel

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SJH 8017R-X

SHB 3328E-X

17/Dec- 2:43pm - Revised preli advise via email.


Karl

REF: fci

6148A

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Car Times Antelution
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt.: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLH 8017R Yr Regn: 18 Nov 2016
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda Accel c.c. 1496
 Colour: Red A/C: Insured / Std / NI / NA
 Sp. Reading: 27964 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RH 11 205 265
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 245/60 R16
 R: u
 BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 11-12-18
 Survey held at w/s 5:30pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

11/12 Finalized \$1322 with Ange / (Red: 5092.60; 79%)

RECEIVED 18 DEC 2018

Date/Time, File Pass to? ☐ : Preli. Report
 1) 12 Typist ☒ : Final Report
 Date/Time, File Return to?

Days Of Repair: 3
 Resurvey No. of Trip: 1

Survey Fee: 145
 Transportation: 50
 S + RS: SI
 Photos: 25
 Others: _____

Report Format: _____
 Lump Sum / L.S.: (\$ 1322)

Add Fee: ☐ : Site Insp. (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

TOTAL

220



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008739MFSH

Date: 17/12/2018

Our Ref: CS/FCI18022256/Gtd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLH 8017R

Please be informed that we had conducted the inspection of the abovementioned vehicle 11/12/2018 at the premises of M/s Car Times Autolution have the following to report: -

Workshop Estimate Amount	: S\$ 6,414.60
Revised Estimate Amount	: S\$ 1,322.00
"Check" Items Amount	: S\$ -
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Guo Qiang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	10-12-2018	Our Ref No. D18008739MFSH
Accident Date	09-12-2018	Claim Type. Third Party
Insured Vehicle	SHB3328E	Third Party Vehicle. SLH8017R
Survey Location	160 SIN MING DRIVE AUTOCITY #02-04	
Contact Person.	ANGEL LIM	
Contact No.	64715111/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE; WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CAR TIMES AUTOLUTION PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 17 December 2018 2:43 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008739MFSH/1
Attachments: PRELI ADVISED SLH 8017R.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SKU 3291R**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 11 December 2018 12:40 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008739MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 11 December 2018 11:49 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008739MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	6148A

Vehicle Details

Vehicle No.:	SLH8017R
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Dec 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	L15B4405265
Chassis No.:	RU11205265
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$22,284.00
Original Registration Date:	18 Nov 2016
First Registration Date:	18 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$13,198.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Nov 2026
PARF Rebate Amount:	\$9,898.00

Intended COE Rebate Details

COE Expiry Date:	17 Nov 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,668.00
COE Rebate Amount:	\$41,768.00
Total Rebate Amount:	\$51,666.00

The information contained herein is correct as at 12 Dec 2018

OK

CARTIMES

autolution

17/12
C.

Vehicle No. SLH 8017 R

MODEL: HONDA VEZEL

PG.


QTY	DESCRIPTION	REPAIRER'S ESTIMATE(\$\$)	SURVEY ADJUST
PARTS (LIST ITEMS)			
1	TAILGATE Repair X NN	965.00	
1	HONDA LOGO X	26.00	
1	VEZEL WORDING - AL	45.00	/
2	TAILGATE TAILLAMP LHS & RHS X NN	530.00	
1	REAR BUMPER - ee	510.00	/
2	REFLECTOR LHS & RHS X	302.00	
1	REAR END PANEL X	451.00	
1	REAR END PANEL TOP GARNISH X	55.00	
1	TAILGATE WEATHER STRIP X	110.00	
1	TAIL GATE LOCK X	125.00	
1	TAIL GATE INNER GARNISH X	195.00	
1	REAR BUMPER UNDER CARRIAGE COVER X	125.00	
2	REAR BUMPER LHS & RHS TOP COVER X	302.00	
1	TAILGATE OPENER X	126.00	
1	REAR WINDSCREEN MOULDING X	180.00	
1	SMART BUZZER X	95.00	
1	KEY ANTENNA X	110.00	
1	REAR BUMPER LOWER CHROME - Cut	185.00	/
		4437.00	
		20% 887.40	20%
		3549.60	
SPECIAL NETT ITEMS			
1	Rear number plate w/holder X NN	45.00	
1 set	Rear Bumper clips - AL	60.00	30
1	Rear windscreen sealant X	100.00	
1 set	Reverse sensor X	280.00	
1 set	Tailgate inner trim clips X NN	60.00	
		545.00	
TOTAL PART		4094.60	

Vehicle No.SLH 8017 R

MODEL: HONDA VEZEL

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEY OF ADJUSTME
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	900.00	400
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	600.00	200
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	150.00	X NN
4	To remove and refix/replace rear trims, garnish and fittings so as to facilitate repairs at rear compartment	250.00	60.
5	To remove and replace reverse sensors & reverse camera and check for proper function	150.00	40
6	To remove and refix rear tailgate windscreen	150.00	X { NN
7	To provide anti-rust treatment on affected areas	120.00	X { NN
	Labour Total :	2320.00	
	TOTAL (PARTS & LABOUR):	6414.60	

3 Days.


 17/12/18

1322

part by part.

before paint photos.

After paint photos.

Gino Ariz

11/12/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18022256/Gtd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3328E	Veh. Inspected	SLH 8017R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008739MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	11/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU11205265	Colour	RED	
Odometer	27964	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/12/2018	Inspection Date	11/12/2018	
Survey held at	160 SIN MING DRIVE# 02-04			
Repairer	CAR TIMES AUTOLUTION PTE LTD			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 8017R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE	TO REPAIR SEE LABOUR	965.00	-
1	HONDA LOGO	NOT NECESSARY	26.00	-
1	VEZEL WORDING	NECESSARY	45.00	45.00
2	TAILGATE TAILLAMP LHS & RHS	NOT NECESSARY	530.00	-
1	REAR BUMPER	DEFORMED	510.00	510.00
2	REFLECTOR LHS & RHS	NOT NECESSARY	302.00	-
1	REAR END PANEL	NOT NECESSARY	451.00	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	55.00	-
1	TAILGATE WEATHER STRIP	NOT NECESSARY	110.00	-
1	TAIL GATE LOCK	NOT NECESSARY	125.00	-
1	TAIL GATE INNER GARNISH	NOT NECESSARY	195.00	-
1	REAR BUMPER UNDER CARRIAGE COVER	NOT NECESSARY	125.00	-
2	REAR BUMPER LHS & RHS TOP COVER	NOT NECESSARY	302.00	-
1	TAILGATE OPENER	NOT NECESSARY	126.00	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	180.00	-
1	SMART BUZZER	NOT NECESSARY	95.00	-
1	KEY ANTENNA	NOT NECESSARY	110.00	-
1	REAR BUMPER LOWER CHROME	CUT	185.00	185.00
	LESS 20% DISCOUNT		-887.40	-148.00
			3,549.60	592.00
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE W/HOLDER (SN)	NOT NECESSARY	45.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	100.00	-
1	SET REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
1	SET TAILGATE INNER TRIM CLIPS (SN)	NOT NECESSARY	60.00	-
			545.00	30.00

Report Ref No. CS/FC118022256/Gtd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF TAILGATE.		900.00	400.00
	TO SUPPLY PAINT MATERIALS; EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		600.00	200.00
	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIX/REPLACE REAR TRIMS, GARNISH AND FITTINGS SO AS TO FACILITATE REPAIRS AT REAR COMPARTMENT.		250.00	60.00
	TO REMOVE AND REPLACE REVERSE SENSORS & REVERSE CAMERA AND CHECK FOR PROPER FUNCTION.		150.00	40.00
	TO REMOVE AND REFIX REAR TAILGATE WINDSCREEN.	NOT NECESSARY	150.00	-
	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS.	NOT NECESSARY	120.00	-
			2,320.00	700.00
	GRAND TOTAL		6,414.60	1,322.00
	RECOMMENDED COST OF REPAIRS			1,322.00

Report Ref No. CS/FCI18022256/Gtd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

CARTIMES

autolution

Vehicle No. SLH 8017 R

MODEL: HONDA VEZEL

PG.1

QTY	DESCRIPTION	REPAIRER'S ESTIMATE(S\$)	SURVEYORS ADJUSTMENT
PARTS (LIST ITEMS)			
1	TAILGATE <i>Repair X</i>		
1	HONDA LOGO <i>X</i>	965.00	
1	VEZEL WORDING <i>- AC</i>	26.00	
2	TAILGATE TAILLAMP LHS & RHS <i>X NN</i>	45.00	/
1	REAR BUMPER <i>- AC</i>	530.00	
2	REFLECTOR LHS & RHS <i>X</i>	510.00	/
1	REAR END PANEL <i>X</i>	302.00	
1	REAR END PANEL TOP GARNISH <i>X</i>	451.00	
1	TAILGATE WEATHER STRIP <i>X</i>	55.00	
1	TAIL GATE LOCK <i>X</i>	110.00	
1	TAIL GATE INNER GARNISH <i>X</i>	125.00	
1	REAR BUMPER UNDER CARRIAGE COVER <i>X</i>	195.00	
2	REAR BUMPER LHS & RHS TOP COVER <i>X</i>	125.00	
1	TAILGATE OPENER <i>X</i>	302.00	
1	REAR WINDSCREEN MOULDING <i>X</i>	126.00	
1	SMART BUZZER <i>X</i>	180.00	
1	KEY ANTENNA <i>X</i>	95.00	
1	REAR BUMPER LOWER CHROME <i>- Cut</i>	110.00	
		185.00	/
		4437.00	
	20%	887.40	20%
		3549.60	
SPECIAL NETT ITEMS			
1	Rear number plate w/holder <i>X NN</i>		
1 set	Rear Bumper clips <i>- AC</i>	45.00	
1	Rear windscreen sealant <i>X</i>	60.00	
1 set	Reverse sensor <i>X</i>	100.00	
1 set	Tailgate inner trim clips <i>X NN</i>	280.00	
		60.00	
		545.00	
	TOTAL PART	4094.60	

740
20%: 592