

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 13 Dec 2018

Preliminary Advice

Insured Vehicle No : SLS8217Y

TP Vehicle No : SLL5805G

Make : BMW X6 XDRIVE

Date of Inspection : 11/12/2018

Inspection At : Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby Performance Centre
Singapore 159941

Accident Date : 06/11/2018

Assignment Date : 11/12/2018

Est. Duration of Repair : 3 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,253.25
Revised Amount	:S\$	4,351.40
Check Items (Estimated)	:S\$	2,197.65
Total	:S\$	6,549.05

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.