

ASS. REC. BY:

REF: CS/E6718022263/Usbnz

Special Instruction:

Surveyor

**ASSIGNMENT (Office)**

From (Person): Yee Poi Li of E61 Date/Time: 11.12.2018 1021am

Estimated Cost: Bill to:

OB / FD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBD 4165L Insured: SJX 8023L

at Workshop m/s Yew Tee Automobile Tel:

of Bk 6 Yew Tee Ind Est 399F

Policy No: Claim No: SJX 8023L / SL / pl

Sum Insured: Excess:

Make of Veh: D.O.A. 06.12.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

12/12/2018 @ 5pm owner waiting

H.O.D. Endorsement:

Date/Time: 11.12.2018 10.28am Person Contacted: Vinnie Vehicle: IN / OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	GBD 4165L - X
	SJX 8023L - X

REF: EGI

## ASSIGNMENT

From: Date: 12/12/18  
 Estimated Cost:  
 OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: GBD 4165L  
 at Workshop n/s: Yew Tee Automobile  
 of: Blk 6, Yew Tee Ind. Est 399F  
 Insured:  
 Policy No:  
 Claims No:  
 Sum Insured: Excess:  
 (Client's Record)  
 Make of Veh: Spm owner writing

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

Bal. or Market Value: 38  
 IDAC Accident Rpt: Consistent? : Yes or No  
 G/A / R Seen: Consistent? : Yes or No  
 Est. Repairs: 5 days Res: Yes or No  
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (DS) 43900  
 Date: Person Contacted: Vehicle: IN / OUT

Veh No: GBD 4165L Yt Regn: 10 14  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or Cam  
 Make: Nissan NV200 CC: 1461  
 Colour: white A/C: Insured / Std / NI / NA  
 Sp. Reading: 128769 T/Radio: Insured / Std / NI / NA  
 Eng/No:  
 C/No: VSKYBAM2020090332  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 175/70R14  
 R:  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Komendo  
 Front: 6 mm Rear: 6 mm  
 R/Bal: 6 mm L/Bal: 6 mm  
 D.O.A: 6/12/18 D.O.I: 12/12/18  
 Survey held at  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 Rear  
 The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 21 DEC 2018.

Date/Time: File Pass to? 21/12/18  
 1) Typist ☐ : Preli. Report  
☒ : Final Report

Days Of Repair: 5  
 Resurvey No. of Trip: 2

Survey Fee:  
 Transportation:

2)

Add Fee: ☐ Site Insp (\$)  
☐ Interview (\$)  
☐ Tech. Invs (\$)  
☐ Weekend (\$)

) S + RS \$  
 ) Photos  
 ) Others

Report Format :

Lump Sum / I.B.I: (\$ 5,200/- L/S )

350

TOTAL



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SJX8023L/SL/pl

Date: 13 December 2018

Our Ref: CS/EG18022263/Usb

The Motor Claims Department  
ERGO INSURANCE PTE LTD

Dear Sir/Madam,


**PRELIMINARY ADVICE OF VEHICLE NO. GBD 4165L .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/12/2018 at the premises of M/s Yew Tee Automobile Tech Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>11,222.57</u> .
Revised Estimate Amount	: S\$ <u>5,626.78</u> .
"Check" Items Amount	: S\$ <u>1,410.30</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

**Description of Damage:**

The vehicle sustained damages at the rear portion.



**Comments/ Present Status:**

Damages Consistent.

Repair days: 5 Days

Yours faithfully,  
Marcus Chua  
Automotive Assessor

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Thursday, 13 December 2018 4:51 PM  
**To:** 'Yee Pei Li'; 'Survey Report (ERGO Insurance Pte. Ltd.)'  
**Cc:** assignments; SUR; Admin-D (LKKAuto)  
**Subject:** RE: SJX8023L / TP : GBD4165L/LKK / DOA : 06/12/2018  
**Attachments:** GBD 4165L - Preli Advise .pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle GBD 4165L.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]  
**Sent:** Tuesday, 11 December 2018 10:27 AM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>  
**Cc:** assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** RE: SJX8023L / TP : GBD4165L/LKK / DOA : 06/12/2018

Dear Pei Li,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]  
**Sent:** Tuesday, 11 December, 2018 10:21 AM  
**To:** 'admin-d@lkkauto.com' <admin-d@lkkauto.com>  
**Cc:** 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>  
**Subject:** OI : SJX8023L / TP : GBD4165L/LKK / DOA : 06/12/2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

## Catherine Chong (LKK Auto)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Tuesday, 11 December, 2018 10:21 AM  
**To:** 'admin-d@lkkauto.com'  
**Cc:** 'ASSIGNMENTS@LKKAUTO.COM'  
**Subject:** OI : SJX8023L / TP : GBD4165L/LKK / DOA : 06/12/2018  
**Attachments:** SJX8023L - SAS.pdf; GBD4165L - SAS.pdf; GBD4165L - PRS FORM.pdf

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **YEW TEE AUTOMOBILE TECH PTE LTD**,

ADDRESS : BLK 6 WOODLANDS ROAD 399F  
YEW TEE INDUSTRIAL ESTATE  
SINGAPORE 678006

PERSON TO CONTACT : VINNIE LIM @ 6765 3373 / 6762 2081 / 6764 9042

ERGO OFFICER-IN-CHARGE : STEVE LIM

***Note: To survey on DIRECT SETTLEMENT basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.***

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards,  
Yee Pei Li  
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five  
Singapore 038985  
DID : +65 6829 9194  
Tel. : +65 6829 9199  
Fax : +65 6829 9247

[www.ergo.com.sg](http://www.ergo.com.sg)

# ERGO

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

# ERGO

Date: 11.12.2018  
Our Reference: SJX 8023L/SL/pl  
Your Reference: GBD 4165L

Sent via Fax

or

Email

info@yewteegroup.com

To: YEW TEE AUTOMOBILE TECH PTE LTD

## Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: GBD 4165L  
Insured's Vehicle: SJX 8023L  
Date Of Accident: 06.12.2018


We acknowledge receipt of your request for PRS on: 07.12.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked \*.

\* LKK Auto Consultants P/L

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.  
☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.  
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.  
☐ Our Insured's driver has not reported the accident to us to date.  
☒ Others: OFFICER-IN-CHARGE - STEVE LIM

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

### Assessor use only:

Assignment Date: \_\_\_\_\_  
Assignment Time: \_\_\_\_\_

Remarks:

### Workshop use only:

#### Assessor attended workshop on:

Date: \_\_\_\_\_  
Time: \_\_\_\_\_  
Inspector: \_\_\_\_\_

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

## Das WeltAuto.

Used cars you can trust. Guaranteed.

## Some rides are better than others.

Brace yourself for adrenaline pumping offers on certified, pre-owned VW cars at the sgCarMart Carnival @ Downtown East.

Find out more



## Post an Advertisement

Sell it yourself! Advertise it at just

**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

## New 10 Years Coe Renewal Toyota Estima 2.4A



2.88% P.A. Lowest Interest @ GV  
Cars Financing \$5800  
Downpayment Monthly From \$900  
GV Credit Pte Ltd StarAd

**AutoIn**  
An Inspiration For Car & B.

click here to view  
our **PRISTINE USED**  
at GREAT







Browse by Category

Sort by Date Posted

9 vehicles

nv200

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
<b>Search Selection</b>	nv200		Any	Any	2014	Any	Any	Any
	Nissan	NV200 1.5M	\$37,800	\$7,010 /yr	05-May-2014	1,461 cc	-	Van
<b>Fuel Type:</b> Diesel 1 Owner! Excellent Condition, No Repair Needed, Bank Or In-House Available, High Trade-In And Price Negotiable. SG Motor Link Pte Ltd Posted: 12-Dec-2018 Tags: 2014 Nissan NV200, 2014 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan								
	Nissan	NV200 1.6A	\$37,000	\$6,630 /yr	12-Jul-2014	1,597 cc	-	Van
<b>Fuel Type:</b> Petrol Cheapest In Markt! 1 Owner Only. Low Mileage. Almost New Nissan NV200 Auto Model! Up To 100% Loan Available. Still In Its Original Condition (Paintwork, Etc). Seats Have Been Well Protected By Covers ... Car (S) Pte Ltd Posted: 10-Dec-2018 Tags: 2014 Nissan NV200, 2014 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan								
	Nissan	NV200 1.5M	\$37,000	\$6,980 /yr	31-Mar-2014	1,461 cc	120,000 km	Van
<b>Fuel Type:</b> Diesel Bought From Tan Chong Motor. Excellent And Original Condition And Accident-Free. Driven By Single Careful Owner And Not Workers. Fully Reg Serviced In Tan Chong From Day 1. Under Tan Chong 5 Yea... Posted: 01-Dec-2018 Tags: 2014 Nissan NV200, 2014 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan								
	Nissan	NV200 1.5M	\$37,800	\$6,370 /yr	17-Nov-2014	1,461 cc	-	Van
<b>Fuel Type:</b> Diesel Posted: 28-Nov-2018 Tags: 2014 Nissan NV200, 2014 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan								
	<b>Nissan to unveil two concept vehicles</b> Nissan will be revealing two customised vehicle concepts - the Paramedic Concept and the e-NV200 Fridge Concept - at the Tokyo Motor Show. Read this article							
	Nissan	NV200 1.5M	\$38,800	\$7,010 /yr	25-Jun-2014	1,461 cc	-	Van
<b>Fuel Type:</b> Diesel 1 Owner, Excellent Condition, Easy To Maintained, Fuel Efficient, Strong Engine, Book For Test Drive, No Obligation, We Are Able To Do 100% And High Trade In. 994) Pte Ltd ad: 27-Nov-2018 Tags: 2014 Nissan NV200, 2014 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan								

Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	4390C
<b>Vehicle Details</b>	
Vehicle No.:	GBD4165L
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Dec 2018
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5L MT ABS AIRBAG 2WD 6DR EURO 5
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	K9KC400D054017
Chassis No.:	VSKYBAM20Z0090332
Maximum Power Output:	-
Open Market Value:	\$20,286.00
Original Registration Date:	18 Oct 2014
First Registration Date:	18 Oct 2014
Transfer Count:	0
Actual ARF Paid:	\$1,015.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	17 Oct 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$49,901.00
COE Rebate Amount:	\$29,162.00
<b>Total Rebate Amount:</b>	<b>\$29,162.00</b>

The information contained herein is correct as at 13 Dec 2018

OK



**YEW TEE AUTOMOBILE TECH PTE LTD**

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

**Tel: 6702 3113 (3Lines) Fax: 6702 3773**

EMAIL: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

ROC: 200311009C GST: 200311009C

Website: [www.ytauto.com.sg](http://www.ytauto.com.sg)

ON BEHALF OF OWNER :

**Policy Particulars: - THIRD PARTY CLAIM**

Insured veh.	GBD4165L	Excess.	NIL
Policy No.	5084580188-02	Coverage.	Comprehensive
Claiming Against.	SJX8023L		
Insured Under.	NTUC	ERGO	

### Vehicle Particulars & Condition

Make & Model	Nissan NV200
Engine No.	K9KC400D054017
Chassis No.	VSKYBAM20Z0090332
Odometer	
Engine CC.	1461
Year Of Reg.	2014
Colour.	WHITE
Parf/COE Rebate.	

### Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

### Description Of Damages

Rear portion damaged.

### General Information

Accident Date. 6/12/2018

Survey held at

**Yew Tee Automobile Tech Pte Ltd**

Blk 6, unit 399F Woodlands Road, Yew Tee Industrial Estate, Singapore 678006

## Remarks

**KINDLY LET US HAVE THE LIABILITY SOON.**

### Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR: \_\_\_\_\_ Days

# YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

ROC: 200311009C GST: 200311009C

Website: [www.ytauto.com.sg](http://www.ytauto.com.sg)

Qty.	Description Of Parts	Pricing
1	Rear bumper 624.80	70/02 \$ 650.40
1	Rear door LH 1281.10	Body \$ 1,510.00
1	Rear door RH 960	Body \$ 1,470.00
1	Rear end panel inner-panel inner	R \$ 840.00 X
1	Rear carriage floor panel	R \$ 2,600.47 X
1	Rear fender RH	R Rpr X
		List \$ 7,070.87
		Less 30% \$ 2,121.26
		Total \$ 4,949.61
1	Rear bumper reflector LH	11 \$ 132.00 X
1	Rear bumper reflector RH	11 \$ 132.00 X
1	Rear door NV200 emblem LH	11 \$ 163.50
1	Rear door logo LH	11 \$ 76.40 X
1	Rear door top hinges LH	11 \$ 122.50 X
1	Rear door bottom hinges LH	11 \$ 122.50 X
1	Rear door rubber 97.30	11 \$ 280.00 ?
1	Rear door lock LH	11 \$ 330.00 ?
1	Rear door lock catch LH	11 \$ 67.00 ?
1	Rear door lock RH	11 \$ 330.00 ?
1	Rear door lock catch RH	11 \$ 67.00 X
1	Rear door DCI emblem RH 68.50	11 \$ 131.50 ?
1	Rear door top hinges RH	11 \$ 122.50 X
1	Rear door bottom hinges RH	11 \$ 122.50 X
1	Rear door vertical rubber RH	11 \$ 155.00 X
1	Rear taillamp LH	11 \$ 280.00 X
1	Rear taillamp RH 252.10	11 \$ 280.00 X
1	Rear end panel outer panel 598.40	300 \$ 650.00
		Nett \$ 3,564.40
		Less 10% \$ 356.44
		Total \$ 3,207.96

# YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

ROC: 200311009C GST: 200311009C

Website: [www.ytauto.com.sg](http://www.ytauto.com.sg)

Qty.	Description Of Parts	Pricing
1	Rear bumper clips	<i>ru</i> \$ 45.00 ✓
1	Rear 70 km/h sticker	<i>ru</i> \$ 15.00 10
1	Rear bumper sensors (set)	<i>short</i> \$ 260.00 200
1	Rear door glass sealant LH	<i>ru</i> \$ 60.00 40
1	Rear 6pax sticker	<i>ru</i> \$ 15.00 10
1	Rear door glass sealant RH	<i>ru</i> \$ 60.00 40
	S/N	\$ 455.00

## LABOUR

To apply undercoating on the repaired and replaced panels for rust protection.	\$ 80.00 ✓
To carry-out body cavity preservation.	\$ 60.00
To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts.	\$ 50.00 20
To remove and refit rear bumper sensors.	\$ 80.00 50
To dismantle and refit rear windscreen glass x 2.	\$ 120.00 ✓
To transfer rear door LH.	\$ 80.00 60
To transfer rear door RH.	\$ 80.00 60
To supply spray terostat sealant on the cutting areas.	<i>11</i> \$ 60.00 x
To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.	\$ 1,100.00 800
To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.	\$ 900.00 700

LABOUR \$ 2,610.00

Sub Total. \$ 11,222.57

7% GST \$ 785.58

Grand Total \$ 12,008.15

12636.74

*P-4773.10*  
*102*  
*7 + 4295.79*  
*S.N + 345.00*  
*1660 + 1890*  
*6530.79*  
*5224.*

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EG18022263/Usbn2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 24-12-2018		
		Code : EGI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJX 8023L	Veh. Inspected	GBD 4165L	
Policy No.		Coverage (\$)	0.00	
Claim No.	SJX8023L/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	11/12/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN NV200 (M)	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VSKYBAM20Z0090332	Colour	WHITE	
Odometer	128169	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	175/70 R14	KOMENDO	6 mm	
L/H Front Tyre	175/70 R14	KOMENDO	6 mm	
R/H Rear Tyre	175/70 R14	KOMENDO	6 mm	
L/H Rear Tyre	175/70 R14	KOMENDO	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	06/12/2018	Inspection Date	12/12/2018	
Survey held at	YEW TEE AUTOMOBILE TECH PL (HQ) BLK 6 WOODLANDS ROAD 399F YEW TEE IND. ESTATE SINGAPORE 678006			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 4165L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	DENTED / DEFORMED	650.40	624.80
1	REAR DOOR LH	BADLY DENTED	1,510.00	1,281.10
1	REAR DOOR RH	BADLY DENTED	1,470.00	960.00
1	REAR END PANEL INNER	TO REPAIR SEE LABOUR	840.00	-
1	REAR CARRIAGE FLOOR PANEL	TO REPAIR SEE LABOUR	2,600.47	-
1	REAR FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	132.00	-
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	132.00	-
1	REAR DOOR NV200 EMBLEM LH	NECESSARY	163.50	163.50
1	REAR DOOR LOGO LH	NOT NECESSARY	76.40	-
1	REAR DOOR TOP HINGES LH	NOT NECESSARY	122.50	-
1	REAR DOOR BOTTOM HINGES LH	NOT NECESSARY	122.50	-
1	REAR DOOR RUBBER	TORN	280.00	97.30
1	REAR DOOR LOCK LH	TWISTED / JAMMED	330.00	330.00
1	REAR DOOR LOCK CATCH LH	TWISTED	67.00	67.00
1	REAR DOOR LOCK RH	TWISTED / JAMMED	330.00	330.00
1	REAR DOOR LOCK CATCH RH	NOT NECESSARY	67.00	-
1	REAR DOOR DCI EMBLEM RH	NECESSARY	131.50	68.90
1	REAR DOOR TOP HINGES RH	NOT NECESSARY	122.50	-
1	REAR DOOR BOTTOM HINGES RH	NOT NECESSARY	122.50	-
1	REAR DOOR VERTICAL RUBBER RH	NOT NECESSARY	155.00	-
1	REAR TAILLAMP LH	NOT NECESSARY	280.00	-
1	REAR TAILLAMP RH	CRACKED	280.00	252.10
1	REAR END PANEL OUTER PANEL	BADLY DENTED	650.00	598.40
	LESS 10% DISCOUNT		-1,063.53	-477.31
			9,571.74	4,295.79
<b>SPECIAL NETT ITEMS</b>				
1	REAR BUMPER CLIPS (SN)	NECESSARY	45.00	45.00

Report Ref No. CS/EGI18022263/Usbn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR 70KM/H STICKER (SN)	NECESSARY	15.00	10.00
1	SET REAR BUMPER SENSORS (SN)	SHORTED	260.00	200.00
1	REAR DOOR GLASS SEALANT LH (SN)	NECESSARY	60.00	40.00
1	REAR 6PAX STICKER (SN)	NECESSARY	15.00	10.00
1	REAR DOOR GLASS SEALANT RH (SN)	NECESSARY	60.00	40.00
			455.00	345.00
	<b>LABOUR</b>			
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION. }		80.00	80.00
	TO CARRY-OUT BODY CAVITY PRESERVATION. }		60.00	-
	TO DISCONNECT AND RECONNECT,CHECK ELECTRICAL WIRING HARNESS WIRE,SOCKETS,REPLACE DAMAGED PARTS.		50.00	20.00
	TO REMOVE AND REFIT REAR BUMPER SENSORS.		80.00	50.00
	TO DOSMANTLE AND REFIT REAR WINDSCREEN GLASS X2.		120.00	120.00
	TO TRANSFER REAR DOOR LH.		80.00	60.00
	TO TRANSFER REAR DOOR RH.		80.00	60.00
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.	NOT NECESSARY	60.00	-
	TO REMOVE & REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN & REPAIR INCLUDING CUT & WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.INCLUSIVE OF THE REPAIR OF REAR END PANEL INNER,REAR CARRIAGE FLOOR PANEL AND REAR FENDER (RH).		1,100.00	800.00
	TO SPRAY PAINTING ON THE REPLACED & REPAIR PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPERS,CLEANING & SANDING OF SURFACES,FINAL POLISHING & WAXING ARE ALSO AVAILABLE.		900.00	700.00
	-		-	-
	-		-	-
	-		-	-
			2,610.00	1,890.00
	<b>GRAND TOTAL</b>		<b>12,636.74</b>	<b>6,530.79</b>

Report Ref No. CS/EGI18022263/Usbn2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,200.00
---	--	--	----------

Report Ref No. CS/EGI18022263/Usbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.