

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 7113U

MAKE :

MODEL : HYUNDAI i40

DATE 10/12/2018 14:45

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover X AXA			\$ 544.50
	Front Bumper Bracket Top (RH) ?			\$ 22.40
	Front Bumper Bracket (RH) ?			\$ 24.60
	Front Fender (RH) /			\$ 566.30
	Front Fender Shield (RH) X			\$ 175.90
	Front Fender Retainer X			\$ 24.60
	Front Wheel Hub Cap (RH) X			\$ 107.10
	SUB TOTAL			\$ 1,465.40
	LESS 20%			\$ 293.08
	DISCOUNTED TOTAL			\$ 1,172.32
	Labour Charge			
	Panel Beating			\$ 400.00 200
	Spray Painting Charge			\$ 600.00 200
	Tuff Kote			\$ 50.00 X
	Frt Wheel Alignment			\$ 80.00 X
	TOTAL LABOUR			\$ 1,130.00
	ESTIMATE TOTAL			\$ 2,302.32
1/2 1/2 1/2 11/12/18 1505 4/5 After Repair LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

REPAIR ESTIMATE*

MAKE :

MODEL : HYUNDAI i40

DATE 10/12/2018 14:52

[illegible]

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.