

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Josey Loh

Date: 12 Dec 2018

## **Preliminary Advice**

Vehicle No	: SGN8785J	Accident Date	: 07/12/2018
Make	: BMW 520I	Policy No.	: PNPV2017-00003480-01
Assignment Date	: 10/12/2018	Excess	: S\$800.00
Date of Inspection	: 11/12/2018	Est. Duration of Repair	: 8 days
Inspection At	: Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,842.00
Revised Amount	:S\$	12,902.00
Check Items (Estimated)	:S\$	9,320.00
Total	:S\$	22,222.00

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	82,000.00
COE / PARF Rebate	:S\$	61,138.00
Salvage Value	:S\$	
Margin for Repair	:S\$	20,862.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : REPAIRER AGREED TO UNDERTAKE THE REPAIR COST NOT EXCEEDING \$ 20,000.00 ON PART BY PART BASIS.