

22/03/2002

ASS. REC. BY:

REF:

CS/FWD18022266/Gsber

Special Instruction:

Survivor:

ASSIGNMENT (Office)

From (Person):

Josey Loh

of

FWD

Date/Time:

10/12/2018 6:57pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGN 8785J

Insured:

at Workshop m/s

Vin's Motor

Tel:

of

160 Sin Ming Drive #03-03

Policy No:

ANPR2017-00003480-01

Claim No:

1201800017963

Sum Insured:

Excess:

\$800.00

Make of Veh:

D.O.A.

07/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11/12/2018 9:07am

Person Contacted:

Raymond

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SGN 8785J - NBR / FWD 18015318 / Y

DA: 22082018

Yme.

IND

2042c

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

*Vin's Motor
Raymond.*

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


\$800

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$82K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGN 8785J

Yr Regn:

29 May 2013

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

BMW 520i

C.C

1997

Colour:

Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

90157

T/Radio:

Insured / Std / NI / NA

Eng/No:

wBA XG 2030DX 53864

C/No:

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

225/55 R17

R:

"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

11-12-18

Survey held at

w/s

Des. of Damages

☒ Frt

Rear / O/S / N/S / U/C / Rooftop or

5pm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/12

~~offer to workshop~~ Inform w/s repair limit not more than ~~\$18K~~ *20K*. w/s will get back it.

12/12/18 @ 16:23 p.m. revised IA to Josey Loh via meimur.

12/12/18 @ 16:31 p.m. mandate requeste authorize repair to Josey Loh via meimur.

12/12/18 @ 18:43 p.m. mandate approved by Lionel Tan.

13/12/18 @ 14:01 p.m. revert authorize repair to Raymond (repairs) via email.

Date/Time, File Pass to?

05/03/19



Preli. Report



Final Report

Date/Time, File Return to?

Days Of Repair:

10

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

1)

Typing

2)

RECEIVED 05 MAR 2019

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$ *20K p/p*)

<i>500</i>
<i>50</i>
<i>50+50</i>
<i>10</i>

04/03/19

Combined P/P \$20k @ 8 days with XGQ
(\$ 3,842.00 Red - 16%)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Dec 2018 Sendback Est	10 Dec 2018 16:17 S\$23,842.00	10 Dec 2018 18:57 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	CHUA YONG KWANG KEVIN, ID: S7412042C, Tel: +6598009179, Email: DR@KEVINCHUA.COM.SG		
Vehicle Reg. No.:	SGN8785J	Date of Loss:	07/12/2018 20:00 - :59 [66 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201800017963	Policy/Cover Note No.:	PNPV2017-00003480-01 (Comprehensive)
		Excess:	S\$800.00
Repairer:	Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64532121		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/12/2018]		
Driver/Custodian:	CHUA YONG KWANG KEVIN (44 / Male), NRIC: S7412042C, Tel: +6598009179		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2042C

Vehicle Details

Vehicle No.: SGN8785J
Vehicle to be Exported: No
Intended Deregistration Date: 10 Dec 2018
Vehicle Make: B.M.W.
Vehicle Model: 520i 2.0L AT D/AB 2WD 4DR
GAS/D NAV

Primary Colour: Brown
Manufacturing Year: 2013
Engine No.: A5170463N20B20B
Chassis No.: WBAXG12030DX53864
Maximum Power Output: 135.0 kW (181 bhp)
Open Market Value: \$41,044.00
Original Registration Date: 29 May 2013
First Registration Date: 29 May 2013
Transfer Count: 0
Actual ARF Paid: \$44,462.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 May 2023
PARF Rebate Amount: \$31,123.00

Intended COE Rebate Details

COE Expiry Date: 28 May 2023
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$67,304.00
COE Rebate Amount: \$30,051.00
Total Rebate Amount: \$61,174.00

The information contained herein is correct as at 08 Dec 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2042C
Vehicle Details	
Vehicle No.:	SGN8785J
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Dec 2018
Vehicle Make:	B.M.W.
Vehicle Model:	520i 2.0L AT D/AB 2WD 4DR GAS/D NAV
Primary Colour:	Brown
Manufacturing Year:	2013
Engine No.:	A5170463N20B20B
Chassis No.:	WBAXG12030DX53864
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$41,044.00
Original Registration Date:	29 May 2013
First Registration Date:	29 May 2013
Transfer Count:	0
Actual ARF Paid:	\$44,462.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 May 2023
PARF Rebate Amount:	\$31,123.00
Intended COE Rebate Details	
COE Expiry Date:	28 May 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$67,304.00
COE Rebate Amount:	\$30,015.00
Total Rebate Amount:	\$61,138.00

The information contained herein is correct as at 12 Dec 2018

OK

Shirley Hiew (LKK Auto)

From: Admin @ VAuG <admin@vinsautogroup.com.sg>
Sent: Tuesday, 5 March 2019 12:10 PM
To: Shirley Hiew (LKK Auto)
Cc: Guo Qiang (LKKAuto); SUR; Veron Chen (LKKAuto)
Subject: Re: SGN8785J Finalization

Good afternoon Shirley,
We accept the offer @ \$20,000 before excess and GST
Please proceed
Thanks!
Best Regards
Raymond Teo

On Mon, Mar 4, 2019 at 4:50 PM Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Dear Raymond,

Please confirmed final fig \$20,000.00 @ 10 days of repairs before excess \$800/- & GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 13 December 2018 2:01 PM
To: 'Admin @ VAuG'
Cc: SUR
Subject: RE: SGN 8785J OD (FWD)

Dear Raymond,

As instructed by our client, please proceed at repair cost not exceeding \$20,000.00 (inclusive supplementary) to repair the insured vehicle **SGN 8785J (Excess \$ 800/-)** on part by part basis.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin @ VAuG [mailto:admin@vinsautogroup.com.sg]
Sent: Wednesday, 12 December 2018 3:58 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: Re: SGN 8785J OD (FWD)

Good afternoon Shirley,
As we just spoken, we will undertake the repair for the vehicle not exceeding \$20,000.00 on part by part basis.
Please confirm
Thanks!
Best Regards
Raymond Teo

On Wed, Dec 12, 2018 at 2:47 PM Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Hi Raymond,

Kindly check the repair cost limit whether you are able to repair the vehicle not exceeding \$ 18,000.00 on part by part basis.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315


Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

--



Sin Ming AutoCity
160 Sin Ming Drive
Singapore 575722
Showroom/Office: #03-03
Workshops: #08-08/09
Tel: 64532121 (4 lines)
Fax: 64599795
Website: www.vinsautogroup.com.sg
Email: admin@vinsautogroup.com.sg

Follow us on :



**** w.e.f 15th May 2017, we have shifted location! ****

**** w.e.f 20th November 2017, we have changed our email address! ****

View Received Message

This mail is associated with :

SGN8785J (1201800017963)

OD

Dec 7 2018 8:00PM

[CHUA YONG KWANG KEVIN]

Vin's Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 12/12/2018 18:43 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$20000.00) - SGN8785J - Claim Handler: Josey Loh

Approved:20000.00.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Josey Loh

Date: 12 Dec 2018

Preliminary Advice

Vehicle No	: SGN8785J	Accident Date	: 07/12/2018
Make	: BMW 520I	Policy No.	: PNPV2017-00003480-01
Assignment Date	: 10/12/2018	Excess	: S\$800.00
Date of Inspection	: 11/12/2018	Est. Duration of Repair	: 8 days
Inspection At	: Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,842.00
Revised Amount	:S\$	12,902.00
Check Items (Estimated)	:S\$	9,320.00
Total	:S\$	22222.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	82,000.00
COE / PARF Rebate	:S\$	61,138.00
Salvage Value	:S\$	
Margin for Repair	:S\$	20,862.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER AGREED TO UNDERTAKE THE REPAIR COST NOT EXCEEDING \$ 20,000.00 ON PART BY PART BASIS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/12/2018 08:44
Date Of Accident	07/12/2018 20:00
Exact Location Of Accident	ALONG ORCHARD ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGN8785J
Insured/Policyholder	
Name Of Registered Owner	CHUA YONG KWANG KEVIN
NRIC No	S7412042C
Email Address	DR@KEVINCHUA.COM.SG
Mobile Phone No	(LOCAL) +65-98009179
Alternative Phone No	OFFICE-98009179

Vehicle Particulars

Manufacturer	BMW
Model	520I-2.0 L AT D/AB 2WD 4DR GAS/D NAV (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00003480-01
Cover Note Number	

Driver

Name of Driver	CHUA YONG KWANG KEVIN
NRIC No	S7412042C
Date Of Birth	19/04/1974
Occupation	INDOOR
Date Of Driving Pass	21/07/1994
Driving Experience	24 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98009179
Fax Number	
Contact Number	OFFICE-98009179
EMail Address	DR@KEVINCHUA.COM.SG

Address	170 WATTEN ESTATE ROAD
Postcode	287615
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLF9009T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN KING SUAN
NRIC/Passport Number	S6917202D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHD6660P
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category

TAXI

Name of Driver

LEONG POON MENG

NRIC/Passport Number

S6914094G

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN



A: SGN885J
B: SHD 6660P
C: SLF9009T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 7th December 2018, at about 2000 hrs.

I was driving along Orchard Road. All of the sudden,

the vehicle in front of me slowed down. I was not able to

stop in time and hit on the vehicle SHD6660P in front of me.

After I came out from my vehicle, I realized it was a

chain collision. The vehicle SHD6660P hit the front vehicle

SLF9009T.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



VIN'S MOTOR PTE LTD

BLOCK 12, SIN MING ROAD, #01-67, SINGAPORE 575656. TEL : 6453 2121 (4 LINES) FAX : 6459 9795

INSURER: **FWD Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/122018/3709
Policy No:	PNPV2017-00003480-01	Date of Loss:	07/12/2018
Vehicle Reg. No.:	SGN8785J	Driveable?	
Driver Age/Info:	44 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHUA YONG KWANG KEVIN	Contact No:	+6598009179
Driver:	CHUA YONG KWANG KEVIN		
Make/Model:	BMW 520I, 2.0 L AT D/AB 2WD 4DR GAS/D NAV (A)	Vehicle Reg. Date:	29/05/2013
Vehicle Colour:	BROWN		
Engine No:	A5170463N20B20B	Chassis No:	WBAXG12030DX53864
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Description of Accident/Loss	REFER TO SKETCH PLAN		
Present Location:	VIN'S MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	21,532.00
Miscellaneous Items	120.00
Labour	1,210.00
Paintwork Labour	980.00
Towing	0.00
Gross Total (\$\$)	23,842.00
+ GST 7.00% (\$\$)	1,668.94
Nett Amount (\$\$)	25,510.94

This claim is handled by: **TAN YIN LEI**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Dec 2018)

Parts: 143 BMW 520I 2.0 L AT D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Vin's Motor Pte Ltd/SGN8785J/10/12/2018 16:17

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bonnet / <i>buc</i> - BT	0.00	0.00	*1,700.00 F ✓
2	2		*Front bonnet hinge @ \$60.00 - <i>BT</i>	0.00	0.00	*120.00 F ✓
3	2		*Front bonnet adsorber @ \$130.00 <i>X</i> <i>mc</i>	0.00	0.00	*260.00 F ✓
4	1		*Front bonnet insulator - <i>mc</i>	0.00	0.00	*210.00 F ✓
5	16		*Front bonnet clips @ \$2.00 - <i>mc</i>	0.00	0.00	*32.00 F ✓
6	2		*Front bonnet top hinge @ \$60.00 - <i>BT</i>	0.00	0.00	*120.00 F ✓
7	1		*Front bonnet lock cable <i>P</i> / <i>Cut</i>	0.00	0.00	*30.00 F ✓
8	2		*Front bonnet lower lock @ \$170.00 - <i>BT</i>	0.00	0.00	*340.00 F ✓
9	2		*Front headlamp @ \$2050.00 - <i>CRA</i>	0.00	0.00	*4,100.00 F ✓
10	2		*Front headlamp HID bulb @ \$210.00 <i>X</i> <i>RH-NW</i>	0.00	0.00	*420.00 F ✓
11	2		*Front headlamp ECU No 1 @ \$610.00 <i>X</i> <i>CHX NN</i>	0.00	0.00	*1,220.00 F ✓
12	2		*Front headlamp ECU No 2 @ \$590.00 <i>X</i> <i>CHX NN</i>	0.00	0.00	*1,180.00 F ✓
13	2		*Front grille @ \$110.00 - <i>CRA</i>	0.00	0.00	*220.00 F ✓
14	1		*Front bumper - <i>CRA</i> <i>CH-SAR</i>	0.00	0.00	*1,050.00 F ✓
15	2		*Front bumper fog lamp @ \$210.00 <i>RH</i> <i>CRA</i>	0.00	0.00	*420.00 F ✓
16	2		*Front bumper fog lamp cover @ \$60.00 <i>CH-CP</i>	0.00	0.00	*120.00 F ✓
17	2		*Front bumper moulding @ \$30.00 <i>RH</i> <i>CH-CP</i>	0.00	0.00	*60.00 F ✓
18	1		*Front bumper centre grille - <i>CH-CP</i> <i>CH-CP</i> <i>CHX NN</i>	0.00	0.00	*50.00 F ✓
19	2		*Front bumper nozzle gun @ \$160.00 <i>CH-CP</i>	0.00	0.00	*320.00 F ✓
20	2		*Front bumper nozzle gun cover @ \$30.00 <i>CH-CP</i>	0.00	0.00	*60.00 F ✓
21	2		*Front bumper nozzle gun hose @ \$40.00 <i>CH-CP</i>	0.00	0.00	*80.00 F ✓
22	1		*Front bumper logo - <i>MS</i>	0.00	0.00	*60.00 F ✓
23	1		*Front bumper top rubber - <i>TV</i>	0.00	0.00	*30.00 F ✓
24	2		*Front bumper retainer @ \$20.00 - <i>BT</i>	0.00	0.00	*40.00 F ✓
25	1		*Front bumper reinforcement - <i>BT</i>	0.00	0.00	*520.00 F ✓
26	2		*Front bumper bracket @ \$50.00 <i>X</i> <i>BT</i>	0.00	0.00	*100.00 F ✓
27	2		*Front bumper parking sensor @ \$190.00 - <i>DM</i>	0.00	0.00	*380.00 F ✓
28	1		*Front bumper under cover - <i>TV</i>	0.00	0.00	*190.00 F ✓
29	2		*Front fender @ \$680.00 - <i>BT</i>	0.00	0.00	*1,360.00 F ✓
30	2		*Front fender inner fabric @ \$110.00 <i>X</i> <i>CRA</i>	0.00	0.00	*220.00 F ✓
31	2		*Front fender top cover @ \$50.00 <i>X</i> <i>CRA</i>	0.00	0.00	*100.00 F ✓
32	1		*Front support panel (front) <i>P</i> / <i>BT</i>	0.00	0.00	*170.00 F ✓
33	1		*Front support panel (rear) <i>P</i> / <i>BT</i>	0.00	0.00	*110.00 F ✓
34	2		*Front V bar @ \$20.00 <i>X</i> <i>BT</i>	0.00	0.00	*40.00 F ✓
35	2		*Front headlamp panel \$ 110.00 <i>X</i> <i>CRA</i>	0.00	0.00	*220.00 F ✓
36	2		*Front headlamp panel top cover @ \$40.00 - <i>Cut</i>	0.00	0.00	*80.00 F ✓
37	1		*Front air dust <i>X</i> <i>O/S</i>	0.00	0.00	*250.00 F ✓
38	1		*Front air cond condensor <i>X</i>	0.00	0.00	*810.00 F ✓
39	1		*Front air cond pipe no 1 <i>X</i> <i>BT</i>	0.00	0.00	*240.00 F ✓
40	1		*Front air cond pipe no 2 <i>X</i> <i>BT</i>	0.00	0.00	*230.00 F ✓
41	1		*Front radiator <i>X</i> <i>BT</i>	0.00	0.00	*710.00 F ✓
42	1		*Front radiator fan motor assy <i>X</i> <i>DM</i>	0.00	0.00	*1,100.00 F ✓
43	2		*Front seat headrest @ \$550.00 <i>X</i> <i>Repair</i>	0.00	0.00	*1,100.00 F ✓
44	2		*Front seat headrest sensor @ \$140.00 <i>X</i> <i>Act</i>	0.00	0.00	*280.00 F ✓
45	1		*Front ECU <i>X</i> <i>NW</i>	0.00	0.00	*800.00 F ✓
46	1		*Front number plate <i>X</i> <i>NN</i>	0.00	0.00	*40.00 F ✓
47	1		*Rear battery cable <i>X</i> <i>NN</i>	0.00	0.00	*240.00 F ✓

F=Franchise part.

Total Parts (\$\$)

18532

21,532.00

Vin's Motor Pte Ltd/SGN8785J/10/12/2018 16:17. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	To towing (double trainer) <i>XX NN</i>	120.00
Sub Total (S\$)			120.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	To spray painting	New	<i>880</i> 980.00
Labour Items			
2	To refill air cond gas	New	<i>120</i> 150.00
3	To reset air bag system	New	<i>150</i> 180.00
4	To repair front damage	New	<i>780</i> 880.00
Gross Labour Cost (S\$)			2,190.00

Vin's Motor Pte Ltd/SGN8785J/10/12/2018 16:17. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

8 Days.

part by part.

before paint photos.

Guo Qiang - 82880282

11/12/18.

Not Authorised.

Excess \$ 800.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date:



友興汽車零件私人有限公司 YEW HENG AUTO PARTS PTE LTD

BLK 3017 UBI ROAD 1 #04-129 SINGAPORE 408708
TEL: 6743 9858 A/C: 6392 0830 FAX: 6749 0858
Email: yawheng@yewhengauto.sg
Co. Reg. No.: 201130046W GST Reg. No.: 201130046W

TAX INVOICE

NO: YLH1216209
PAGE: 2

M/S: VIN'S MOTOR PTE LTD

Part No	Description	Location	Qty	Unit Price SIN	Amount SIN
22	5111 7 200 699	GRILLE AIR INLET CLOSED LH	1	60.00	60.00 /
23	5111 7 231 859	FINISHER ROD LH	1	30.00	30.00 /
24	5111 7 231 860	FINISHER ROD RH	1	30.00	30.00 /
25	5111 7 285 950	GRILLE AIR INLER CENTER	1	50.00	50.00 /
	6167 7 377 667	HIGH PRESSURE NOZZLE LHS	1	160.00	160.00 /
27	6167 7 377 668	HIGH PRESSURE NOZZLE RHS	1	160.00	160.00 /
28	5114 7 057 794	BONNET EMBLEM	1	60.00	60.00 /
29	5176 7 206 521	BONNET SEAL FRT	1	30.00	30.00 /
30	5111 7 263 325	SUPPORT	2	20.00	40.00 /
31	5111 7 200 705	CARRIER BUMPER FRONT	1	520.00	520.00 /
32	5111 7 186 513	ADAPTER PLATE LH	1	50.00	50.00 /
33	5111 7 186 514	ADAPTER PLATE RH	1	50.00	50.00 /
34	6620 9 270 495	PDC SENSOR(BLACK)	2	190.00	380.00 /
35	5175 7 185 113	BMW UNDER BONNET SCREEN F	1	190.00	190.00 /
36	4135 7 248 659	FRONT SIDE PANEL LH	1	680.00	680.00 /
37	4135 7 248 660	FRONT SIDE PANEL RH	1	680.00	680.00 /
38	5171 7 186 727	MUD.COVERING F.LH	1	110.00	110.00 /
	5171 7 186 728	BMW MUD.COVERING F.RH	1	110.00	110.00 /
40	5176 7 019 803	LOCATOR,SEAL F.LH	1	50.00	50.00 /
41	5176 7 019 804	LOCATOR,SEAL,FRT RHS	1	50.00	50.00 /
42	5164 7 200 689	BMW CONNECTION, TOP F.	1	170.00	170.00 /
43	5164 7 200 690	BMW CONNECTION, TOP RR	1	110.00	110.00 /
44	5164 7 187 095	BMW SUPPORT LH	1	20.00	20.00 /
45	5164 7 187 096	BMW SUPPORT RH	1	20.00	20.00 /
46	5164 7 200 793	HEADLAMP LWR BRACKET LHS	1	110.00	110.00 /

...Cont

Print / KXM / 26/12/2018 1:48:13 PM





友興汽車零件私人有限公司 YEW HENG AUTO PARTS PTE LTD

BLK 3017 UBI ROAD 1 #04-129 SINGAPORE 408708

TEL: 6743 9858 A/C: 6392 0830 FAX: 6749 0858

Email: yewheng@yewhengauto.sg

Co. Reg. No.: 201130046W GST Reg. No.: 201130046W

TAX INVOICE

M/S: VIN'S MOTOR PTE LTD

NO: YLI1216209
PAGE: 3

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
47 5164 7 200 794	HEADLAMP LWR BRACKET RHS	1N-44A	1	110.00	110.00 /
48 1711 7 645 650	HEADLAMP PANEL TOP COVER	1N-20C	2	40.00	80.00 /
49 5174 7 200 781	BMW AIR DUCT	YDS	1	250.00	250.00 /
6 6453 6 805 453	CONDENSER AIR CONDITIONER	1N-20C	1	810.00	810.00 /
51 6453 9 120 003	FRT AIR CON PIPE NO.1	YDS	1	240.00	240.00 /
52 6453 9 201 927	SUCTION PIPE W/O FILLER NECK	1B1-07	1	230.00	230.00 /
53 1711 8 672 011	RADIATOR	1N-24C	1	710.00	710.00 /
54 1741 8 642 161	RADIATOR FAN ASSY	YDS	1	1,100.00	1,100.00 /
55 5210 7 264 576	REPAIR KIT, CRASH-ACTIVE HEAD	YDS	2	140.00	280.00 /
56 6577 6 837 358	FRT ECU	YDS	1	800.00	800.00 /
57 6112 9 217 036	BATTERY CABLE/SBK CABLE(PLUS HOLE)	1N-15A	1	240.00	240.00 /
TOTAL QUANTITY:			76	TOTAL	SIN 18,582.00
				ADD GST @ 7%	1,300.74
				GRAND TOTAL	SIN 19,882.74

Print / KXM / 26/12/2018 1:48:14 PM

SALESMAN: KXM

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE





友興汽車零件私人有限公司 YEW HENG AUTO PARTS PTE LTD

BLK 3017 UBI ROAD 1 #04-129 SINGAPORE 408708
TEL: 6743 9858 A/C: 6392 0830 FAX: 6749 0858
Email: yewheng@yewhengauto.sg
Co. Reg. No.: 201130046W GST Reg. No.: 201130046W

TAX INVOICE

M/S: VIN'S MOTOR PTE LTD

160 SIN MING DRIVE #03-03 SIN MING AUTOCITY
SINGAPORE 575722
WORKSHOP: 160 #08-09 SIN MING AUTOCITY

NO: YLI1216209
PAGE: 1
DATE: 17/12/2018
A/C CODE: LYVIN001
TERMS: 30 DAYS

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 4161 7 207 194	FRONT BONNET	1N-26A	1	1,700.00	1,700.00 ✓
4100 7 270 883	BMW BONNET HINGE LH	1N-43B6	1	60.00	60.00 ✓
3 4100 7 270 884	BMW BONNET HINGE RH	1N-43B6	1	60.00	60.00 ✓
4 5148 6 989 301	BMW BONNET SPONGE	2N-11A	1	210.00	210.00 ✓
5 5148 9 119 216	BONNET INSULATOR CLIP	YDS	16	2.00	32.00 ✓
6 5123 7 183 763	BMW BONNET LOCK LH(UPPER)	1N-44B1	1	60.00	60.00 ✓
7 5123 7 183 764	BMW BONNET LOCK RH(UPPER)	1N-44B1	1	60.00	60.00 ✓
8 5123 7 183 773	BOWDEN CABLE, FRON	1N-15B1	1	30.00	30.00 ✓
9 5123 7 183 762	BONNET LOCK RH	1N-45C	1	170.00	170.00 ✓
10 5123 7 206 453	BONNET LOCK LH	1N-45C	1	170.00	170.00 ✓
11 6311 7 271 909	HEAD LAMP LH	1N-35A	1	2,050.00	2,050.00 ✓
12 6311 7 271 910	HEAD LAMP RH	1N-35A	1	2,050.00	2,050.00 ✓
13 6321 7 217 509	BULB XENON LIGHT W.IGNITION ELEMENT	1N-44C6	1	210.00	△ 210.00
6311 7 316 217	HEADLIGHT DRIVER MODULE AHL XENON LIGHT	1N-46C	1	610.00	△ 610.00
15 6311 7 318 327	CONTROL UNIT XENON LIGHT	YDS	1	590.00	△ 590.00
16 5113 7 203 649	GRILLE LH	YDS	1	110.00	110.00 ✓
17 5113 7 203 650	GRILLE RH	YDS	1	110.00	110.00 ✓
18 5111 7 285 961	FRT BUMPER 5111 7 246 863	133557	1	1,050.00	1,050.00 ✓
19 6317 7 216 885	FOG LIGHT LH	133557	1	210.00	210.00 ✓
20 6317 7 216 886	FOG LIGHT RH	133557	1	210.00	210.00 ✓
21 5111 7 200 698	GRILLE AIR INLET OPEN RH	1N-16B8	1	60.00	△ 60.00 △

Print / KXM / 26/12/2018 1:48:11 PM

...Cont'd



...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Dec 2018 Sendback Est	10 Dec 2018 16:17 \$23,842.00	10 Dec 2018 18:57 Edit Adj Rpt	\$20,000.00 Edit Estimates	\$20,000.00 View Rpt		Pending for Survey Report Cancel Case



















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: CHUA YONG KWANG KEVIN , ID: S7412042C, Tel: +6598009179, Email: DR@KEVINCHUA.COM.SG									
Vehicle Reg. No.: SGN8785J		Date of Loss: 07/12/2018 20:00 - :59 [66 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 1201800017963		Policy/Cover Note No.: PNPV2017-00003480-01 (Comprehensive)							
		Excess: \$800.00							
Repairer: Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64532121									
Handling Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 19/12/2018]									
Driver/Custodian: CHUA YONG KWANG KEVIN (44 / Male), NRIC: S7412042C, Tel: +6598009179 Email: DR@KEVINCHUA.COM.SG									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• FWD_SG (12/12/2018): Alert - Adj Mandate Approved (\$20000.00) - SGN8785J - Claim Handler: Josey Loh									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















































Claim Documents
















SGN8785J (1201800017963)
OD
Dec 7 2018 8:00PM
[CHUA YONG KWANG KEVIN]
Vin's Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Assessment Reports									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)								Thumbnail	Print			
1	10/12/18 16:17	Repairer Estimates							1	Load HTM				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	12/12/18 16:23	Adjuster Immediate Advice							1	Load HTM				
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
2	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
3	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
4	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
5	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
6	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
7	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
8	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
9	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
10	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
11	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
12	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
13	12/12/18 16:26	Odometer Reading							1	Load JPG	<input checked="" type="checkbox"/>			
14	12/12/18 16:26	Chassis Number							1	Load JPG	<input checked="" type="checkbox"/>			
15	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
16	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
17	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
18	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
19	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
20	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
21	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
22	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
23	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
24	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
25	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
26	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
27	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
28	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
29	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
30	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
31	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
32	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
33	12/12/18 16:26	General View							1	Load JPG	<input checked="" type="checkbox"/>			
34	12/12/18 16:26	General View								Load JPG				














Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
36	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
37	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
38	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
39	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
40	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
41	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
42	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
43	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
44	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
45	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
46	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
47	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
48	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
49	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
50	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
51	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
52	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
53	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
54	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
55	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
56	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
57	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
58	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
59	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
60	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
61	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
62	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
63	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
64	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
65	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
66	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
67	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
68	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
69	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
70	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
71	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
72	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
73	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
74	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
75	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
76	12/12/18 16:26	General View	 Load JPG	<input checked="" type="checkbox"/>
77	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
84	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
85	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
86	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
87	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
88	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
89	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
90	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
91	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
92	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
93	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
94	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
95	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
96	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
97	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
98	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
99	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
100	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
101	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
102	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
103	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
104	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
105	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
106	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
107	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
108	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
109	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
110	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
111	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
112	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
113	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
114	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
115	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
116	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
117	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
118	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
119	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
120	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
121	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
122	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
123	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
124	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
125	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
126	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
127	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
128	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
129	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
130	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
131	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
132	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
133	01/03/19 17:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
134	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
135	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
136	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
137	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
138	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
139	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
140	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
141	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
142	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
143	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
144	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
145	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
146	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
147	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
148	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
149	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
150	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
151	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
152	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
153	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
154	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
155	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
156	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
157	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
158	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
159	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
160	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
161	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
162	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
163	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
164	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
165	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
166	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
167	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
168	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
169	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
170	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
171	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
172	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
173	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
174	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
175	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
176	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
177	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
178	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
179	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
180	01/03/19 17:07	Dismantled Parts		<input checked="" type="checkbox"/>
181	01/03/19 17:08	Reinspection Photo		<input checked="" type="checkbox"/>
182	01/03/19 17:08	Reinspection Photo		<input checked="" type="checkbox"/>
183	01/03/19 17:08	Reinspection Photo		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
184	01/03/19 17:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
185	01/03/19 17:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
186	01/03/19 17:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
187	01/03/19 17:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
188	01/03/19 17:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
189	01/03/19 17:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
190	01/03/19 17:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
191	01/03/19 17:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
192	01/03/19 17:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
193	01/03/19 17:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
194	01/03/19 17:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
195	01/03/19 17:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/12/18 16:27	ESTIMATE MARKED.pdf	 Load PDF	
2	04/03/19 16:43	ESTIMATE MARKED 1.pdf	 Load PDF	
3	05/03/19 15:25	Parts Invoice	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	10/12/18 09:01	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	10/12/18 08:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	10/12/18 08:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	10/12/18 08:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	10/12/18 08:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	10/12/18 08:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	10/12/18 08:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	10/12/18 08:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	10/12/18 08:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	10/12/18 08:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	10/12/18 08:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	10/12/18 08:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	10/12/18 08:58	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD18022266/GSBE2

Date: 05/03/2019

REFERENCE

Insured/Claimant: CHUA YONG KWANG KEVIN Policy No: PNPV2017-00003480-01

Date of Loss: 07/12/2018

Nature of Claim: OD

Claim No: 1201800017963

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGN8785J**
Make & Model: BMW 520i, 2.0 L AT D/AB 2WD 4DR GAS/D NAV (A) Engine No: A5170463N20B20B
Reg. Date: 29/05/2013 (Man. Year: 2013) Chassis No: WBAXG12030DX53864
Colour: Brown Odometer: 90157 km
Engine Capacity: 1997 cc
Market Value/New Car Price: S\$82,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,532.00	18,492.00	3,040.00	14.12
Miscellaneous Items	120.00	0.00	120.00	100.00
Labour	1,210.00	1,050.00	160.00	13.22
Paintwork Labour	980.00	880.00	100.00	10.20
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,842.00	20,422.00	3,420.00	14.34
Approved Total (Overridden) (S\$)		20,000.00		
- Excess (S\$)	0.00	800.00	-800.00	
(S\$)	23,842.00	19,200.00	4,642.00	19.47
+ GST 7.00/7.00% (S\$)	1,668.94	1,344.00	324.94	19.47
Nett Amount (S\$)	25,510.94	20,544.00	4,966.94	19.47

INSPECTION

Date of Assignment: 10/12/2018 Present Location:

Date Inspected: 11/12/2018 Inspected At:

Vin's Motor Pte Ltd (Sin Ming)

Vin's Motor Pte Ltd (Sin Ming)

160 Sin Ming Drive, #03-03, Sin Ming

AutoCity

Singapore 575722

Estimated Period of Repair: 10.0 days

Adjuster: XING GUO QIANG**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Mar 2019)
Parts:	143	BMW 520I 2.0 L AT D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGN8785J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front bonnet	Buckled	1,700.00 F	*1,700.00 F
2	2		*Front bonnet hinge @ \$60.00	Bent	120.00 F	*120.00 F
3	2		*Front bonnet adsorber @ \$130.00	Not Necessary	260.00 F	*- F
4	1		*Front bonnet insulator	Deformed	210.00 F	*210.00 F
5	16		*Front bonnet clips @ \$2.00	Necessary	32.00 F	*32.00 F
6	2		*Front bonnet top hinge @ \$60.00	Bent	120.00 F	*120.00 F
7	1		*Front bonnet lock cable	Cut	30.00 F	*30.00 F
8	2		*Front bonnet lower lock @ \$170.00	Bent	340.00 F	*340.00 F
9	2		*Front headlamp @ \$2050.00	Cracked	4,100.00 F	*4,100.00 F
10	1		*Front headlamp HID bulb @ \$210.00	O/SNotWorking/N/SNotNecessary	420.00 F	*210.00 F
11	1		*Front headlamp ECU No 1 @ \$610.00	O/SNotWorking/N/SNotNecessary	1,220.00 F	*610.00 F
12	1		*Front headlamp ECU No 2 @ \$590.00	O/SNotWorking/N/SNotNecessary	1,180.00 F	*590.00 F
13	2		*Front grille @ \$110.00	Cracked	220.00 F	*220.00 F
14	1		*Front bumper	Cracked	1,050.00 F	*1,050.00 F
15	2		*Front bumper fog lamp @ \$210.00	N/S Scratched / O/S Cracked	420.00 F	*420.00 F
16	1		*Front bumper fog lamp cover @ \$60.00	N/DDeformed / O/SNot Necessary	120.00 F	*60.00 F
17	1		*Front bumper moulding @ \$30.00	N/S Broken / O/S Not Necessary	60.00 F	*30.00 F
18	1		*Front bumper centre grille	Deformed	50.00 F	*50.00 F
19	2		*Front bumper nozzle gun @ \$160.00	Damaged	320.00 F	*320.00 F
20	2		*Front bumper nozzle gun cover @ \$30.00	Not Necessary	60.00 F	*- F
21	2		*Front bumper nozzle gun hose @ \$40.00	Not Necessary	80.00 F	*- F
22	1		*Front bumper logo	Missing	60.00 F	*60.00 F
23	1		*Front bumper top rubber	Twisted	30.00 F	*30.00 F
24	2		*Front bumper retainer @ \$20.00	Necessary	40.00 F	*40.00 F
25	1		*Front bumper reinforcement	Bent	520.00 F	*520.00 F
26	2		*Front bumper bracket @ \$50.00	Bent	100.00 F	*100.00 F
27	2		*Front bumper parking sensor @ \$190.00	Damaged	380.00 F	*380.00 F
28	1		*Front bumper under cover	Torn	190.00 F	*190.00 F
29	2		*Front fender @ \$680.00	Bent	1,360.00 F	*1,360.00 F
30	2		*Front fender inner fibric @ \$110.00	Cracked	220.00 F	*220.00 F
31	2		*Front fender top cover @ \$50.00	Cracked	100.00 F	*100.00 F
32	1		*Front support panel (front)	Bent	170.00 F	*170.00 F
33	1		*Front support panel (rear)	Bent	110.00 F	*110.00 F
34	2		*Front V bar @ \$20.00	Bent	40.00 F	*40.00 F
35	2		*Front headlamp panel \$ 110.00	Cracked	220.00 F	*220.00 F
36	2		*Front headlamp panel top cover @ \$40.00	Cut	80.00 F	*80.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
37	1		*Front air dust	Distorted	250.00 F	*250.00 F
38	1		*Front air cond condensor	Bent	810.00 F	*810.00 F
39	1		*Front air cond pipe no 1	Bent	240.00 F	*240.00 F
40	1		*Front air cond pipe no 2	Bent	230.00 F	*230.00 F
41	1		*Front radiator	Bent	710.00 F	*710.00 F
42	1		*Front radiator fan motor assy	Damaged	1,100.00 F	*1,100.00 F
43	2		*Front seat headrest @ \$550.00	Repair	1,100.00 F	*- F
44	2		*Front seat headrest sensor @ \$140.00	Activated	280.00 F	*280.00 F
45	1		*Front ECU	Not Working	800.00 F	*800.00 F
46	1		*Front number plate	Not Necessary	40.00 F	*- F
47	1		*Rear battery cable	Necessary	240.00 F	*240.00 F
Total Parts (S\$)					21,532.00	18,492.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	To towing (double trainer) (NOT NECESSARY)	120.00	0.00
Sub Total (\$\$)			120.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	To spray painting	New	980.00	880.00
<u>Labour Items</u>				
2	To refill air cond gas	New	150.00	120.00
3	To reset air bag system	New	180.00	150.00
4	To repair front damage	New	880.00	780.00
Gross Labour Cost (\$\$)			2,190.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >