

15/3/2018

INS. CASE OWNER:

CC 4, Asm 180

LKK:
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

Insured Liability: %

TP GIA REPORT: YES / NO

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

2,728.50

Loss of Rental (LOR):

S\$

456.484.5

(days)

101.44

Loss of Use (LOU):

S\$

-

(\$

x

days)

Loss of Income (LOI):

S\$

-

(\$

x

days)

LOR only ☐ LOU only ☐

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

2.44

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$

3,186.98

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

3,186.98

Name 1:

PREMIER AUTOMOTIVE SERVICES PTE LTD

Payee 2: (Strike if N.A.)

S\$

X

Name 2:

X

Payee 3: (Strike if N.A.)

S\$

X

Name 3:

X

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

10-Dec-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8906 D

1 pc	Bonnet grille	cut	\$	386.00
1 pc	Front bumper	X Rep	\$	531.00
1 pc	Front bumper emblem	me	\$	44.00
1 pc	Front bumper centre grille	X m	\$	174.00
1 pc	Front bumper lower stiffer	X m	\$	134.00
1 pc	Front bumper tow hook cover	X m	\$	14.00
1 pc	Front bumper inner sponge	X m	\$	110.00
1 pc	Front bumper reinforcement	X m	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00	X m	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00	X m	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00	X m	\$	32.00
1 pc	Rear bumper	Rehd	\$	696.00
1 pc	Rear bumper lower cover	X Rep	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	X m	\$	58.00
1 pc	Rear bumper inner sponge	✓ top	\$	114.00
1 pc	Rear bumper reinforcement	✓ m	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	X m	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	✓ m	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	✓ m	\$	36.00
				\$ 3,678.00
Less 10%				\$ 367.80
				\$ 3,310.20

S/NETT

1 set	Rear bumper clips	me	\$	48.00
1 set	Reverse sensor	shld	\$	280.00 200
1 pc	Rear bumper top protector	me	\$	80.00 50
1 pc	Front no. plate with casing	me	\$	50.00 35
1 pc	Front bumper clips	X m	\$	48.00
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00	X m	\$	12.00
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00	X m	\$	6.00

10-Dec-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8906 D

Sundry	net \$	50.00 20
To check for wiring and to focus head lamps	\$	80.00 X 1,
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 X 1,
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc	\$	950.00 400
To putty and spray painting on front bumper, bonnet grille, rear bumper, end panel	\$	800.00 720
To apply rustproofing on the repaired and replaced panels.	\$	120.00 X 1,
	\$	<u>6,134.20</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin 16KKH

11/10/12/18 1600L
3 hr.

45

21/1/19
all up \$2550/3 hr
11

After Repair

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

10-Dec-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8906 D

1 pc	Bonnet grille ✓	\$	386.00
1 pc	Front bumper X Rep	\$	531.00
1 pc	Front bumper emblem ✓	\$	44.00
1 pc	Front bumper centre grille X	\$	174.00
1 pc	Front bumper lower stiffer X	\$	134.00
1 pc	Front bumper tow hook cover X	\$	14.00
1 pc	Front bumper inner sponge X	\$	110.00
1 pc	Front bumper reinforcement X	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 X	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 X	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 X	\$	32.00
1 pc	Rear bumper ✓	\$	696.00
1 pc	Rear bumper lower cover X Rep	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 X	\$	58.00
1 pc	Rear bumper inner sponge ?	\$	114.00
1 pc	Rear bumper reinforcement ?	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 !	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ?	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ?	\$	36.00
		\$	3,678.00
Less 10%		\$	367.80
		\$	3,310.20

S/NETT

1 set	Rear bumper clips ✓	\$	48.00
1 set	Reverse sensor ✓	\$	280.00 200
1 pc	Rear bumper top protector ✓	\$	80.00 50
1 pc	Front no. plate with casing ✓	\$	50.00 35
1 pc	Front bumper clips X	\$	48.00
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00 X	\$	12.00
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00 X	\$	6.00

10-Dec-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8906 D

Sundry	\$	50.00 20
To check for wiring and to focus head lamps	\$	80.00 X
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc	\$	950.00 400
To putty and spray painting on front bumper, bonnet grille, rear bumper, end panel X rear bumper cover	\$	800.00 720
To apply rustproofing on the repaired and replaced panels.	\$	120.00 X
	\$	<u>6,134.20</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin LKK

10/12/18 1600h
3 hrs.

45

After Repair Lito

LKK Auto Consultants hereby notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Service Request Details

Claim

S8M015W3

Reference

None 

Loss Date

December 7, 2018

Request Date

December 10, 2018

Due Date

December 17, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

10.12.2018 @ 2.15pm
Gary with in
Khalin

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SHB8906D

Make

TPVD KIA

Model

OPTIMA-1.7 D (A)

Service Address

...

Primary Contact/Insured

ONG KHENG HOE

33 PASIR RIS STREET 72, #03-28, 518770, Singapore

81021129

ONGKHENGHOE@YAHOO.COM.SG

Claim Handler

HO Winnie

6568804833

winnie.ho@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: Goh Wee Dek <weedek.goh@premiertaxi.com>
Sent: Monday, 10 December, 2018 12:32 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: Gary Shi
Subject: Pre-inspection SHB8906D & SMA4611B on 07.12.2018
Attachments: 10122018123028-0001.pdf

Categories: Namrata

Dear All

We refer to the above mentioned

Kindly arrange for survey.

We prefer LKK Auto as SJE

Regards

Goh Wee Dek
Assistant Claims Manager
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 068 | DID: 6544 6682 | Fax: 6214 1511 Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

♻ Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION ♻



MANDATE IA

Type

🔗 Question

Message

Hi Joy, Accident was on 07.12.2018 @ 20:00, date check in - 08.12.18 @ 18.48, date check out - 13.12.18 @ 14.15. if based on check in/check out voucher, total only 5 days. pls propose rental @ days

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

WE DID NOT AUTHORIZE REPAIRS. CHAIN COLLISION 4 VEHICLES.
INSURED 3RD. BOLA 28.

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	2,728.50
Loss of rental	\$	608.64 \$101.44 x 6days
LTA search fees	\$	2.00
Proposed Total	\$	3,339.14

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMA 4611B (Insd veh)	Model:	KIA OPTIMA
	SHB 8906D (TP veh)		
Date of Accident:	07/12/2018		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	6,563.59
Final Repair Cost	:	\$	2,728.50
Loss of Token Sum	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	456.48 4.5 days
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$
---------	---	----

	:	\$
Final Settlement Sum	:	\$ 3,186.98

Is Third Party Workshop GIA Registered?		[] YES	[X] NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 0 _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____ _____				

Payment Instruction: Payee's Breakdown			
1)	PREMIER AUTOMOTIVE SERVICES PTE LTD	:	\$ 3,186.98

NUR SHAQILAH BTE ABDOL
WAHAB

20/03/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18022272/K1ja3s2		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811 ATTN: WINNIE HO		Date : 20-03-2019		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMA 4611B	Veh. Inspected	SHB 8906D	
Policy No.	VPA/P2133208	Coverage (\$)	0.00	
Claim No.	S8M015W3	Excess (\$)	0.00	
Assign From	WINNIE HO	Assign Date	10/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KNAGM414ME5462270	Colour	SILVER	
Odometer	500213	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65R16	MAXXIS	7 mm	
L/H Front Tyre	205/65R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/12/2018	Inspection Date	10/12/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8906D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET GRILLE (CONSISTENT)	CUT	386.00	386.00
1	FRONT BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	531.00	-
1	FRONT BUMPER EMBLEM (CONSISTENT)	NECESSARY	44.00	44.00
1	FRONT BUMPER CENTRE GRILLE (CONSISTENT)	SERVICEABLE	174.00	-
1	FRONT BUMPER LOWER STIFFER (CONSISTENT)	SERVICEABLE	134.00	-
1	FRONT BUMPER TOW HOOK COVER (CONSISTENT)	SERVICEABLE	14.00	-
1	FRONT BUMPER INNER SPONGE (CONSISTENT)	SERVICEABLE	110.00	-
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	SERVICEABLE	328.00	-
2	FRONT BUMPER O/S & N/S SIDE RETAINER @ \$16.00 (CONSISTENT)	SERVICEABLE	32.00	-
2	FRONT BUMPER O/S & N/S UPPER BRACKET @ \$16.00 (CONSISTENT)	SERVICEABLE	32.00	-
2	FRONT BUMPER O/S & N/S SUPPORT BRACKET @ \$16.00 (CONSISTENT)	SERVICEABLE	32.00	-
1	REAR BUMPER (CONSISTENT)	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER (CONSISTENT)	TO REPAIR SEE LABOUR	206.00	-
2	REAR BUMPER SIDE BRACKET O/S & N/S @ \$29.00 (CONSISTENT)	SERVICEABLE	58.00	-
1	REAR BUMPER INNER SPONGE (CONSISTENT)	TORN	114.00	114.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	CRACKED	607.00	607.00
2	REAR BUMPER STAY O/S & N/S @ \$53.00 (CONSISTENT)	SERVICEABLE	108.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @ \$18.00 (CONSISTENT)	CRACKED	36.00	36.00
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @ \$18.00 (CONSISTENT)	CRACKED	36.00	36.00
LESS 10% DISCOUNT			-367.80	-191.90
			3,310.20	1,727.10
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	48.00	48.00
1	SET REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	280.00	200.00
1	REAR BUMPER TOP PROTECTOR (SN) (CONSISTENT)	NECESSARY	80.00	50.00

Report Ref No. CC4/ASM18022272/K1ja3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT NO. PLATE WITH CASING (SN) (CONSISTENT)	CRACKED	50.00	35.00
1	FRONT BUMPER CLIPS (SN) (CONSISTENT)	NOT NECESSARY	48.00	-
2	FRONT N/S & O/S HEAD LAMP LOWER CLIP @ \$6.00 (SN) (CONSISTENT)	NOT NECESSARY	12.00	-
2	FRONT N/S & O/S HEAD LAMP SIDE CLIP @ \$3.00 (SN) (CONSISTENT)	NOT NECESSARY	6.00	-
1	SUNDRY (SN) (CONSISTENT)	NECESSARY	50.00	20.00
			574.00	353.00
	LABOUR			
	TO CHECK FOR WIRING AND TO FOCUS HEAD LAMPS.	NOT NECESSARY	80.00	-
	TO DISMANTLE / REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	30.00
	TO DISMANTLE / REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE END PANEL ETC. INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND REAR BUMPER LOWER COVER.		950.00	400.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER, BONNET GRILLE, REAR BUMPER, END PANEL.		800.00	720.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			2,250.00	1,150.00
	GRAND TOTAL		6,134.20	3,230.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,550.00

Report Ref No. CC4/ASM18022272/K1ja3s2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.