

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

10-Dec-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8906 D

1 pc	Bonnet grille ✓	\$	386.00
1 pc	Front bumper X Rep	\$	531.00
1 pc	Front bumper emblem ✓	\$	44.00
1 pc	Front bumper centre grille X	\$	174.00
1 pc	Front bumper lower stiffer X	\$	134.00
1 pc	Front bumper tow hook cover X	\$	14.00
1 pc	Front bumper inner sponge X	\$	110.00
1 pc	Front bumper reinforcement X	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 X	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 X	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 X	\$	32.00
1 pc	Rear bumper ✓	\$	696.00
1 pc	Rear bumper lower cover X Rep	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 X	\$	58.00
1 pc	Rear bumper inner sponge ?	\$	114.00
1 pc	Rear bumper reinforcement ?	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 !	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ?	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ?	\$	36.00
		\$	3,678.00
Less 10%		\$	367.80
		\$	3,310.20

### S/NETT

1 set	Rear bumper clips ✓	\$	48.00
1 set	Reverse sensor ✓	\$	<del>280.00</del> 200
1 pc	Rear bumper top protector ✓	\$	<del>80.00</del> 50
1 pc	Front no. plate with casing ✓	\$	<del>50.00</del> 35
1 pc	Front bumper clips X	\$	48.00
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00 X	\$	12.00
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00 X	\$	6.00

10-Dec-18

**ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8906 D**

Sundry	\$	<del>50.00</del> 20
To check for wiring and to focus head lamps	\$	<del>80.00</del> X
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	<del>120.00</del> 30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	<del>180.00</del> X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc	\$	<del>950.00</del> 400
To putty and spray painting on front bumper, bonnet grille, rear bumper, end panel X rear Bumper cover	\$	<del>800.00</del> 720
To apply rustproofing on the repaired and replaced panels.	\$	<del>120.00</del> X
	\$	<u>6,134.20</u>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

Kalvin 16KK

10/12/18 1600h  
3 hr.

45

*After Repair Lito*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_