

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 3594Y

DATE 8/12/2018 10:34

MAKE :

MODEL : HYUNDAI i40

LKK/Kalvin

L/Sun

Like

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 2,174.90
	Boot Lid Rubber ✕			\$ 96.50
	Boot Lid Lock Upper ✕			\$ 102.60
	Boot Lid Lock Lower ✕			\$ 31.70
	Boot Lid 'H' Emblem ✓			\$ 28.70
	Boot Lid CRDI Plate ✓			\$ 27.90
	Bootlid Moulding ✕			\$ 227.90
	Bootlid i40 Emblem ✓			\$ 27.90
	Bootlid Lower Garnish ✕ repr			\$ 227.90
	Rear Bumper ✓			\$ 553.00
	Rear Bumper Reinforcement ?			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs ✓			\$ 22.00
	Rear Bumper Bracket ?		\$ 35.60	\$ 71.20
	Rear Bumper Sponge ?			\$ 103.50
	Rear Bumper Under Cover ✓			\$ 228.00
	SUB TOTAL			\$ 4,512.70
	LESS 20%			\$ 902.54
	DISCOUNTED TOTAL			\$ 3,610.16
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00
	Rear Bumper Reverse Sensor ✓			\$ 135.70
	Rear Bumper Rubber Mat ✓			\$ 50.00
				\$ 215.70
	Labour Charge			
	Panel Beating			\$ 500.00 400
	Spray Painting Charge			\$ 500.00 400
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 20
	Remove/Refix Reverse Sensor			\$ 80.00 20
	TOTAL LABOUR			\$ 1,180.00
	ESTIMATE TOTAL			\$ 5,005.86

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kalin 11/12/18

10/12/18

3/12/18

L/S

After Rep

pLL