

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

(car In

Estimate No. : b1 49404	Page No. : 1 of 5
Date Estimated : 11/12/2018	
Prepared By : Kevin Leong Wai Kit	

- ESTIMATE REPAIR FOR - Ng Yuan Xin (Huang YuanXin) 61 Lorong Sarhad #03-07 Singapore 119174	- ACCOUNT - 238 AXA Insurance Pte Ltd 8 Shenton Way #24-01 AXA Tower Singapore 068811
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMA1075T	NU82160	28/05/2018	318i	0

DESCRIPTION	VALUE
To replace frt bumper, frt LH headlamp bracket & all attachments cause by accident.	850 1,700.00
Painting on frt bumper panel & frt LH side panel	882 1,624.00
To check electrical wiring systems at the front section for proper function.	150 177.00
To replace left headlight.	408 481.00
To check steering geometry and conduct wheel alignment according to BMW specification (1x)	451 531.00
To replace tyre and wheel rim including balancing. (1x).	94.00
Sundries.	? 150.00
Total Labour 1:	4,767.00

DESCRIPTION	QTY	PRIC	VALUE
BLIND RIVET	2	1.55	3.10
ALLOY RIM 8Jx18 DOUBLE SPK 397	1	1,089.10	1,089.10
FRT BUMPER TOP MOUNT	1	370.70	370.70
FRT LH DEFORMATION ELEMENT	1	99.80	99.80
FRT LH LOWER DEFORMATION ELEMENT	1	84.70	84.70
SUPPORT CENTRAL	1	11.35	11.35
MOUNT FOR SUPPORT	1	6.60	6.60
INSERT AIR INLET MIDDLE	1	121.95	121.95
LH FOG LAMP SUPPORT	1	41.85	41.85
FINISHER ROD CENTRE (SPORT)	1	53.40	53.40
LH FINISHER ROD (SPORT)	1	40.20	40.20
LH AIR INLET FINISHER (SPORT)	1	53.20	53.20
FRT SHOCK ABSORBER ECE	1	53.45	53.45
LH SPRAY NOZZLE COVER PRIMED	1	43.25	43.25
SET MOUNTING PDC/PMA SENSOR FRT	1	84.10	84.10

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 49404**
Date Estimated : **11/12/2018**
Prepared By : **Kevin Leong Wai Kit**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMA1075T	NU82160	28/05/2018	318i	0

DESCRIPTION	QTY	PRIC	VALUE
SET MOUNTING PDC/PMA SENSOR FRT ?	1	84.10	84.10
FRT BUMPER PANEL PRIMED (SPORT LINE) <i>DE</i>	1	1,007.30	1,007.30
LH PARTIALLY OPEN GRID (SPORT EDITI) ?	1	88.40	88.40
FRT LH GRILLE (SPORT EDITION) <i>SEA</i>	1	118.55	118.55
LH SUPPORT ?	1	55.30	55.30
FRT LH WHEEL HOUSING COVER <i>JOHN</i>	1	116.55	116.55
LH COVER BOTTOM ?	1	116.55	116.55
DEFLECTOR LIP LH ?	1	52.80	52.80
FANFARE HORN HIGH TONE ELECTRONIC ?	1	94.70	94.70
FANFARE HORN LOW TONE ELECTRONIC ?	1	94.70	94.70
LH HEADLIGHT LED TECHNOLOGY <i>SEA</i>	1	3,068.40	3,068.40
DECOUPLING RING PDC TORQUE CONVERTE ?	4	5.05	20.20
PDC SENSOR MINERALWEISS (A96) ?	1	368.80	368.80
(DG/SL) ADHESIVE SET K6 <i>NE</i>	1	53.05	53.05

Total Parts : **7,496.15**Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time **11/12/18 @ 1600** Excess S\$ _____Surveyor's Name **R. Tan** Sign _____Surveyor's Tel **90060068** Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend **4 days**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	4,767.00
Parts	:	7,496.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	858.42
Grand Total	:	13,121.57

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **