

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9692C**AAD1812-057***Not Authen*
L/Sing &

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 9692C

KL1LA69RJB121769

CHEVROLET

EPICA 2.0

6.12.2018

III**PART****LIST**

1	1	Rear Bumper	\$	B ₁	1,202.00	✓
2	1	Rear Bumper Beam	\$	B ₁	239.94	✓
3	1	Rear Bumper Centre Absorber	\$	CM	260.00	✓
4	1	Rear Bumper Side Retainer RH	\$	CM	68.76	✓
5	1	Rear Bumper Side Retainer LH	\$	D ₁	68.76	✓
6	1	Rear Bumper Reflectors RH	\$	Br	119.74	✓
7	1	Rear Bumper Reflectors LH	\$	Br	119.74	✓
8	1	Rear Bumper Tow Hook Cover	\$	Sc	93.00	X
9	1	Rear End Panel Outer	\$	B ₁	623.76	✓
10	1	Rear End Panel Inner Trim	\$	D ₁	263.84	✓
11	1	Rear Luggage Floor Panel	\$	BT/B ₁	2,911.70	✓
12	1	Rear Luggage Floor Panel Insulator	\$	Sc	1,991.70	X
13	1	Rear Luggage Floor Panel Trim Board	\$	Sc	2,011.60	X
14	1	Bootlid	\$	B ₁	973.00	✓
15	1	Bootlid inner trim board	\$	Sc	400.00	X
16	1	Bootlid Weatherstrip	\$	Gr	344.28	50% in
17	1	Bootlid Lock - Top	\$	ND	466.56	✓
18	1	Bootlid 'CHEVROLET' Badge	\$	Me	120.62	✓
19	1	Bootlid Logo	\$	Me	138.84	✓
20	1	Bootlid 'EPICA LT' Badge	\$	Me	119.84	✓
21	1	Bootlid Reflector Centre	\$	Sc	217.97	X
22	1	Bootlid Reflector RH	\$	Sc	128.40	X
23	1	Bootlid Reflector LH	\$	CM	128.40	✓
24	1	Rear Tail Lamp RH	\$	MZ/CM	479.30	✓
25	1	Rear Tail Lamp LH	\$	CM	479.30	✓
26	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	B ₁	1,110.00	✓
27	1	Rear Fender RH	\$	R	1,145.00	X
28	1	Rear Fender Inner Trim RH	\$	Sc	418.44	X
29	1	Rear Fender LH	\$	R	1,145.00	X

Trans-cab Auto Services Pte Ltd**AAD1812-057**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9692C

30	1	Rear Fender Inner Trim LH	\$	<i>Sn</i> 418.44	X
31	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>Answer</i> 1,961.70	X
32	1	Shield -RR Muffler Protv	\$	<i>n</i> 402.30	X
33	1	Rear Exhaust Box (Box-DPF) (Centre)	\$	<i>n</i> 120.00	X
34	1	Rear Exhaust Mounting	\$	<i>Sn</i> 180.00	X
35	1	Rear Exhaust Heat Shield	\$	<i>n</i> 57.00	X
36	1	Rear exhaust box - J hook	\$	<i>Sn</i> 36.20	X
37	1	Rear exhaust box chrome pipe	\$	<i>nsp</i> 791.70	X
38	1	Rear Exhaust Mounting Bracket	\$	<i>Sn</i> 311.90	X
39	1	Centre Exhaust Pipe	\$	<i>n</i> 481.40	X
40	1	Rear Exhaust Pipe	\$	<i>n</i> 216.90	X

TOTAL	\$	22,767.03
10%	\$	2,276.70
	\$	20,490.33

Specical Nett

1	1Set	Bootlid inner trim board Clip	\$	<i>n</i> 40.00	X
2	1Set	Rear Bumper Parking Sensor	\$	<i>short</i> 300.00	✓
3	1Set	Rear Bumper Fastener Clip	\$	<i>n</i> 44.00	✓
4	1Set	Rear Fender Inner Trim Clip LH	\$	<i>n</i> 30.00	X
5	1Set	Rear Bumper End Dust Cover Clip	\$	<i>n</i> 30.00	X
6	1	Rear Exhaust Mounting	\$	<i>Sn</i> 300.00	X
7	2	Rear Windscreen Sealant	\$	<i>n</i> 80.00	X
8	1	Rear Windscreen Inner Sponge Seal	\$	<i>n</i> 100.00	X
9	1	Spare Tyre	\$	<i>Sn</i> 180.00	X
10	1	Spare Wheel Rim	\$	<i>Sn</i> 126.74	X

TOTAL	\$	1,230.74
--------------	-----------	-----------------

TOTAL PARTS	\$	21,721.07
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$

3,500.00 *1400h*

Trans-cab Auto Services Pte Ltd**AAD1812-057**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9692C

To Check Electrical Lighting Concerned.	\$	170.00 <i>20%</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>90%</i>
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 <i>1000%</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>60%</i>
To transfer of end panel fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of boot fittings and conduct water seepage test.	\$	170.00 <i>60%</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 <i>100%</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>

\$ 7,950.00

TOTAL \$ 29,671.07

Repair Days (LUMP SUM)~~**20 DAYS**~~*12 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: