

22/09/2007

ASS. REC. BY:

REF:

CS/FCI18022294/Kvd3n

Special Instruction:

Surveyor:

(WS)

Kenneth

ASSIGNMENT (Office)

From (Person):

Gerene Ter

of

FCI

Date/Time:

3:58pm 11/12/2018

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SMD 9138C

Insured:

SHD 3569R

at Workshop m/s

Lai Hwai (Meng Kee)

Tel:

64538110

of

160 Sin Ming Drive # 04-02 / 07-03

Policy No:

Claim No:

D18008754 mfst

Sum Insured:

Excess:

Make of Veh:

D.O.A. 06/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS '0s'

19-12-2018

H.O.D. Endorsement:

Date/Time:

4:06pm 11/12/18

Person Contacted:

Jenny

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMD 9138C - X
	SHD 3569R - CS/FCI17009469 / Mlvbm2 DOA: 8/5/2017
12/12/18 -	Vehicle not in yet
20/12/18	Email preli revised to FCI
4/1/19	@ 335pm Jenny will email us finalised

REF: FCI

ASSIGNMENT

From: Date: 19/12/18

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SMD 9138C

at Workshop n/s Heri Huat (Meng Kee)
of 160 Sin Ming Drive # 04-02 / 07-03

Insured:

Policy No:

Claims No:


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$14K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'DS'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SMD 9138C Yr Regn: 10 09

Type: ☒ M. Car / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Fit CC: 1339

Colour: White A/C Insured / Std / NI / NA

Sp. Reading: 207463 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GE6 1209810

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R15

R:

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 3 mm

Rear R/Bal. 4 mm

L/Bal. 3 mm

L/Bal. 4 mm

D.O.A. 8/12/18 D.O.I. 19/12/18

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26/12 Mile pen to Catherine
28/12 @ 252pm Jenny will check

9/4 @ 11am LS \$2500 (Red 943.20, 279) Confirmed with Jenny

MV: \$14K(EST) LTA: \$8722 NV: \$5278

RECEIVED 09 APR 2019

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

Date/Time, File Return to?

21 9/4 - typist

Report Format :

Lump Sum / I.B.I. (\$) 2500/-

Days Of Repair: 4

Resurvey No. of Trip: -

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

130
50
13
193



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18008754MFSH

Our ref: CS/FCI18022294/Kvd3

Date : 20/12/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SMD 9138C


We thank for your instruction on 11/12/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 19/12/2018 at the premises of M/s LAI HUAT (MENG KEE) MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$3,443.20
Revised Estimate Amount	: S\$3,173.20
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	11-12-2018	Our Ref No. D18008754MFSH
Accident Date	06-12-2018	Claim Type. Third Party
Insured Vehicle	SHD3569R	Third Party Vehicle. SMD9138C
Survey Location	160 SIN MING DRIVE #04-01/#04-02/#07-03 SIN MING AUTOCITY	
Contact Person.	JENNY LIM	
Contact No.	64538110/ 0	Fax No. 64596267
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LAI HUAT (MENG KEE) MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 20 December 2018 12:43 PM
To: 'CWS Motor Claims'
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008754MFSH/1, SMD 9138C
Attachments: SMD 9138C PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SMD 9138C
Date of survey: 19/12/2018
Number of days : 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 11 December 2018 4:09 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <SereneLer@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008754MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 11 December 2018 3:57 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <SereneLer@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008754MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

Veron Chen (LKKAUTO)

From: Jenny Lim <jenny.lim@laihuat.com.sg>
Sent: Tuesday, 9 April 2019 9:35 AM
To: Kenneth Kong (LKKAUTO)
Subject: RE: Finalisation - SMD 9138C / Honda Fit

Dear Sir

We are unable to provide after repair photos due to SD card faulty.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

From: Kenneth Kong (LKKAUTO) [mailto:KennethKong@lkkauto.com]
Sent: Tuesday, 9 April, 2019 9:21 AM
To: Jenny Lim
Subject: RE: Finalisation - SMD 9138C / Honda Fit

L/Sump \$2500.00, 4days confirmed. Can I have after paint photos??

From: Jenny Lim [mailto:jenny.lim@laihuat.com.sg]
Sent: Saturday, 6 April, 2019 11:19 AM
To: Kenneth Kong (LKKAUTO)
Subject: Finalisation - SMD 9138C / Honda Fit

Dear Sir

For your confirmation, please:

- Parts: \$1,443.20
 - SN: \$ 300.00
 - L&P: \$1,430.00
- Sub-total: \$3,173.20
LS -20%: \$ 634.64 = \$2,538.56
Lump sum: \$2500.00 / 5 days

Supporting document are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267



Thank you

Lai Mei Ling Deborah has successfully logged out.

Your last login date and time was 06 Dec 2018, 13:27:38.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No. 	Asset Type	Asset ID	Asset Owner ID	Transaction Type
1	Vehicle	SHD3569R	-	18.32 Insurance Enquiry (GIRO Pay
• Log Date/Time 06 Dec 2018 / 13:28:33				

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	1427C

Vehicle Details

Vehicle No.:	SMD9138C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	06 Dec 2018
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	L13A4230081
Chassis No.:	GE61209810
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$14,702.00
Original Registration Date:	12 Oct 2009
First Registration Date:	12 Oct 2009
Transfer Count:	1
Actual ARF Paid:	\$14,702.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Oct 2019
PARF Rebate Amount:	\$7,351.00

Intended COE Rebate Details

COE Expiry Date:	11 Oct 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$16,201.00
COE Rebate Amount:	\$1,371.00
Total Rebate Amount:	\$8,722.00

The information contained herein is correct as at 06 Dec 2018

OK

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S8413076A**

Name: **CHAI MU FENG**

Birth Date: **07 May 1984**

Issue Date: **14 Apr 2004**

001193256H

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S8413076A**

Name: **CHAI MU FENG**
蔡沐峰

Race: **CHINESE**

Date of birth: **07-05-1984**

Sex: **M**

Country/Place of birth: **SINGAPORE**

88413076A

Land Transport & Authority

VOCATIONAL LICENCE

License No: **S8413076A**

Name: **CHAI MU FENG**

Card Issue Date: **30/08/2017**

Please visit www.lta.gov.sg to check the status of this vocational licence

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE: **14 Apr 2004**

97436927
ECHOLOB

NP 428A

License No: **S8413076A**

5409772

NRIC No **S8413076A**

Date of Issue: **13-01-2015**

Address: **50B RACE COURSE ROAD
SINGAPORE 218562**

This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to the LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
13	PRIVATE HIRE CAR VL	30/08/2017



来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0020949
Tokyo Jazz Pte Ltd

Page 1 of 2
Your ref. TP-SHD 3569R MS Fir
Job No. 70053
Our ref. 18.12.11
Payment
Date 10/12/2018

Attn

Vehicle No ... SMD 9138C
Vehicle Model : Honda Fit
Accident on ... 6/12/2018

Not Authorized
612500
Recovery After Paint 4 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Rear bumper	772.10	20.00	<i>Bu</i> 617.68 ✓
1.00	Pc	Rear tailgate	926.50	20.00	<i>B1</i> 741.20 ✓
1.00	Pc	Rear tailgate FIT emblem	35.20	20.00	<i>re</i> 28.16 ✓
2.00	Pcs	Rear windscreen moulding	35.10	20.00	<i>re</i> 56.16 ✓
Special nett item:					
1.00	Pc	Rear bumper lower spoiler (after market)	300.00		<i>CMA</i> 300.00 ✓
Labour & Misc:					
1.00		To dismantle + refix rear windscreen	160.00		<i>1200</i> 160.00
1.00		To supply sealant	40.00	nec	40.00 ✓
1.00		Tuff coat	40.00		40.00 <i>300</i>
1.00		To dismantle + renew rear bumper lower	120.00		120.00 <i>1000</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0020949
Tokyo Jazz Pte Ltd

Page 2 of 2
Your ref. TP-SHD 3569R MS Fir
Job No. 70053
Our ref. 18.12.11
Payment
Date 10/12/2018

Attn

Vehicle No SMD 9138C
Vehicle Model : Honda Fit
Accident on ... 6/12/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		spoiler			
1.00		To transfer parking sensor	40.00		40.00 ✓
1.00		To knock dents on rear tail lamp panel LH, rear end panel and renew of parts	600.00		600.00 500
1.00		To spray paint	700.00		700.00 600

Sub-Total 3,443.20
GST 7.00% 241.02
Total S\$ 3,684.22

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0020949
Tokyo Jazz Pte Ltd

Page 1 of 2
Your ref TP-SHD 3569R MS Fir
Job No 70053
Our ref 18.12.11
Payment
Date 10/12/2018

Attn

Vehicle No SMD 9138C
Vehicle Model Honda Fit
Accident on 6/12/2018

Not Authorized

11 Sep 07

Repair After Paint 4 days

Quantity	Unit	Description	Unit price	Disc pct	Amount
Supply of Parts					
1.00	Pc	Rear bumper	772.10	20.00	617.68 ✓
1.00	Pc	Rear tailgate	926.50	20.00	741.20 ✓
1.00	Pc	Rear tailgate FIT emblem	35.20	20.00	28.16 ✓
2.00	Pcs	Rear windscreen moulding	35.10	20.00	56.16 ✓
Special nett item					
1.00	Pc	Rear bumper lower spoiler (after market)	300.00		CM 300.00 ✓
Labour & Misc.					
1.00		To dismantle + refix rear windscreen	160.00		160.00 ✓
1.00		To supply sealant	40.00		40.00 ✓
1.00		Tuff coat	40.00		40.00 ✓
1.00		To dismantle + renew rear bumper lower	120.00		120.00 ✓

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0020949
Tokyo Jazz Pte Ltd

Page 2 of 2
Your ref TP-SHD 3569R MS Fir
Job No 70053
Our ref 18.12.11
Payment
Date 10/12/2018

Attn

Vehicle No SMD 9138C
Vehicle Model Honda Fit
Accident on 6/12/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		spoiler			
1.00		To transfer parking sensor	40.00		40.00 ✓
1.00		To knock dents on rear tail lamp panel LH, rear end panel and renew of parts	600.00		600.00 500
1.00		To spray paint	700.00		700.00 600

Sub-Total 2,443.20
GST 7.00% 241.02
Total S\$ 3,684.22

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
除外，还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18022294/Kvd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 09-04-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3569R	Veh. Inspected	SMD 9138C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008754MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	11/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT (A)	c.c	1339	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	GE61209810	Colour	WHITE	
Odometer	207463	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	BRIDGESTONE	3 mm	
L/H Front Tyre	195/55 R15	BRIDGESTONE	3 mm	
R/H Rear Tyre	195/55 R15	BRIDGESTONE	4 mm	
L/H Rear Tyre	195/55 R15	BRIDGESTONE	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/12/2018	Inspection Date	19/12/2018	
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 9138C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BUCKLED	772.10	772.10
1	REAR TAILGATE	BENT	926.50	926.50
1	REAR TAILGATE FIT EMBLEM	NECESSARY	35.20	35.20
2	REAR WINDSCREEN MOULDING @\$35.10	NECESSARY	70.20	70.20
	LESS 20% DISCOUNT		-360.80	-360.80
			1,443.20	1,443.20
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER LOWER SPOILER (AFTER MARKET)(SN)	CRACKED	300.00	300.00
1	SEALANT (SN)	NECESSARY	40.00	40.00
			340.00	340.00
	<u>LABOUR</u>			
	TO DISMANTLE + REFIX REAR WINDSCREEN.		160.00	120.00
	TUFF COAT.		40.00	30.00
	TO TRANSFER PARKING SENSOR.		40.00	40.00
	TO KNOCK DENTS ON REAR TAIL LAMP PANEL LH,REAR END PANEL AND RENEW OF PARTS.		600.00	500.00
	TO SPRAY PAINT.		700.00	600.00
	TO DISMANTLE + RENEW REAR BUMPER LOWER SPOILER.		120.00	100.00
			1,660.00	1,390.00
	GRAND TOTAL		3,443.20	3,173.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,500.00

Report Ref No. CS/FCI18022294/Kvd3n2

MARKET VALUE: \$14,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$8,722.00=NETT VALUE: \$5,278.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
 No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.