LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Lionel Tan Date: 08 Jan 2019

Preliminary Advice

Insured Vehicle No : SFY2820J

TP Vehicle No : SME8877D Accident Date : 08/12/2018

Make : MERCEDES-BENZ B180 Assignment Date : 11/12/2018

Date of Inspection : 07/01/2019 Est. Duration of Repair : 3/Days

Inspection At : CYCLE & CARRIAGE INDUSTRIES (1986) PL

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...Rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,344.05
Revised Amount	:S\$	3,681.57
Check Items (Estimated)	:S\$	342.48
Total	:S\$	4,024.05

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$
Pre-Accident Value :S\$
COE / PARF Rebate :S\$
Salvage Value :S\$
Margin for Repair :S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments :We have not authorized repairs.