

Surveyor

WAPERS

DOI:

ASSIGNMENT

11/2/18

Date / Time:

11/12/18

Registered in Merimen:

11/2/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLK 2496P

Name of Insured:

Brachis Enterprise LLC

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

10-12-18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

MO. Yusuf B. Haji

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

Opp of TMAH RD

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJR 47481



INSRS:

WSP:

Tel:

Liability:

RMKS:

Private Auto



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

14/12
Am

SJR 47481 - X; SLK 2496P - X

2/3/2020 - FILE PAS TO HAWA TO WORK

Report Case
By: JIA LG
Reviewed: Yes
31-01-20

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320

COPY SENT
2/3/2020

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJR 47 482at Workshop m/s precise

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 20 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: 24/6/19

Date / Time Action / Instruction

6/2.05h. Rental car per month 1300
LTA 8897

L/s - \$6000 (Red \$ 8976.59 / 601)

Veh No: SJR 47 482Yr Regn: 25/6/09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (9)Make: Toyota corolla Axio c.c1496Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 154604

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NZE1416096261Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6

mm

R/Bal. 6

mm

L/Bal. 6

mm

L/Bal. 6

mm

D.O.A. _____

D.O.I. 11/12/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

)

PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-34/36 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

d
Jiale

A4

26/06/2019

Date Of Accident : 10-12-2018

OUR REF : SJR 4748L/T/18

1st - Mercedes

Not Adult
2nd

1/5 \$6000
20dy.

PRECISE CAR RENTAL

No.1 Kaki Bukit Ave 6

#02-33

Singapore 417883

Date In/Out: 10-12-18 to 05/01/19 20dy.

ESTIMATE BILL ON VEH. NO. : SJR 4748L

MODEL : TOYOTA COROLLA AXIO

CHASSIS NO. : NZE1416096261

LIST ITEM

Rear Bumper Fascia		705	687.20	
Rear Bumper Side Retainer	2pcs @ 122.20	Misc	244.40	1/2
Rear Bumper Side Attachment	2pcs @ 141.25	11	282.50	X
Rear Bumper Clips	SV 10pcs @ 12.90	ru	129.00	
Rear Bumper Stay - LH		11	141.85	X
Tail Lamp - LH		one	233.70	
Tail Lamp Sealant		11	56.00	X
Tail Lamp Clips	2pcs @ 12.90	11	25.80	X
Tail Lamp Base Panel - LH		but	187.20	
Boot Lid		70/30	972.40	
Boot Lid Lock		701	374.55	
Boot Lid Lock Striker		11	43.70	X
Boot Lid Lock Cable		11	174.40	X
Boot Lid Weatherstripe		701	203.10	
Boot Lid Hinge	2pcs @ 132.10	11	264.20	X

Boot Lid Outer Garnish Clips	2pcs @ 12.90	11	25.80 X
Boot Lid Outer Garnish Badge		11	27.75 X
Boot Lid Emblum "Axio"		11	29.40
Boot Lid Emblum "X"		11	27.75
Rear Fender - LH		Dis	980.80
Rear Fender Splash Shield	2pcs @ 181.25	11/5 Torn	362.50 1pc
Rear Fender Splash Shield Clips	6pcs @ 12.90	11	77.40 X
Rear Fender Inner Trim Board	11/5 366.10	Dis	781.25
Rear Fender Inner Trim Board Clips	50 12pcs @ 12.90	11	154.80
Rear End Panel		Dis	589.40
Rear End Panel Top Trim		Dis	281.90
Rear End Panel Top Trim Clips	4pcs @ 12.90	11	51.60 X
Rear Floor Panel		compd/suc	972.40
Rear Floor Panel Board		11/5	372.80
Rear Floor Panel Insulator Cloth		11	561.60 180s
Rear Sub Chassis Frame Member - LH		11	691.55 X
Rear Windscreen Glass Moulding		11	182.25
Rear Windscreen Glass		11	1,145.00 X
Rear Windscreen Glass Clips	10pcs @ 12.90	11	129.00 X
Rear Wheel Housing Panel (Inner & Outer)	2pcs @ 385.00	11/5	770.00
	7763.29		12,235.45
	Less Discount 25%:		3,058.86
			9,176.59

LABOUR CHARGE

To Check Wiring System.

30

100.00

To Tuff Coat Affected Areas.	120	200.00
To Remove & Refix Interior Upholstery.	80	180.00
To Remove & Refix Reverse Sensor.	50	120.00
To Remove & Refix Rear Windscreen Glass.	120	200.00
To Remove & Refix Exhaust Silencer & Straighten Exhaust Center Pipe.	11 X	280.00
To Respray Affected Areas.	1300	1,800.00
To Check & Adjust Chassis Alginment On Car O Liner.	11 X	380.00
To Renew Damaged Parts, Straighten & Repair Rear Chassis Member & Rear RH Fender & Aligned All Parts.	1900	2,000.00
To Remove & Refix Fuel Tank.	60	20.00
To Remove & Refix Rear Undercarriage.	200	280.00
Computer 4 Wheel Alignment.	80	120.00

	14,976.59
GST 7%:	1,048.36
AMOUNT DUE :	<u>16,024.95</u>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	8221G
Vehicle Details	
Vehicle No.:	SJR4748L
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	1NZD185466
Chassis No.:	NZE1416096261
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$16,441.00
Original Registration Date:	25 Jun 2009
First Registration Date:	25 Jun 2009
Transfer Count:	2
Actual ARF Paid:	\$16,441.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jun 2019
PARF Rebate Amount:	\$8,220.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jun 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$12,899.00
COE Rebate Amount:	\$677.00
Total Rebate Amount:	\$8,897.00

The information contained herein is correct as at 12 Dec 2018

OK

Das WeltAuto.

Used cars you can trust. Guaranteed.

Some rides are better than others.

Brace yourself for adrenaline pumping offers on certified, pre-owned VW cars at the sgCarMart Carnival @ Downtown East.

Find out more



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Land Rover Range Rover Evoque 5DR at \$123,888.



Super Low Mileage Done 8.5k
km /yr! Come With 4 Pc New
Tyres! Ret Tax 18 05/2018
Speedo Motoring 30000

ABWIN

ONE-STOP
AUTOMOTIVE SERVICES

Browse by Category

Sort by Date Posted

9 vehicles

Toyota axio

Advanced Search

Image	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
Search Selection	Toyota axio	Any	Any	2009	Any	Any	Any
	Toyota Corolla Axio 1.5A X (New 5-yr COE)	\$28,800	\$5,760 /yr	30-Jan-2009	1,496 cc	64,920 km	Seda
Low Mileage Done 6,800Km Per Year, Up To 90% In House Loan Available, No Gimmicks! 1 Owner, Fuel Efficiency, Silver In Colour, Tip Top Condition, Serviced Regularly, No More Repair Needed, Option To R...							
Posted: 08-Dec-2018 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota							
	Toyota Corolla Axio 1.5A X (New 5-yr COE)	\$28,777	\$5,750 /yr	24-Feb-2009	1,496 cc	-	Seda
Beautiful White Corolla Axio! 1st Owner! Original Paintwork. New COE! Regularly Serviced And Maintained. Flexible Financing. Low Monthly Of \$							
Clean And Neat Interior. Best Fuel Efficiency Of 15Km/...							
Posted: 06-Dec-2018 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota							
	Toyota Corolla Axio 1.5A X Special Edition (New 5-yr COE)	\$31,800	\$5,360 /yr	08-Jan-2009	1,496 cc	160,000 km	Seda
1 Owner Only. Great For New Driver Or Family Sedan. Currently One And Only Special Edition Unit. Smooth Engine, Easy To Maintain Unit, Immaculate Condition, Depreciation Is Even Cheaper. Do Not Miss, ...							
Posted: 04-Dec-2018 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota							
	Toyota Corolla Axio 1.5A X (New 5-yr COE)	\$27,800	\$5,560 /yr	24-Mar-2009	1,496 cc	141,000 km	Seda
\$3000 Drive Away Inclusive Of 1st Installment And Insurance, Monthly At \$628. Bank And In-House Loan Available! High Approval Rate! Super Maintained By Previous Owner Who Believes In Weekly Polis...							
Viking Motor Pte Ltd							
Posted: 04-Dec-2018 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota							

GET YOUR
COE
RENEWAL
LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and approval in 2 days without effort! Enquire today.



Compare

Toyota Corolla Axio 1.5A X (New 5-yr COE)

\$28,888**\$5,770 /yr****04-Feb-2009****1,496 cc****98,000 km****Seda**

Vicing Upon Purchase! 1 Years Warranty Engine And Gearbox \$1k Cash Down Payment! 100% Loan Approval! Bank And In House Lo
Low Down Payment Available! Trade In Welcome! Priced Lo...

- Pre repair inspection request - SJR4748L VS SLK2496P (OI) DOA: 10/12/2018

From: Azlan, Syazairdina
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Hor, Yinrul, Chan, Yoke Shi
Sent: 11/12/2018 12:23:32 PM
Attachments: 11122018111448.pdf

Hi,

Please refer to the enclosed request from **Precise Auto Service**.

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks and regards,

Syaza Indina Azlan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: support@preciseauto.sg [mailto:support@preciseauto.sg]

Sent: Tuesday, December 11, 2018 12:17 PM

To: Azlan, Syazairdina

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinrul; Chan, Yoke Shi; support@preciseauto.sg

Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLK2496P AND SJR 4748L ON 10/12/2018

Dear Sir,

We refer to your email on dated 11-12-2018. Please be informed that we are choose Mr. Marcus Chua from LKK Auto Consultant as our SJE.

Thanks & Regards
Arine

From: Azlan, Syazairdina

Sent: Tue, 11 Dec 2018 03:48:59 +0000

To: Support@preciseauto.sg

Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Hor, Yinrul, Chan, Yoke Shi

Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLK2496P AND SJR 4748L ON 10/12/2018

Without Prejudice

Your Reference : SJR 4748L
Our Reference : SLK2496P

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd

12:44pm @ 11/12/18
vehicle In
person @ Arine.

Kalyin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: AIG SGP, Claims-Survey
Sent: Tuesday, December 11, 2018 11:35 AM
To: Azlan, Syazairdina
Subject: FW: Pre-repair Inspection for SJR 4748L. Your Insured Veh no : SLK 2496P.

From: Precise Auto Service [mailto:Support@preciseauto.sg]
Sent: Tuesday, December 11, 2018 11:28 AM
To: AIG SGP, Claims-Survey
Cc: Tan, Lily (AIG)
Subject: Pre-repair Inspection for SJR 4748L. Your Insured Veh no : SLK 2496P.

Dear Sir,

We refer to the above mentioned subject. Herewith enclosed 2 days notice for your attention.

Please arrange a date and time to do PRI for our client's vehicle (**SJR 4748L**) in our workshop ASAP.

Thank You.

Best Regards
Arine

--

T : 6745 7367 | **F :** 6841 3390
E : support@preciseauto.sg
W : www.preciseauto.sg
A : No.1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883

Follow us on social media:

<https://www.instagram.com/preciseautosvs/>
<https://twitter.com/preciseautosvs>
<https://www.facebook.com/PreciseAutoService/>

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

Date: 11/12/18 @ 11:13am

M/s AIG Asia Pacific Insurance Pte Ltd
M/S Chartis Singapore Insurance Pte Ltd
78 Shenton Way
#08-16 CHARTIS Building
Singapore 079120

By Fax 6835 7416 Only

Dear Sirs

ACCIDENT BETWEEN VEHICLE NO. SJR 4748L AND VEHICLE NO. SLK 2496P ON 10-12-18 @ 1610hrs AT Traffic Junction Between Upper Bt. Timah Rd & Old Juncy Road.

We refer to the above matter.

We are the appointed repair workshop of vehicle no. SJR 4748L.

We understand that you are the insurer of vehicle no. SLK 2496P.

The owner of vehicle no. SJR 4748L has authorised us to carry out the repairs to his vehicle which was damaged by your insured's vehicle. The owner intends to make a claim against your insured and/or insured's authorised driver for the accident which is caused wholly and/or contributed by your insured and/or your insured's authorised driver's negligence.

We hereby give you notice of the accident and an opportunity to inspect the damaged to the vehicle prior to the commencement of the repairs.

Kindly take note that we hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle no. SJR 4748L at my premises.



Yours faithfully

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 # 02-33/34/36 AUTOBAY SINGAPORE 417883

TEL : 6745 7367 FAX : 6841 3390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

23-07-19

Your Ref. : SLK 2696P

Vehicle No. : SJR 4748L/T/18(SJE)

M/s AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#08-16 CHARTIS Building

Singapore 079120

ATTN : Ms. Jia Le (LKK Motor Claim Department)

Dear Sir

RE : ACCIDENT INVOLVING VEHICLE NO. SJR 4748L AND SLK 2496P ON 10 DEC 2018
@ 16 : 10 HRS ALONG TRAFFIC JUNCTION BETWEEN UPP BUKIT TIAMH RD.

We are the repairer for vehicle no. **SJR 4748L** and instructed by the owner, **Precise Car Rental Pte Ltd**, on his behalf to submit the claims against your insured's vehicle no. **SLK 2496P** that was involved in the above mentioned accident.

The accident was clearly caused by your insured's negligence. In order to save the legal cost, we will process the claim to you directly as follows:

1. Cost of Repair (Survey By Mr. Marcus)	\$	6,420.00 (Including GST)
2. Loss Of Use (25 days X \$120.00)	\$	3,000.00
3. Towing Fees With ERP	\$	124.00
4. LTA Search	\$	8.00
	\$	<u>9,552.00</u>

Please let us have your payment in our favour of "**Precise Auto Service**".
Your prompt reply of the above claims will be much appreciated.

Yours faithfully

Yan Hong



PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-33/34/36 AUTOBAY SINGAPORE 417883

TEL : 6745 7367 FAX : 6841 3390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

=====

Accident Date : 10-12-18

OUR REF : SJR 4748L/T/18(SJE)

TAX INVOICE

PRECISE CAR RENTAL

No. 1 Kaki Bukit Ave 6

#02-33

Singapore 417883

Invoice No. : TP1906-013

DATE : 28-06-19

FINAL BILL ON VEH. NO. : SJR 4748L
VEHICLE MODEL : TOYOTA COROLLA AXIO

LUMP SUM REPAIR

INCLUDING SUPPLY OF PARTS & LABOUR

PANEL BEATING & SPRAY PAINTING

6,000.00

SUB-TOTAL	:	<u>6,000.00</u>
ADD GST 7%	:	<u>420.00</u>
TOTAL AMOUNT SGD	:	<u><u>6,420.00</u></u>

This is a computer generated document and requires no signature.





MICASA MARINE PTE LTD
BLK 850 Yishun ST.81 #01-106
Singapore (760850)
H/P : 8348 4004

☐ INVOICE/CASH
10 12 18
D D M M Y Y

☐ WORK ORDER
No. Q 13470

Customers: Police Auto Sns. Tel/Hp: _____
Vehicle No: SIR 4748 L
From: Upp Juru Road Attend time: _____ Two to: #02-36 Complete time: _____
h s: 120 + 858 3400 = 4124 Cheque: _____

ADDITIONAL CHARGE:
PE OF SERVICES

Breakdown Tow
Change Tyre
Cancellation Fee

PES OF VEHICLES

☒ Car ☐ Van
☐ Lorry or Pick-up

Other: _____

- | | | |
|--|---|--|
| <input checked="" type="checkbox"/> Use King Trolley | <input type="checkbox"/> Basement / Multi Storey Car Park | <input type="checkbox"/> Jurong Port / Island |
| <input type="checkbox"/> Vehicles With Goods/Fridge | <input type="checkbox"/> Causeway / 2nd link | |
| <input checked="" type="checkbox"/> Accident Tow | <input type="checkbox"/> Standby/Waiting time (per Hour) | <input type="checkbox"/> Battery Jump Start |
| <input type="checkbox"/> Crane-up Services | <input type="checkbox"/> Windscreen Cracked | |
| <input type="checkbox"/> Scrap Vehicles | <input type="checkbox"/> Others: _____ | |
| <input type="checkbox"/> 10/ft Lorry/With Cover | <input type="checkbox"/> 14/ft Lorry/With Cover | <input type="checkbox"/> Mini Bus (Seater) |
| <input type="checkbox"/> Taxi | <input type="checkbox"/> 24/ft Lorry/With Cover | <input type="checkbox"/> Tow Truck / With Crane |
| <input type="checkbox"/> Motor Bike | <input type="checkbox"/> Compressor/Lane Rover | <input type="checkbox"/> Ambulance / Car Carrier |

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damage or other misdemeanor to your vehicle whilst being towed.

cheque should be crossed and payable to " MICASA MARINE PTE LTD "

Truck No: 11 L5972C Driver's Name: Dani

Authorized by: _____

DISCREPANCIES Please X damaged area for scratch and Y for dent

sh card • hubcaps • spare wheel • tools headlining • speakers • amplifiers • front seats • rear seats • floor covering • radio • key • aerial



12/11/2018

Vehicle Hub

Enquire Vehicle & Owner Information (Vehicle No. SLK2496P As At 10 Dec 2018 / 16:10:00)**Law Firm Search Details:**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: PRECISE - SJR4748L

Current Owner Details

Owner ID Type: Company

Owner ID: 201429970C

Owner Name: BRAELISS ENTERPRISE PTE. LTD.

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 25

Registered Street Name: KAKI BUKIT ROAD 4

Registered Unit No.: # 05 - 34

Registered Building Name: SYNERGY @ KB

Registered Postal Code: 417800

Current Vehicle Details

Vehicle No.: SLK2496P

Make Description/Model: TOYOTA / COROLLA ALTIS CLASSIC 1.6 CVT

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Jia Le (LKK Auto)

From: Jia Le (LKK Auto)
Sent: Monday, 6 January 2020 3:21 PM
To: Precise Auto Service
Subject: RE: ACCIDENT INVOLVING SLK 2496P(AIG) AND SJR 4748L ON 10/12/2018

WITHOUT PREJUDICE

Dear Sirs/Mdm,

Kindly let us have the PIR for our necessary action.

Thank you.

"Wishing you a Happiness and Prosperity New Year"

Best Regards,

Chan Jia Le | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Precise Auto Service [mailto:Support@preciseauto.sg]
Sent: Wednesday, 3 July 2019 5:04 PM
To: Jia Le (LKK Auto)
Subject: Re: ACCIDENT INVOLVING SLK 2496P(AIG) AND SJR 4748L ON 10/12/2018

Without Prejudice

Dear Ms. Jia Le

We refer to your above email.

We enclose herewith accident scene photo for your attention.

Thank you

Best Regards
Yan Hong



Virus-free. www.avg.com

On Thu, 27 Jun 2019 at 12:39, Jia Le (LKK Auto) <JiaLe@lkkauto.com> wrote:

Without Prejudice

Dear Sirs/Mdm,

ACCIDENT INVOLVING SLK 2496P(AIG) AND SJR 4748L ON 10/12/2018

We refer to the above matter.

Please be informed that liability is unclear for this matter. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request a copy of video footage/witness statement/scene photos(if any) in order for us to look into the matter.

We shall revert upon hearing from you.

Thank You.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

T : 6745 7367 | **F** : 6841 3390

E : support@preciseauto.sg

W : www.preciseauto.sg

A : No.1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883



Follow us on social media:



<https://www.instagram.com/preciseautosvs/>



<https://twitter.com/preciseautosvs>



<https://www.facebook.com/PreciseAutoService/>



Virus-free. www.avg.com

Jia Le (LKK Auto)

From: Md Noor, Norsiah <Norsiah.MdNoor@aig.com>
Sent: Tuesday, 28 January 2020 10:29 AM
To: Jia Le (LKK Auto)
Subject: RE: Claim No: 5844495436SG003- Video footage & Status *LKK REF: CC4/AIG18022300/Uda3
Attachments: Traffic police investigation result.pdf

Dear Jia Le,

Refer to the attached.

Please proceed to reject the third party claim.

Thank you

Kind regards
Norsiah

Norsiah Md Noor
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419-1606
Norsiah.MdNoor@aig.com | www.aig.com.sg



Celebrating 100 Years:
Visit 100.aig to learn more.

Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Jia Le (LKK Auto) [<mailto:JiaLe@lkkauto.com>]
Sent: Thursday, July 4, 2019 3:05 PM
To: Md Noor, Norsiah <Norsiah.MdNoor@aig.com>
Subject: [EXTERNAL] RE: Claim No: 5844495436SG003- Video footage & Status *LKK REF: CC4/AIG18022300/Uda3

This message is from an external sender; be cautious with links and attachments.

Dear Norsiah,

Third Party do not have any video footage and they only provided scene photo as attached.

Based on the accident report and accident scenario, our insured was going straight and Third Party was making a turn, BOLA 5 is applicable. Thus, we would like to reject Third Party claim.

Kindly let us have your approval/instruction.

Best Regards,

Carlhor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Saturday, 22 June 2019 12:39 PM

To: Md Noor, Norsiah

Cc: Cheok, Lee Wai; Jia Le (LKK Auto); CS A Team; Admin A

Subject: RE: Claim No: 5844495436SG003- Video footage & Status *LKK REF: CC4/AIG18022300/Uda3

Hi Norsiah,

We will check and get back to you.

By copy to Jia Le,

FYNA. CC4/AIG18022300/Uda3

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Md Noor, Norsiah <Norsiah.MdNoor@aig.com>

Sent: Monday, 17 June 2019 2:35 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Cheok, Lee Wai <Cheok.Leewai@aig.com>

Subject: Claim No: 5844495436SG003- Video footage & Status

Dear Hsiao Tong,

Refer to the above.

Any video footage and please update status of this case.

Thank you

Kind regards

Norsiah

Norsiah Md Noor

AIG


Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419-1606

Norsiah.MdNoor@aig.com | www.aig.com.sg



Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

Jia Le (LKK Auto)

From: Jia Le (LKK Auto)
Sent: Friday, 31 January 2020 9:27 AM
To: 'Precise Auto Service'
Subject: RE: ACCIDENT INVOLVING SLK 2496P(AIG) AND SJR 4748L ON 10/12/2018
Attachments: PIR.pdf

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING SLK 2496P & SJR 4748L ON 10/12/2018

We refer to the above matter.

We have received the Police Investigation Result which is against your driver for inconsiderate driving.

Therefore, we have our principal instruction to deny liability and unable to look into your client's claim.

Thank you.

"Wishing you a Happy and Prosperous Lunar New Year"



Best Regards,

Chan Jia Le | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jia Le (LKK Auto)
Sent: Monday, 6 January 2020 3:21 PM
To: Precise Auto Service
Subject: RE: ACCIDENT INVOLVING SLK 2496P(AIG) AND SJR 4748L ON 10/12/2018

WITHOUT PREJUDICE

Dear Sirs/Mdm,

Kindly let us have the PIR for our necessary action.

Thank you.

"Wishing you a Happiness and Prosperity New Year"

Best Regards,

Chan Jia Le | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Precise Auto Service [<mailto:Support@preciseauto.sg>]
Sent: Wednesday, 3 July 2019 5:04 PM
To: Jia Le (LKK Auto)
Subject: Re: ACCIDENT INVOLVING SLK 2496P(AIG) AND SJR 4748L ON 10/12/2018

Without Prejudice

Dear Ms. Jia Le

We refer to your above email.

We enclose herewith accident scene photo for your attention.

Thank you

Best Regards
Yan Hong



Virus-free. www.avg.com

On Thu, 27 Jun 2019 at 12:39, Jia Le (LKK Auto) <JiaLe@lkkauto.com> wrote:

Without Prejudice

Dear Sirs/Mdm,

ACCIDENT INVOLVING SLK 2496P(AIG) AND SJR 4748L ON 10/12/2018

We refer to the above matter.

Please be informed that liability is unclear for this matter. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request a copy of video footage/witness statement/scene photos(if any) in order for us to look into the matter.

We shall revert upon hearing from you.

Thank You.

“Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.”

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

--

T : 6745 7367 | **F** : 6841 3390

E : support@preciseauto.sg

W : www.preciseauto.sg

A : No.1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883




Follow us on social media:



<https://www.instagram.com/preciseautosvs/>



<https://twitter.com/preciseautosvs>



<https://www.facebook.com/PreciseAutoService/>



Virus-free. www.avg.com

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Dec 2018 Edit Reg		11 Dec 2018 00:00 Edit Adj Rpt	S\$6,000.00 Edit Estimates	S\$6,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS				[Created by adjuster]	
Insured:	BRAELISS ENTERPRISE PTE LTD, Co. Reg. No.: NA				
Main Claimant:	PRECISE CAR RENTAL PTE LTD, Co. Reg. No.: 201818221G				
Vehicle Reg. No.:	SJR4748L	Date of Loss:	10/12/2018 15:00 - :59 [113 Months and 15 Days From LTA Reg Date (Man Yr)]		
Claim Type:	TP / 5844495436SG	Policy/Cover Note No.:	0999994385 (Comprehensive)		
Vehicle Reg. No. (Insured):	SLK2496P	Policy No. (Claimant):	5101115310-01		
		Excess:			
Repairer:	Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36, 417883 Kaki Bukit - Tel: 67457367				
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com				
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 20/12/2018]				

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
























































[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

























































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									









Claim Documents

*SJR4748L (5844495436SG)
[SLK2496P]
TP
PRECISE CAR RENTAL PTE LTD
Dec 10 2018 3:00PM
[BRAELISS ENTERPRISE PTE LTD]
Precise Auto Service

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	11/12/18 17:55	Odometer Reading				Load JPG	<input checked="" type="checkbox"/>
2	11/12/18 17:55	Chassis Number				Load JPG	<input checked="" type="checkbox"/>
3	11/12/18 17:55	General View				Load JPG	<input checked="" type="checkbox"/>
4	11/12/18 17:55	General View				Load JPG	<input checked="" type="checkbox"/>
5	11/12/18 17:55	General View				Load JPG	<input checked="" type="checkbox"/>
6	11/12/18 17:55	General View				Load JPG	<input checked="" type="checkbox"/>
7	11/12/18 17:55	General View				Load JPG	<input checked="" type="checkbox"/>
8	11/12/18 17:55	General View				Load JPG	<input checked="" type="checkbox"/>
9	11/12/18 17:55	General View				Load JPG	<input checked="" type="checkbox"/>
10	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
11	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
12	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
13	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
14	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
15	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
16	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
17	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
18	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
19	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
20	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
21	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
22	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
23	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
24	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
25	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
26	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
27	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
28	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
29	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
30	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
31	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
32	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
33	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
34	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
35	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
36	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
37	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
38	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
39	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
40	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
41	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
42	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>
43	11/12/18 17:56	General View				Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
45	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
46	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
47	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
48	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
49	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
50	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
51	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
52	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
53	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
54	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
55	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
56	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
57	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
58	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
59	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
60	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
61	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
62	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
63	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
64	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
65	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
66	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
67	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
68	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
69	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
70	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
71	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
72	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
73	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
74	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
75	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
76	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
77	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
78	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
79	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
80	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
81	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
82	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
83	11/12/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
84	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	19/12/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	19/12/18 18:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	04/01/19 18:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	04/01/19 18:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	04/01/19 18:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
156	04/01/19 18:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	04/01/19 18:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	04/01/19 18:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	04/01/19 18:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	04/01/19 18:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	04/01/19 18:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	04/01/19 18:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	04/01/19 18:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	04/01/19 18:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	04/01/19 18:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
166	04/01/19 18:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
167	04/01/19 18:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/12/18 16:38	ACKNOWLEDGEMENT EMAIL TO AIG DD 11.12.2018	 Load PDF	
2	11/12/18 16:38	EMAIL FROM AIG DD 11.12.2018	 Load PDF	
3	11/12/18 16:38	NOTIFICATION FROM WORKSHOP + LTA SEARCH	 Load PDF	
4	13/12/18 11:11	TP GIA REPORT	 Load PDF	
5	31/01/20 09:31	email to reject TP claim on 31012020	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	13/12/18 13:40	OI GIA REPORT	 Load PDF	
2	17/07/19 11:04	Traffic investigation result	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note:

Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18022300/UDA3Q2

Date: 06/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994385
Claimant
Vehicle No : SJR4748L **Insured Vehicle No :** SLK2496P
Date of Loss: 10/12/2018 **Nature of Claim:** TP **Claim No:** 5844495436SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJR4748L
Make & Model: TOYOTA COROLLA, 1.5 X AXIO (A) **Engine No:** 1NZD185466
Reg. Date: 25/06/2009 (Man. Year: 2008) **Chassis No:** NZE1416096261
Colour: Grey **Odometer:** 154604 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 **Rear Tyre Size:** 195/60 R15
Front Left Side: Bridgestone 6 mm **Rear Left Side:** Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm **Rear Right Side:** Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,176.59	5,876.17	3,300.42	35.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,680.00	3,940.00	1,740.00	30.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,856.59	9,816.17	5,040.42	33.93
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	14,856.59	6,000.00	8,856.59	59.61
+ GST 7.00/7.00% (S\$)	1,039.96	420.00	619.96	59.61
Nett Amount (S\$)	15,896.55	6,420.00	9,476.55	59.61
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 11/12/2018
Date Inspected: 11/12/2018 **Inspected At:** Precise Auto Service (HQ)
 No 1 Kaki Bukit Ave 6, #02-34/36
 Singapore 417883
Estimated Period of Repair: 20.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Distorted	687.20 FL	*687.20 FL
2	1		*REAR BUMPER SIDE RETAINER	N/S Cracked	244.40 FL	*122.20 FL
3	2		*REAR BUMPER SIDE ATTACHMENT	Not Necessary	282.50 FL	*- FL
4	10		*REAR BUMPER CLIPS	Necessary	129.00 FL	*50.00 FL
5	1		*REAR BUMPER STAY -LH	Not Necessary	141.85 FL	*- FL
6	1		*TAIL LAMP -LH	Cracked	233.70 FL	*233.70 FL
7	1		*TAIL LAMP SEALANT	Not Necessary	56.00 FL	*- FL
8	2		*TAIL LAMP CLIPS	Not Necessary	25.80 FL	*- FL
9	1		*TAIL LAMP BASE PANEL -LH	Bent	187.70 FL	*187.70 FL
10	1		*BOOT LID	Dented / Bent	972.40 FL	*972.40 FL
11	1		*BOOT LID LOCK	Twisted	374.55 FL	*374.55 FL
12	1		*BOOT LID LOCK STRIKER	Not Necessary	43.70 FL	*- FL
13	1		*BOOT LID LOCK CABLE	Not Necessary	174.40 FL	*- FL
14	1		*BOOT LID WEATHERSTRIPE	Twisted	203.10 FL	*203.10 FL
15	2		*BOOT LID HINGE	Not Necessary	264.20 FL	*- FL
16	2		*BOOT LID OUTER GARNISH CLIPS	Not Necessary	25.80 FL	*- FL
17	1		*BOOT LID OUTER GARNISH BADGE	Not Necessary	27.75 FL	*- FL
18	1		*BOOT LID EMBLEM AXIO	Necessary	29.40 FL	*29.40 FL
19	1		*BOOT LID EMBLEM X	Necessary	27.75 FL	*27.75 FL
20	1		*REAR FENDER -LH	Distorted	980.80 FL	*980.80 FL
21	1		*REAR FENDER SPLASH SHIELD	N/S Torn	362.50 FL	*181.25 FL
22	6		*REAR FENDER SPLASH SHIELD CLIPS	Not Necessary	77.40 FL	*- FL
23	1		*REAR FENDER INNER TRIM BOARD N/S	Distorted	781.25 FL	*366.10 FL
24	1		*REAR FENDER INNER TRIM BOARD CLIPS (12 PCS)	Necessary	154.80 FL	*50.00 FL
25	1		*REAR END PANEL	Distorted	589.40 FL	*589.40 FL
26	1		*REAR END PANEL TOP TRIM	Distorted	281.90 FL	*281.90 FL
27	4		*REAR END PANEL TOP TRIM CLIPS	Not Necessary	51.60 FL	*- FL
28	1		*REAR FLOOR PANEL	Crumpled / Buckled	972.40 FL	*972.40 FL
29	1		*REAR FLOOR PANEL BOARD	Warped	372.80 FL	*372.80 FL
30	1		*REAR FLOOR PANEL INSULATOR CLOTH	Necessary	421.20 FS	*150.00 FS
31	1		*REAR SUB CHASSIS FRAME MEMBER -LH	Repair	691.55 FL	*- FL
32	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	182.25 FL	*182.25 FL
33	1		*REAR WINDSCREEN GLASS	Not Necessary	1,145.00 FL	*- FL
34	10		*REAR WINDSCREEN GLASS CLIPS	Not Necessary	129.00 FL	*- FL
35	2		*REAR WHEEL HOUSING PANEL (INNER & OUTER)	Badly Dented	770.00 FL	*770.00 FL

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	12,095.05	7,784.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,918.46	1,908.73
Total Parts (\$\$)	9,176.59	5,876.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM	New	100.00	30.00
2	TO TUFF COAT AFFECTED AREAS	New	200.00	120.00
3	TO REMOVE & REFIX INTERIOR UPHOLSTERY	New	180.00	80.00
4	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
5	TO REMOVE & REFIX REAR WINDSCREEN GLASS	New	200.00	120.00
6	TO REMOVE & REFIX EXHAUST SILENCER & STRAIGHTEN EXHAUST CENTER PIPE	New	280.00	0.00
7	TO RESPRAY AFFECTED AREAS	New	1,800.00	1,300.00
8	TO CHECK & ADJUST CHASSIS ALIGNMENT ON CAR O LINER	New	380.00	0.00
9	TO RENEW DAMAGED PARTS ,STRAIGHTEN & REPAIR REAR CHASSIS MEMBER & REAR RH FENDER & ALIGNED ALL PARTS	New	2,000.00	1,900.00
10	TO REMOVE & REFIX FUEL TANK	New	20.00	60.00
11	TO REMOVE & REFIX REAR UNDERCARRIAGE	New	280.00	200.00
12	COMPUTER 4 WHEEL ALIGNMENT	New	120.00	80.00
Gross Labour Cost (S\$)			5,680.00	3,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >