



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



PORSCHE

EQ INSURANCE COMPANY LTD		NAME :	Mr Yeo Seh Huat	WIP :	40561
5 Maxwell Road		ADDRESS :	12H Poh Huat Road	EXCESS :	
#17-00 Tower Block			Singapore 544940	DATE:	11.12.2018
MND Complex, Singapore 069110		TEL :			
ATTN. : MOTOR CLAIMS					
FAX :					
VEH NO :	SFM3636G	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WPOZZZ99ZFS111067	MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	911 Carrera S	DATE REG.:	12.05.2015	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description			REVISED	PRICES
	QTY				
1	REAR BUMPER <i>URA</i>	1	P991-505-020-22-		\$ 2,027.50
2	SENSOR PARKASSIST <i>?</i>	1	P150-919-275-C -G2L		\$ 256.90
3	REAR BUMPER LOWER COVER BLACK <i>DE</i>	1	P991-505-811-00-1E0		\$ 170.00
4	COVER TAIL PIPE BLACK LH <i>X</i>	1	P991-505-651-00-1E0		\$ 63.10
5	COVER TAIL PIPE BLACK RH <i>SEA</i>	1	P991-505-652-00-1E0		\$ 63.10
6	BLIND RIVET <i>ne</i>	1	P999-190-191-30-		\$ 5.20
7	REAR BUMPER REINFORCEMENT <i>?</i>	1	P991-505-141-00-		\$ 877.10
8	COVERING, INSTALLATION FRAME LH <i>?</i>	1	P991-504-661-01-		\$ 13.10
9	COVERING, INSTALLATION FRAME RH <i>?</i>	1	P991-504-662-01-		\$ 13.10
10	LOGO "PORSCHE" GALVANO SILVER <i>ne</i>	1	P991-559-235-00-		\$ 191.10
11	LOGO "CARRERA" GALVANO SILVER <i>ne</i>	1	P991-559-237-01-		\$ 131.60
12	LOGO "S" GALVANO SILVER 991 <i>ne</i>	1	P991-559-243-01-		\$ 95.20
13	LOGO "911" SMALL <i>ne</i>	1	P991-559-231-02-		\$ 130.00
14	LICENSE PLATE LIGHT <i>THIS</i>	1	P1K8-943-021-C -		\$ 171.80
15	TAIL PIPE RH <i>SEA</i>	1	P991-111-362-03-		\$ 1,049.40
16	CLAMP <i>X</i>	1	P997-111-240-30-		\$ 58.90

TOTAL PARTS

\$ 5,317.10

LESS 10%

\$ 531.71

TOTAL PARTS COST

\$ 4,785.39

Labour Description

1	TO REMOVE / REPLACE REAR BUMPER, OTHER DAMAGED PARTS & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1560	\$ 3,120.00
2	TO RESPRAY REAR BUMPER.	1300	\$ 1,500.00
3	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.	NETT	\$ X 780.00
4	TO SUPPLY 1 PC NUMBER PLATE WITH CASING.	NETT	\$ <i>URA</i> 70.00
5	TO APPLY SPECIAL COATING. <i>(invoice)</i>	NETT	TBA

6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 150 250.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT	\$ 480 600.00
8	SUNDRIES.	NETT	\$ 20 50.00
TOTAL LABOUR		\$ -	\$ 6,370.00
TOTAL PARTS		\$ -	\$ 4,785.39
TOTAL		\$ -	\$ 11,155.39
LESS EXCESS		\$ -	\$ -
TOTAL AFTER EXCESS		\$ -	
GST 7%		\$ -	\$ -
GRAND TOTAL		\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
3 to 4 days
13/12/18 @ 1530
Reay 64 paint