

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2018 08:50
Date Of Accident	30/12/2017 14:20
Exact Location Of Accident	SIGLAP WALK X SIGLAP DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD3595P
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS HYBRID 4G
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0016
Cover Note Number	
Driver	
Name of Driver	MOHD TAIB B WAN EMBONG
NRIC No	S1023407G
Address	BLK 54 CHAI CHEE STREET #12-865

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
Number of Passengers (Including Driver)	2

Circumstances of Accident

REFER ATTACHED * TYPE OF ACCIDENT - HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJY1995Y
Vehicle Make/Model/Colour	LEXUS
Name of Driver	ZHANG YANHUA
Insurance Company Name	

Sketch Plan Pg. 1

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by their insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of this report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the issuing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in reviewing, investigating, controlling or managing fraud, litigation, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

NEWPORT TRANSPORTATION PTE. LTD.
S - REG. NO. 19937352 (1)


Policyholder's Signature
Date: 5/1/2024

Driver's Signature
If driver is not the policyholder
Date: 5/1/2024

Reporting Centre Personnel's Signature
Name: NAYON ETIHA

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As seen in the video, as I was crossing Siglap Walk junction at the time traffic was light, my taxi was hit by a fast-approaching car B (55Y 1995Y) on Siglap Drive.

One female passenger in my taxi also report of injury

DECLARATION

(We declare the foregoing particulars are true in every respect.)

INFORMANT TRANSPORTATION P.T. (REG NO 199303821)

Reporting Officer's Signature
(Name in Print)

Driver's Signature
(If a person not the police officer)
(Name in Print)

Es Soan
1997

Reporting Officer's Signature
(Name in Print)
1997

Accident Photo




Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo




SCENE



SCENE



SCENE



SCENE



Law Firm Search Details

Law Firm Case No.: E21,MISC.18,SJY1995Y

Registered Postal Code: 575717

Insurance Company Name:INDIA INT'L INS PTE LTD

Print OK



redefining / insurance

AXA Insurance Pte Ltd
 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

Certificate of Insurance

01730
 01730

AXA Insurance Pte Ltd is a company limited by guarantee, incorporated in Singapore. Its registered office is at 110 Robinson Road, Singapore 068902. Its principal place of business is at 110 Robinson Road, Singapore 068902. Its principal business is to provide insurance cover to its policyholders.

Policy details

Policyholder name	ZHANG YAN HUA	Certificate number	GA044657 / 1
Cover	Comprehensive	Class number	JTHR1SGY00031517
Plan name	Flexi	Engine number	2ARF045651
NCD applicable	20%		
Vehicle registration number	SJY1955Y		
Period of insurance	From 17/06/2017 to 16/06/2018 (both dates inclusive)		
Finance loan company	DES BANK LTD		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
 (b) Any person who is driving on the Policyholder's order or with their permission

*Provides that the person driving is permitted in accordance with the licensing or other relevant regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation that relate to driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, competitive, reliability trials, speed testing, the carriage of goods or in any manner in connection with any trade or business or use for any purpose in connection with motor trade, other than the Motor Car, together with other equipment, in any manner or in connection with any trade, business, pleasure or other activity which involves the carriage of goods or the carriage of persons or the carriage of goods or persons in any manner.

*Covering is not valid in respect of the Motor Vehicle's use for hire or reward, other than the Motor Car, together with other equipment, in any manner or in connection with any trade, business, pleasure or other activity which involves the carriage of goods or the carriage of persons or the carriage of goods or persons in any manner.

EXCESS	Basic Own Damage Excess	S\$0 600 00
	Voluntary Excess	S\$0 100 00
An additional Excess is applicable as follows:		
1. S\$500 for Uninsured Autostrided Driver		
2. S\$500 for the third young and inexperienced driver		
3. S\$5 000 for under 21 year old and the second driver. This maximum excess is reduced to S\$2 500 for new drivers on AXA Premium		
No Excess		

Additional clauses & endorsements to your policy

AXA Insurance Pte Ltd

[Signature]

Representative of

E M SOLUTION PTE LTD

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722

Tel: 64560226

Fax: 64584500

GST Reg. No: 201016308K

24.10.2018

Proforma Invoice:

TI05219

Zhang Yanhua

FINAL REPAIR BILL FOR TOYOTA LEXUS ES250 - SJY 1995 Y

Lump sum for total repair cost inclusive of labour charge
and spare parts.

20,200.00

GST 7% 1,414.00

\$ 21,614.00





Invoice

ZHANG YAN HUA
90 SIGLAP DRIVE
S(456193)

Invoice No : GPLIN0000666
Invoice Date : 13/1/2018
Due Date : 13/1/2018
VHA No : 0903
Referral ID : E001

Description :	Amount
Rental for 9 Day/s @ \$200 per Day	\$1,800

Vehicle No : SLT6006Y

Vehicle Description : Mazda 6

Rental Period : 02/01/2018 to 11/01/2018

Total Amount Payable : \$1,800

GOOD WAY RENT-A-CAR PTE LTD

8 Kaki Bukit Ave 4 #06-04 Premier@Kaki Bukit Singapore 415875

Tel: 6315 8479 H/P: 9833 0807

(S20 1955 8)

VHA No: 0903

UEN: 201505120D

VEHICLE RENTAL AGREEMENT

HIRER'S PARTICULAR Name: (as in I/C) _____ NRIC/PASSPORT No: _____ Address (Res): _____ Name & Address of Employer: _____ Occupation: _____ Driving Exp: _____ Driving Licence No: _____ D/L Type: Local / International Issue Date: _____ Date of Birth: _____ Tel: (O) _____ (H) _____ HP/PG: _____	Vehicle No: _____ Replace Veh No: _____ Mileage Out: _____ Mileage Out: _____ Make & Model: _____ Auto / Manual Group: _____ Out Date: _____ Time: _____ HIRE / PERIOD EXPIRY: _____ Time: _____ NON-WAIVER EXCESS=\$ _____																																																
ADDITIONAL DRIVER'S PARTICULARS Name: (as in I/C) _____ NRIC/PASSPORT No: _____ Address (Res): _____ Driving License No: _____ D/L Type: Local / International Issue Date: _____ Date of Birth: _____ Occupation: _____ Driving Exp: _____	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="3">CHARGES</th> </tr> <tr> <td>Daily</td> <td>@ \$</td> <td>per day</td> </tr> <tr> <td>Weekly</td> <td>@ \$</td> <td>per week</td> </tr> <tr> <td>Monthly</td> <td>@ \$</td> <td>per month</td> </tr> <tr> <td>Hours</td> <td>@ \$</td> <td>per hour</td> </tr> <tr> <td>Others</td> <td>@ \$</td> <td></td> </tr> <tr> <td>CDW</td> <td>@ \$</td> <td>per day/month</td> </tr> <tr> <td>PAI</td> <td>@ \$</td> <td>per day/month</td> </tr> <tr> <td colspan="3">Delivery/Collection Service</td> </tr> <tr> <td colspan="3" style="text-align: right;">SUB-TOTAL \$</td> </tr> <tr> <td colspan="3">PETROL LEVEL</td> </tr> <tr> <td>Out</td> <td>E</td> <td>1/4 1/2 3/4 F</td> </tr> <tr> <td>In</td> <td>E</td> <td>1/4 1/2 3/4 F</td> </tr> <tr> <td colspan="3">EXTENSION</td> </tr> <tr> <td colspan="3">Misc.</td> </tr> <tr> <td colspan="3" style="text-align: right;">TOTAL CHARGES \$</td> </tr> </table>	CHARGES			Daily	@ \$	per day	Weekly	@ \$	per week	Monthly	@ \$	per month	Hours	@ \$	per hour	Others	@ \$		CDW	@ \$	per day/month	PAI	@ \$	per day/month	Delivery/Collection Service			SUB-TOTAL \$			PETROL LEVEL			Out	E	1/4 1/2 3/4 F	In	E	1/4 1/2 3/4 F	EXTENSION			Misc.			TOTAL CHARGES \$		
CHARGES																																																	
Daily	@ \$	per day																																															
Weekly	@ \$	per week																																															
Monthly	@ \$	per month																																															
Hours	@ \$	per hour																																															
Others	@ \$																																																
CDW	@ \$	per day/month																																															
PAI	@ \$	per day/month																																															
Delivery/Collection Service																																																	
SUB-TOTAL \$																																																	
PETROL LEVEL																																																	
Out	E	1/4 1/2 3/4 F																																															
In	E	1/4 1/2 3/4 F																																															
EXTENSION																																																	
Misc.																																																	
TOTAL CHARGES \$																																																	
VEHICLE CHECK LIST INDICATE: D - DENTS S - SCRATCHES A - ACCIDENTS RIGHT FRONT TOP LEFT																																																	
ACCESSORIES CHECK ☐ Ashtray ☐ Cig Lighter ☐ S/Tyre ☐ STD Tools ☐ Jack ☐ Hub Caps ☐ Radio/Cass ☐ CD ☐ Cartridges	Hirer's Signature _____ Additional Driver's Signature _____																																																

I have read and agree to the terms and condition on both sides of the agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given GOOD WAY RENT-A-CAR PTE LTD in connection with this agreement is true.

*IMPORTANT

1. ONLY PERSON ABOVE 21 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE AUTHORIZED LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
2. ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REQUIRED TO BE.
3. THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUDING OF CDW AND/OR PAI WHERE APPLICABLE.
4. IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTIN OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
5. THE VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY, AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY GOOD WAY RENT-A-CAR PTE LTD.

RETURN OF VEHICLE: THE HIRER/DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SINGAPORE OF HIRER/DRIVER" DURING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE THE DAY AND TIME THE VEHICLE IS RETURNED TO GOOD WAY RENT-A-CAR PTE LTD AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	
SIGNATURE OF HIRER/DRIVER					

PAR Automotive Consultancy

Regn No: S29869741

Thomson Rd Post Office PO Box 029 Singapore 915701 Tel: 64531173, Fax: 64536131
Consultants: Vehicle appraisal & inspection, accident investigation, expert witness

Report No: 0045-18-EMAm

22 October 2018

Zhang Yanhua
90 Siglap Drive
Singapore 456193

INVOICE No. 0045-18-EMAm

Vehicle No. SJY1995Y

<u>S/NO.</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport and photographs.	\$1,024.00
2	Re-inspection work in progress and post repair inspection.	\$60.00
Total amount payable		<u>\$1,084.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



P'AR Automotive Consultancy

Thomson Rd Post Office PO Box 029 Singapore 915701 Tel: 64531173, Fax: 64536131
Appraisal & inspection, accident investigation, expert witness

Repn. No: 52986974L

Consultancy Vehicle

Report No: 0045-18-EMAm

22 October 2018

ACCIDENT VEHICLE SURVEY REPORT

Zhang Yanhua
90 Siglap Drive
Singapore 456193

VEHICLE INFORMATION:

Vehicle Reg No.	SJY1995Y	Odometer	29510km
Make & Model:	Toyota Lexus ES250 Luxury / Colour:		White
Chassis number:	JTHBJ1GGX02081817	Date of accident:	30/12/2017
Year of Regn.	17/06/2015	Date inspected:	03/01/2018
Repairer at:	EM Solution Pte Ltd	Date inspected (After Repair):	-
	160 Sin Ming Drive #03-19 Sin Ming Autocity		
	Singapore 575722		

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	6mm/Yokohama	6mm/Yokohama	215/55R17
Rear:	6mm/Yokohama	6mm/Yokohama	215/55R17

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the RH front portion.

Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

Report No: 0045-18-EMAm Vehicle No: SJY1995Y

Description of part	Qty	Condition as inspected	Repairer's estimate	Our adjustment
Front bonnet	1	buckled	1,062.10	1,062.10 R X
Front bonnet weatherstrip	1	necessary	65.10	65.10 NN X
Front bonnet insulator clip set	1	necessary	50.00	50.00 NN X
Front bonnet lock	1	bent	185.30	185.30 NN X
Front head lamp RH	1	broken	3,269.60	3,269.60 BR ✓
Front bumper radiator grille	1	fractured	541.00	541.00 BR ✓
Front bumper radiator grille emblem 'Lexus' logo	1	necessary	95.10	95.10 NE ✓
Front bumper radiator grille clip	3	necessary	19.50	19.50 NE ✓
Front bumper	1	torn	617.10	617.10 BR ✓
Front bumper centre chrome moulding	1	broken	215.10	215.10 BR ✓
Front bumper number plate garnish	1	deformed	143.70	143.70 NN X
Front bumper head lamp washer cover RH/LH	1 → 2	ripped/fractured	273.80	136.90 273.80 C/T ✓
Front bumper head lamp washer nozzle RH/LH	1 → 2	fractured	1,033.50	516.50 1,033.50 C/T ✓
Front bumper head lamp washer nozzle clamp RH/LH	1 → 2	necessary	26.00	13.00 26.00 C/T
Front bumper head lamp washer relay	1	shorted	264.30	264.30 NN X
Front bumper ultrasonic sensor centre	1 → 2	shorted	708.00	354.00 708.00 C/T ✓
Front bumper ultrasonic sensor retainer centre	2	necessary	60.00	60.00 NN X
Front bumper ultrasonic sensor side	1 → 2	shorted	708.00	354.00 708.00 C/T ✓
Front bumper ultrasonic sensor retainer side	1 → 2	necessary	60.00	30.00 60.00 C/T ✓
Front bumper ultrasonic sensor wire harness	1	shorted	298.90	298.90 NN X
Front bumper tow cover	1	ripped	23.90	23.90 M/S ✓
Front bumper lower centre garnish	1	fractured	230.30	230.30 D/D ✓
Front bumper fog lamp RH/LH	1 → 2	fractured	745.40	330.00 745.40 BR ✓
Front bumper fog lamp chrome bezel RH/LH	1 → 2	fractured	234.30	117.15 234.30 BR ✓
Front bumper fog lamp bracket RH/LH	1 → 2	bent	275.30	137.65 275.30 B/T ✓
Front bumper sponge	1	deformed	110.40	110.40 BR ✓
Front bumper side retainer RH/LH	2	necessary	264.50	131.60 264.50 NE ✓
Front bumper clip	10	necessary	45.00	45.00 NE ✓
Wiper washer tank	1	deformed	137.60	137.60 D/D ✓
Head lamp washer motor	1	shorted	214.65	214.65 NN X
Head lamp washer motor hose	1	deformed	162.30	162.30 C/T ✓
Head lamp washer hose	1	deformed	182.25	182.25 C/T ✓
Front fender RH	1	buckled	1,082.70	1,082.70 D/D ✓
Front fender top protector RH	1	deformed	105.20	105.20 B/T ✓

Front fender inner shield RH	1	deformed	252.72	252.72 DD ✓
Front fender inner shield clip	15	necessary	52.50	52.50 NEC ✓
Front fender inner protector RH	1	deformed	110.10	110.10 DD ✓
Front engine under cover RH	1	deformed	194.95	194.95 TN ✓
Front engine under cover LH	1	deformed	194.95	194.95 NN X
Front engine under cover clip	5 10	necessary	45.00	22.50 45.00
Front sport rim RH	1	abraded	1,080.00	1,080.00 RX
Front shock absorber RH	1	bent	836.60	836.60
Front shock absorber top mounting RH	1	necessary	270.60	270.60 } KKA
Front knuckle arm RH	1	bent	726.10	726.10
Front knuckle arm bearing RH	1	dislodged	931.60	931.60 ✓
Front stabiliser link RH	1	bent	130.50	130.50
Front lower arm RH	1	bent	938.80	938.80 } NN
Front lower arm ball joint RH	1	bent	123.30	123.30
Front door RH	1	buckled	1,019.20	✓ 1,019.20 DD ✓
Front door frame black tape top RH	1	necessary	42.30	42.30
Front door frame black tape RH	1	necessary	45.10	45.10
Front door frame outer garnish RH	1	necessary	65.30	65.30 } NEC ✓
Front door glass outer chrome moulding RH	1	necessary	242.10	242.10
Front door frame outer chrome moulding RH	1	necessary	165.10	165.10 } KKA
Front door glass inner moulding RH	1	necessary	161.35	161.35
Front door glass run channel RH	1	deformed	262.10	262.10 DD X
Front door weatherstrip RH	1	deformed	263.10	263.10 cut ✓
Front door weatherstrip bottom RH	1	deformed	124.30	124.30 cut ✓
Front door hinge RH	2	bent	19.40	19.40 NN X
Front door inner trim board RH	1	deformed	897.50	897.50 NN X
Front door inner lock RH	1	bent	509.10	509.10 NN ✓
Front door window regulator RH	1	bent	269.10	269.10 BT ✓
Front door window regulator motor RH	1	shorted	509.10	509.10 NN X
Rocker panel garnish RH	1	deformed	767.40	561.60 767.40 DD ✓
Rocker panel garnish retainer RH	2	necessary	220.20	SIC 220.20 NEC X
Subtotal before discount			24,979.37	24,979.37
Percentage discount 0% and 10%			0.00	2,497.94
Parts-total			24,979.37	22,481.43

LABOUR

1. To straighten and panel beating RH front fender inner panel, RH front door pillar, RH rocker panel and RH front frame members. To remove and refit above parts.	1,120.00	880.00 700
2. To putty, re-spray painting and polish affected areas.	1,500.00	200.00 1,200.00
3. To check and rectify wiring system.	80.00	50.00
4. To rust proof affected areas.	120.00	60.00
5. To remove, refit RH front sport rim/tyre and balancing.	50.00	30 40.00 NNX
6. To remove and refit front suspension system.	400.00	150.00 NNX
7. To conduct electronic wheel alignment test.	180.00	150.00 NNX
8. To remove, transfer and refit RH front door components.	150.00	60.00 100.00
	Labour total	3,600.00
	Parts & Labour total	28,579.37
		2,830.00
		25,311.43

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on LUMP SUM repairs is : **\$20,200.00**
and the recommended number of working days for the repairs is : **8**


B J Loi (J Eng MIML AIRTE)
Automotive Appraiser

Repair days 6


12/12/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CS3/III18000097/Bsbs2-1		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 19-12-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3595P	Veh. Inspected	SJY 1995Y	
Policy No.	MCOM0015	Coverage (\$)	0.00	
Claim No.	MCT17121051	Excess (\$)	0.00	
Assign From	JOEL NAH	Assign Date	11/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA LEXUS	c.c	2494	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JTHBJ1GGX02081817	Colour	PEARL WHITE	
Odometer	29510	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55R17	YOKOHAMA	7 mm	
L/H Front Tyre	215/55R17	YOKOHAMA	7 mm	
R/H Rear Tyre	215/55R17	YOKOHAMA	7 mm	
L/H Rear Tyre	215/55R17	YOKOHAMA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/12/2017	Inspection Date	03/01/2018	
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 1995Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET	TO REPAIR SEE LABOUR	1,062.10	-
1	FRONT BONNET WEATHERSTRIP	NOT NECESSARY	65.10	-
1	SET FRONT BONNET INSULATOR CLIP	NOT NECESSARY	50.00	-
1	FRONT BONNET LOCK	NOT NECESSARY	185.30	-
1	FRONT HEAD LAMP RH	BROKEN	3,269.60	3,269.60
1	FRONT BUMPER RADIATOR GRILLE	BROKEN	541.00	541.00
1	FRONT BUMPER RADIATOR GRILLE EMBLEM 'LEXUS' LOGO	NECESSARY	95.10	95.10
3	FRONT BUMPER RADIATOR GRILLE CLIP	NECESSARY	19.50	19.50
1	FRONT BUMPER	BROKEN	617.10	617.10
1	FRONT BUMPER CENTRE CHROME MOULDING	BROKEN	215.10	215.10
1	FRONT BUMPER NUMBER PLATE GARNISH	NOT NECESSARY	143.70	-
2	FRONT BUMPER HEAD LAMP WASHER COVER RH/LH	O/S CUT	273.80	136.90
2	FRONT BUMPER HEAD LAMP WASHER NOZZLE RH/LH	O/S CUT	1,033.50	516.50
2	FRONT BUMPER HEAD LAMP WASHER NOZZLE CLAMP RH/LH	O/S CUT	26.00	13.00
1	FRONT BUMPER HEAD LAMP WASHER RELAY	NOT NECESSARY	264.30	-
2	FRONT BUMPER ULTRASONIC SENSOR CENTRE	CUT 1PC ONLY	708.00	354.00
2	FRONT BUMPER ULTRASONIC SENSOR RETAINER CENTRE	NOT NECESSARY	60.00	-
2	FRONT BUMPER ULTRASONIC SENSOR SIDE	CUT 1PC ONLY	708.00	354.00
2	FRONT BUMPER ULTRASONIC SENSOR RETAINER SIDE	CUT 1PC ONLY	60.00	30.00
1	FRONT BUMPER ULTRASONIC SENSOR WIRE HARNESS	NOT NECESSARY	298.90	-
1	FRONT BUMPER TOW COVER	MISSING	23.90	23.90
1	FRONT BUMPER LOWER CENTRE GARNISH	DENTED	230.30	230.30
2	FRONT BUMPER FOG LAMP RH/LH	O/S BROKEN	745.40	330.00
2	FRONT BUMPER FOG LAMP CHROME BEZEL RH/LH	O/S BROKEN	234.30	117.15
2	FRONT BUMPER FOG LAMP BRACKET RH/LH	O/S BENT	275.30	137.65
1	FRONT BUMPER SPONGE	BROKEN	110.40	110.40
2	FRONT BUMPER SIDE RETAINER RH/LH	NECESSARY	264.50	131.60
10	FRONT BUMPER CLIP	NECESSARY	45.00	45.00
1	WIPER WASHER TANK	DENTED	137.60	137.60
1	HEAD LAMP WASHER MOTOR	NOT NECESSARY	214.65	-
1	HEAD LAMP WASHER MOTOR HOSE	NOT NECESSARY	162.30	-

Report Ref No. CS3/III18000097/Bsbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HEAD LAMP WASHER HOSE	NOT NECESSARY	182.25	-
1	FRONT FENDER RH	DENTED	1,082.70	1,082.70
1	FRONT FENDER TOP PROTECTOR RH	BENT	105.20	105.20
1	FRONT FENDER INNER SHIELD RH	DENTED	252.72	252.72
15	FRONT FENDER INNER SHIELD CLIP	NECESSARY	52.50	52.50
1	FRONT FENDER INNER PROTECTOR RH	DENTED	110.10	110.10
1	FRONT ENGINE UNDER COVER RH	TORN	194.95	194.95
1	FRONT ENGINE UNDER COVER LH	NOT NECESSARY	194.95	-
10	FRONT ENGINE UNDER COVER CLIP	NECESSARY 5PCS ONLY	45.00	22.50
1	FRONT SPORT RIM RH	TO REPAIR SEE LABOUR	1,080.00	-
1	FRONT SHOCK ABSORBER RH	NOT NECESSARY	836.60	-
1	FRONT SHOCK ABSORBER TOP MOUNTING RH	NOT NECESSARY	270.60	-
1	FRONT KNUCKLE ARM RH	NOT NECESSARY	726.10	-
1	FRONT KNUCKLE ARM BEARING RH	DISLODGE	931.60	931.60
1	FRONT STABILIZER LINK RH	NOT NECESSARY	130.50	-
1	FRONT LOWER ARM RH	NOT NECESSARY	938.80	-
1	FRONT LOWER ARM BALL JOINT RH	NOT NECESSARY	123.30	-
1	FRONT DOOR RH	DENTED	1,019.20	1,019.20
1	FRONT DOOR FRAME BLACK TAPE TOP RH	NECESSARY	42.30	42.30
1	FRONT DOOR FRAME BLACK TAPE RH	NECESSARY	45.10	45.10
1	FRONT DOOR FRAME OUTER GARNISH RH	NECESSARY	65.30	65.30
1	FRONT DOOR GLASS OUTER CHROME MOULDING RH	NECESSARY	242.10	242.10
1	FRONT DOOR FRAME OUTER CHROME MOULDING RH	NOT NECESSARY	165.10	-
1	FRONT DOOR GLASS INNER MOULDING RH	NOT NECESSARY	161.35	-
1	FRONT DOOR GLASS RUN CHANNEL RH	NOT NECESSARY	262.10	-
1	FRONT DOOR WEATHERSTRIP RH	CUT	263.10	263.10
1	FRONT DOOR WEATHERSTRIP BOTTOM RH	CUT	124.30	124.30
2	FRONT DOOR HINGE RH	NOT NECESSARY	19.40	-
1	FRONT DOOR INNER TRIM BOARD RH	NOT NECESSARY	897.50	-
1	FRONT DOOR INNER LOCK RH	BENT	509.10	509.10
1	FRONT DOOR WINDOW REGULATOR RH	BENT	269.10	269.10
1	FRONT DOOR WINDOW REGULATOR MOTOR RH	NOT NECESSARY	509.10	-
1	ROCKER PANEL GARNISH RH	DENTED	767.40	561.60
2	ROCKER PANEL GARNISH RETAINER RH	SERVICEABLE	220.20	-

Report Ref No. CS3/III18000097/Bsbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-	-1,331.89
			24,979.37	11,986.98
	LABOUR			
	TO STRAIGHTEN AND PANEL BEATING RH FRONT FENDER INNER PANEL, RH FRONT DOOR PILLAR, RH ROCKER PANEL AND RH FRONT FRAME MEMBERS. TO REMOVE AND REFIT ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT BONNET AND FRONT SPORT RIM RH.		1,120.00	700.00
	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS.		1,500.00	800.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	50.00
	TO RUST PROOF AFFECTED AREAS.		120.00	60.00
	TO REMOVE, REFIT RH FRONT SPORT RIM / TYRE AND BALANCING.		50.00	30.00
	TO REMOVE AND REFIT FRONT SUSPENSION SYSTEM.		400.00	120.00
	TO CONDUCT ELECTRONIC WHEEL ALIGNMENT TEST.		180.00	80.00
	TO REMOVE, TRANSFER AND REFIT RH FRONT DOOR COMPONENTS.		150.00	60.00
			3,600.00	1,900.00
	GRAND TOTAL		28,579.37	13,886.98
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,100.00

Report Ref No. CS3/III18000097/Bsbs2-1

LIM TEOW GUAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.