

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

AIG

Owner : Wong Sing Hua

Accident Date : 14-Nov-18

Vehicle No : JKK 798

Vehicle Model : Yamaha LC135

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
2	Front fork tubes assy	\$ 640.00x
1	Front wheel rim	\$ 280.00x
1	Fork under bracket	\$ 185.00x
1	Front rim shaft	\$ 45.00x
1	Front rim bearing	\$ 38.00x
1	Front brake disc	\$ 155.00x
1	Handle bar	\$ 75.00
1	Handle bar end	\$ 32.00
1	Hand grip (1 set)	\$ 55.00x
1	Handle bar inner bracket	\$ 68.00x
1	Side mirror	\$ 55.00
1	Front signal	\$ 70.00
1	Headlamp	\$ 185.00x
1	Fairing assy (1 set)	\$ 475.00
1	Front footrest bracket	\$ 65.00
1	Front footrest rubber	\$ 35.00
1	Gear pedal	\$ 42.00
1	Rear footrest	\$ 40.00
1	Rear footrest bracket	\$ 78.00x
1	Rear absorber (1 set)	\$ 350.00x
1	Side stand	\$ 75.00x
1	Main stand	\$ 95.00x
1	Rear taillamp	\$ 135.00x
1	Rear wheel rim	\$ 280.00x
1	Rear fender	\$ 120.00
1	Rear fender reflector	\$ 40.00x
1	Rear rim shaft	\$ 45.00x
1	Rear rim bearing	\$ 38.00x
1	Swing arm	\$ 425.00x
		\$ 4,221.00
	Less 10%	\$ 422.10
		\$ 3,798.90

c/f: \$ 3,798.90

Special Nett Items

1	Number plate (1 set)	\$ 11	28.00	α
2	Fork oils	\$ 11	30.00	α
2	Fork oil seals	\$ 11	56.00	α
1	Steering cone (1 set)	\$ 11	90.00	α
1	Rear box	\$ 647	250.00	180
1	Rear box bracket	\$ 54	100.00	—
1	Helmet	\$ R	120.00	α
1	Sticker (1 set)	\$ 25	95.00	—
		\$	769.00	

S/No. Labour

1	To provide towing service.	\$ 35	50.00
2	To check wiring and reset headlamp focusing.	\$ 11	80.00
3	To provide labour.	\$ 250	380.00
		\$	510.00

Grand Total

\$ 5,077.90

15681
1254.

Dollars: Five Thousand Seventy-Seven And Ninety Cents Only.



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: