



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



### ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
MR AZLAN BIN BAHAROM	Cust No/Name /MR AZLAN BIN BAHAROM
BLK 304 WOODLANDS ST 31	Reg No/Reg Date SLA1332M / 23/02/201
#04-117	Date In/Mileage / 0
SINGAPORE 730304	Chassis No KNAFZ411MF5534218
Contact No Mobile: 96499234	Engine No G4FGFH799593
	Make/Model KIA/FORTE K3 1.6 A SX ADQ
	Colour/Trim SWP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	10/12/2018/ 17:20		465 / Tay Jian Ye	40523			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								550 1650.00
TO RENEW REAR BUMPER, LWR BUMPER CTR, REPAIR REAR END PANEL								420 1260.00
E PNT98000								60.00
PAINT WORK SPRAY REAR BUMPER , END PANEL								30.00
E PNT88000								200.00
TO TRANSFER REAR PARKING SENSOR TO NEW PART								20.00
A 54900099								
TO CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								
SUNDRIES					1.00	75.00	00.00	x 75.00
M STAY-RR BUMPER LH					1.00	75.00	00.00	x 75.00
M STAY-RR BUMPER RH					1.00	365.00	00.00	? 365.00
M BEAM-RR BUMPER					2.00	5.00	00.00	? 10.00
M BRACKET-RR BEAM LWR MTG					1.00	5.00	00.00	? 5.00
M BRACKET-RR BEAM LWR,CTR					1.00	791.00	00.00	de 791.00
M COVER-RR BUMPER					1.00	245.00	00.00	de 245.00
M COVER-RR BUMPER,UPR					1.00	172.00	00.00	? 172.00
M ULTRASONIC SENSOR ASSY-FBWS					1.00	172.00	00.00	x 172.00
M ULTRASONIC SENSOR ASSY-FBWS								

SURVEYOR NAME: Tan Jian 97495749SURVEYOR SIGNATURE: [Signature]DATE: 16/1/19 3:50 pm WPREMARKS: Renew before paintsure (Mian to in  
03 days

Confirm &amp; accepted by

Authorized signatory and company stamp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

7% GST on

Nett

5130.00

5,130.00

359.10

Total Payable

5,489.10

Validity of this estimate is 14 days from date of quote. This is a final estimate and no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.