

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>rep</i>			\$ 1,052.20 X
	Front Bumper Bracket (LH) <i>NH</i>			\$ 24.60 X
	Headlamp Support Panel Assy <i>briker</i>			\$ 907.40 ✓
	Headlamp (LH) <i>briker</i>			\$ 1,388.00 ✓
	Front Fender (LH) <i>Dented</i>			\$ 566.30 ✓
	Front Fender Apron Panel (LH) <i>Dented</i>			\$ 637.00 ✓
	Front Fender Shield (LH) <i>deformed</i>			\$ 174.90 ✓
	Front Door (LH) <i>Dented</i>			\$ 2,256.40 ✓
	Front Door Rubber <i>HLC</i>			\$ 290.50 ✓
	Front Door Gear / Regulator (LH) <i>NH</i>			\$ 250.60 X
	Front Door Power Motor, LH <i>NH</i>			\$ 172.70 X
	Rocker Panel Outer Garnish <i>rep</i>			\$ 341.40 X
	Front Windscreen Moulding <i>HLC</i>			\$ 113.30 ✓
	Front Windscreen Pillar Outer(LH) <i>Dented</i>			\$ 1,745.50 ✓ photo
	Front Wheel Rim (LH) <i>2 distorted</i>			\$ 325.30 2 ✓
	Front Wheel Hub Cap (LH) <i>red</i>			\$ 107.10 ✓
	Front Wheel Bearing <i>2 Don</i>			\$ 540.50 2 ✓
	Front Shock Absorber (Assy) (LH) <i>2 distorted</i>			\$ 342.20 2 ✓
	Front Shock Absorber Mounting (LH) <i>NH</i>			\$ 108.80 X
	Front Drive Shaft (LH) <i>NH</i>			\$ 1,030.80 X
	Rack & Pinion Assy <i>NH</i>			\$ 969.60 X
	STG Tie End <i>2 distorted</i>			\$ 62.60 2 ✓
	Stabilizer Bar <i>2 distorted</i>			\$ 252.30 2 ✓
	Stabilizer Bar Bush (LH) <i>NH</i>			\$ 16.40 X
	Stabilizer Bar Link <i>2 distorted</i>			\$ 61.10 2 ✓
	Stabilizer Bracket <i>NH</i>			\$ 24.00 X
	Front Suspension Lower Arm (LH) <i>2 distorted</i>			\$ 529.30 2 ✓
	Knuckle Arm (LH) <i>2 distorted</i>			\$ 552.00 2 ✓
	Engine Under Cover <i>NH</i>			\$ 334.60 X
	Engine Crossmember <i>NH</i>			\$ 2,094.40 X
	ABS Sensor <i>NH</i>			\$ 234.00 X
	Wiring-Engine <i>2 mounting briker</i>			\$ 3,326.00 2 ✓
	Electric Power Steering <i>NH</i>			\$ 4,880.50 X
	SUB TOTAL			\$ 25,712.30
	LESS 20%			\$ 5,142.46
	DISCOUNTED TOTAL			\$ 20,569.84
	Front Door Comfort Logo (LH) <i>HLC</i>			\$ 75.00 Nett ✓
	Front Windscreen Sealant <i>HLC</i>			\$ 46.00 Nett ✓
	Front Tyre (LH) <i>SYC</i>			\$ 216.00 Nett X
				\$ 337.00

SHD 3466D

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating		\$ 2,000.00	800/-
	Spray Painting Charge		\$ 1,500.00	700/-
	Wiring Charge		\$ 50.00	30/-
	Tuff Kote		\$ 100.00	40/-
	Towing Charge		\$ 50.00	44
	Remove/Refix Undercarriage (FRT)		\$ 200.00	150/-
	FRT Wheel Alignment		\$ 120.00	60/-
	Re-set Frt ABS System		\$ 200.00	44
	Re-set Frt Power Window System		\$ 200.00	44
	Remove/Refix Aircon & Refill Gas		\$ 150.00	44
	Remove/Refix Dashboard		\$ 450.00	150/-
	Remove/Refix Fuse Box		\$ 180.00	50/-
	Remove/Refix Front Windscreen Glass		\$ 120.00	80/-
	Remove/Refix Cushion & Upholstery Front		\$ 90.00	60/-
	Diagnostic & Resetting To Erase Fault Code		\$ 480.00	44
	TOTAL LABOUR			\$ 5,890.00
	ESTIMATE TOTAL			\$ 26,796.84
	11/12/2018 @ 1400hrs HA Antmal 2/Sum 8 days. ryan LKK Auto			
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			