



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 11.12.2018

India International Insurance Pte Ltd
64 Cecil Street #04/#05
IOB Building
Singapore 049711

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2410X HONDA SHUTTLE (2017)

To Supply

1)	1pc	Right rear door	PA ✓	\$	958.50
2)	1pc	Right lower rocker panel	under repair	\$	435.00
Sub total parts				\$	1,393.50
Less: 20% discount				\$	278.70
				\$	1,114.80

To supply S.Nett Parts

1)	1pc	Right side skirt	cut ✓	\$	580.00
Sub total S.Nett Parts				\$	580.00

L/charges

1)	To tuff kote	\$	50.00 ✓
2)	To transfer right rear door handle, door trim cover and mechanism parts	\$	60.00 ✓
3)	To remove & replace right rear door & right side skirt. Knock & repair right rear fender. Replace the above parts.	\$	700.00 500

- 4) To putty, respray painting right rear door inlet & outer, right side skirt & right rear fender. To polish

\$

900.00

600
~~500~~

Sub total L/charges	\$	1,710.00
Estimated Grand Total	\$	3,404.80

Revised

Hp 90010068

5 days

4/8

~~11/11~~ 11/12/18 @ 1125

Revised after report