

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

10/12/2018

TPAXA.

Vic

Accident date: 07/12/2018

Estimated repair cost for vehicle no: SKZ16M BMW 252i XL 2.5 A '09

CHASSIS: WBANU52020C228596

S/n	Qty	Items	U/price	Amount
1	1	Front Bumper <i>Detached</i>		\$1,178.55 ✓
2	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 30
3	1	Front Bumper Inner Sponge <i>2nd</i>		\$112.20 x
4	1	Front Bumper Reinforcement <i>new</i>		\$673.85 x
5	4	Front Bumper Sensor <i>1 piece damaged</i>	\$236.85	\$947.40 236.85
6	4	Front Bumper Sensor Holder <i>new</i>	\$56.85	\$227.40 x
7	1	Front L/H Bumper Side Retainer <i>new</i>		\$19.05 ✓
8	1	Front L/H Bumper Fog Lamp <i>lit</i>		\$234.65 ✓
9	1	Front L/H Bumper Fog Lamp Cover <i>lit</i>		\$65.85 ✓
10	1	Front L/H Head Lamp <i>lit</i>		\$2,517.15 ✓
11	1	Front L/H Head Lamp Lower Bracket <i>new</i>		\$27.65 x
12	1	Front L/H Fender <i>Dented</i>		\$840.65 ✓
13	1	Front L/H Fender Cowling <i>new</i>		\$155.40 x
14	1	Front L/H Rim <i>lit</i>		\$810.75 ✓
15	1	Front L/H Tyre <i>new</i>		\$550.00 x
16	1	Front L/H Lower Arm <i>Best</i>		\$372.65 ✓
17	1	Front L/H Knuckle Arm <i>new</i>		\$606.65 x
18	1	Front L/H Knuckle Arm Bearing <i>new</i>		\$484.35 ✓
19	1	Front L/H Shock Absorber <i>2</i>		\$597.40 x
20	1	Front L/H Drive Shaft <i>new</i>		\$2,324.60 x
21	1	Front Steering Rack <i>new</i>		\$3,900.65 x

Subtotal :- **\$16,711.85**

6780.50

6450.97

Labour charges

To remove & refit front L/H undercarriage	\$380.00 220
To remove & refit drive shaft & steering rack	\$450.00 X
To check wheel alignment	\$150.00 80
To check wiring	\$60.00 30
Tuff kote	\$150.00 X
Panel beating	\$1,400.00 400
Spray painting	\$1,400.00 400.

Subtotal :- \$3,990.00

Total:- \$20,701.85

total 7580.97
h/s: 6K
05Days

6K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: