

INS. CASE OWNER:

CC 4, LPC 180 22327, R1/2a3n2

LKK:
IDAC:

Sub-Owner:

RAGUL

DOI:

ASSIGNMENT

12/12/18

Date / Time:

10/12/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

XE 8080E

Claim No.:

18/18/18/000/02197

Name of Insured:

TROPIC PLANNERS XIOMASOPE P/L

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

7/12/18

Place of Accident:

TROPIC BANGSAH GREEN C

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SJS3492A



INSRS:

WSP:

Tel:

Liability:

RMKS:

Hitachi



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

13/12/18
SJSSJS3492A 15/12/18/000/02197/TP: 00A: 9/1/18
XE 8080E 15/12/18/000/02197/TP: 00A: 9/1/18
15/12/18/000/02197/TP: 00A: 9/1/18

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE:

After call ltr to OE:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

17/09/19

TYPE REPORT FOR URGENT APPROVAL

21/11/19

REPORT DONE

26/11/19

LPC APPROVED MANDATE.

10/12/19

SEND 1st OFFER TO TP.

TP ACCEPTED OFFER.

RECEIVED ORIG ON 4 RTA.

ALL DONE IN ORDER.

TO CLOSURE.

PRELIMINARY ADVICE Date/Time: 14/12/18

Sent By:

as

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

L19 SS 5,800.00 (9 days) Reduction: 60 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost (w/ GOR)

SS 5,886.00

COPY SENT

Loss of Rental (LOR):

SS - (days)

Loss of Use (LOU):

SS 720.00 (560 x 12 days)

Loss of Income (LOI):

SS - (5 x days)

LOR only ☐ LOU only ☒LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search:

SS 1.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost:

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4450.00

Total:

SS 6,607.00

Global Sum SS: -

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS 6,607.00

Name 1:

HITACHI CAPITAL ASIA PACIFIC PTE LTD

Payee 2: (3rd Party if N.A.)

SS -

Name 2:

Payee 3: (3rd Party if N.A.)

SS -

Name 3:

Form

REF:

JPC

22327/12/18

3563F

COE XPIRY: 2019/12/18

ASSIGNMENT

From: Date: 11/12/18

Estimated Cost:

QU ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MY

To inspect Vehicle No: SJS 3492A
at Workshop no: Hitachi Capital
of: 8 Fourth Lok Yang Road

Insured

Policy No

Claims No

Sum Insured

Excess:


(Client's Record)

Make of Veh:

Avoid 12pm-1pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

15K

IDAC Accident Rpt:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repair:

9

days

Res:

Yes or No

Lump Sum

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS ^{lup}

Vehicle: IN / OUT

Date:

Person Contacted

Veh No

SJS 3492A

V Regn: 2009 MY

Type: ☒ M. Car ☐ M. Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover ☐

Truck / Trailer or

Make

TOYOTA COROLLA (M7) 1.6A 1598

Colour

Grey

A/C

Insured / Std / NI / NA

Sp. Reading

100640

T/Radio

Insured / Std / NI / NA

Eng/No:

C/N:

MR053200106151692

Gen. Cond: Good ☒ Fair ☐ Poor ☐ Burnt ☐

Steering: Inorder ☒ Jammed ☐ Leaked ☐ Burnt ☐

Brake: Inorder ☒ Jammed ☐ Leaked ☐ Burnt ☐

Modi: Nil ☒ / R/Rim ☐ / STD A/Rim ☐

Tyre Size:

F:

195/65R15

R:

BS ☒ DUN ☐ EXNOVA ☐ GY ☐ FS ☐ LIZA ☐ MIC ☐ OHTSU ☐ PIR ☐ SUMI ☐

TOYO / YOKO or

Front

Rear

R/Bal

5

mm

R/Bal

5

mm

L/Bal

5

mm

L/Bal

5

mm

D.O.A.

07/12/18

D.O.L

12/12/18

Survey held at

HITACHI

Des. of Damage: ☒ Frt ☐ Rear ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

refer to email

Us \$5,000.00

CRAB: \$8,248.25 (60%)

MV = \$10,000 (cost)

LTA = \$9,876 (cost)

Nett = \$6,124.00 (cost)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

1) \$ + PC \$

1) Travel

1) Other

Report Format:

Lump Sum / L.B.I: (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

TOTAL



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 18/18/18/VC00/021197
Our ref: CC4/LPC18022327/R1ja3

Date: 14/12/2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJS 3492A

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12/12/2018 at the premises of M/s Hitachi Capital Asia Pacific Pte. Ltd. and have the following to report:-

Workshop Estimate Amount	: S\$	13,778.25
Revised Estimate Amount	: S\$	5,249.50
"Check" Items Amount	: S\$	2,988.25
Total (Including Check Items)	: S\$	8,237.75
Market Value	: S\$	16,000.00 (est.)
LTA Reimbursement Value	: S\$	9,876.00 (est.)
Nett Value	: S\$	6,124.00 (est.)

Description of Damage:

The vehicle sustained damages at the
Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 9.0 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	3563F

Vehicle Details

Vehicle No.:	SJ53492A
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	3ZZ4920596
Chassis No.:	MR053ZEE106151692
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,853.00
Original Registration Date:	13 Aug 2009
First Registration Date:	13 Aug 2009
Transfer Count:	0
Actual ARF Paid:	\$17,853.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Aug 2019
PARF Rebate Amount:	\$8,926.00

Intended COE Rebate Details

COE Expiry Date:	12 Aug 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$14,310.00
COE Rebate Amount:	\$892.00
Total Rebate Amount:	\$9,818.00

The information contained herein is correct as at 07 Dec 2018

OK

→ Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Singapore NRIC
Owner ID:	3563F
Vehicle Details	
Vehicle No.:	SJ53492A
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	3ZZ4920596
Chassis No.:	MR053ZEE106151692
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,853.00
Original Registration Date:	13 Aug 2009
First Registration Date:	13 Aug 2009
Transfer Count:	0
Actual ARF Paid:	\$17,853.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Aug 2019
PARF Rebate Amount:	\$8,926.00
Intended COE Rebate Details	
COE Expiry Date:	12 Aug 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$14,310.00
COE Rebate Amount:	\$950.00
Total Rebate Amount:	\$9,876.00

The information contained herein is correct as at 13 Dec 2018

OK

16,000
9,876

6,124

OK

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 10/12/2018

LONPAC

ACCIDENT DATE : 07/12/2018 @ 09:30

ATTN: MOTOR CLAIMS DEPT

VRN : SJS3492A

MODEL : TOYOTA ALTIS 1.6

TP VRN : XE8080E

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 FRONT BUMPER <i>OC</i>	1	\$ 510.00	\$ 510.00	
2 FRONT BUMPER CLIPS <i>re</i>	10	\$ 5.50	\$ 55.00	
3 FRONT BUMPER OUTER BRACKET R/L <i>re</i>	2	\$ 55.00	\$ 110.00	
4 FRONT REINFORCEMENT <i>re</i>	1	\$ 345.00	\$ 345.00	
5 FRONT CENTER GRILLE <i>sce</i>	1	\$ 315.00	\$ 315.00	
6 FRONT BUMPER LOGO <i>re</i>	1	\$ 75.00	\$ 75.00	
7 BONNET HINGE R/L ?	2	\$ 60.00	\$ 120.00	
8 FRONT LOWER GRILLE X	1	\$ 105.00	\$ 105.00	
9 HEADLAMP R/L <i>sce</i>	2	\$ 715.00	\$ 1,430.00	
10 SUPPORT PANEL <i>repair</i>	1	\$ 721.00	\$ 721.00	
11 FRONT BRACE PANEL <i>re</i>	1	\$ 115.00	\$ 115.00	
12 CONDENSER ?	1	\$ 1,507.00	\$ 1,507.00	
13 CONDENSER SUCTION <i>re</i>	1	\$ 375.00	\$ 375.00	
14 CONDENSER DISCHARGE X	1	\$ 435.00	\$ 435.00	
15 RADIATOR ?	1	\$ 1,984.00	\$ 1,984.00	
16 RADIATOR TOP COWLING X	1	\$ 105.00	\$ 105.00	
17 WIPER TANK X	1	\$ 145.00	\$ 145.00	
18 FRONT FENDER LOGO "VVT-I" R/L <i>re</i>	2	\$ 40.00	\$ 80.00	
19 CHASSIS RH <i>Repair</i> ?	1	\$ 600.00	\$ 600.00	
20 RADIATOR FAN COWLING ?	1	\$ 240.00	\$ 240.00	
21 RADIATOR FAN MOTOR X	1	\$ 463.00	\$ 463.00	
22 RADIATOR FAN BLADE X	1	\$ 160.00	\$ 160.00	
			\$ 9,995.00	
Discount -25%			\$ 2,498.75	
			\$ 7,496.25	

Special Nett

23 COOLANT	1	\$	42.00	\$	42.00
				\$	42.00
24 FRONT FENDER RH	Repair				
25 FRONT FENDER LH	Repair				
26 FRONT DOOR RH	Repair				
27 BONNET	Repair				

PARTS TOTAL \$ 7,538.25

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of FRONT Affected Area	900	\$	2,750.00
Putty, Blend And Spray Paint on FRONT Affected Area	1500	\$	2,250.00
Check Wiring, Re-align Headlamps, and Ensure Proper Functioning	30	\$	80.00
Remove and Replace A/C Condenser, Pipes and Radiator, Vacuum A/C System and Refill Gas	120	\$	180.00
Towing Charge	receipt	\$	? 100.00
Remove and Replace Front RH Door Window Glass to Facilitate Repair and Spray Painting		\$	X 100.00
Dismantle and Transfer Front RH Door Fittings & Mechanisms to Facilitate Repair		\$	X 180.00
Re-align/Repair Chassis Member	100	\$	600.00

LABOURS TOTAL \$ 6,240.00

Grand Total : \$ 13,778.25
Add 7% GST : \$ 964.48
Nett Total : \$ 14,742.73

No. of repair days: 20

Rahul
Hp 90010068

9 days

4/5

12/12/18 @ 1050



CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

Repair after repair

LKM Auto Consultants hence notify the Repairer of the following:

- To survey before spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurers Company

Acknowledged by Repairer

Signature:

Date:

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre .

804

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64863022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 10/12/2018

LONPAC

ACCIDENT DATE : 07/12/2018 @ 09:30

VRN : SJS3492A

ATTN: MOTOR CLAIMS DEPT

MODEL : TOYOTA ALTIS 1.6

TP VRN : XE8080E

	Qty	S\$ Unit	S\$ Amt	S\$ Labor
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 FRONT BUMPER <i>DE</i>	1	\$ 510.00	\$ 510.00	
2 FRONT BUMPER CLIPS <i>de</i>	10	\$ 5.50	\$ 55.00	
3 FRONT BUMPER OUTER BRACKET R/L <i>ne</i>	2	\$ 55.00	\$ 110.00	
4 FRONT REINFORCEMENT <i>M</i>	1	\$ 345.00	\$ 345.00	
5 FRONT CENTER GRILLE <i>sce</i>	1	\$ 315.00	\$ 315.00	
6 FRONT BUMPER LOGO <i>ne</i>	1	\$ 75.00	\$ 75.00	
7 BONNET HINGE R/L <i>? x su</i>	2	\$ 60.00	\$ 120.00	
8 FRONT LOWER GRILLE <i>X su</i>	1	\$ 105.00	\$ 105.00	
9 HEADLAMP R/L <i>sce</i>	2	\$ 715.00	\$ 1,430.00	
10 SUPPORT PANEL <i>repair</i>	1	\$ 721.00	\$ 721.00	
11 FRONT BRACE PANEL <i>pt</i>	1	\$ 115.00	\$ 115.00	
12 CONDENSER <i>? bl</i>	1	\$ 1,507.00	\$ 1,507.00	
13 CONDENSER SUCTION <i>* pt</i>	1	\$ 375.00	\$ 375.00	
14 CONDENSER DISCHARGE <i>X su</i>	1	\$ 435.00	\$ 435.00	
15 RADIATOR <i>? bl</i>	1	\$ 1,984.00	\$ 1,984.00	
16 RADIATOR TOP COWLING <i>X su</i>	1	\$ 105.00	\$ 105.00	
17 WIPER TANK <i>X su</i>	1	\$ 145.00	\$ 145.00	
18 FRONT FENDER LOGO "VVT-I" R/L <i>ne</i>	2	\$ 40.00	\$ 80.00	
19 CHASSIS RH <i>repair</i>	1	\$ 600.00	\$ 600.00	
20 RADIATOR FAN COWLING <i>? x su</i>	1	\$ 240.00	\$ 240.00	
21 RADIATOR FAN MOTOR <i>* dis</i>	1	\$ 463.00	\$ 463.00	
22 RADIATOR FAN BLADE <i>X su</i>	1	\$ 160.00	\$ 160.00	
			\$ 9,995.00	
Discount -25%			\$ 2,498.75	
			\$ 7,496.25	

hufin
20/12/18

P = \$ 7,364.00
- 25%

\$ 5,523.00

SN = \$ 42.00

L = \$ 2,700.00

\$ 8,265.00
- 20% LS

\$ 6,612.00

LS = \$ 5,500

Special Nett

23 COOLANT *nm*

1 \$

42.00 \$ 42.00
\$ 42.00

24 FRONT FENDER RH

Repair

25 FRONT FENDER LH

Repair

26 FRONT DOOR RH

Repair

27 BONNET

Repair

PARTS TOTAL \$ 7,538.25

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of FRONT Affected Area *900* \$ 2,750.00
Putty, Blend And Spray Paint on FRONT Affected Area *1500* ~~1500~~ \$ 2,250.00
Check Wiring, Re-align Headlamps, and Ensure Proper Functioning *30* ~~80.00~~ \$ 30.00
Remove and Replace A/C Condenser, Pipes and Radiator, Vacuum A/C System and Refill Gas *120* \$ 180.00
Towing Charge *50* ~~100.00~~ \$ 50.00
Remove and Replace Front RH Door Window Glass to Facilitate Repair and Spray Painting *nm* \$ X 100.00
Dismantle and Transfer Front RH Door Fittings & Mechanisms to Facilitate Repair *nm* \$ X 180.00
Re-align/Repair Chassis Member *100* \$ 600.00

LABOURS TOTAL *2700* \$ 6,240.00

Grand Total : \$ 13,778.25
Add 7% GST : \$ 964.48
Nett Total : \$ 14,742.73

No. of repair days: 20

Ram
Hp 90010068
9 days
4/3
12/12/18 @ 1050

CUSTOMER SIGNATURE



HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

Recovery after repair

LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before *nm* spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Catherine Chong (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 10 December, 2018 2:10 PM
To: Admin-D (LKKAuto)
Cc: MT_Claim_SG; vonnlm.siow@hcspl.com.sg
Subject: FW: SJS3492A / XE8080E DOA: 7/12/2018 TP SURVEY & LIABILITY
Attachments: SJS3492A.pdf

3:27pm @ 10/12/18

vehicle In

penon@von

agreed survey on 11/12/18

Our Ref : 18/18/18/VC00/021197

Dear Catherine,

Kindly proceed to survey and revert to them on liability.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: Vonn, LM Siow [mailto:vonnlm.siow@hcspl.com.sg]

Sent: Monday, 10 December, 2018 1:30 PM

To: CHEW BENG KEE; GERALD POH WEE BIN

Cc: Jamilah, Binte MohdKassim; JiongHow, Ng

Subject: SJS3492A / XE8080E DOA: 7/12/2018 TP SURVEY & LIABILITY

Dear sirs,

We refer to the subject above and the attachment is for your reference.

Vehicle is IN workshop.

Kindly arrange survey with us and advise on the liability.

Thanks & Regards

Vonn Siow

Motor Claims Advisor

Auto Servicing

Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705

DID: 6833 6274 Mobile: 96435107

e: vonnlm.siow@hcspl.com.sg


Mei Kwan (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 12 December, 2018 8:58 AM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: SJS3492A / XE8080E DOA: 7/12/2018 TP SURVEY & LIABILITY *** LKK REF: CC4/LPC18022327/ja3
Attachments: 12122018085440.pdf
Categories: HMK

Dear Mei Kwan,

Attached copy of insured's GIA report for your attention.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Tuesday, 11 December, 2018 8:39 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; Admin A; CS A Team; Joy Irene (LKKAUTO)
Subject: RE: SJS3492A / XE8080E DOA: 7/12/2018 TP SURVEY & LIABILITY *** LKK REF: CC4/LPC18022327/ja3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

LPC ref: 18/18/18/VC00/021197
LKK REF: CC4/LPC18022327/ja3

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of insured's accident report for our necessary action.

Please take note that the case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Vehicle is IN workshop.

Kindly arrange survey with us and advise on the liability.

Thanks & Regards

Vonn Siow
Motor Claims Advisor
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
DID: 6833 6274 Mobile: 96435107
e: vonnlm.slow@hcspl.com.sg
w: www.hitachi-capital.com.sg



This email has been checked for viruses by AVG antivirus software.
www.avg.com



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18022327/R1ha3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 15-01-2020		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 8080E	Veh. Inspected	SJS 3492A	
Policy No.	Z/18/VC00/102393	Coverage (\$)	0.00	
Claim No.	18/18/18/VC00/021197	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	10/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS 1.6 (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MR053ZEE106151692	Colour	GREY	
Odometer	100640	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	BRIDGESTONE	5 mm	
L/H Front Tyre	195/65 R15	BRIDGESTONE	5 mm	
R/H Rear Tyre	195/65 R15	BRIDGESTONE	5 mm	
L/H Rear Tyre	195/65 R15	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/12/2018	Inspection Date	12/12/2018	
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 3492A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	510.00	510.00
10	FRONT BUMPER CLIPS @\$5.50	NECESSARY	55.00	55.00
2	FRONT BUMPER OUTER BRACKET R/H @\$55.00	NECESSARY	110.00	110.00
1	FRONT REINFORCEMENT	BENT	345.00	345.00
1	FRONT CENTER GRILLE	SCRATCHED	315.00	315.00
1	FRONT BUMPER LOGO	NECESSARY	75.00	75.00
2	BONNET HINGE R/L @\$60.00	SERVICEABLE	120.00	-
1	FRONT LOWER GRILLE	SERVICEABLE	105.00	-
2	HEADLAMP R/L @\$715.00	SCRATCHED	1,430.00	1,430.00
1	SUPPORT PANEL	TO REPAIR SEE LABOUR	721.00	-
1	FRONT BRACE PANEL	BENT	115.00	115.00
1	CONDENSER	BENT	1,507.00	1,507.00
1	CONDENSER SUCTION	BENT	375.00	375.00
1	CONDENSER DISCHARGE	SERVICEABLE	435.00	-
1	RADIATOR	BENT	1,984.00	1,984.00
1	RADIATOR TOP COWLING	SERVICEABLE	105.00	-
1	WIPER TANK	SERVICEABLE	145.00	-
2	FRONT FENDER LOGO "VVT-I" R/L @\$40.00	NECESSARY	80.00	80.00
1	CHASSIS RH	TO REPAIR SEE LABOUR	600.00	-
1	RADIATOR FAN COWLING	SERVICEABLE	240.00	-
1	RADIATOR FAN MOTOR	DISTORTED	463.00	463.00
1	RADIATOR FAN BLADE	SERVICEABLE	160.00	-
1	FRONT FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT FENDER LH (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT DOOR RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	BONNET (NPA)	TO REPAIR SEE LABOUR	-	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-2,498.75	-1,841.00
			7,496.25	5,523.00
	SPECIAL NETT ITEMS			
1	COOLANT (SN)	NECESSARY	42.00	42.00
			42.00	42.00
	LABOUR			
	PANEL BEAT ,CUT ,WELD ,RE-ALIGN & REPLACE DAMAGED PARTS OF FRONT AFFECTED AREA ,INCLUSIVE OF THE RPAIR OF SUPPORT PANEL,CHASSIS RH,FRONT FENDER RH,FRONT FENDER LH,FRONT DOOR RH AND BONNET.		2,750.00	900.00
	PUTTY,BLEND AND SPRAY PAINT ON FRONT AFFECTED AREA.		2,250.00	1,500.00
	CHECK WIRING ,RE-ALIGN HEADLAMPS ,AND ENSURE PROPER FUNCTIONING.		80.00	30.00
	REMOVE AND REPLACE A/C CONDENSER ,PIPES AND RADIATOR ,VACUUM A/C SYSTEM AND REFILL GAS.		180.00	120.00
	TOWING CHARGE.		100.00	50.00
	REMOVE AND REPLACE FRONT RH DOOR WINDOW GLASS TO FACILITATE REPAIR AND SPRAY PAINTING.	NOT NECESSARY	100.00	-
	DISMANTLE AND TRANSFER FRONT RH DOOR FITTINGS & MECHANISMS TO FACILITATE REPAIR.	NOT NECESSARY	180.00	-
	RE-ALIGN /REPAIR CHASSIS MEMBER.		600.00	100.00
			6,240.00	2,700.00
GRAND TOTAL			13,778.25	8,265.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,500.00

Report Ref No. CC4/LPC18022327/R1ha3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.