

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 10/12/2018

LONPAC

ATTN: MOTOR CLAIMS DEPT

ACCIDENT DATE : 07/12/2018 @ 09:30
 VRN : SJS3492A
 MODEL : TOYOTA ALTIS 1.6
 TP VRN : XE8080E

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 FRONT BUMPER <i>OE</i>	1	\$ 510.00	\$ 510.00	
2 FRONT BUMPER CLIPS <i>new</i>	10	\$ 5.50	\$ 55.00	
3 FRONT BUMPER OUTER BRACKET R/L <i>new</i>	2	\$ 55.00	\$ 110.00	
4 FRONT REINFORCEMENT <i>PA</i>	1	\$ 345.00	\$ 345.00	
5 FRONT CENTER GRILLE <i>Sca</i>	1	\$ 315.00	\$ 315.00	
6 FRONT BUMPER LOGO <i>new</i>	1	\$ 75.00	\$ 75.00	
7 BONNET HINGE R/L <i>?</i>	2	\$ 60.00	\$ 120.00	
8 FRONT LOWER GRILLE <i>X</i>	1	\$ 105.00	\$ 105.00	
9 HEADLAMP R/L <i>Sca</i>	2	\$ 715.00	\$ 1,430.00	
10 SUPPORT PANEL <i>repair</i>	1	\$ 721.00	\$ 721.00	
11 FRONT BRACE PANEL <i>PA</i>	1	\$ 115.00	\$ 115.00	
12 CONDENSER <i>?</i>	1	\$ 1,507.00	\$ 1,507.00	
13 CONDENSER SUCTION <i>* PA</i>	1	\$ 375.00	\$ 375.00	
14 CONDENSER DISCHARGE <i>X</i>	1	\$ 435.00	\$ 435.00	
15 RADIATOR <i>?</i>	1	\$ 1,984.00	\$ 1,984.00	
16 RADIATOR TOP COWLING <i>X</i>	1	\$ 105.00	\$ 105.00	
17 WIPER TANK <i>X</i>	1	\$ 145.00	\$ 145.00	
18 FRONT FENDER LOGO "VVT-I" R/L <i>new</i>	2	\$ 40.00	\$ 80.00	
19 CHASSIS RH <i>Repair</i>	1	\$ 600.00	\$ 600.00	
20 RADIATOR FAN COWLING <i>?</i>	1	\$ 240.00	\$ 240.00	
21 RADIATOR FAN MOTOR <i>X</i>	1	\$ 463.00	\$ 463.00	
22 RADIATOR FAN BLADE <i>X</i>	1	\$ 160.00	\$ 160.00	
			<u>\$ 9,995.00</u>	
Discount -25%			<u>\$ 2,498.75</u>	
			<u>\$ 7,496.25</u>	

Special Nett

23 COOLANT	1	\$	42.00	\$	42.00
				\$	42.00
24 FRONT FENDER RH	Repair				
25 FRONT FENDER LH	Repair				
26 FRONT DOOR RH	Repair				
27 BONNET	Repair				

PARTS TOTAL \$ 7,538.25

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of FRONT Affected Area	900	\$	2,750.00
Putty, Blend And Spray Paint on FRONT Affected Area	1500 1450	\$	2,250.00
Check Wiring, Re-align Headlamps, and Ensure Proper Functioning	30	\$	80.00
Remove and Replace A/C Condenser, Pipes and Radiator, Vacuum A/C System and Refill Gas	120	\$	180.00
Towing Charge	receipt	\$	100.00
Remove and Replace Front RH Door Window Glass to Facilitate Repair and Spray Painting	X	\$	100.00
Dismantle and Transfer Front RH Door Fittings & Mechanisms to Facilitate Repair	X	\$	180.00
Re-align/Repair Chassis Member	100	\$	600.00

LABOURS TOTAL \$ 6,240.00

Grand Total : \$ 13,778.25
Add 7% GST : \$ 964.48
Nett Total : \$ 14,742.73

No. of repair days: 20

Ramal
Hp 90010068
9 days
4/3
12/12/18 @ 1050



HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

CUSTOMER SIGNATURE

Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: